



File No.: 04-1000-20-2022-372

August 12, 2022

s.22(1)

Dear s.22(1)

Re: Request for Access to Records under the Freedom of Information and Protection of Privacy Act (the "Act")

I am responding to your request of July 11, 2022 under the *Freedom of Information and Protection of Privacy Act, (the Act)*, for:

Records regarding the origin and cause of a fire at 203 Abbott Street on April 8, 2022, including the following:

- 1. Two years of building inspection reports including orders issued or contraventions:
- 2. Two years of fire prevention inspection reports including orders issued or contraventions; and
- 3. Order issued following first event of fire specific to the sprinkler system reactivation.

Date Range: July 1, 2020 to July 7, 2022.

All responsive records are attached. Some information in the records has been severed (blacked out) under s.22(1) of the Act. You can read or download this section here: http://www.bclaws.ca/EPLibraries/bclaws_new/document/ID/freeside/96165_00.

Under section 52 of the Act, and within 30 business days of receipt of this letter, you may ask the Information & Privacy Commissioner to review any matter related to the City's response to your FOI request by writing to: Office of the Information & Privacy Commissioner, info@oipc.bc.ca or by phoning 250-387-5629.

If you request a review, please provide the Commissioner's office with: 1) the request number (#04-1000-20-2022-372); 2) a copy of this letter; 3) a copy of your original request; and 4) detailed reasons why you are seeking the review.

Yours truly,

Kevin Tuerlings, FOI Case Manager, for

[Signed by Kevin Tuerlings]

Cobi Falconer, MAS, MLIS, CIPP/C Director, Access to Information & Privacy <u>cobi.falconer@vancouver.ca</u> 453 W. 12th Avenue Vancouver BC V5Y 1V4

If you have any questions, please email us at foi@vancouver.ca and we will respond to you as soon as possible. Or you can call the FOI Case Manager at 604-871-6584.

Encl. (Response package)

:pm





FIRE & RESCUE SERVICES

NOTICE OF VIOLATION

General

Firehall Office Use only			
Routine Insp	ection	☐ Incident	
Entered into	Date: _		

Date: _	of Moletian	Tot nous	Time:	· C
	of Violation;	LICENSE H		Fax#:
	s Owner:	4 (6)		Phone#: \(\frac{1}{2}\) \(\frac{1}{2}\) \(\frac{1}{2}\)
	of Notice:	100 4000		(signature)
ITEM	CODE	Vancouver Fire By-La	w Violations - FO	OR IMMEDIATE COMPLIANCE
	6.1.1.5.(4) DIV B	Have Portable Fire Extinguis securely affixed to serviced ed		TBC qualified technician, and service tag
	6.1.1.5.(4) DIV B		serviced by ASTTBC	qualified technician, and service tag
	6.1.1.5.(4) DIV B	Have EMERGENCY LIGHTIN	IG SYSTEMS serviced	by ASTTBC qualified technician, and
	6,1.1.5.(4) DIV B	service tag securely affixed to Have SPRINKLER SYSTEM securely affixed to serviced ed	serviced by ASTTBC q	ualified technician, and service tag
	2.7.1.6.(1) DIV B		N- CHI TO THE TOTAL CONTRACT OF THE TOTAL CO	e clear and free of any obstructions at all
	2.1.5.1.(2) DIV B	Provide 5lbs "ABC" Class P	ortable Fire Extinguis	her.
	6.1.1.4.(1) DIV B	Provide 24 Hour Fire Watch functional.	until such time that fi	re alarm system is reset and fully
		104 5070 KENSPO	crond just	ONE WELL
		Jan/25/2021 -	re fro ch Va ea be th Fa	his Notice of Violation makes you legally sponsible for any consequences arising om this matter. A re-inspection service harge of \$200.00 (or as per the current ancouver Fire By-law fee schedule) for ich hour or part thereof (plus G.S.T.) will e assessed for each re-inspection, until e violations noted have been corrected.
	MPORTANT INFORM	ATION RENSEIGNEMI	ents importants	重要資料 競技人馬你問題

Form 2019 July

FOR RE-INSPECTION APPOINTMENT DIAL 311

FD 20-G





FIRE & RESCUE SERVICES

NOTICE OF VIOLATION

General

Firehall Office Use only			
Routine Insp	ection	☐ Incident	
Entered into	Date: _		

	s Owner:		4 7/15 1/16 Fax#:
son	Notice Civen To:	Title:	1 (*
eipt	of Notice: 5 Marie	e Vanembort.	(signati
M	CODE	Vancouver Fire By-Law Violations -	FOR IMMEDIATE COMPLIANCE
	6.1.1,5.(4) DIV B	Have Portable Fire Extinguishers serviced by a securely affixed to serviced equipment.	ASTTBC qualified technician, and service tag
	6.1.1.5.(4) DIV B	Have FIRE ALARM SYSTEM serviced by ASTT securely affixed to serviced equipment.	BC qualified technician, and service tag
4	6.1.1.5.(4) DIV B	Have EMERGENCY LIGHTING SYSTEMS serv service tag securely affixed to serviced equipme	
Ĭ	6.1.1.5.(4) DIV B	Have SPRINKLER SYSTEM serviced by ASTTE securely affixed to serviced equipment.	
	2.7.1.6.(1) DIV B	Ensure all means of egress and access to exit	ts are clear and free of any obstructions at all
	2.1.5.1.(2) DIV B	Provide 5lbs "ABC" Class Portable Fire Exting	guisher.
	6.1.1.4.(1) DIV B	Provide 24 Hour Fire Watch until such time the functional.	nat fire alarm system is reset and fully
		18 All The down most be	short and todahed
		Ex riors norded on has a	1 mis "Fin dead horry 3
		of No stelling in holling	3.
	e 22/4)	Pilo Source on appoint p	entaile.
	11 6 (G. A. S.22(1)	ally storate on intelled	upt @Enselv Meson
-	() s.22(1)	Depth of the leave by 75%	This Notice of Violation makes you legally
	1	Dut it it rules from smoke	responsible for any consequences arising from this matter. A re-inspection service
	· ·	alutator.	charge of \$200.00 (or as per the current Vancouver Fire By-law fee schedule) for
7	5.22(1)	Orix a mile welling	each hour or part thereof (plus G.S.T.) will be assessed for each re-inspection, until
	(No delega en aprimater papa.	the violations noted have been corrected. Failure to comply with the above
			instructions may result in legal action against the Owner/Occupier.
	MPORTANT INFORM		rs 重要資料 前投人爲你看譯
	मूर्व लटकर्व व्यथ बरवे विमे बेले दि	CHÍ DẪN QUAN TRONG प्रात को के người dịch hố emises disclosed violations which may constitute a hazard to l	INFORMACIÓN IMPORTANTE Busque alguien gue le traduzca

Form 2019 July



Property - Inspection History Report

Property Address: 203 ABBOTT ST

Building Name: WINTERS RESIDENCE SRO (L) FH District:

FPO District: 50

02

3 - Ordinary - Protected/Unprotected Combustible

Date of Report: July 13, 2022

Business Name: Winters Residence

Last Inspection Date: December 8, 2021

Property class: C Residential Tenant

Inspection Class

Inspected Date

Status

Assigned To

Inspector

Complaint

December 8, 2021

Satisfactory

FP Capt Problem Buildingice, Fraser

Complaint - Hallway Storage - Verbal

Complaint

Capt Lee/FPI Price attended. Minimal clutter outside room. Verbal warning to management. No further action required.

Inspection Class

Inspected Date

Status

Assigned To

Inspector

Residential Tenant - C

September 14, 2021

Satisfactory

FP Single Room Occupanicieticholas

- Fire Alarm Systems

Status Satisfactory

The fire alarm system has past its service date and is now in need of servicing by a qualified service contractor.

Note:

NOV recheck - Cleared

NOV recheck revealed that the FA had been serviced

NSD 22 Jun 22

Inspection Class

Inspected Date

Status

Assigned To

Inspector

Residential Tenant - C

June 15, 2021

Unsatisfactory

FP Single Room Occupanic eticholas

Violation Notice: Issued

Received by: Stella

Position: Manager

- Fire Alarm Systems

Status Unsatisfactory

The fire alarm system has past its service date and is now in need of servicing by a qualified service contractor.

- Other (Specify)

Status Satisfactory

- Storage in path of egress (Halls)
- Reduce fuel load by 75% in unit

Note: Reinspection failed

Inspection recheck of the fire alarm revealed that it remains in Fail status.

Contacted Royal City Fire Supplies to confirm issues. Fail due to non access to CRU. Atira confirmed that they are currently working with owner to have techs access the CRU by the end of the week.

Spoke to tenants of CRU that Fire protection techs will be accessing their units.



Property - Inspection History Report

Property Address: 203 ABBOTT ST

Building Name: WINTERS RESIDENCE SRO (L) FH District:

02

FPO District: 50

Inspection Class

Inspected Date

Status

Assigned To

Inspector

Complaint

April 28, 2021

Satisfactory

FP Capt Problem Buildings, Clifford

Note: MTI issued

Alarm has a failed service tag.

Multiple NOV's issued by fire prevention.

MTI issued for fail to maintain alarm.

TA59124

Inspection Class

Inspected Date

Status

Assigned To

Inspector

Residential Tenant - C

April 27, 2021

Unsatisfactory

FP Single Room Occupanicie dicholas

Violation Notice: Issued

Received by: See previous inspection

Position: [None selected]

- Emergency Lighting

The emergency lighting unit has past its service date and is now in need of servicing by a qualified service contractor.

- Fire Alarm Systems

Status Unsatisfactory

Status Satisfactory

The fire alarm system has past its service date and is now in need of servicing by a qualified service contractor.

- Other (Specify)

Status Unsatisfactory

- Storage in path of egress (Halls)
- Reduce fuel load by 75% in unit 2201

Note: NOV Recheck - Failed

Inspection recheck on the NOV resulted in the following:

- Emergancy lighting violation cleared - NSD 22 Feb 23

The following violations remain:

- FA failed Service tag failure
- Obstructions in hall/egress
- Units 22(1) remains hoarded

Inspection Class After Incident

Inspected Date

Status

Assigned To

Inspector

February 19, 2021

Satisfactory

FP Capt Problem Buildings, Clifford

After fire Note:

After fire.

Sprinkler activated.

Sprinkler head replaced.

Alarm has been reset, however the alarm requires additional work from a previous inspection.

People Who Care About You

Page 2 of 46



Property - Inspection History Report

Property Address: 203 ABBOTT ST

FH District:

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

Alarm tech requires access to commercial units in order to complete the annual alarm service.

Inspection Class

Inspected Date

Status

Assigned To

Inspector

02

Hazard Assessment Inspection

February 11, 2021

Satisfactory

FP Capt Problem Buildings, Clifford

- Housekeeping

Status Satisfactory

Reduce fuel load in Unit # 220 and # 220 by 75%

Note: Hoarding recheck

Rooms have been reduced of contents and access in and around room is OK.

Inspection Class

Inspected Date

Status

Assigned To

Inspector

Hazard Assessment Inspection

January 20, 2021

Unsatisfactory

FP Capt Problem Buildingselak, Justin

Status Unsatisfactory

Violation Notice: Issued

Received by: Stella G

Position: [None selected]

- Housekeeping

Reduce fuel load in Unit # 2211 and # 2211 by 75%

Note: Hoarding Unit # 22(1)

On site we met with Stella, Staff.

Room # is no longer an issue. 3/9 CIRS at time of inspection.

Room # has not chnaged, reduce fuel load by 75%.

Inspection Class

Inspected Date

Status

Assigned To

Inspector

Residential Tenant - C

January 20, 2021

Unsatisfactory

FP Single Room Occupationek, Justin

Violation Notice: Issued

Received by: Stella G

Position: [None selected]

- Emergency Lighting

The emergency lighting unit has past its service date and is now in need of servicing by a qualified service contractor.

2 - Fire Alarm Systems

Status Unsatisfactory

Status Unsatisfactory

The fire alarm system has past its service date and is now in need of servicing by a qualified service contractor.

Sprinklers. - Sprinkler Systems

Status Satisfactory

The sprinkler system has past its service date and is now in need of servicing by a qualified service contractor.

Note: NoV issued - FA

On site we met with staff, Stella.

Violations found during inspection:

EL - Red X.



Property - Inspection History Report

Property Address: 203 ABBOTT ST

Building Name: WINTERS RESIDENCE SRO (L) FH District:

02 FPO District: 50

Fire Alarm - additional work reg.

Storage in halls.

ABC/Sprinkler NSD - Nov.2021

RIOK

Inspection Class Residential Tenant - C Inspected Date

Status

Assigned To

Inspector

Violation Notice: Issued

October 22, 2020

Unsatisfactory

FP Single Room Occupationsk, Justin

Position: [None selected]

- Exit Signs

Received by: Ellen

The alternating current (normal power) bulbs in the exit sign are missing/burnt-out and shall be replaced.

- Fire & Exit Doors

Status Satisfactory

Status Satisfactory

Install "FIRE DOOR - KEEP CLOSED" signage on the visible side of the door when in the open position.

Remove hold open device on fire door.

- Fire Alarm Systems

Status Unsatisfactory

The fire alarm system has past its service date and is now in need of servicing by a qualified service contractor.

Sprinklers. - Sprinkler Systems

Status Unsatisfactory

The sprinkler system has past its service date and is now in need of servicing by a qualified service contractor.

NoV issued Note:

On site we met with the manager.

Violations found during inspection:

- Sprinkler due for servicing Oct.2020
- FA due for service asap
- No storage in halls.
- Reduce fuel load in unit # and 5200 by 50%

NoV issued

Inspection Class	Inspected Date	Status	Assigned To	Inspector
Hazard Assessment Inspection	October 22, 2020	Unsatisfactory	FP Capt Problem Buildingelak, Justin	

Position: [None selected] Violation Notice: Issued Received by: Ellen

- Housekeeping

Status Unsatisfactory

Reduce fuel load in Unit # 220 and # 5220 by 75%



Property - Inspection History Report

Property Address: 203 ABBOTT ST

FH District: 02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

Note: Hoarding unit # and and

Reduce fuel load in Unit # and # to 75%.

6/9 CIRS.

NoV issued

Inspection Class

Inspected Date

Status

Assigned To

Inspector

Hazard Assessment Inspection

July 28, 2020

Unsatisfactory

FP Capt Problem Buildingselak, Justin

Violation Notice: Issued

Received by: Gina Vanemberg

Position: [None selected]

- Housekeeping

Reduce fuel load in Unit # 2011 by 75%

Status Unsatisfactory

Note: Hoarding Unit # 5.22(1) and \$22(1)

On site we met with the manager, Gina.

Unit # - Not hoarded ~ 2/9 CIRS.

Unit # Reduce fuel load by 75% ~ 7/9 CIRS. Remove cover from smoke detector.

Not hoarded ~ 3/9 CIRS. No storage from sprinkler pipe.

Inspection Class

Inspected Date

Status

Assigned To

Inspector

Status Unsatisfactory

Residential Tenant - C

July 28, 2020

Unsatisfactory

FP Single Room Occupatheitek, Justin

Violation Notice: Issued

Received by: Gina Vanemberg

Position: [None selected]

- Exit Signs

The alternating current (normal power) bulbs in the exit sign are missing/burnt-out and shall be replaced.

- Fire & Exit Doors

Status Unsatisfactory

Install "FIRE DOOR - KEEP CLOSED" signage on the visible side of the door when in the open position.

Remove hold open device on fire door.

- Fire Alarm Systems

Status Unsatisfactory

The fire alarm system has past its service date and is now in need of servicing by a qualified service contractor.

NoV Issued - Multiple Violations

On site we met with the manager, Gina.

- Fire Alarm needs to be serviced, additional work required.
- Singage on fire doors is needed.
- Exit bulbs need to be replaced
- No storage in hallways/common areas



Property - Inspection History Report

Property Address: 203 ABBOTT ST

Building Name: WINTERS RESIDENCE SRO (L) FH District:

02

FPO District: 50

Sprinkler NSD - Oct.2020 EL/ABC NSD - Oct.2020

NoV issued.

Inspection Class Complaint

Inspected Date June 11, 2020

Status Satisfactory Assigned To FP General

Inspector

De arcangelis, Lore

Note: breeze way

Complaint - Breeze way common area with restaurant, cluttered, egress/access compromised.

11-Jun 203 Abbott C. Lee / L. De Arcangelissatisfactory Complaint

SRO

Garbage /

combustibles in breezeway

Verbal to manager to clean up.

shared with 102 Water St - responsibility shared, complaint justified.

Inspection Class

Inspected Date

Status

Assigned To

Inspector

Hazard Assessment Inspection

May 13, 2020

Satisfactory

FP Capt Problem Buildings, Clifford

Note: Hoarding

Issues regarding hoarding for rooms \$.22(1)

Spoke with manager.

is OK now.

22(1) is better than before and manager asked us to check it, but due to covid and we didnt post 24 hours notice to tenant, we did not see the room.

Advised manager to monitor room and if it gets worse call 3-1-1

Inspection Class

Inspected Date

Status

Assigned To

Residential Tenant - C

May 13, 2020

Satisfactory

Inspector FP Single Room OccupancejeSlifford

Note:

RIOK

Only checked alarm, NSD Oct 2020.

Inspection Class

Inspected Date

Status

Assigned To

Inspector

Problem Building

March 19, 2020

Satisfactory

FP Capt Problem Buildingselak, Justin

COVID-19 Note:

> Delivered COVID 19 information package to the Manager Fire safety during COVID 19 outbreak

Inspection Class

Inspected Date

Status

Assigned To

Inspector

People Who Care About You

Page 6 of 46



Property - Inspection History Report

Property Address: 203 ABBOTT ST

WINTERS RESIDENCE SRO (L)

FH District:

02

FPO District: 50

Hoarding

November 28, 2019

Satisfactory

FP Capt Problem Buildings, Clifford

Note:

DNO

Building Name:

Met with manager Joanna.

Inspection of room due to hoarding.

Room is hoarded level 8. DNO placed on room 22(1)

Spare room available for tenant.

Inspection Class Hoarding

Inspected Date

November 27, 2019

Status Satisfactory Assigned To

Inspector

FP Capt Problem Buildings, Clifford

Note:

DNO removed

Met witth manager Joanna.

Previous DNO on rooms 22(1) and 22(1)

Both rooms are cleanand clear.

No longer DNO.

RIOK.

Inspection Class Hoarding

Inspected Date November 5, 2019 Status Satisfactory Assigned To

Inspector

FP Capt Problem Buildings, Clifford

Note:

Hoarding

Meet with manager Motty.

Issues with hoarding in rooms 5.22(1)

Discussed hoarding protocol.

Spare room is being prepared for use in case DNO is required.

Will follow up.

Inspection Class

Inspected Date

Status

Assigned To

Inspector

Single Room Occupancy

November 4, 2019

Satisfactory

FP Single Room Occupancie Slifford

Note:

RIOK

Met with manager Joana.

Extinguishers, alarm, sprinkler, expires October 2020.

Inspection Class

Inspected Date

Status

Assigned To

Inspector

Hoarding

July 11, 2019

Satisfactory

FP Capt Problem Buildi Museske, Darren

Note:

Complaint # 2211

Access provide by management / BC housing rep.

People Who Care About You

Page 7 of 46



Property - Inspection History Report

Property Address:

FH District:

02 FPO District: 50

Building Name:

WINTERS RESIDENCE SRO (L)

Inspection revealed the room in a satisfactory condition.

Main portion of room was mostly cleared.

Verbal order to staff to have tenant clear items from door swing and entrance area.

Inspection Class

Inspected Date

Status

Assigned To

Inspector

Hoarding

July 10, 2019

Satisfactory

FP Capt Problem Buildi Museske, Darren

Complaint unit Note:

- Request from BC Housing staff to inspect \$2200 for hoarding.
- Tenant is storing items in half of room for somebody else.
- Tenant stated that items will be removed within one week.
- No issues with access into room door and entry area are clear.

Verbal to management and tenant to clear out items and will re-check in one week.

Inspection Class Inspected Date Status Assigned To Inspector Meeting February 8, 2019 Satisfactory FP Capt Problem Buildings minden, Marcus

- Accessibility

Status Satisfactory

Remove unauthorized pad locks on door to room

Reinspection ok Note:

Locks removed from door

Inspection Class Meeting

Inspected Date February 7, 2019 Status Unsatisfactory

Assigned To FP Capt Problem Buildings, Clifford

Inspector

Status Unsatisfactory

Violation Notice: Issued

Received by: Stella

Position: Employee

- Accessibility

Remove unauthorized pad locks on door to room 2211

Note: Meeting (NOV issued)

Meeting follow up regarding hoarding rooms.

Room is all clean, case closed.

Phoenix cleaning company on site cleaning the last little bit.

NOV issued for unauthorized door locks on unit seeing

2 pad locks latched on door at room \$22(1)

Ordered to have them removed.

Inspection Class Inspected Date Hoarding January 29, 2019 Status Satisfactory

Assigned To

Inspector

FP Single Room Occupatorieminden, Marcui

- Combustible Load

Status Satisfactory

Hoarding in room CIRS 5/8



Property - Inspection History Report

Property Address:

FH District: 02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

2 - Fire & Exit Doors

Status Satisfactory

The fire door shall swing, on a vertical axis, in the direction of exit travel.

Astronomy

Remove stored materials away from the fire door.

Fire door is to be repaired to an acceptable working condition.

3 - Fire Alarm Systems

Status Satisfactory

The fire alarm smoke detector is missing and shall be re-installed by a qualified service contractor.

Note: hoarding recheck

Management dealt with all issues in these rooms. No further cause for concern

Inspection Class
Single Room Occupancy

Inspected Date January 29, 2019 Status Satisfactory Assigned To

Inspector

FP Single Room Occupatoriesninden, Marcus

Note: RIOK

Fire protection equipment serviced by Royal City. NSD Sept 2019

F/A - ok

F/E - ok

E/L - ok

Sprklr - Ok

Ī	Inspection Class
	Hoarding

Inspected Date January 24, 2019

Status Unsatisfactory Assigned Tc

Inspector

FP Single Room Occupation € lifford

Violation Notice: Issued

Received by: Leslie Craig

Position: Manager

1 - Combustible Load

Status Unsatisfactory

Hoarding in room CIRS 5/8

2 - Fire & Exit Doors

Status Unsatisfactory

The fire door shall swing, on a vertical axis, in the direction of exit travel.

Remove stored materials away from the fire door.

Fire door is to be repaired to an acceptable working condition.

- Fire Alarm Systems

Status Unsatisfactory

The fire alarm smoke detector is missing and shall be re-installed by a qualified service contractor.

Note: Hoarding Room

Room Hoarded CIRS 5

Missing h/w smoke alarm

Room door unable to open 90 degrees

No clear path of travel into room



Property - Inspection History Report

Property Address:

FH District:

02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

Hoarding Room 22(1) Note:

> Room hoarded CIRS 7/8 Cannot gain access to room

Room door has multiple door panels missing from door. Breach in fire separation.

Note: Hoarding Room 5.72(1)

Room hoarded CIRS 8/9.

Occupant of room also known to light fires in room and in hallways.

DNO issued immediately for this room as room unfit and unsafe to occupy. Management in contact withs.22(1) Occupant not at home at time of DNO. Occupant will be found alternative accommodations my management immediately or through occupants assessment team.

Inspection Class

Inspected Date

Status

Assigned To

Inspector

Lockbox

December 21, 2018

Satisfactory

FP General

Price, Fraser

Note: Knox FDC Installation

2 Knox caps installed at FDC location in front of building.

Inspection Class

Inspected Date

Status

Assigned To

Inspector

Single Room Occupancy

July 21, 2017

Satisfactory

FP Single Room Occupation cangelis, Lore

Fire Doors. - 1531 Maintenance

Status Satisfactory

Article 2.2.2.4.v

Inspection and Maintenance

3) Doors in fire separations shall be operated at intervals not greater than 1 month to ensure that they are properly maintained in accordance with Sentence (1), as specified in the fire safety plan prepared in conformance with Section

2.8.

203 ABBOTT ST - SARAH - SATISFACTORY Note:

> 203 ABBOTT ST - SARAH - SATISFACTORY - ATIRA NOW CONTRACTOR NEW DOORS BEING INSTALLED

Inspection Class Single Room Occupancy Inspected Date June 15, 2017

Status

Assigned To

Inspector

Unsatisfactory

FP Single Room Occupations Lorne

Violation Notice: Issued

Received by: n/A

Position: [None selected]

Fire Doors. - 1531 Maintenance

Status Unsatisfactory

Article 2.2.2.4.v

Inspection and Maintenance

3) Doors in fire separations shall be operated at intervals not greater than 1 month to ensure that they are properly maintained in accordance with Sentence (1), as specified in the fire safety plan prepared in conformance with Section 2.8.



Property - Inspection History Report

Property Address:

FH District:

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

02

Note: Annual Inspection

Annual inspection NSD June 17/2017

NOV written to have standpipe put into proper working order, tag currently showing add't work required. Also written for fire escape door on the third floor is impeded by the door jam. Verbal from on site contractor that they would start the work this coming monday. NOV also issued to have the paint cans removed from the basement.

Inspection Class

Inspected Date

Status

Assigned To

Inspector

Single Room Occupancy

December 20, 2016

Satisfactory

FP Single Room Occupateciascangelis, Lore

Fire Separations. - 2020 Repair breech in fire separation

Status Satisfactory

2020

Article 2.2.1.2.

Damage to Fire Separations

Sentence:

 Where fire separations are damaged so as to affect their integrity, they shall be repaired so that the integrity of the fire separation is maintained.

2 Smoke Alarms. - 2411 Smoke Alarm Maintenance

Status Satisfactory

2411

Article 2.1.3.3.

Smoke Alarms [See Appendix A]

Sentence:

2) Smoke alarms shall be installed, inspected, tested and maintained in conformance with manufacturers' instructions. [See Appendix A for 6.1,1.4.]

3 Other - 9000 Attention required

Status Satisfactory

9000

Fire escape(s) require engineers report, Water St and Abbott st alley.

Note: continue fire watch

203 Abbott

Tue 12/20/2016

12/1300

Inspection satisfactory continuing with firewatch until city inspector finalizes fire scape for reuse

Inspection Class
Single Room Occupancy

Inspected Date November 8, 2016 Status Unsatisfactory Assigned To

Inspector

FP Single Room Occupateciescangelis, Lore



Property - Inspection History Report

Property Address:

FH District:

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

Fire Separations. - 2020 Repair breech in fire separation

Status Unsatisfactory

02

2020

Article 2.2.1.2.

Damage to Fire Separations

Sentence:

1) Where fire separations are damaged so as to affect their integrity, they shall be repaired so that the integrity of the fire separation is maintained.

Smoke Alarms. - 2411 Smoke Alarm Maintenance

Status Unsatisfactory

2411

Article 2.1.3.3.

Smoke Alarms [See Appendix A]

Sentence:

Smoke alarms shall be installed, inspected, tested and maintained in conformance with manufacturers' instructions. [See Appendix A for 6.1,1.4.]

Other - 9000 Attention required

Status Unsatisfactory

9000

Fire escape(s) require engineers report, Water St and Abbott st alley.

Not billabel Note:

Met with manager Kevin.

Engineers report for the fire escape pending

Verbal given to Kevin to have the main floor room under construction to have the fire separation installed.

Continue Fire watch

Inspection Class Single Room Occupancy Inspected Date November 7, 2016 Status Satisfactory Assigned To FP General

Inspector Kuva, Lorne

Note (Billable) Note:

Met with manager Kevin. Requested to have the engineers report for the fire escape to be emailed to the office. Verbal given to Kevin to have the main floor room under construction to have the fire separation installed. The room is current room is bare down to the studs. It was also mentioned to Kevin that there is a re-inspect fee for the inspection.

Inspection Class	
Single Room Occu	pancy

Inspected Date November 4, 2016 Status Unsatisfactory Assigned To FP Single Room Occupations Lorne

Inspector

Fire Separations. - 2020 Repair breech in fire separation

Status Unsatisfactory

2020



Property - Inspection History Report

Property Address:

FH District:

02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

Article 2.2.1.2.

Damage to Fire Separations

Sentence:

 Where fire separations are damaged so as to affect their integrity, they shall be repaired so that the integrity of the fire separation is maintained.

Smoke Alarms. - 2411 Smoke Alarm Maintenance

Status Unsatisfactory

2411

Article 2.1.3.3.

Smoke Alarms [See Appendix A]

Sentence:

2) Smoke alarms shall be installed, inspected, tested and maintained in conformance with manufacturers' instructions. [See Appendix A for 6.1.1.4.]

Other - 9000 Attention required

Status Unsatisfactory

9000

Fire escape(s) require engineers report, Water St and Abbott st alley.

Note: ReCheck

Manager Kevin not in at time of reinspection. I had a quick look at the fire escape and on visual it looks like the fire escape had recently been upgraded/repaired. Unable to check up on other deficiencies in building as my reference material did not list specifics of the deficiencies.

Phone call to manager Kevin@ 13:55. He had mentioned that the engineers report had been email to the wardens office. Will follow up with this.

Inspection Class
Single Room Occupancy

Inspected Date September 13, 2016 Status Unsatisfactory Assigned To

Inspector

FP Single Room Occupation angelis, Lorer

Fire Separations. - 2020 Repair breech in fire separation

Status Unsatisfactory

2020

Article 2.2.1.2.

Damage to Fire Separations

Sentence:

 Where fire separations are damaged so as to affect their integrity, they shall be repaired so that the integrity of the fire separation is maintained.

2 Smoke Alarms. - 2411 Smoke Alarm Maintenance

Status Unsatisfactory

2411

Article 2.1.3.3.

Smoke Alarms [See Appendix A]

Sentence:

2) Smoke alarms shall be installed, inspected, tested and maintained in conformance with manufacturers'

People Who Care About You

Page 13 of 46



Property - Inspection History Report

Property Address:

FH District:

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

instructions. [See Appendix A for 6.1.1.4.]

3 Other - 9000 Attention required

Status Unsatisfactory

02

9000

Fire escape(s) require engineers report, Water St and Abbott st alley.

Note: UNSATISFACTORY

September 13, 2016 203 Abbott Street 1400-1500

Spoke with Kevin at front desk no real concrete updates explained that if there is nothing presented by the end of the week there would be MTI's issued,until correspondence was presented

Peter Plet owner

Inspection Class

Inspected Date

Status

Assigned Tc

Inspector

De_arcangelis, Lore

Single Room Occupancy

August 23, 2016

Unsatisfactory

FP General

Do_uroungono, Le

Fire Separations. - 2020 Repair breech in fire separation

Status Unsatisfactory

2020

Article 2.2.1.2.

Damage to Fire Separations

Sentence:

 Where fire separations are damaged so as to affect their integrity, they shall be repaired so that the integrity of the fire separation is maintained.

2 Smoke Alarms. - 2411 Smoke Alarm Maintenance

Status Unsatisfactory

2411

Article 2.1.3.3.

Smoke Alarms [See Appendix A]

Sentence:

2) Smoke alarms shall be installed, inspected, tested and maintained in conformance with manufacturers' instructions. [See Appendix A for 6.1.1.4.]

3 Other - 9000 Attention required

Status Unsatisfactory

9000

Fire escape(s) require engineers report ,Water St and Abbott st alley.

Note: report

Tue 08/23/2016

1500-1600

Fire watch up-to-date steel fabricators come but Work not started, engineer report will be delivered soon

203 Abbott

FIRE WATCH CHECK

F/W DUE TO FIRE ESCAPE



Property - Inspection History Report

Property Address:

FH District:

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

Inspection Class

Inspected Date

Status

Assigned To

Inspector

02

-3

Single Room Occupancy

July 18, 2016

Unsatisfactory

FP General

De_arcangelis, Lore

Fire Separations. - 2020 Repair breech in fire separation

Status Unsatisfactory

2020

Article 2.2.1.2.

Damage to Fire Separations

Sentence:

 Where fire separations are damaged so as to affect their integrity, they shall be repaired so that the integrity of the fire separation is maintained.

2 Smoke Alarms. - 2411 Smoke Alarm Maintenance

Status Unsatisfactory

2411

Article 2.1.3.3.

Smoke Alarms [See Appendix A]

Sentence:

2) Smoke alarms shall be installed, inspected, tested and maintained in conformance with manufacturers' instructions. [See Appendix A for 6.1.1.4.]

3 Fire Watch. - 6110 Maintain fire watch

Status Satisfactory

6110

Article 2.8.4.

Fire Watch - for FIRE ESCAPE ISSUES

Sentence:

v 1) Where the Fire Chief specifies a fire watch as a condition on a permit, the fire watch shall conform with requirements in sentence 2.9.3.4.(2) and 2.9.3.5.(2) of this By-law.

4 Other - 9000 Attention required

Status Unsatisfactory

9000

Fire escape(s) require engineers report ,Water St and Abbott st alley.

Note: FIRE WATCH

FIRE WATCH CHECK RIOK

Mon 07/18/2016

12:20

Inspection Class	
Single Room Occupancy	

Inspected Date June 28, 2016 Status Unsatisfactory Assigned To FP General

Inspector

De arcangelis, Lore

Means of Egress. - 1420 Remove obstructions from means of egress

Status Satisfactory

1420



Property - Inspection History Report

Property Address:

FH District: 02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

HOARDING ISSUES Article 2.7.1.6.

Sentence:

 Means of egress shall be maintained in good repair and free of obstructions. [See Appendix A]

Appendix:

A-2.7.1.6(1) Means of Egress.

Where a fire escape is ordered to be replaced or rebuilt, a Professional Engineer's certification is generally required to ascertain that the fire escape is structurally sound. The authority comes from Sentence 1.4.4.1. (1) of this By-law.

2 Fire Separations. - 2020 Repair breech in fire separation

Status Unsatisfactory

2020

Article 2.2.1.2.

Damage to Fire Separations

Sentence:

 Where fire separations are damaged so as to affect their integrity, they shall be repaired so that the integrity of the fire separation is maintained.

3 Smoke Alarms. - 2411 Smoke Alarm Maintenance

Status Unsatisfactory

2411

Article 2.1.3.3.

Smoke Alarms [See Appendix A]

Sentence:

2) Smoke alarms shall be installed, inspected, tested and maintained in conformance with manufacturers' instructions. [See Appendix A for 6.1.1.4.]

4 Fire Watch. - 6110 Maintain fire watch

Status Unsatisfactory

6110

Article 2.8.4.

Fire Watch - for FIRE ESCAPE ISSUES

Sentence:

v 1) Where the Fire Chief specifies a fire watch as a condition on a permit, the fire watch shall conform with requirements in sentence 2.9.3.4.(2) and 2.9.3.5.(2) of this By-law.

5 Other - 9000 Attention required

Status Unsatisfactory

9000

Fire escape(s) require engineers report ,Water St and Abbott st alley.

Note: FIRE ESCAPE

NO BILL



Property - Inspection History Report

Property Address:

FH District: 02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

DUE TO FIRE ESCAPE ISSUES , THE F/E'S HAVE BEEN PLACED OUT OF SERVICES UNTIL REPAIR'S ARE COMPLETE.

MANAGMENT HAS BEEN ODER TO POST NOTICE ON EACH F/E DOOR Fire Watch - for FIRE ESCAPE ISSUES

Sentence:

v 1) Where the Fire Chief specifies a fire watch as a condition on a permit, the fire watch shall conform with requirements in sentence 2,9.3.4.(2) and 2,9.3.5.(2) of this By-law.

Inspection Class

Inspected Date

Status

Assigned Tc

Inspector

Single Room Occupancy

June 27, 2016

Unsatisfactory

FP General

De_arcangelis, Lore

Violation Notice: Issued

Received by: KEVIN LOUGHLIN

Position: Manager

1 Emergency Planning. - 1010 Provide fire watch

Status Satisfactory

1010

Article 2.4.5.2.v

Permit conditions for open air or outdoor area fires

Sentence:

v 1) As a condition of issuance of a permit under Sentence 2.4.5.1.(1), the Fire Chief may:

Clause:

a) require a fire watch

2 Means of Egress. - 1420 Remove obstructions from means of egress

Status Unsatisfactory

1420

ROOM\$ 22(1)

HOARDING ISSUES

Article 2.7.1.6.

Maintenance

Sentence:

 Means of egress shall be maintained in good repair and free of obstructions. [See Appendix A]

Appendix:

A-2.7.1.6(1) Means of Egress.

Where a fire escape is ordered to be replaced or rebuilt, a Professional Engineer's certification is generally required to ascertain that the fire escape is structurally sound. The authority comes from Sentence 1.4.4.1. (1) of this By-law.

3 Fire Separations. - 2020 Repair breech in fire separation

Status Unsatisfactory

2020

Article 2.2.1.2.

Damage to Fire Separations



Property - Inspection History Report

Property Address:

FH District:

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

Sentence:

 Where fire separations are damaged so as to affect their integrity, they shall be repaired so that the integrity of the fire separation is maintained.

4 Smoke Alarms. - 2411 Smoke Alarm Maintenance

Status Unsatisfactory

02

2411

Article 2.1.3.3.

Smoke Alarms [See Appendix A]

Sentence:

2) Smoke alarms shall be installed, inspected, tested and maintained in conformance with manufacturers' instructions. [See Appendix A for 6.1.1.4.]

5 Fire Watch. - 6110 Maintain fire watch

Status Unsatisfactory

6110

Article 2.8.4.

Fire Watch - for FIRE ESCAPE ISSUES

Sentence:

v 1) Where the Fire Chief specifies a fire watch as a condition on a permit, the fire watch shall conform with requirements in sentence 2.9.3.4.(2) and 2.9.3.5.(2) of this By-law.

6 Fire Watch. - 6120 Maintain fire watch during all system repairs

Status Satisfactory

6120

Article 2.9.3.5.

Fire Alarm System

Sentence:

v 2) When any portion of a fire alarm system is temporarily shut down or not functional for any reason, including maintenance or periodic inspection, alternative measures including the provision of an acceptable fire watch shall be taken to ensure that all persons in the building can be informed promptly, and the Fire Department notified, if a fire should occur while the alarm system is out of service.

7 Other - 9000 Attention required

Status Unsatisfactory

9000

Fire escape(s) require engineers report, Water St and Abbott st alley.

Note: FIRE WATCH

 A 24/HR FIRE WATCH IS ISSUED UNTIL FIRE ESCAPE(S), BREECHES IN FIRE SEPARATION AND SMOKE DETECTOR ISSUES ARE IN COMPLIANCE

FULL ENGINEERS REPORT REQUIRED FOR FIRE ESCAPE LANDING ISSUES.

Inspection Class	Inspected Date	Status	Assigned To	Inspector
Single Room Occupancy	August 22, 2014	Satisfactory	FP Single Room (Occupatritiesninck, Patrick

Smoke Alarms. - 2411 Smoke Alarm Maintenance

Status Satisfactory

Article 2.1.3.3.



Property - Inspection History Report

Property Address:

FH District:

t: 02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

Smoke Alarms [See Appendix A]

Sentence:

2) Smoke alarms shall be installed, inspected, tested and maintained in conformance with manufacturers' instructions. [See Appendix A for 6.1.1.4.]

2 Other - 9000 Attention required

Status Satisfactory

Complete K3 form

Note: RIOK

Inspection Class

Inspected Date

Status

Assigned To

Inspector

Single Room Occupancy

August 13, 2014

Unsatisfactory

FP Single Room Occupation inck, Patrick

Smoke Alarms. - 2411 Smoke Alarm Maintenance

Status Unsatisfactory

Article 2.1.3.3.

Smoke Alarms [See Appendix A]

Sentence

2) Smoke alarms shall be installed, inspected, tested and maintained in conformance with manufacturers' instructions. [See Appendix A for 6.1.1.4.]

2 Other - 9000 Attention required

Status Unsatisfactory

Complete K3 form

Note: Note

- 1. Smoke detectors not installed will go back Aug. 22 at 11 am for excess into the rooms
- 2. Sign need to be installed in kitchen and K3 form

Inspection Class
Single Room Occupancy

Inspected Date July 15, 2014 Status Unsatisfactory Assigned To

Inspector

FP Single Room Occupation inck, Patrick

1 Fire Separations. - 2020 Repair breech in fire separation

Status Satisfactory

Article 2.2.1.2.

Damage to Fire Separations

Sentence

 Where fire separations are damaged so as to affect their integrity, they shall be repaired so that the integrity of the fire separation is maintained.

2 Smoke Alarms. - 2411 Smoke Alarm Maintenance

Status Unsatisfactory

Article 2.1.3.3.

Smoke Alarms [See Appendix A]

Sentence:

2) Smoke alarms shall be installed, inspected, tested and maintained in conformance with manufacturers' instructions. [See Appendix A for 6.1.1.4.]

3 Other - 9000 Attention required

Status Unsatisfactory

People Who Care About You

Page 19 of 46



Property - Inspection History Report

Property Address:

FH District:

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

Complete K3 form

Note: Note

With manager

Still need smoke installed in some rooms

K3 form not returned and sign not installed in kitchen

Inspection Class

Inspected Date

Status

Assigned To

Inspector

02

Single Room Occupancy

June 4, 2014

Unsatisfactory

FP Single Room Occupation inck, Patrick

Means of Egress. - 1420 Remove obstructions from means of egress

Status Satisfactory

Article 2.7.1.6. Maintenance

Sentence:

1) Means of egress shall be maintained in good repair and free of obstructions. [See Appendix A]

A-2.7.1.6(1) Means of Egress.

Where a fire escape is ordered to be replaced or rebuilt, a Professional Engineer's certification is generally required to ascertain that the fire escape is structurally sound. The authority comes from Sentence 1.4.4.1.(1) of this By-law,

Fire Doors. - 1531 Maintenance

Status Satisfactory

Article 2.2.2.4.v

Inspection and Maintenance

Sentence:

3) Doors in fire separations shall be operated at intervals not greater than 1 month to ensure that they are properly maintained in accordance with Sentence (1), as specified in the fire safety plan prepared in conformance with Section

2.8.

Fire Separations. - 2020 Repair breech in fire separation

Status Unsatisfactory

Article 2.2.1.2.

Damage to Fire Separations

Sentence:

1) Where fire separations are damaged so as to affect their integrity, they shall be repaired so that the integrity of the fire separation is maintained.

Smoke Alarms. - 2411 Smoke Alarm Maintenance

Status Unsatisfactory

Article 2.1.3.3.

Smoke Alarms [See Appendix A]

2) Smoke alarms shall be installed, inspected, tested and maintained in conformance with manufacturers' instructions. [See Appendix A for 6.1.1.4.]

Other - 9000 Attention required

Status Unsatisfactory

Complete K3 form

Note: Note

- Reinspection with Building Manager Kevin
- Working on smoke detectors and fire separation

Page 20 of 46



Property - Inspection History Report

Property Address:

FH District:

02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

- Kevin ask if they can install a kitchen hood instead of doing a K3 form
- 4. I explained the if so it would have to be compliant with NFPA 96

Inspection Class

Inspected Date

Status

Assigned To

Inspector

Single Room Occupancy

May 5, 2014

Unsatisfactory

FP Single Room Occupationsinck, Patrick

Violation Notice: Issued

Received by: Robert Kiddey

Position: Manager

Means of Egress. - 1420 Remove obstructions from means of egress

Status Unsatisfactory

Article 2.7.1.6. Maintenance

Sentence:

1) Means of egress shall be maintained in good repair and free of obstructions, [See Appendix A]

Appendix:

A-2.7.1.6(1) Means of Egress.

Where a fire escape is ordered to be replaced or rebuilt, a Professional Engineer's certification is generally required to ascertain that the fire escape is structurally sound. The authority comes from Sentence 1.4.4.1.(1) of this By-law.

Fire Doors. - 1531 Maintenance

Status Unsatisfactory

Article 2,2,2,4,v

Inspection and Maintenance

Sentence:

3) Doors in fire separations shall be operated at intervals not greater than 1 month to ensure that they are properly maintained in accordance with Sentence (1), as specified in the fire safety plan prepared in conformance with Section

2.8.

Fire Separations. - 2020 Repair breech in fire separation

Status Unsatisfactory

Article 2.2.1.2.

Damage to Fire Separations

Sentence:

1) Where fire separations are damaged so as to affect their integrity, they shall be repaired so that the integrity of the fire separation is maintained.

Smoke Alarms. - 2411 Smoke Alarm Maintenance

Status Unsatisfactory

Article 2.1.3.3.

Smoke Alarms [See Appendix A]

2) Smoke alarms shall be installed, inspected, tested and maintained in conformance with manufacturers' instructions. [See Appendix A for 6.1.1.4.]

5 Combustible Materials. - 5020 Excessive amount of stored combustibles in and around building

Status Satisfactory

Article 2.4.1.1.

Accumulation of Combustible Materials [see also 3.2.3.3.]

Sentence:

v 1) Except as provided in sentence 2.4.1.5., combustible materials in and around buildings shall not be permitted to accumulate in such quantities or locations that will constitute a fire hazard. [See Appendix A]

Appendix:



Property - Inspection History Report

Property Address:

FH District: 02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

A-2.4.1.1. (1) Combustible Waste Materials.

The accumulation of a certain amount of combustible waste material in and around buildings may be necessary for the day-to-day operation of many industrial or commercial premises. If basic measures of good housekeeping are observed, the presence of these combustibles may not constitute a fire hazard. Combustible waste material should be stored away from exits, and should only be there for the duration between garbage pick-ups. For the occupants' own safety, the materials should be stored in a manner that discourages vandals.

6 Other - 9000 Attention required

Status Unsatisfactory

 Have sprinkler heads cleaned Complete K3 form

Note: Note

Coordinated inspection with PUI Andy Chinfen and Manager Kevin Loughlin

Smoke detectors Missing, broken or bagged in suite 22(1)

- 2. Repair fire separation in suite (ceiling) wall around window and ceiling by electrical room (on 1st floor) and hallways
- 3. Repair North exit Fire doors (don't open and close smooth and easy)
- 4. Have sprinkler heads cleaned
- 5. Complete K3 form and install sign in 1st floor kitchen.
- 6. Have door in suite open 90° MIN

Inspection Class
Single Room Occupancy

Inspected Date April 10, 2014

Status Unsatisfactory Assigned To

Inspector

FP Single Room Occupation inck, Patrick

Combustible Materials. - 5020 Excessive amount of stored combustibles in and around building

Status Unsatisfactory

Article 2.4.1.1.

Accumulation of Combustible Materials [see also 3.2.3.3.]

Sentence:

v 1) Except as provided in sentence 2.4.1.5., combustible materials in and around buildings shall not be permitted to accumulate in such quantities or locations that will constitute a fire hazard. [See Appendix A]

Appendix:

A-2.4.1.1. (1) Combustible Waste Materials.

The accumulation of a certain amount of combustible waste material in and around buildings may be necessary for the day-to-day operation of many industrial or commercial premises. If basic measures of good housekeeping are observed, the presence of these combustibles may not constitute a fire hazard. Combustible waste material should be stored away from exits, and should only be there for the duration between garbage pick-ups. For the occupants' own safety, the materials should be stored in a manner that discourages vandals.

Note: Note

1. Spoke with manager Kevin



Property - Inspection History Report

Property Address:

FH District: 02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

still full of combustibles and now also in the hall way. Kevin ensured me the combustibles well be removed immediately

Inspection Class

Inspected Date

Status

Assigned To

Inspector

Single Room Occupancy

January 6, 2014

Unsatisfactory

FP Single Room Occupantinesninck, Patrick

Combustible Materials. - 5020 Excessive amount of stored combustibles in and around building

Status Unsatisfactory

Article 2.4.1.1.

Accumulation of Combustible Materials [see also 3,2,3,3,]

Sentence:

v 1) Except as provided in sentence 2.4.1.5., combustible materials in and around buildings shall not be permitted to accumulate in such quantities or locations that will constitute a fire hazard. [See Appendix A]

Appendix:

A-2.4.1.1. (1) Combustible Waste Materials.

The accumulation of a certain amount of combustible waste material in and around buildings may be necessary for the day-to-day operation of many industrial or commercial premises. If basic measures of good housekeeping are observed, the presence of these combustibles may not constitute a fire hazard. Combustible waste material should be stored away from exits, and should only be there for the duration between garbage pick-ups. For the occupants' own safety, the materials should be stored in a manner that discourages vandals.

Inspection Class Single Room Occupancy Inspected Date November 7, 2013

Status Unsatisfactory Assigned To

Inspector

FP Single Room Occupationinck, Patrick

Combustible Materials. - 5020 Excessive amount of stored combustibles in and around building

Status Unsatisfactory

Article 2.4.1.1.

Accumulation of Combustible Materials [see also 3.2.3.3.]

Sentence:

v 1) Except as provided in sentence 2.4.1.5., combustible materials in and around buildings shall not be permitted to accumulate in such quantities or locations that will constitute a fire hazard. [See Appendix A]

Appendix:

A-2.4.1.1. (1) Combustible Waste Materials.

The accumulation of a certain amount of combustible waste material in and around buildings may be necessary for the day-to-day operation of many industrial or commercial premises. If basic measures of good housekeeping are observed, the presence of these combustibles may not constitute a fire hazard. Combustible waste material should be stored away from exits, and should only be there for the duration between garbage pick-ups. For the occupants' own safety, the materials should be stored in a manner that discourages vandals.

Note: Fire load



Property - Inspection History Report

Property Address:

FH District: 02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

Still have fire load in Suite 220

Inspection Class

Inspected Date

Status

Assigned To

Inspector

Single Room Occupancy

October 3, 2013

Unsatisfactory

FP Single Room Occup@ritiosninck, Patrick

1 Closures, - 1621 Maintenance

Status Satisfactory

Article 2.2.2.4.v

Inspection and Maintenance

Sentence:

v 1) Closures in fire separations shall be maintained free of defects which may impair proper operation, such maintenance to include but not be limited to:

Clause:

(b) keeping guides, bearings and stay rolls clean and lubricated,

2 Combustible Materials. - 5020 Excessive amount of stored combustibles in and around building

Status Unsatisfactory

Article 2.4.1.1.

Accumulation of Combustible Materials [see also 3.2.3.3.]

Sentence:

v 1) Except as provided in sentence 2.4.1.5., combustible materials in and around buildings shall not be permitted to accumulate in such quantities or locations that will constitute a fire hazard. [See Appendix A]

Appendix:

A-2,4,1,1, (1) Combustible Waste Materials.

The accumulation of a certain amount of combustible waste material in and around buildings may be necessary for the day-to-day operation of many industrial or commercial premises. If basic measures of good housekeeping are observed, the presence of these combustibles may not constitute a fire hazard. Combustible waste material should be stored away from exits, and should only be there for the duration between garbage pick-ups. For the occupants' own safety, the materials should be stored in a manner that discourages vandals.

Other - 9000 Attention required

Status Satisfactory

- This is my 3rd time at this address. Improvements have been made but some items need to be resolved by the building owner
- Fire separation at Abbott street Hole in ceiling
- Fire separation § 22(1) Water street
- Obstruction of sprinkler water
- Loft in and Water not to code
- Fire load needs to be reduced in suite

Inspection Class

Inspected Date

Status

Assigned To

Inspector



Property - Inspection History Report

Property Address:

FH District:

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

Single Room Occupancy

September 3, 2013

Unsatisfactory

FP Single Room Occupatrities inck, Patrick

1 Means of Egress. - 1410 Provide proper access to exit

Status Satisfactory

02

Article 2.7.1.2. Open Floor Areas

Sentence:

2) Every required egress doorway shall be served by an aisle that

Clause:

a) has a clear width not less than 1 100 mm.

b) has access to at least one additional egress doorway, and

 c) at every point on the aisle, provides a choice of 2 opposite directions by which to reach an egress doorway.

2 Means of Egress. - 1440 Ensure exit doors open in direction of travel

Status Satisfactory

Article 2.7.2.1.

Exit Doors

Sentence:

- 1) Except as provided in Sentences (2), (3) and (4), all doors forming part of a means of egress shall be tested at intervals not greater than one month to ensure that they are operable.
- 2) The safety features of revolving doors shall be tested at intervals not greater than 12 months,
- Sliding doors that are required to swing on their vertical axes in the direction of egress when pressure is applied shall be tested at intervals not great than 12 months.
- 4) When doors are equipped with electromagnetic locks, these locks shall be tested at intervals not greater than 12 months.
- v 5) Exit doors shall be readily openable in the direction of exit travel, unless it is equipped with an acceptable locking device as specified in Clause 3.4.6,15.(4) of the Building By-law.

3 Closures. - 1621 Maintenance

Status Unsatisfactory

Article 2.2.2.4.v

Inspection and Maintenance

Sentence:

v 1) Closures in fire separations shall be maintained free of defects which may impair proper operation, such maintenance to include but not be limited to:

Clause:

(b) keeping guides, bearings and stay rolls clean and lubricated,

4 Combustible Materials. - 5020 Excessive amount of stored combustibles in and around building

Status Unsatisfactory

Article 2.4.1.1.

Accumulation of Combustible Materials [see also 3.2.3.3.]

Sentence:

v 1) Except as provided in sentence 2.4.1.5., combustible materials in and around buildings shall not be permitted to accumulate in such quantities or locations that will constitute a fire hazard. [See Appendix A]

People Who Care About You

Page 25 of 46



Property - Inspection History Report

Property Address:

FH District: 02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

Appendix:

A-2.4.1.1. (1) Combustible Waste Materials.

The accumulation of a certain amount of combustible waste material in and around buildings may be necessary for the day-to-day operation of many industrial or commercial premises. If basic measures of good housekeeping are observed, the presence of these combustibles may not constitute a fire hazard. Combustible waste material should be stored away from exits, and should only be there for the duration between garbage pick-ups. For the occupants' own safety, the materials should be stored in a manner that discourages vandals.

5 Other - 9000 Attention required

Status Unsatisfactory

- This is my 3rd time at this address. Improvements have been made but some items need to be resolved by the building owner
- Fire separation at Abbott street Hole in ceiling
- Fire separation \$.22(1) Water street
- Obstruction of sprinkler water
- Loft in and Water not to code
- Fire load needs to be reduced in suite

Note: Exit doors

- I spoke with manager Kevin Loughlin, to get an update on the repairs.
- Most of the repair are completed and when I was there they were just about the install the self-closers on the exit doors that are now opening in the direction of travel
- Fire load in suite and the hall way is still a problem and they are hoping to get the tenant out by the end of the month

Inspection Class
Single Room Occupancy

Inspected Date July 23, 2013

Status Unsatisfactory Assigned To

Inspector

FP Single Room Occupation inck, Patricl

Means of Egress. - 1410 Provide proper access to exit

Status Unsatisfactory

Article 2.7.1.2. Open Floor Areas

Sentence

2) Every required egress doorway shall be served by an aisle that

Clause

a) has a clear width not less than 1 100 mm,

b) has access to at least one additional egress doorway, and

 c) at every point on the aisle, provides a choice of 2 opposite directions by which to reach an egress doorway.

Means of Egress. - 1440 Ensure exit doors open in direction of travel

Status Unsatisfactory

Article 2,7.2.1, Exit Doors

Sentence:

- 1) Except as provided in Sentences (2), (3) and (4), all doors forming part of a means of egress shall be tested at intervals not greater than one month to ensure that they are operable.
- 2) The safety features of revolving doors shall be tested at intervals not greater than 12 months.
- 3) Sliding doors that are required to swing on their vertical axes in the direction of egress when

Page 26 of 46



Property - Inspection History Report

Property Address:

FH District: 02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

pressure is applied shall be tested at intervals not great than 12 months.

4) When doors are equipped with electromagnetic locks, these locks shall be tested at intervals not

greater than 12 months.

v 5) Exit doors shall be readily openable in the direction of exit travel, unless it is equipped with an acceptable locking device as specified in Clause 3.4.6.15.(4) of the Building By-law.

Closures. - 1621 Maintenance

Status Unsatisfactory

Article 2.2.2.4.v

Inspection and Maintenance

Sentence:

v 1) Closures in fire separations shall be maintained free of defects which may impair proper operation, such maintenance to include but not be limited to:

Clause

(b) keeping guides, bearings and stay rolls clean and lubricated,

4 Other - 9000 Attention required

Status Unsatisfactory

- This is my 3rd time at this address. Improvements have been made but some items need to be resolved by the building owner
- Fire separation at Abbott street Hole in ceiling
- Fire separation 5.22(1) Water street
- Obstruction of sprinkler water
- Loft in and Water not to code
- · Fire exit door need to open in direction of travel
- Fire load needs to be reduced in suite

Note: Fire separation

Inspection Class Inspected Date Status Assigned To Inspector Single Room Occupancy June 18, 2013 Unsatisfactory FP Single Room Occupantineshinck, Patrick

Means of Egress. - 1410 Provide proper access to exit

Status Unsatisfactory

Article 2.7.1.2. Open Floor Areas

Sentence

2) Every required egress doorway shall be served by an aisle that

Clause:

a) has a clear width not less than 1 100 mm,

b) has access to at least one additional egress doorway, and

 at every point on the aisle, provides a choice of 2 opposite directions by which to reach an egress doorway.

2 Means of Egress. - 1411 Maintenance

Status Satisfactory

Article: 2.7.1.1.

Means Of Egress



Property - Inspection History Report

Property Address:

FH District:

02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

1) Means of egress shall be maintained in good repair and free of obstructions.

Means of Egress. - 1420 Remove obstructions from means of egress

Status Satisfactory

Article 2.7.1.6. Maintenance

Sentence:

1) Means of egress shall be maintained in good repair and free of obstructions. [See Appendix A]

Appendix:

A-2.7.1.6(1) Means of Egress.

Where a fire escape is ordered to be replaced or rebuilt, a Professional Engineer's certification is generally required to ascertain that the fire escape is structurally sound. The authority comes from Sentence 1.4.4.1.(1) of this By-law.

Means of Egress. - 1440 Ensure exit doors open in direction of travel

Status Unsatisfactory

Article 2.7.2.1. Exit Doors

Sentence:

- 1) Except as provided in Sentences (2), (3) and (4), all doors forming part of a means of egress shall be tested at intervals not greater than one month to ensure that they are operable.
- The safety features of revolving doors shall be tested at intervals not greater than 12 months.
- 3) Sliding doors that are required to swing on their vertical axes in the direction of egress when pressure is applied shall be tested at intervals not great than 12 months.
- 4) When doors are equipped with electromagnetic locks, these locks shall be tested at intervals not greater than 12 months.
- 5) Exit doors shall be readily openable in the direction of exit travel, unless it is equipped with an acceptable locking device as specified in Clause 3.4.6.15.(4) of the Building By-law.

Means of Egress. - 1450 Remove unauthorized locking device from exit door

Status Satisfactory

Article 2.7.2.1. Exit Doors

Sentence:

v 6) The requirements of Sentence (5) shall not apply to:

Clause:

a) doors of rooms where persons are under legal restraint,

- b) doors in a care and detention occupancy where patient safety may be compromised by uncontrolled egress,
- c) doors to and from high security areas where the Fire Chief has approved the door locking devices, and
- d) doors equipped with electromagnetic locks conforming to the Building By-law requirements, provided there is an acceptable means of unlocking these doors in an emergency.

Closures. - 1621 Maintenance

Status Unsatisfactory

Article 2.2.2.4.v

Inspection and Maintenance

Sentence:

 V 1) Closures in fire separations shall be maintained free of defects which may impair proper operation, such maintenance to include but not be limited to:



Property - Inspection History Report

Property Address:

FH District:

02 FPO District: 50

Building Name:

WINTERS RESIDENCE SRO (L)

Clause:

(b) keeping guides, bearings and stay rolls clean and lubricated,

Smoke Alarms. - 2430 Smoke Alarms not installed in sleeping units and hallways

Status Satisfactory

Article 2.1.3.3. Smoke Alarma

Sentence:

v 6) Smoke alarms within dwelling units shall be installed between each area containing sleeping rooms and the remainder of the dwelling unit, and where the sleeping areas are served by hallways, the smoke alarms shall be installed in the hallways.

8 Indoor Storage. - 6020 Maintain aisle width

Status Satisfactory

Article 3.2.2.2.

Access Aisles [See Appendix A]

2) Access aisles not less than 1.0 m wide shall be provided fire department access panels and to fire protection equipment.

Appendix:

A-3,2,2,2. Access aisles

The purpose of this Article is to provide adequate access to the interior of the storage area for firefighting and overhaul operations. Means of egress must also be provided in accordance with Section 2.7, of this By-law. The use of dead-end aisles in storage areas should be minimized because of the potential hazard they create with respect to egress. Access aisles requires in Sentence (2) include aisles to fire department access panels, or to fire protection equipment such as sprinkler control valves, fire hose stations, portable extinguishers and fire alarm pull stations.

Sentence (4) to (8) prescribe requirements for main access in the storage area. More than one main access aisle may be required depending on the storage configuration and alternate arrangements to a single main access aisle are permitted in Sentence (7). These requirements are in addition to the general requirement for 2.4 m aisles separating individual storage areas. The width of subsidiary aisles within individual storage areas is determined by material handling needs.

Fire department access to a storage area can be by means of doors or access panels on exterior walls, or through doors from another fire compartment in the building, provided that fire compartment in turn has adequate fire department access. The access points should be as remote from each other as possible. Where feasible, the preferred arrangement is for main aisles to terminate at exterior doors on opposite sides of the building.

9 Indoor Storage. - 6060 Lower height of stored material

Status Satisfactory

Article 3.2.2.3. Clearances

3) In unsprinklered buildings, a clearance of not less than 1 m between top of storage and underside of floor or roof deck shall be maintained. [See Appendix A]

Appendix:

A-3.2.2.3.(3) Clearance for Hose Streams.

In unsprinklered buildings, a clear space is required above the storage to permit hose streams to be directed onto the top of storage.

Note: Working on issues

Spoke with Kevin Loughlin the manager

Some issues are resolved but more work needs to be done

- -Self closers on doors
- -South Fire escape doors need to open in direction of travel.-
- -Reduce fire load in unit
- -Repair fire separation between and Water st. and Abbott st.

People Who Care About You

Page 29 of 46



Property - Inspection History Report

Property Address:

FH District: 02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

Inspection Class

Inspected Date

Status

Assigned To

Inspector

Single Room Occupancy

April 22, 2013

Unsatisfactory

FP Single Room Occupativaies, Jonathan

Means of Egress. - 1410 Provide proper access to exit

Status Unsatisfactory

Article 2.7.1.2. Open Floor Areas

2) Every required egress doorway shall be served by an aisle that

a) has a clear width not less than 1 100 mm,

b) has access to at least one additional egress doorway, and

c) at every point on the aisle, provides a choice of 2 opposite directions by which to reach an egress doorway.

Means of Egress. - 1411 Maintenance

Status Unsatisfactory

Article: 2.7,1.1.

Means Of Egress

1) Means of egress shall be maintained in good repair and free of obstructions.

Means of Egress. - 1420 Remove obstructions from means of egress

Status Unsatisfactory

Article 2.7.1.6. Maintenance

1) Means of egress shall be maintained in good repair and free of obstructions. [See Appendix A)

A-2.7.1.6(1) Means of Egress.

Where a fire escape is ordered to be replaced or rebuilt, a Professional Engineer's certification is generally required to ascertain that the fire escape is structurally sound. The authority comes from Sentence 1.4.4.1.(1) of this By-law.

Means of Egress. - 1440 Ensure exit doors open in direction of travel

Status Unsatisfactory

Article 2.7.2.1. Exit Doors

Sentence:

- 1) Except as provided in Sentences (2), (3) and (4), all doors forming part of a means of egress shall be tested at intervals not greater than one month to ensure that they are operable.
- 2) The safety features of revolving doors shall be tested at intervals not greater than 12 months.
- 3) Sliding doors that are required to swing on their vertical axes in the direction of egress when pressure is applied shall be tested at intervals not great than 12 months.
- 4) When doors are equipped with electromagnetic locks, these locks shall be tested at intervals not

greater than 12 months.

v 5) Exit doors shall be readily openable in the direction of exit travel, unless it is equipped with an acceptable locking device as specified in Clause 3.4.6.15.(4) of the Building By-law.

Unsatisfactory

People Who Care About You

Page 30 of 46



Property - Inspection History Report

Property Address:

FH District:

02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

5 Means of Egress. - 1450 Remove unauthorized locking device from exit door

Status

Article 2.7.2.1.

Exit Doors

Sentence:

v 6) The requirements of Sentence (5) shall not apply to:

Clause

a) doors of rooms where persons are under legal restraint,

 b) doors in a care and detention occupancy where patient safety may be compromised by uncontrolled egress.

 c) doors to and from high security areas where the Fire Chief has approved the door locking devices, and

 d) doors equipped with electromagnetic locks conforming to the Building By-law requirements, provided there is an acceptable means of unlocking these doors in an emergency.

6 Closures. - 1621 Maintenance

Status Unsatisfactory

Article 2.2.2.4.v

Inspection and Maintenance

Sentence:

v 1) Closures in fire separations shall be maintained free of defects which may impair proper operation, such maintenance to include but not be limited to:

Clause:

(b) keeping guides, bearings and stay rolls clean and lubricated,

Smoke Alarms. - 2430 Smoke Alarms not installed in sleeping units and hallways

Status Unsatisfactory

Article 2.1.3.3. Smoke Alarms

Sentence:

v 6) Smoke alarms within dwelling units shall be installed between each area containing sleeping rooms and the remainder of the dwelling unit, and where the sleeping areas are served by hallways, the smoke alarms shall be installed in the hallways.

8 Indoor Storage. - 6020 Maintain aisle width

Status Unsatisfactory

Article 3.2.2.2.

Access Aisles [See Appendix A]

Sentence

Access aisles not less than 1.0 m wide shall be provided fire department access panels and to fire protection equipment.

Appendix:

A-3.2.2.2. Access aisles

The purpose of this Article is to provide adequate access to the interior of the storage area for firefighting and overhaul operations. Means of egress must also be provided in accordance with Section 2.7. of this By-law. The use of dead-end aisles in storage areas should be minimized because of the potential hazard they create with respect to egress. Access aisles requires in Sentence (2) Include aisles to fire department access panels, or to fire protection equipment such as sprinkler control valves, fire hose stations, portable extinguishers and fire alarm pull stations.

Sentence (4) to (8) prescribe requirements for main access in the storage area. More than one main access aisle may be required depending on the storage configuration and alternate arrangements to a single main access aisle are permitted in Sentence (7). These requirements are in addition to the general requirement for 2.4 m aisles separating individual storage areas. The width of subsidiary aisles within individual storage areas is determined by material handling needs.

Fire department access to a storage area can be by means of doors or access panels on exterior walls, or through doors from another fire compartment in the building, provided that fire compartment in turn has adequate fire department access. The access points should be as remote from each other as possible. Where feasible, the preferred arrangement is for main aisles to terminate at exterior doors on opposite sides of the



Property - Inspection History Report

Property Address:

FH District: 02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

building.

Indoor Storage. - 6060 Lower height of stored material

Status Unsatisfactory

Article 3.2,2,3. Clearances

3) In unsprinklered buildings, a clearance of not less than 1 m between top of storage and underside of floor or roof deck shall be maintained. [See Appendix A]

A-3.2.2.3.(3) Clearance for Hose Streams.

In unsprinklered buildings, a clear space is required above the storage to permit hose streams to be directed onto the top of storage.

Note: notes

all unit doors require approved self closing device

south fire escape doors need to have door open in direction of travel, and remove unauthorized

locking devices

smoke alarms needed in suite 3.22(1)

reduce fireload in ubnit

secure steps to north fire escape floors 1 and 3

remove floor runners in common area hallways fire seperation between units and also in abbott

Inspection Class Single Room Occupancy Inspected Date

Status

Assigned To

Inspector

September 18, 2012

Unsatisfactory

FP Single Room Occupations Chris

Violation Notice: Issued

Received by: Kevin Loughlin

Position: Manager

Means of Egress. - 1420 Remove obstructions from means of egress

Status Unsatisfactory

Article 2716 Maintenance

1) Means of egress shall be maintained in good repair and free of obstructions. [See Appendix A]

Appendix:

A-2.7.1.6(1) Means of Egress.

Where a fire escape is ordered to be replaced or rebuilt, a Professional Engineer's certification is generally required to ascertain that the fire escape is structurally sound. The authority comes from Sentence 1.4.4.1.(1) of this By-law.

Fire Separations. - 2020 Repair breech in fire separation

Status Satisfactory

Article 2.2.1.2.

Damage to Fire Separations

1) Where fire separations are damaged so as to affect their integrity, they shall be repaired so that the integrity of the fire separation is maintained.

Movie Shoot/ Truck Strike

Movie Shoot. Electrical Cable being run up Fire Escape.

Spoke to Movie Crew and ensred that cable weight is supported by means other than escape. Cable must be kept to side of escape.

Also deformation of support at bottom is a concern.

Appears to have been struck by truck.

Need repairs to escape and engineers report.

People Who Care About You

Page 32 of 46



Property - Inspection History Report

Property Address:

FH District:

02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

Inspection Class
Single Room Occupancy

Inspected Date July 16, 2012 Status Unsatisfactory Assigned Tc

Inspector

FP Single Room Occupations Chris

Means of Egress. - 1420 Remove obstructions from means of egress

Status Unsatisfactory

Article 2.7.1.6. Maintenance

Sentence:

 Means of egress shall be maintained in good repair and free of obstructions. [See Appendix A]

Appendix:

A-2.7.1.6(1) Means of Egress.

Where a fire escape is ordered to be replaced or rebuilt, a Professional Engineer's certification is generally required to ascertain that the fire escape is structurally sound. The authority comes from Sentence 1.4.4.1.(1) of this By-law.

Fire Doors. - 1530 Remove all door wedges and unauthorized hold open devices

Status Satisfactory

Article 2.2.2.4.v Inspection and Maintenance

Sentence:

- Doors in fire separations shall be inspected by the owner or occupant at intervals not greater than 24h to ensure that they remain closed unless the door is equipped with a hold-open device conforming to the building by-law.
- 3) Doors in fire separations shall be operated at intervals not greater than 1 month to ensure that they are properly maintained in accordance with sentence (1), as specified in the fire safety plan prepared to conformance with Section 2.8.
- 4) Doors in fire separations shall not be locked, wedged or otherwise held open.

Fire Separations. - 2020 Repair breech in fire separation

Status Unsatisfactory

Article 2.2.1.2.

Damage to Fire Separations

Sentence:

 Where fire separations are damaged so as to affect their integrity, they shall be repaired so that the integrity of the fire separation is maintained.

4 Exit Lighting / Emergency Lighting. - 2850 Inspect test and tag all emergency lights

Status Satisfactory

Article 6.7.1.7.

Inspection of Emergency Lights

Sentence:

 Except as provided in Article 6.7.1.6., emergency lights shall be inspected and tagged at intervals not greater than 12 months to ensure that they are functional.



Property - Inspection History Report

Property Address:

FH District:

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

5 Sprinklers. - 3070 Inspect test and tag sprinkler system

Status Satisfactory

02

Article 6.5.4.12.

Sprinkler Inspection and Replacement

Sentence:

 Sprinklers shall be inspected at intervals not greater than 12 months for damage, corrosion or accumulations of grease, paint or other deposits and shall be replaced where such conditions would impair the operation of the sprinkler. [See Appendix A]

Appendix:

A-6.5.4.12(1) Sprinklers.

Sprinklers in service frequently accumulate a deposit of dust, grease or other foreign material. Where these deposits are light, they often do not impair the proper operation of the sprinkler. Heavier deposits can often be removed by light cleaning methods. Where deposits cannot readily be removed, and doubt exists with respect to the effects of the contamination, a sampling of the sprinklers should be removed and forwarded to a recognized testing laboratory for an assessment of their operational characteristics to determine the necessity of replacing other sprinklers in the system.

Note: Email from Fire Hall 2, May 20,2012

From: Firehall 02 - B Shift

Sent: Sunday, May 20, 2012 12:39 **To:** Sziklai, Les; Critchlow, Rick **Cc:** Clinaz, Mauro; Firehall 02 - DL

Subject: 203 Abbott Street Fire Inspection

Chief,

Today E2 had a call for an alarm activated at 203 ABBOTT, ST. incident # 120017369

After investigating I could not find cause for the alarm and the system could not be reset

I wrote a notice of violation to have the system serviced / repaired in proper working order

and maintain a 24 fire watch until the notice of violation is in compliance.

I do have a serious concern that this system is so antiquated it will not be able to be serviced properly.

Would it be possible to have one of your wardens inspect this multi dwelling?

Also, we are out of the new Notice of violations.

Thank-you,

Capt. Reiffer, D

2B shift

Inspection Class	Inspected Date	Status	Assigned To	Inspector
Single Room Occupancy	April 2, 2012	Unsatisfactory	FP General	Short, Chris

Violation Notice: Issued

Received by: Kevin Loughilan

Position: [None selected]



Property - Inspection History Report

Property Address:

FH District:

02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

Means of Egress. - 1420 Remove obstructions from means of egress

Status Unsatisfactory

Article 2.7.1.6. Maintenance

Sentence:

 Means of egress shall be maintained in good repair and free of obstructions. [See Appendix A)

Appendix:

A-2.7.1.6(1) Means of Egress.

Where a fire escape is ordered to be replaced or rebuilt, a Professional Engineer's certification is generally required to ascertain that the fire escape is structurally sound. The authority comes from Sentence 1.4.4.1.(1) of this By-law.

Fire Doors. - 1530 Remove all door wedges and unauthorized hold open devices

Status Unsatisfactory

Article 2.2.2.4.v

Inspection and Maintenance

Sentence:

- 2) Doors in fire separations shall be inspected by the owner or occupant at intervals not greater than 24h to ensure that they remain closed unless the door is equipped with a hold-open device conforming to the building by-law.
- 3) Doors in fire separations shall be operated at intervals not greater than 1 month to ensure that they are properly maintained in accordance with sentence (1), as specified in the fire safety plan prepared to conformance with Section 2.8.
- 4) Doors in fire separations shall not be locked, wedged or otherwise held open.

3 Fire Separations. - 2020 Repair breech in fire separation

Status Unsatisfactory

Article 2.2.1.2.

Damage to Fire Separations

Sentence:

 Where fire separations are damaged so as to affect their integrity, they shall be repaired so that the integrity of the fire separation is maintained.

4 Exit Lighting / Emergency Lighting. - 2850 Inspect test and tag all emergency lights

Status Unsatisfactory

Article 6.7.1.7.

Inspection of Emergency Lights

Sentence:

 Except as provided in Article 6.7.1.6., emergency lights shall be inspected and tagged at intervals not greater than 12 months to ensure that they are functional.

5 Sprinklers. - 3070 Inspect test and tag sprinkler system

Status Unsatisfactory

Article 6.5.4.12.

Sprinkler Inspection and Replacement

Sentence:



Property - Inspection History Report

Property Address:

FH District:

02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

 Sprinklers shall be inspected at intervals not greater than 12 months for damage, corrosion or accumulations of grease, paint or other deposits and shall be replaced where such conditions would impair the operation of the sprinkler. [See Appendix A]

Appendix:

A-6.5.4.12(1) Sprinklers.

Sprinklers in service frequently accumulate a deposit of dust, grease or other foreign material. Where these deposits are light, they often do not impair the proper operation of the sprinkler. Heavier deposits can often be removed by light cleaning methods. Where deposits cannot readily be removed, and doubt exists with respect to the effects of the contamination, a sampling of the sprinklers should be removed and forwarded to a recognized testing laboratory for an assessment of their operational characteristics to determine the necessity of replacing other sprinklers in the system.

Note: Re-inspection

Re-inspection.

Fire Safety Equipment Overdue.

Storage in hallways such as bed frame, bikes, dresser drawers.

Maintenance were clearing out as I inspected.

Will be billed for overdue safety equipment.

Inspection Class

Inspected Date

Status Unsatisfactory Assigned To

Inspector

Single Room Occupancy

October 6, 2011

FP General

Short, Chris

Violation Notice: Issued

Received by: Kevin L.

Position: Manager

Means of Egress. - 1420 Remove obstructions from means of egress

Status Unsatisfactory

Article 2.7.1.6. Maintenance

Sentence:

 Means of egress shall be maintained in good repair and free of obstructions. [See Appendix A]

Appendix:

A-2.7.1.6(1) Means of Egress.

Where a fire escape is ordered to be replaced or rebuilt, a Professional Engineer's certification is generally required to ascertain that the fire escape is structurally sound. The authority comes from Sentence 1.4.4.1.(1) of this By-law.

Fire Doors. - 1530 Remove all door wedges and unauthorized hold open devices

Status Unsatisfactory

Article 2.2.2.4.v

Inspection and Maintenance

Sentence:

- 2) Doors in fire separations shall be inspected by the owner or occupant at intervals not greater than 24h to ensure that they remain closed unless the door is equipped with a hold-open device conforming to the building by-law.
- 3) Doors in fire separations shall be operated at intervals not greater than 1 month to ensure that they are properly maintained in accordance with sentence (1), as specified in the fire safety plan prepared to conformance with Section 2.8.
- 4) Doors in fire separations shall not be locked, wedged or otherwise held open.



Property - Inspection History Report

Property Address:

FH District: 02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

3 Fire Separations. - 2020 Repair breech in fire separation

Status Unsatisfactory

Article 2.2.1.2.

Damage to Fire Separations

Sentence:

 Where fire separations are damaged so as to affect their integrily, they shall be repaired so that the integrity of the fire separation is maintained.

Exit Lighting / Emergency Lighting. - 2850 Inspect test and tag all emergency lights

Status Unsatisfactory

Article 6.7.1.7

Inspection of Emergency Lights

Sentence

 Except as provided in Article 6.7.1.6., emergency lights shall be inspected and tagged at intervals not greater than 12 months to ensure that they are functional.

5 Sprinklers. - 3070 Inspect test and tag sprinkler system

Status Unsatisfactory

Article 6.5.4.12.

Sprinkler Inspection and Replacement

Sentence

 Sprinklers shall be inspected at intervals not greater than 12 months for damage, corrosion or accumulations of grease, paint or other deposits and shall be replaced where such conditions would impair the operation of the sprinkler. [See Appendix A]

Appendix:

A-6.5.4.12(1) Sprinklers.

Sprinklers in service frequently accumulate a deposit of dust, grease or other foreign material. Where these deposits are light, they often do not impair the proper operation of the sprinkler. Heavier deposits can often be removed by light cleaning methods. Where deposits cannot readily be removed, and doubt exists with respect to the effects of the contamination, a sampling of the sprinklers should be removed and forwarded to a recognized testing laboratory for an assessment of their operational characteristics to determine the necessity of replacing other sprinklers in the system.

Note: Building in good repair.

Building in good repair.

Notice Issued.

Met manager Kevin L.

604-683-5403.

Could not access sprinkler.

Will check on re-check.

Inspection Class	Inspected Date	Status	Assigned To	Inspector
Complaint	September 2, 2010	Satisfactory	FP General	Cooke, Brett

Sprinklers. - 3060 Repair sprinkler hangers

Status Unsatisfactory

Article 6.5.4.5.

Piping and Hangers

Sentence:

1) Sprinkler piping and hangers shall be kept in good repair.



Property - Inspection History Report

Property Address:

FH District:

02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

Sprinkler hanger in unit has been damaged and needs to be repaired immediately. Access must be provided to do necessary repairs as this could compromise the sprinkler systems ability to work effectively

Note: Complaint

Sprinkler hanger has been broken and pipe is hanging. Tenant will not let manager have access to do repairs.

Inspection Class FPO General

Inspected Date August 20, 2010 Status Satisfactory Assigned To FP General

Inspector Stolp, Ronald

Smoke Alarms. - 2450 Smoke Alarm needs repair

Status Satisfactory

Article 2.1.3.3. Smoke Alarms

Sentence:

8) Smoke alarms shall be kept installed and shall be maintained in working condition by the owner or occupant.

SMOKE ALARMS IN THE FOLLOWING UNITS NEED TO BE TESTED, REPAIRED OR REPLACED, UNITS 522(1)

5.22(1)

Recheck 08/19/2010

s.22(1)

still need to be repaired

Note:

fdm maint

Locked as satisfactory to clean data chain

Inspection Class **FPO General**

Inspected Date August 19, 2010 Status Unsatisfactory Assigned To FP General

Inspector Cooke, Brett

Smoke Alarms. - 2450 Smoke Alarm needs repair

Status Unsatisfactory

Article 2.1.3.3. Smoke Alarms

Sentence:

8) Smoke alarms shall be kept installed and shall be maintained in working condition by the owner or occupant.

SMOKE ALARMS IN THE FOLLOWING UNITS NEED TO BE TESTED, REPAIRED OR REPLACED, UNITS 122(1)



Property - Inspection History Report

Property Address:

FH District: 02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

5.22(1)

Recheck 08/19/2010

still need to be repaired

2 Sprinklers. - 3060 Repair sprinkler hangers

Status Satisfactory

Article 6,5,4,5,

Piping and Hangers

Sentence:

1) Sprinkler piping and hangers shall be kept in good repair.

REPAIR CEILING AND SPRINKLER HANGER IN UNIT



3 Combustible Materials. - 5020 Excessive amount of stored combustibles in and around building

Status Satisfactory

Article 2.4.1.1.

Accumulation of Combustible Materials [see also 3.2.3.3.]

Sentence:

v 1) Except as provided in sentence 2.4.1.5., combustible materials in and around buildings shall not be permitted to accumulate in such quantities or locations that will constitute a fire hazard. [See Appendix A]

Appendix:

A-2.4.1.1. (1) Combustible Waste Materials.

The accumulation of a certain amount of combustible waste material in and around buildings may be necessary for the day-to-day operation of many industrial or commercial premises. If basic measures of good housekeeping are observed, the presence of these combustibles may not constitute a fire hazard. Combustible waste material should be stored away from exits, and should only be there for the duration between garbage pick-ups. For the occupants' own safety, the materials should be stored in a manner that discourages vandals.

REDUCE THE AMOUNT OF COMBUSTIBLES STORED IN ROOM AND ON SPRINKLER PIPES IN THE FOLLOWING UNITS. \$22(11)

AND 5.22(1)

Note: recheck

Inspection Class **FPO General**

Inspected Date April 27, 2010

Status Unsatisfactory Assigned To FP General

Inspector Cooke, Brett

Smoke Alarms. - 2450 Smoke Alarm needs repair

Status Unsatisfactory

Article 2.1.3.3. Smoke Alarms



Property - Inspection History Report

Property Address:

FH District: 02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

Sentence:

8) Smoke alarms shall be kept installed and shall be maintained in working condition by the owner or occupant.

SMOKE ALARMS IN THE FOLLOWING UNITS NEED TO BE TESTED, REPAIRED OR REPLACED, UNITS \$22(1)

5.22(1)

2 Sprinklers. - 3060 Repair sprinkler hangers

Status Unsatisfactory

Article 6.5.4.5.

Piping and Hangers

Sentence:

1) Sprinkler piping and hangers shall be kept in good repair.

REPAIR CEILING AND SPRINKLER HANGER IN UNIT



Combustible Materials. - 5020 Excessive amount of stored combustibles in and around building

Status Unsatisfactory

Article 2.4.1.1.

Accumulation of Combustible Materials [see also 3.2.3.3.]

Sentence:

v 1) Except as provided in sentence 2.4.1.5., combustible materials in and around buildings shall not be permitted to accumulate in such quantities or locations that will constitute a fire hazard. [See Appendix A]

Appendix:

A-2.4.1.1. (1) Combustible Waste Materials.

The accumulation of a certain amount of combustible waste material in and around buildings may be necessary for the day-to-day operation of many industrial or commercial premises. If basic measures of good housekeeping are observed, the presence of these combustibles may not constitute a fire hazard. Combustible waste material should be stored away from exits, and should only be there for the duration between garbage pick-ups. For the occupants' own safety, the materials should be stored in a manner that discourages vandals.

REDUCE THE AMOUNT OF COMBUSTIBLES STORED IN ROOM AND ON SPRINKLER PIPES IN THE FOLLOWING UNITS. 8.22(1)

AND \$.22(1)

Note: SRO inspection

Building in decent shape. Violation to be issued to to manager Kevin for smoke alarms and room storage.

Inspection Class FPO General Inspected Date April 13, 2010 Status Satisfactory Assigned To FP General Inspector Suzuki, Kenneth



Property - Inspection History Report

Property Address:

FH District:

02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

Inspection Class **FPO General**

Inspected Date March 2, 2010

Status Satisfactory Assigned To FP General

Inspector

Suzuki, Kenneth

Note: fire

> recheck after fire PFE been replaced FAS has been tested by Royal City Fire and HWSA has been replace in fire room

Inspection Class

Inspected Date

Status

Assigned To

Inspector

Single Room Occupancy

September 21, 2009

Satisfactory

FP General

Cooke, Brett

Means of Egress. - 1450 Remove unauthorized locking device from exit door

Status Satisfactory

Article 2.7.2.1. Exit Doors

Sentence:

v 6) The requirements of Sentence (5) shall not apply to:

Clause:

- a) doors of rooms where persons are under legal restraint,
- b) doors in a care and detention occupancy where patient safety may be compromised by uncontrolled egress,
- c) doors to and from high security areas where the Fire Chief has approved the door locking devices, and
- d) doors equipped with electromagnetic locks conforming to the Building By-law requirements. provided there is an acceptable means of unlocking these doors in an emergency.

Unit doors may not have padlocks, eyebolt's or any other non approved locking device on them. Units 5.22(1)

2 Smoke Alarms. - 2450 Smoke Alarm needs repair

Status Satisfactory

Article 2.1.3.3. Smoke Alarms

Sentence:

8) Smoke alarms shall be kept installed and shall be maintained in working condition by the owner or occupant.

Smoke alarms need to be replaced, repaired or tested in the following units \$22(1) s.22(1)

Combustible Materials. - 5020 Excessive amount of stored combustibles in and around building

Status Satisfactory

Article 2.4.1.1.

Accumulation of Combustible Materials [see also 3.2.3.3.]

People Who Care About You

Page 41 of 46



Property - Inspection History Report

Property Address:

FH District:

02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

Sentence:

v 1) Except as provided in sentence 2.4.1.5., combustible materials in and around buildings shall not be permitted to accumulate in such quantities or locations that will constitute a fire hazard. [See Appendix A]

Appendix:

A-2.4.1.1. (1) Combustible Waste Materials.

The accumulation of a certain amount of combustible waste material in and around buildings may be necessary for the day-to-day operation of many industrial or commercial premises. If basic measures of good housekeeping are observed, the presence of these combustibles may not constitute a fire hazard. Combustible waste material should be stored away from exits, and should only be there for the duration between garbage pick-ups. For the occupants' own safety, the materials should be stored in a manner that discourages vandals.

Note: INSPECTION

Building had annual fire inspection Sept 2009. Management monitors smoke alarms by doing monthly room checks. Padlocks have been removed by manager. Coudl not access sprinkler system at time of inspection.

Inspection Class	
Single Room Occu	pancy

Inspected Date September 16, 2008 Status Unsatisfactory Assigned To FP General Inspector Cooke, Brett

Violation Notice: Issued

Received by:

Position: [None selected]

Means of Egress. - 1450 Remove unauthorized locking device from exit door

Status Unsatisfactory

Article 2.7.2.1. Exit Doors

Sentence:

v 6) The requirements of Sentence (5) shall not apply to:

Clause:

a) doors of rooms where persons are under legal restraint,

b) doors in a care and detention occupancy where patient safety may be compromised by uncontrolled egress.

 c) doors to and from high security areas where the Fire Chief has approved the door locking devices, and

d) doors equipped with electromagnetic locks conforming to the Building By-law requirements, provided there is an acceptable means of unlocking these doors in an emergency.

Unit doors may not have padlocks, eyebolt's or any other non approved locking device on them. Units \$22(1)

2 Smoke Alarms. - 2450 Smoke Alarm needs repair

Status Unsatisfactory

Article 2.1.3.3. Smoke Alarms

Sentence:



Property - Inspection History Report

Property Address:

FH District:

02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

8) Smoke alarms shall be kept installed and shall be maintained in working condition by the owner or occupant.

Smoke alarms need to be replaced, repaired or tested in the following units \$22(1)

Combustible Materials. - 5020 Excessive amount of stored combustibles in and around building

Status Unsatisfactory

Article 2.4.1.1.

Accumulation of Combustible Materials [see also 3.2.3.3.]

Sentence:

v 1) Except as provided in sentence 2.4.1.5., combustible materials in and around buildings shall not be permitted to accumulate in such quantities or locations that will constitute a fire hazard. [See Appendix A]

Appendix:

A-2.4.1.1. (1) Combustible Waste Materials.

The accumulation of a certain amount of combustible waste material in and around buildings may be necessary for the day-to-day operation of many industrial or commercial premises. If basic measures of good housekeeping are observed, the presence of these combustibles may not constitute a fire hazard. Combustible waste material should be stored away from exits, and should only be there for the duration between garbage pick-ups. For the occupants' own safety, the materials should be stored in a manner that discourages vandals.

Combustible material needs to be reduced in units to lower the fire load and allow access to Emergency Personnel, Units 22(1) and

Inspection Class **FPO General**

Inspected Date May 20, 2008

Status Satisfactory Assigned To FP General

Inspector Rusticus, Martin

Fire Alarms. - 2210 Inspect Test and Tag fire alarm system

Status Satisfactory

Article 6.3.1.2. Article 6.3.1.2.

Inspection and Testing

- 1) Fire alarm systems shall be inspected and tested in conformance with CAN/ULC-S536-M, "inspection and Testing of Fire Alarm Systems."
- 2) Fire alarm and detection system components shall be accessible for purposes of inspection or maintenance.

2 Fire Extinguishers. - 2650 Inspect Test and Tag all extinguishers

Status Satisfactory

Article 6.2.4.1.

Inspection, Testing and Maintenance

Sentence:

 Except as otherwise required in this Section, inspection, testing, maintenance and recharging of portable extinguishers shall be in conformance with NFAP 10, "Portable

People Who Care About You

Page 43 of 46



Property - Inspection History Report

Property Address:

FH District: 02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

Fire Extinguishers."

3 Exit Lighting / Emergency Lighting. - 2850 Inspect test and tag all emergency lights

Status Satisfactory

Article 6.7.1.7.

Inspection of Emergency Lights

Sentence:

 Except as provided in Article 6.7.1.6., emergency lights shall be inspected and tagged at intervals not greater than 12 months to ensure that they are functional.

4 Sprinklers. - 3070 Inspect test and tag sprinkler system

Status Satisfactory

Article 6.5.4.12.

Sprinkler Inspection and Replacement

Sentence

 Sprinklers shall be inspected at intervals not greater than 12 months for damage, corrosion or accumulations of grease, paint or other deposits and shall be replaced where such conditions would impair the operation of the sprinkler. [See Appendix A]

Appendix:

A-6.5.4.12(1) Sprinklers.

Sprinklers in service frequently accumulate a deposit of dust, grease or other foreign material. Where these deposits are light, they often do not impair the proper operation of the sprinkler. Heavier deposits can often be removed by light cleaning methods. Where deposits cannot readily be removed, and doubt exists with respect to the effects of the contamination, a sampling of the sprinklers should be removed and forwarded to a recognized testing laboratory for an assessment of their operational characteristics to determine the necessity of replacing other sprinklers in the system.

5 Combustible Materials. - 5030 Combustible materials stored in service room

Status Satisfactory

Article 2.4.1.1.

Accumulation of Combustible Materials [see also 3.2.3.3.1]

Sentence:

2) Combustible materials, other than those for which the location, room or space is designed, shall not be permitted to accumulate:

Clause:

 a) in any part of an elevator shaft, ventilation shaft, means of egress, service room or service space,

Appendix:

A-2.4.1.1.(2) Combustible Storage in Garbage Rooms.

The defined term for service rooms includes boiler rooms, furnace rooms, incinerator rooms, garbage rooms, janitors' closets and rooms to accommodate air-conditioning or heating appliances, pumps, compressors and electrical services. The intent of Sentence 2.4.1.1.(2) then is to discourage the use of these rooms for storage of miscellaneous combustible materials. If storage space is needed in a building, a room that does not contain building service equipment should be provided. Even in garbage rooms, combustible materials should not be allowed to accumulate. When the garbage is periodically cleared from the room, the room should be empty, except for the garbage container itself.

Inspection Class
FPO General

Inspected Date April 14, 2008 Status Unsatisfactory Assigned To FP General Inspector Rusticus, Martin

Violation Notice: Issued

Received by: Kevin Loughlin

Position: [None selected]

1 Fire Alarms. - 2210 Inspect Test and Tag fire alarm system

Status Unsatisfactory



Property - Inspection History Report

Property Address:

FH District: 02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

Article 6.3.1.2. Article 6.3.1.2. Inspection and Testing

Sentence:

- Fire alarm systems shall be inspected and tested in conformance with CAN/ULC-S536-M, "inspection and Testing of Fire Alarm Systems."
- Fire alarm and detection system components shall be accessible for purposes of inspection or maintenance.

2 Fire Extinguishers. - 2650 Inspect Test and Tag all extinguishers

Status Unsatisfactory

Article 6.2.4.1.

Inspection, Testing and Maintenance

Sentence:

 Except as otherwise required in this Section, inspection, testing, maintenance and recharging of portable extinguishers shall be in conformance with NFAP 10, "Portable Fire Extinguishers."

Exit Lighting / Emergency Lighting. - 2850 Inspect test and tag all emergency lights

Status Unsatisfactory

Article 6.7.1.7.

Inspection of Emergency Lights

Sentence

 Except as provided in Article 6.7.1.6., emergency lights shall be inspected and tagged at intervals not greater than 12 months to ensure that they are functional.

4 Sprinklers. - 3070 Inspect test and tag sprinkler system

Status Unsatisfactory

Article 6.5.4.12.

Sprinkler Inspection and Replacement

Sentence:

 Sprinklers shall be inspected at intervals not greater than 12 months for damage, corrosion or accumulations of grease, paint or other deposits and shall be replaced where such conditions would impair the operation of the sprinkler. [See Appendix A]

Appendix:

A-6.5.4.12(1) Sprinklers.

Sprinklers in service frequently accumulate a deposit of dust, grease or other foreign material. Where these deposits are light, they often do not impair the proper operation of the sprinkler. Heavier deposits can often be removed by light cleaning methods. Where deposits cannot readily be removed, and doubt exists with respect to the effects of the contamination, a sampling of the sprinklers should be removed and forwarded to a recognized testing laboratory for an assessment of their operational characteristics to determine the necessity of replacing other sprinklers in the system.

5 Combustible Materials. - 5030 Combustible materials stored in service room

Status Unsatisfactory

Article 2.4.1.1.

Accumulation of Combustible Materials [see also 3.2.3.3.]

Sentence:

Combustible materials, other than those for which the location, room or space is designed, shall not be permitted to accumulate:

Clause

a) in any part of an elevator shaft, ventilation shaft, means of egress, service room or

People Who Care About You

Page 45 of 46



Property - Inspection History Report

Property Address:

FH District: 02

Building Name:

WINTERS RESIDENCE SRO (L)

FPO District: 50

service space,

Appendix:

A-2.4.1.1.(2) Combustible Storage in Garbage Rooms.

The defined term for service rooms includes boiler rooms, furnace rooms, incinerator rooms, garbage rooms, janitors' closets and rooms to accommodate air-conditioning or heating appliances, pumps, compressors and electrical services. The intent of Sentence 2.4.1.1.(2) then is to discourage the use of these rooms for storage of miscellaneous combustible materials. If storage space is needed in a building, a room that does not contain building service equipment should be provided. Even in garbage rooms, combustible materials should not be allowed to accumulate. When the garbage is periodically cleared from the room, the room should be empty, except for the garbage container itself.

Note: SRO Project

joint inspection conducted with Property Use, and some FDM data gathered. order issued to have all fire systems tested and tagged; already ordered for end of the month.

Inspection Class	Inspected Date	Status	Assigned Tc	Inspector
FPO General	April 5, 2007	Satisfactory	FP General	Von_minden, Marcu





FIRE & RESCUE SERVICES

NOTICE OF VIOLATION

General

Fireh	all Office	Use only
Routine Insp	ection	☐ Incident
Entered into	Date: _	-

iness	Owner:	Phone #:Fax #:
		Phone #:
eipt	of Notice:	g5 A COVID (signatur
М	CODE	Vancouver Fire By-Law Violations - FOR IMMEDIATE COMPLIANCE
	6.1.1.5.(2) DIV B	Have Portable Fire Extinguishers serviced by ASTTBC qualified technician, and service tag securely affixed to serviced equipment.
	6.1.1.5.(1) DIV B	Have FIRE ALARM SYSTEM serviced by ASTTBC qualified technician, and service tag securely affixed to serviced equipment.
	6.1.1.5.(1) DIV B	Have EMERGENCY LIGHTING SYSTEMS serviced by ASTTBC qualified technician, and service tag securely affixed to serviced equipment.
	6.1.1.5.(1) DIV B	Have SPRINKLER SYSTEM serviced by ASTTBC qualified technician, and service tag securely affixed to serviced equipment.
1	2.7.1.6.(1) DIV B	Ensure all means of egress and access to exits are clear and free of any obstructions at all times.
	2.1.5.1.(2) DIV B	Provide 5lbs "ABC" Class Portable Fire Extinguisher.
	6.1.1.4.(1) DIV B	Provide 24 Hour Fire Watch until such time that fire alarm system is reset and fully functional.
		- Have unit # Suske DETERTIES EFTORMED TO DROBER WORKING OR JEE
		- Have wor # 5.22(1) Charle The TECTOR
		REPLACED
		This Notice of Violation makes you legally responsible for any consequences arising
		from this matter. A re-inspection service charge of \$200.00 (or as per the current
		Vancouver Fire By-law fee schedule) for each hour or part thereof (plus G.S.T.) will
		be assessed for each re-inspection, until
		the violations noted have been corrected. Failure to comply with the above
		instructions may result in legal action against the Owner/Occupier.
	MPORTANT INFORM Please have this translat	
		CHÍ DÂN QUAN TRONG INFORMACIÓN IMPORTANTE