

W 15TH AVE
2400























ARBORICULTURE INCIDENT REPORT

(Report of Damage Due to Tree / Branch Failure)
(Revised Nov 16, 2012)

Incident Location: 2406 W 15

Incident Date: 06 / 13 / 23 Incident Time: 11 a.m. / (p.m.)

MM DD YY

Inspector / Crew Leader: CARROLL

Inspection Date: 06 / 14 / 23 Inspection Time: 830 a.m. / p.m.

MM DD YY

Tree and Event Information

Tree Species: Lombardi Poplar Cell: _____ DBH (in): 40+ HGT (ft): 90'

Whole Tree Failure: Yes / (No) If No, size of broken limb: Diameter: 40" Length: 70

Condition of part that failed (e.g. "dead"): ~~dead~~ alive

Probable Cause(s) for Failure: wind

Defects Outwardly Visible, Prior to Failure: Yes (No) Point of failure visible from the ground: Yes/No (No)

Photographs (show number taken): Address: 1 Entire Tree: 1 Fallen Branch: 4

Point of Attachment: 3 Damage: _____ On which Camera? 5856

Damage Information

Description of Damage to Property / Vehicle: extensive damage

to roof, windows, hood

See pics

Damaged Vehicle Information:

1. Make: LAND ROVER Model: DEFENDER License: s.22(1)

2. Make: _____ Model: _____ License: _____

Property / Vehicle Owner: _____ Phone: _____

Property / Vehicle Owner Address: _____

Completed by: M. Carroll Phone: 604 909 4863 Date: 06 / 14 / 23

Inspector / Arborist Signature MM DD YY

Superintendent Section

Listed in VanTree: (Yes) / No Serial # 223706 Species Code: PPNITT Condition: 6

Last Drive-by Inspection Prior to Failure: Date: 06 / 29 / 22 conducted by: BL & JJC

MM DD YY JA

Any work noted at Drive-by Inspection: N/A

Location where photos were uploaded to: ADrive/Risk Management

Reviewed by: [Signature] Phone: 604-257-8513 Date: 06 / 16 / 2023

Supervisor Signature MM DD YY



ARBORICULTURE INCIDENT REPORT

(Report of Damage Due to Tree / Branch Failure)

(Revised Nov 16, 2012)

Incident Location: 2406 W15Incident Date: 06 / 13 / 23 Incident Time: 11 a.m. / (p.m.)
MM DD YYInspector / Crew Leader: CARROLLInspection Date: 06 / 14 / 23 Inspection Time: 9:00 a.m. / p.m.
MM DD YY

Tree and Event Information

Tree Species: _____ Cell: 19 DBH (in): 90+ HGT (ft): 90Whole Tree Failure: Yes / No If No, size of broken limb: Diameter: 40 Length: 20Condition of part that failed (e.g. "dead"): 9 liveProbable Cause(s) for Failure: wind

Defects Outwardly Visible, Prior to Failure: Yes/No Point of failure visible from the ground: Yes/No

Photographs (show number taken): Address: 1 Entire Tree: 2 Fallen Branch: 2Point of Attachment: 2 Damage: 4 On which Camera? 5856

Damage Information

Description of Damage to Property / Vehicle: s.22(1)FENCE DAMAGE, HEDGE DAMAGE
as well as alley pole damage & wires down (tel)

Damaged Vehicle Information:

1. Make: _____ Model: _____ License: _____

2. Make: _____ Model: _____ License: _____

Property / Vehicle Owner: s.22(1) Phone: s.22(1)Property / Vehicle Owner Address: s.22(1) VAN 13C s.22(1)Completed by: M CARROLL Phone: 604 404 4863 Date: 06 / 14 / 23
Inspector / Arborist Signature MM DD YY

Superintendent Section

Listed in VanTree: (Yes/No) Serial # 223706 Species Code: APN11T Condition: 6Last Drive-by Inspection Prior to Failure: Date: 06 / 29 / 22 conducted by: BC#JJC/JA
MM DD YYAny work noted at Drive-by Inspection: N/ALocation where photos were uploaded to: H Drive/Risk ManagementReviewed by: [Signature] Phone: 604.257.8573 Date: 06 / 16 / 2023
Supervisor Signature MM DD YY



ARBORICULTURE INCIDENT REPORT

(Report of Damage Due to Tree / Branch Failure)

(Revised Nov 16, 2012)

Incident Location:

2400 BK W 15 @ BALSAM -

s.22(1)

Incident Date:

06 / 13 / 23
MM DD YY

Incident Time:

11 a.m. / (p.m.)

Inspector / Crew Leader:

CARROLL

Inspection Date:

06 / 14 / 23
MM DD YY

Inspection Time:

850 a.m. / p.m.

Tree and Event Information

Tree Species:

LOMBARD
POP LAR

Cell:

19

DBH (in):

90+

HGT (ft):

90

Whole Tree Failure: Yes / (No)

If No, size of broken limb: Diameter:

40"

Length:

70'

Condition of part that failed (e.g. "dead"):

alive

Probable Cause(s) for Failure:

wind

Defects Outwardly Visible, Prior to Failure: Yes / (No)

Point of failure visible from the ground: (Yes) / No

Photographs (show number taken): Address:

1

Entire Tree:

1

Fallen Branch:

4

Point of Attachment:

3

Damage:

6

On which Camera?

5856

Damage Information

Description of Damage to Property / Vehicle:

windows, roof, hood,
mirrors, side panels - see pics

Damaged Vehicle Information:

1. Make:

Subaru

Model:

Forester

License:

s.22(1)

2. Make:

Model:

License:

s.22(1)

Property / Vehicle Owner:

Phone:

s.22(1)

Property / Vehicle Owner Address:

Vancouver, BC

s.22(1)

Completed by:

M CARROLL

Phone:

604 404 4863

Date:

06 / 14 / 23

Inspector / Arborist Signature

MM DD YY

Superintendent Section

Listed in VanTree: (Yes) / No

Serial #

223706

Species Code:

PPN11T

Condition:

6

Last Drive-by Inspection Prior to Failure: Date:

06 / 29 / 22

conducted by:

PC #554/5A

Any work noted at Drive-by Inspection:

N/A

Location where photos were uploaded to:

H Drive / Risk Management

Reviewed by:

A.

Phone:

604-257-8513

Date:

66 / 16 / 2028

Supervisor Signature

MM DD YY



ARBORICULTURE INCIDENT REPORT

(Report of Damage Due to Tree / Branch Failure)

(Revised Nov 16, 2012)

Incident Location: 2406 W. 15thIncident Date: 06 / 14 / 23 Incident Time: 12:05 a.m. / p.m.
MM DD YYInspector / Crew Leader: Terry MarshallInspection Date: 06 / 14 / 23 Inspection Time: 12:10 a.m. / p.m.
MM DD YY

Tree and Event Information

Tree Species: Lombardy Poplar Cell: 19 DBH (in): _____ HGT (ft): 100Whole Tree Failure: Yes / (No) If No, size of broken limb: Diameter: _____ Length: 80

Condition of part that failed (e.g. "dead"): _____

Probable Cause(s) for Failure: _____

Defects Outwardly Visible, Prior to Failure: Yes (No) Point of failure visible from the ground: (Yes) / NoPhotographs (show number taken): Address: _____ Entire Tree: 2 Fallen Branch: 2Point of Attachment: 3 Damage: 8 On which Camera? 7674

Damage Information

Description of Damage to Property / Vehicle: Two vehicles complete
write off: front end / hood / roof

Damaged Vehicle Information:

1. Make: Subaru Model: Forester XT License: s.22(1)
2. Make: Land Rover Model: Defender License: s.22(1)

Property / Vehicle Owner: _____ Phone: _____

Property / Vehicle Owner Address: _____

Completed by: [Signature] Phone: 604-404-0938 Date: 06 / 14 / 23
Inspector / Arborist Signature MM DD YY

Superintendent Section

Listed in VanTree: (Yes) / No Serial # 223706 Species Code: PPN11T Condition: 6Last Drive-by Inspection Prior to Failure: Date: 06 / 29 / 22 conducted by: PC JX #
MM DD YY JAAny work noted at Drive-by Inspection: N/ALocation where photos were uploaded to: H Drive / Risk ManagementReviewed by: [Signature] Phone: 6042578573 Date: 06 / 19 / 2023
Supervisor Signature MM DD YY

I'm

Dessureault, Sophie

From: Parks - Urban Forestry - Truck Phone - A5856
Sent: Thursday, June 15, 2023 7:22 AM
To: PB Street Trees
Subject: 2406 W 15





s.22(1)



2406 W 15th Av - 2023
















Sent from A5856 on a iPhone



Dessureault, Sophie

From: Parks - Urban Forestry - Truck Phone - A5856
Sent: Thursday, June 15, 2023 7:24 AM
To: PB Street Trees
Subject: 2406 W15 .2





s.22(1)















Sent from A5856 on a iPhone

