

File No.: 04-1000-20-2022-659

January 30, 2023

s.22(1)

Dear s.22(1)

Re: **Request for Access to Records under the Freedom of Information and Protection of Privacy Act (the "Act")**

I am responding to your request of December 21, 2022 under the ***Freedom of Information and Protection of Privacy Act (the Act)*** for:

Records concerning the crosswalk at Beach Avenue and Thurlow Street, specifically:

- 1. Complaints made regarding the crosswalk; and**
 - 2. Changes made to the lighting of the crosswalk.**
- Date range: February 15, 2010 to February 15, 2020.**

All responsive records are attached. Some information in the records has been severed (blacked out) under s.22(1) of the Act. You can read or download this section here:

http://www.bclaws.ca/EPLibraries/bclaws_new/document/ID/freeside/96165_00.

Under section 52 of the Act, and within 30 business days of receipt of this letter, you may ask the Information & Privacy Commissioner to review any matter related to the City's response to your FOI request by writing to: Office of the Information & Privacy Commissioner, info@oipc.bc.ca or by phoning 250-387-5629.

If you request a review, please provide the Commissioner's office with: 1) the request number (#04-1000-20-2022-659); 2) a copy of this letter; 3) a copy of your original request; and 4) detailed reasons why you are seeking the review.

Yours truly,

[Signed by Cobi Falconer]

Cobi Falconer, MAS, MLIS, CIPP/C
Director, Access to Information & Privacy
cobi.falconer@vancouver.ca
453 W. 12th Avenue Vancouver BC V5Y 1V4

If you have any questions, please email us at foi@vancouver.ca and we will respond to you as soon as possible. Or you can call the FOI Case Manager at 604-871-6584.

Encl. (Response package)

:pm

					1. Describe details (who, what, where, when, why): Citizen just noticed a snow pile go by on Thurlow and Beach leaving behind a huge snow pile on top of the bike path and catch basin. Though he understands crews are attending to major roads and trouble areas first, he feels the snow pile with cause a hazard once the snow starts to melt. The catch basin is fully covered and being at the bottom of a hill, all the melted snow will start to flood this part of the street easily. 2. Do you want to be contacted? No 3. Type of feedback: Opinion 4. Feedback regarding: City Department 5. Department: Engineering Services 6. Division or Branch Name: Streets, Traffic, and Electrical Operations		8.22(1)	8.22(1)	2/6/17 10:04	2/6/17 11:49	Feedback	Agent Created Case: Agent Updated Case Details: Reallocated to queue: Feedback Agent Took Ownership of Case: Agent Finished: Case Closed. Closed date : 2017-02-06 11:49:02.507 Directed to Another City Department Sent to Ken Brown
Citizen Feedback Case	101009107733	INTERSECTION	BEACH AV	THURLLOW ST								Agent Created Case: Agent Updated Case Details: Reallocated to queue: Eng_Traffic and Data Management Hansen Service Case Created / Updated: Hansen ServiceRequest Number : 1097541 created / updated at Monday, February 27, 2017 3:00:23 PM Service Provided: 10 - Service Provided. Location does not meet the warrant for a pedestrian signal to be installed. The city, however, will initiate a plan to upgrade the existing parallel crosswalk into a zebra crosswalk in order to boost visibility and awareness. - Resolved on 02/03/2017 8:44:00 AM. Agent Finished: Case Closed. Closed date : 2017-03-02 08:46:31.717 Service Provided 10 - Service Provided. Location does not meet the warrant for a pedestrian signal to be installed. The city, however, will initiate a plan to upgrade the existing parallel crosswalk into a zebra crosswalk in order to boost visibility and awareness. - Resolved on 02/03/2017 8:44:00 AM. Case Reopened: Temporary re-open to 'Add Event' OR 'Move to other Queue' Hansen Service Request has been reviewed: Case reviewed on 02/03/2017 8:44:43 AM. Agent Finished: Case Closed. Closed date : 2017-03-02 08:46:34.01 Back to previous status Closing case after 'Add Event'
Traffic & Pedestrian Signal - New Case	101009207913	INTERSECTION	BEACH AV	THURLLOW ST	1. Type of signal: Pedestrian Signal 2. If Other, provide details: 3. Reason signal is required: Busy Intersection 4. If Other, provide details: 5. What time of day is the problem worst? PM Peak (4:00 - 7:00 pm) 6. What are the intersecting streets? Thurlow and Beach 7. (Don't ask, just record - did caller indicate they want a call back?): No	This area is very busy and there have been many near hit misses and is ever busier with the new bike lane that went on Thurlow. She'd like to see if a Pedestrian light can be put in. There is a crosswalk but its not sufficient.	8.22(1)	8.22(1)	2/27/17 14:57	3/2/17 8:46	Eng_Traffic and Data Management	Agent Created Case: Agent Updated Case Details: Reallocated to queue: Eng_Traffic and Data Management Hansen Service Case Created / Updated: Hansen ServiceRequest Number : 1278879 created / updated at Thursday, April 26, 2018 5:33:36 PM Hansen Service Case Created / Updated: Hansen ServiceRequest Number : 1278879 created / updated at Thursday, April 26, 2018 5:35:01 PM Hansen Service Request has been reviewed: Case reviewed on 27/04/2018 9:05:45 AM. Service Provided: 10 - Service Provided. Beach Av at Thurlow St is extremely unlikely to meet the necessary warrants & priority ranking to have a signal installed at this intersection. Typically locations that are selected for signal installation are high in both traffic volume, and pedestrian volume throughout the day, and these are typically located on arterials. With that being said, the City could schedule a pedestrian study to be conducted for Beach Av & Thurlow St (tentatively in summer). The City of Vancouver will proceed onto the next step once we receive the result from the pedestrian study. If the location meets the warrants for a pedestrian activated signal, we will compare the result of this location to other locations around the city that have also met the warrants. Since the program only receives enough budget for 3-5 pedestrian signals a year, it is imperative for engineering staffs to rank the intersections that meet the warrant and install them in order based on their ranks. - Resolved on 27/04/2018 9:05:00 AM. Agent Finished: Case Closed. Closed date : 2018-04-27 09:11:30.123 Service Provided 10 - Service Provided. Beach Av at Thurlow St is extremely unlikely to meet the necessary warrants & priority ranking to have a signal installed at this intersection. Typically locations that are selected for signal installation are high in both traffic volume, and pedestrian volume throughout the day, and these are typically located on arterials. With that being said, the City could schedule a pedestrian study to be conducted for Beach Av & Thurlow St (tentatively in summer). The City of Vancouver will proceed onto the next step once we receive the result from the pedestrian study. If the location meets the warrants for a pedestrian activated signal, we will compare the result of this location to other locations around the city that have also met the warrants. Since the program only receives enough budget for 3-5 pedestrian signals a year, it is imperative for engineering staffs to rank the intersections that meet the warrant and install them in order based on their ranks. - Resolved on 27/04/2018 9:05:00 AM.
Traffic & Pedestrian Signal - New Case	101011170794	INTERSECTION	BEACH AV	THURLLOW ST	1. Type of signal: Pedestrian Signal 2. If Other, provide details: 3. Reason signal is required: Poor Visibility 4. If Other, provide details: 5. What time of day is the problem worst? PM Peak (4:00 - 7:00 pm) 6. What are the intersecting streets? Beach Ave. and Thurlow St. 7. (Don't ask, just record - did caller indicate they want a call back?): No		8.22(1)	8.22(1)	4/26/18 17:32	4/27/18 9:11	Eng_Traffic and Data Management	Agent Created Case: Agent Updated Case Details: Reallocated to queue: Eng_Traffic and Data Management Hansen Service Case Created / Updated: Hansen ServiceRequest Number : 1130471 created / updated at Wednesday, May 17, 2017 2:50:23 PM Service Provided: 10 - Service Provided. location was reviewed and does not warrant a 4 way stop. Also 4 way stops decrease safety for pedestrians. - Resolved on 01/06/2017 11:45:00 AM. Agent Finished: Case Closed. Closed date : 2017-06-01 11:47:10.103 Service Provided 10 - Service Provided. location was reviewed and does not warrant a 4 way stop. Also 4 way stops decrease safety for pedestrians. - Resolved on 01/06/2017 11:45:00 AM.
Traffic Calming Request Case	101009556606	INTERSECTION	BEACH AV	THURLLOW ST	1. Type of Traffic Calming Measure Request: Multiway Stop Signs 2. If Other, provide details: 3. Is there an existing traffic calming device at this location? Yes 4. Describe in detail traffic concerns in your area: Currently one stop sign on Thurlow. Citizen is requesting they be on Pacific as well to have 3 way stop signs. Email: drivers often do not stop for pedestrians, we have been almost involved in accidents a handful of times in the past year crossing Beach Ave. at Thurlow. Stop signs would help. 5. (Don't ask, just record - did caller indicate they want a call back?): No		8.22(1)	8.22(1)	5/17/17 14:48	6/1/17 11:47	Eng_Traffic and Data Management	Agent Created Case: Agent Updated Case Details: Reallocated to queue: Eng_Traffic and Data Management Hansen Service Case Created / Updated: Hansen ServiceRequest Number : 1130471 created / updated at Wednesday, May 17, 2017 2:50:23 PM Service Provided: 10 - Service Provided. location was reviewed and does not warrant a 4 way stop. Also 4 way stops decrease safety for pedestrians. - Resolved on 01/06/2017 11:45:00 AM. Agent Finished: Case Closed. Closed date : 2017-06-01 11:47:10.103 Service Provided 10 - Service Provided. location was reviewed and does not warrant a 4 way stop. Also 4 way stops decrease safety for pedestrians. - Resolved on 01/06/2017 11:45:00 AM.
Traffic Calming Request Case	101009556606	INTERSECTION	BEACH AV	THURLLOW ST	1. Type of Traffic Calming Measure Request: Multiway Stop Signs 2. If Other, provide details: 3. Is there an existing traffic calming device at this location? Unknown 4. Describe in detail traffic concerns in your area: The following request was received via the online webform and the citizen noted "We are a family with 2 children and we often do not feel safe crossing the intersection at Beach Ave. and Thurlow St. We cross that intersection often and many times cars do not stop for us even though there is a pedestrian crossing sign. We would like to request a stop sign on Beach Ave. or something more visible for drivers to slow down and stop. Thank you." 5. (Don't ask, just record - did caller indicate they want a call back?): No		8.22(1)	8.22(1)	10/15/17 15:08	11/16/17 14:24	Eng_Traffic and Data Management	Agent Created Case: Agent Updated Case Details: Reallocated to queue: Eng_Traffic and Data Management Hansen Service Case Created / Updated: Hansen ServiceRequest Number : 1199131 created / updated at Sunday, October 15, 2017 3:10:22 PM Hansen Service Request has been reviewed: Case reviewed on 17/10/2017 2:51:48 PM. Service Provided: 10 - Service Provided. Investigation showed that Beach Av & Thurlow St does not meet the warrant for a 3 way stop. Therefore, the City will not be installing 3 way stop at this location. For dangerous driving, speeding, failure to stop, and other traffic violations, citizen is encouraged to call the non-emergency VPD number at 604-717-3321 and request traffic enforcement or contact West End Coal Harbour Community Policing Centre located on 1267 Davie Street. - Resolved on 16/11/2017 2:21:00 PM. Agent Finished: Case Closed. Closed date : 2017-11-16 14:24:19.863 Service Provided 10 - Service Provided. Investigation showed that Beach Av & Thurlow St does not meet the warrant for a 3 way stop. Therefore, the City will not be installing 3 way stop at this location. For dangerous driving, speeding, failure to stop, and other traffic violations, citizen is encouraged to call the non-emergency VPD number at 604-717-3321 and request traffic enforcement or contact West End Coal Harbour Community Policing Centre located on 1267 Davie Street. - Resolved on 16/11/2017 2:21:00 PM.

[illegible]

22.02.0 - General Inquiries	107000049420	INTERSECTION	BEACH AVE	THURLOW ST	<p>Type of inquiry: New Stop Sign Request</p> <p>Description Inquiry to detail: Once upon the intersection of Beach Ave and Thurlow St is quite dangerous. There are stop signs on both Beach Ave side, however Thurlow does not have any and there should be. Especially since there is a crosswalk there. This should be a four-way stop instead of just a two-way.</p> <p>Don't ask, just report - do call us before they want a call back!!</p>	6-22(1)	6-22(1)	09/13/22 1:00	11/01/22 1:10	Eng. Parking Management	<p>Agent Created Case:</p> <p>Agent Updated Case Details: Reallocated to queue: Eng_Nightdownroad Parking and Transportation</p> <p>Review Service Case Closed / Updated: Review Service Request Number : 121008 created / updated at: Thursday, October 12, 2022 11:02:49 AM</p> <p>Review Service Request Case Type has changed. Case type changed to PMTCaseRequest on 11/10/2022 1:38:40 AM</p> <p>Alternate Service Provided: 12 - Alternate Service Provided: As per Street Closes: Thurlow Street at Beach Avenue is a T-Intersection. - Beach Avenue is the through road (carrying the larger volume of traffic) and is also a driveway. The signage is appropriate based on road geometry and function. - No call back required. - Case file. - Reviewed on 04/11/2023 12:51:00 AM</p> <p>Agent Feedback: Case Closed</p> <p>Alternate Service Provided: 12 - Alternate Service Provided: As per Street Closes: Thurlow Street at Beach Avenue is a T-Intersection. - Beach Avenue is the through road (carrying the larger volume of traffic) and is also a driveway. The signage is appropriate based on road geometry and function. - No call back required. - Case file. - Reviewed on 04/11/2023 12:51:00 AM</p>
22.02.0 - General Inquiries	107000042641	INTERSECTION	BEACH AVE	THURLOW ST	<p>Type of inquiry: Change Feedback - cycling helmet and safety</p> <p>Description Inquiry to detail: I would like to see if there is a way to make the intersection safer for cyclists. There are some issues with the current layout. I would like to see if there is a way to make the intersection safer for cyclists. There are some issues with the current layout.</p> <p>1. At the end of Thurlow at Beach Avenue there is a pedestrian crossing. It is signed as such. On the south side of this roadway leading down to False Creek, beside the Aquatic Centre, is a paved pathway. The pathway is narrow and the edges have been eroded by water action so there is a channel on either side. On warm days when there are many cyclists who use this pathway to ride up to Beach Avenue and home who ride down, pedestrians are forced off the pathway and onto the area beside where the channel can cause falls or twisted ankles. Cyclists are not completely at fault because the sign from the bicycle path on the western side of the English Bay Seawall points to that route for the Burnard Street Bridge. Sometimes pedestrians and cyclists have to share. They don't share at all well. Cyclists have the upper hand and to my experience never give way to pedestrians. Obviously there is a need for better signage and possibly two separate and distinctly marked pathways.</p> <p>2. Under the Burnard Street Bridge on Beach Avenue there is also a difficulty. Cyclists for some reason have decided that the footpath is a bike freeway. Last week I saw two on two separate occasions they were nearly exceeded being hit by a motor vehicle. The second time I was talking with her when a cyclist came between us at quite a rate in a clip. I suggested to the cyclist that she should not be riding there as it was too fast and I suggested to the motor vehicle driver that she should not be riding there as it was too fast. As you are aware, there are bicycle lanes at the way around False Creek.</p> <p>3. The nightmarish scene from Pacific onto the Burnard Street Bridge where there are two pedestrian crossings and one green bike lane is dangerous for cars, bikes and pedestrians. Traffic lights which are in sync with each other are desperately needed.</p> <p>4. Currently there is a pedestrian crossing on Beach Avenue leading from Burnard Street (the high block section which is on the west side of the bridge). This is not used very much as it does not correspond to the roadway beside the Burnard Street Bridge on the west side which pedestrian use as the link. When this road the</p>	6-22(1)	6-22(1)	10/13/22 14:00	3/29/23 8:07	Eng. Transportation Planning	<p>Agent Created Case:</p> <p>Agent Updated Case Details: Reallocated to queue: Eng_Active Transportation</p> <p>Review Service Case Closed / Updated: Review Service Request Number : 179729 created / updated at: Tuesday, May 23, 2023 11:10:23 PM</p> <p>Review Service Request has been reviewed: Case reviewed on 22/05/2023 8:28:00 AM</p> <p>Review Change in Categories: Comments: Forwarded to Liaison to determine who should deal with this call. (Stratford Drive)</p> <p>Added on 22/05/2023 10:08:00 AM</p> <p>Alternate Service Provided: 12 - Alternate Service Provided: David Rowlands will be reviewing call and providing response to caller. Reviewed on 29/05/2023 9:04:00 AM</p> <p>Agent Feedback: Case Closed</p> <p>Alternate Service Provided: 12 - Alternate Service Provided: David Rowlands will be reviewing call and providing response to caller. Reviewed on 29/05/2023 9:04:00 AM</p>

Work Order Summary

Work Order #: 617384 **T_SLO** Light Luminaire
Asset ID #: 30371 Repair
Group Project #: Street Lighting
Location: 1000 - 1099 BEACH AV
Operational Status: **Ref #1: Standing:** EEL257343 **Ref #2:**
Service Request: **Contact Name:** **Phone#:**
Requested By: Self Initiated **Requested Date:** Jun 14, 2015 **Initiated Date:** Jun 14, 2015

Assigned By: MELVILLE **Assigned To:**
 MILLER
Assigned Date: Jun 14, 2015 **Crew ID:** **Work Started:** Jun 14, 2015
Result: Completed **Work Completed:** Jun 14, 2015

Comments:
 SLO - Pole 6/10 Beach Av.
 Problem found/ action taken (June 14/15 [Self found] K Sanderson): Changed 200W HPS lamp, 22uF capacitor

Work Orders & Accomplishments:

WO#	Result	Completed Date				
617384	Completed	Jun 14, 2015				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Jun 14, 2015		Lamps	1	T_C1702	KRISTIE-LEE SANDERSON	200W HPS
Jun 14, 2015		Stray Voltage Check	1	T_C1702	KRISTIE-LEE SANDERSON	

Work Area Prefix: L **SAP Network #:** **WBS#:**
Parent Network: **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
TOTAL	<u>\$0.00</u>	<u>\$0.00</u>	<u>\$0.00</u>

Work Order Summary

Work Order #: 623502 T_RP Repl Unplanned 2015-LO Light Pole
Asset ID #: 36989 Diagnose or Investigate Rust Damage
Group Project #: 56232 Rusty Pole Replacement - Unplanned - 2015 - LOCAL ROADS Street Lighting
 Rusty Pole discovered while conducting other work that needs to be replaced

Location: 1100 - 1199 BEACH AV

Operational Status:

Ref #1: :

Ref #2:

Service Request:

Contact Name:

Phone#:

Requested By: Eng Traffic & Electrical Ops

Requested Date: Jul 06, 2015

Initiated Date: Jul 08, 2015

Assigned By: BRIAN BABINEAU **Assigned To:**

Assigned Date: Jul 06, 2015

Crew ID:

Work Started: Jul 06, 2015

Result: Completed

Work Completed: Jul 07, 2015

Comments:

Rusty Pole Replacement - Unplanned - 2015 - LOCAL ROADS

Rusty Pole discovered while conducting other work that needs to be replaced

Problem Found/Action Taken (Jul 6/15 [12:30-14:00] D Hamon, B Dosanjh / A5663): Removed 30' Davit pole. **Other Work Required:** Need new 30' pole.

Problem Found/Action Taken (Jul 7/15 [08:30-11:15] D Hamon, B Dosanjh / A5663): Removed rusted nuts nd bottom of pole. Installed new 30' Davit pole and existing 200W fixture. Complete. **Additional Comments:** Rusted nuts, pole had to be cut.

Work Orders & Accomplishments:

WO#	Result	Completed Date	
623502	Completed	Jul 07, 2015	

Work Area Prefix: L

SAP Network #: CELD56232

WBS#: CEL-00018-15-AA

Parent Network:

Billable: N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$220.88	-\$220.88
Labour	\$0.00	\$655.20	-\$655.20
Material	\$0.00	\$843.35	-\$843.35
Other	\$0.00	\$55.80	-\$55.80
TOTAL	\$0.00	\$1,775.23	-\$1,775.23

Work Order Summary

Work Order #: 672347 **T_RP Repl - 2015 - MAJ** **Light Pole**
Asset ID #: 30371 **Replace** **Rust Damage**
Group Project #: 67976 **Rusty Pole Replacement - 2015 - MAJOR Roads** **Street Lighting**
 Requested By: Ofer Marom

Location: 1000 - 1099 BEACH AV

Operational Status: **Ref #1: :** **Ref #2:**
Service Request: **Contact Name:** **Phone#:**
Requested By: Eng Traffic & Electrical Ops **Requested Date:** Dec 04, 2015 **Initiated Date:** Dec 04, 2015

Assigned By: BRIAN BABINEAU **Assigned To:**
Assigned Date: Nov 05, 2015 **Crew ID:** **Work Started:** Nov 05, 2015
Result: Completed **Work Completed:** Nov 05, 2015

Comments:

Rusty Pole Replacement - MAJOR Roads - 2015
Requested By: Ofer Marom

Problem Found / Action Taken (Nov 5/15 [09:00-10:30] D. Hamon & B. Dosanjh B1749): Removed old pole, fixture & signs. Installed new pole, the old fixture & signs. - **Complete**

Work Orders & Accomplishments:

WO#	Result	Completed Date	
672347	Completed	Nov 05, 2015	

Work Area Prefix: L **SAP Network #:** CELD67976 **WBS#:** CEL-00017-15-AA
Parent Network: **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$181.37	-\$181.37
Labour	\$0.00	\$587.01	-\$587.01
Material	\$0.00	\$1,003.82	-\$1,003.82
Other	\$0.00	\$267.82	-\$267.82
TOTAL	<u>\$0.00</u>	<u>\$2,040.02</u>	<u>-\$2,040.02</u>

Work Order Summary

Work Order #: 672354 T_RP Repl - 2015 - MAJ Light Pole
Asset ID #: 50593 Replace Rust Damage
Group Project #: 67976 Rusty Pole Replacement - 2015 - MAJOR Street Lighting
 Roads
 Requested By: Ofer Marom

Location: 1100 - 1199 BEACH AV

Operational Status: **Ref #1:** : **Ref #2:**
Service Request: **Contact Name:** **Phone#:**
Requested By: Eng Traffic & Electrical Ops **Requested Date:** Dec 04, 2015 **Initiated Date:** Dec 04, 2015

Assigned By: BRIAN BABINEAU **Assigned To:**
Assigned Date: Nov 04, 2015 **Crew ID:** **Work Started:** Nov 04, 2015
Result: Completed **Work Completed:** Nov 04, 2015

Comments:

Rusty Pole Replacement - MAJOR Roads - 2015
Requested By: Ofer Marom

Problem Found / Action Taken (Nov 4/15 [08:00-09:30] D. Hamon & B. Dosanjh B1749): Removed old pole, fixture & signs. Installed a new pole, the existing fixture & signs. - **Complete**

Work Orders & Accomplishments:

WO#	Result	Completed Date	
672354	Completed	Nov 04, 2015	

Work Area Prefix: L **SAP Network #:** CELD67976 **WBS#:** CEL-00017-15-AA
Parent Network: **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$181.37	-\$181.37
Labour	\$0.00	\$587.01	-\$587.01
Material	\$0.00	\$1,003.82	-\$1,003.82
Other	\$0.00	\$267.82	-\$267.82
TOTAL	<u>\$0.00</u>	<u>\$2,040.02</u>	<u>-\$2,040.02</u>

Work Order Summary

Work Order #: 952333 T_RP Repl 2018 Major - EL 1 Light Pole
Asset ID #: 39142 Replace Rust Damage
Group Project #: 78393 T_RP Repl 2018 Major - EL 1 Street Lighting
Location: 1000 - 1099 BEACH AV
Operational Status: **Ref #1:** : **Ref #2:**
Service Request: **Contact Name:** **Phone#:**
Requested By: Eng Traffic & Electrical Ops **Requested Date:** Feb 28, 2018 **Initiated Date:** Feb 28, 2018

Assigned By: SANDRO MATTAROLLO **Assigned To:**
Assigned Date: Mar 11, 2018 **Crew ID:** **Work Started:** Mar 11, 2018
Result: Completed **Work Completed:** Mar 11, 2018

Comments:

Rusty Pole Replacement - 2018 - Major - Electrical 1
 Requested By: Hammad Qazi

Problem Found / Action Taken (Mar 11/18 [0900 to 1000] T Page, D Hamon - A5663): Re + Re 30' davit -
COMPLETED

Work Orders & Accomplishments:

WO#	Result	Completed Date	
952333	Completed	Mar 11, 2018	

Work Area Prefix: L **SAP Network #:** CELD78393 **WBS#:** CEL-00017-18-AA
Parent Network: **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$126.01	-\$126.01
Labour	\$0.00	\$599.67	-\$599.67
Material	\$0.00	\$1,016.33	-\$1,016.33
Other	\$0.00	\$51.11	-\$51.11
TOTAL	<u>\$0.00</u>	<u>\$1,793.12</u>	<u>-\$1,793.12</u>

Work Order Summary

Work Order #: 952334 T_RP Repl 2018 Major - EL 1 Light Pole
Asset ID #: 31133 Replace Rust Damage
Group Project #: 78393 T_RP Repl 2018 Major - EL 1 Street Lighting
Location: 1100 - 1199 BEACH AV
Operational Status: **Ref #1:** : **Ref #2:**
Service Request: **Contact Name:** **Phone#:**
Requested By: Eng Traffic & Electrical Ops **Requested Date:** Feb 28, 2018 **Initiated Date:** Feb 28, 2018

Assigned By: SANDRO MATTAROLLO **Assigned To:**
Assigned Date: Mar 11, 2018 **Crew ID:** **Work Started:** Mar 11, 2018
Result: Completed **Work Completed:** Mar 11, 2018

Comments:

Rusty Pole Replacement - 2018 - Major - Electrical 1
 Requested By: Hammad Qazi

Problem Found / Action Taken (Mar 11/18 [1000 to 1200] T Page, D Hamon - A5663): Re + Re 30' davit -
COMPLETED

Work Orders & Accomplishments:

WO#	Result	Completed Date	
952334	Completed	Mar 11, 2018	

Work Area Prefix: L **SAP Network #:** CELD78393 **WBS#:** CEL-00017-18-AA
Parent Network: **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$126.01	-\$126.01
Labour	\$0.00	\$599.67	-\$599.67
Material	\$0.00	\$1,016.33	-\$1,016.33
Other	\$0.00	\$51.11	-\$51.11
TOTAL	\$0.00	\$1,793.12	-\$1,793.12

Work Order Summary

Work Order #: 952335 T_RP Repl 2018 Major - EL 1 Light Pole
Asset ID #: 40821 Replace Rust Damage
Group Project #: 78393 T_RP Repl 2018 Major - EL 1 Street Lighting
Location: 1100 - 1199 BEACH AV
Operational Status: **Ref #1:** : **Ref #2:**
Service Request: **Contact Name:** **Phone#:**
Requested By: Eng Traffic & Electrical Ops **Requested Date:** Feb 28, 2018 **Initiated Date:** Feb 28, 2018

Assigned By: SANDRO MATTAROLLO **Assigned To:**
Assigned Date: Mar 11, 2018 **Crew ID:** **Work Started:** Mar 11, 2018
Result: Completed **Work Completed:** Mar 11, 2018

Comments:

Rusty Pole Replacement - 2018 - Major - Electrical 1
 Requested By: Hammad Qazi

Problem Found / Action Taken (Mar 11/18 [1200 to 1400] T Page, D Hamon - A5663): Re + Re 30' Davit -
COMPLETED

Work Orders & Accomplishments:

WO#	Result	Completed Date	
952335	Completed	Mar 11, 2018	

Work Area Prefix: L **SAP Network #:** CELD78393 **WBS#:** CEL-00017-18-AA
Parent Network: **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$126.01	-\$126.01
Labour	\$0.00	\$599.67	-\$599.67
Material	\$0.00	\$1,016.33	-\$1,016.33
Other	\$0.00	\$51.11	-\$51.11
TOTAL	\$0.00	\$1,793.12	-\$1,793.12

Work Order Summary

Work Order #: 970281 T_RP Repl 2018 Major - EL 1 Light Pole
Asset ID #: 42727 Replace Rust Damage
Group Project #: 78393 T_RP Repl 2018 Major - EL 1 Street Lighting
Location: 1000 - 1099 BEACH AV
Operational Status: **Ref #1:** : **Ref #2:**
Service Request: **Contact Name:** **Phone#:**
Requested By: Eng Traffic & Electrical Ops **Requested Date:** Apr 27, 2018 **Initiated Date:** Apr 27, 2018

Assigned By: SANDRO MATTAROLLO **Assigned To:**
Assigned Date: May 29, 2018 **Crew ID:** **Work Started:** May 29, 2018
Result: Completed **Work Completed:** May 29, 2018

Comments:

Rusty Pole Replacement - 2018 - Major - Electrical 1
 Requested By: Hammad Qazi

Problem Found/ Action Taken (May 29/18 [10:00-11:00] deGraaf & Sanderson B1749) - As per job details. Remove rusty pole. Install new 30' pole. Reinstall sign and 200W HPS Fixture. - Completed

Work Orders & Accomplishments:

WO#	Result	Completed Date	
970281	Completed	May 29, 2018	

Work Area Prefix: L **SAP Network #:** CELD78393 **WBS#:** CEL-00017-18-AA
Parent Network: **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$126.01	-\$126.01
Labour	\$0.00	\$599.67	-\$599.67
Material	\$0.00	\$1,016.33	-\$1,016.33
Other	\$0.00	\$51.11	-\$51.11
TOTAL	\$0.00	\$1,793.12	-\$1,793.12

Work Order Summary

Work Order #: 970282 T_RP Repl 2018 Major - EL 1 Light Pole
Asset ID #: 51161 Replace Rust Damage
Group Project #: 78393 T_RP Repl 2018 Major - EL 1 Street Lighting
Location: 1000 - 1099 BEACH AV
Operational Status: **Ref #1:** : **Ref #2:**
Service Request: **Contact Name:** **Phone#:**
Requested By: Eng Traffic & Electrical Ops **Requested Date:** Apr 27, 2018 **Initiated Date:** Apr 27, 2018

Assigned By: SANDRO MATTAROLLO **Assigned To:**
Assigned Date: May 29, 2018 **Crew ID:** **Work Started:** May 29, 2018
Result: Completed **Work Completed:** May 29, 2018

Comments:

Rusty Pole Replacement - 2018 - Major - Electrical 1
 Requested By: Hammad Qazi

Problem Found/ Action Taken (May 29/18 [09:00-10:00] deGraaf & Sanderson B1749) - As per job details. Remove rusty pole. Install new 30' pole. Reinstall sign and 200W Fixture. - **Completed**

Work Orders & Accomplishments:

WO#	Result	Completed Date	
970282	Completed	May 29, 2018	

Work Area Prefix: L **SAP Network #:** CELD78393 **WBS#:** CEL-00017-18-AA
Parent Network: **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$126.01	-\$126.01
Labour	\$0.00	\$599.67	-\$599.67
Material	\$0.00	\$1,016.33	-\$1,016.33
Other	\$0.00	\$51.11	-\$51.11
TOTAL	\$0.00	\$1,793.12	-\$1,793.12

Work Order Summary

Work Order #: 1104468 **T_SLO** Light Spot Lamp
Asset ID #: 42975 Replace
Group Project #: Street Lighting
Location: 1100 - 1199 BEACH AV
Operational Status: **Ref #1: Standing:** EEL257341 **Ref #2:**
Service Request: **Contact Name:** **Phone#:**
Requested By: Self Initiated **Requested Date:** Jul 06, 2019 **Initiated Date:** Jul 06, 2019

Assigned By: ROBERT LAPOINTE **Assigned To:**
Assigned Date: **Crew ID:** **Work Started:** Jul 06, 2019
Result: Completed **Work Completed:** Jul 06, 2019

Comments: SLO - Pole # 1/11 on Beach Ave.
 Problem Found/Action Taken - (Jul 6/19 [self initiated] Gazzola A5822) Replaced 200W Hps Lamp. - **COMPLETED**

Work Orders & Accomplishments:

WO#	Result	Completed Date				
1104468	Completed	Jul 06, 2019				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Jul 06, 2019		Stray Voltage Check	1			

Work Area Prefix: L **SAP Network #:** **WBS#:**
Parent Network: **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
TOTAL	<u>\$0.00</u>	<u>\$0.00</u>	<u>\$0.00</u>