

What You Told Us

- Maintain path width and separate with pavement markings and signage. (84% Yes, 7% No)
- *Remainder of answers were “Unsure/don’t know”. Results are from October 2015 public open houses and online feedback survey.

Our Recommendation

Recommended Solutions	Why?	When?
Trim vegetation to edge of path.	Overgrown vegetation narrows the path around tight curves.	2016
Provide painted separation and signage to clearly mark walking and cycling paths. See Detail Plan 7A, Below	Separated paths improve safety and comfort for all Seawall users.	2016
Key components of design: <ul style="list-style-type: none">• Existing 6.2m path maintained.		
Future Considerations	Why?	
Redesign the elevated seating area east of Stamps Landing.	Current design reduces visibility around the tight corner.	

