

File No.: 04-1000-20-2017-272

August 10, 2017

s.22(1)

Dear <mark>s.22(1)</mark>

Re: Request for Access to Records under the Freedom of Information and Protection of Privacy Act (the "Act")

I am responding to your request of July 18, 2017 for:

In regards to 1200 West 73rd Avenue from July 18, 1988 to July 18, 2017:

Any environmental records, control orders or violation notices; and
 Any storage tank and/or spill records.

Responsive records since 1994 are attached.

Please note, for records prior to 1994, we recommend you visit the City of Vancouver Archives, located at 1150 Chestnut Street, <u>http://vancouver.ca/your-government/city-of-vancouver-archives.aspx</u>

Under section 52 of the Act you may ask the Information & Privacy Commissioner to review any matter related to the City's response to your request. The Act allows you 30 business days from the date you receive this notice to request a review by writing to: Office of the Information & Privacy Commissioner, <u>info@oipc.bc.ca</u> or by phoning 250-387-5629.

If you request a review, please provide the Commissioner's office with: 1) the request number assigned to your request (#04-1000-20-2017-272); 2) a copy of this letter; 3) a copy of your original request for information sent to the City of Vancouver; and 4) detailed reasons or grounds on which you are seeking the review.

Please do not hesitate to contact the Freedom of Information Office at <u>foi@vancouver.ca</u> if you have any questions.

Yours truly,

Cobi Falconer, FOI Case Manager, for

Barbara J. Van Fraassen, BA Director, Access to Information

Barbara.vanfraassen@vancouver.ca 453 W. 12th Avenue Vancouver BC V5Y 1V4 Phone: 604.873.7999 Fax: 604.873.7419

Encl.

:cf

CITY OF VANCOUVER

PERMITS & LICENSES DEPARTMENT · · City Hall, East Wing 453 West 12th Avenue · Vancouver, British Columbia Canada V5Y 1V4 Phone (604) 873-7611 FAX (604) 873-7100



DIRECTOR: J.A. Perri

DEPUTY DIRECTOR: R.L. Maki, PEng Permits & Inspection Division

PLEASE REFER TO: Mr. J. Curran Supervisor, Property Use Branch at 873-7563 I.R. No. 307583

PU-25

1995 November 17

Akira Industries Co. Ltd. c/o Penreal Management #700 - 1090 West Georgia Street Vancouver, BC V6E 3V7

Dear Sirs:

. .

Re: 1200 West 73rd Avenue (Unit Nos. 1100 and 1240)

The District Property Use Inspector reports that portions of Unit Nos. 1100 and 1240 in your building at the above location are being used as health care offices, without obtaining the necessary Permits in contravention of the Zoning and Development By-law.

To retain this use, you or someone representing you must come in to this office, bring in five sets of plans, sign a Permit Application and pay the prescribed fee.

Enclosed is a check list of plan requirements for Development Permit. Please note that additional information may be required at the time of application.

For further information and before having plans prepared, I suggest you contact the Planning Department at 873-7613 to see if your application could be considered.

If the Development Application is approved, a Building Permit may be required.

In accordance with the By-laws and to avoid further action, you are to either make application as outlined above or cease using any portion of Unit Nos. 1100 and 1240 in this building as health care offices within 30 days of the date of this letter.

DEC 18/95

Yours truly,

J. Curran for J.A. Perri DIRECTOR

HC/LK/jl2

Encl.

cc: Nathalie Bernard, #1100 - 1200 West 73rd Avenue, Vancouver, BC V6P 3E5

Healthserv, Attention: Eileen Anderson #1240 - 1200 West 73rd Avenue, Vancouver, BC V6P 3E5

PERMITS & LICENSES DEPARTMENT Gity Hail; East Wing 453 West 12th Avenue Vancouver, British'Columbia Canada V5Y 1V4 Phone (604) 873-7611 FAX (604) 873-7100

CITY OF VANCOUVER



REGISTERED

DIRECTOR: J.A. Perri

DEPUTY DIRECTOR: R.L. Maki, PEng Permits & Inspection Division

PLEASE REFER TO: Supervisor, Property Use Branch at 873-7563 I.R. No. 314530

1996 April 18

PU-25

Akira Industries Co. Ltd. #1600 - 925 West Georgia Street Co. Search V6C 3L2

Dear Sirs:

Re: 1200 West 73rd Avenue

Our Inspection Services report that two banner signs have been placed on the building at the above location (one on the south side and one on the south west side), in contravention of the Sign By-law.

For your information, banner signs are not permitted under the Vancouver Sign By-law.

Therefore, in accordance with Section 7.1 of the Sign By-law, you are ordered to remove the two banner signs WITHIN 7 DAYS OF THE DATE OF THIS ORDER, and to maintain this site and/or building free from these types of signs thereafter.

Failure to comply with this Order will result in this matter being referred to the City Prosecutor for the laying of charges.

Yours truly,

Perri DIRECTOR

141

HC/HD/kmvb

REGISTERED cc:

Akira Industries Co. Ltd., c/o Penreal Management #700 - 1090 West Georgia Street, Vancouver, BC V6E 3V7 PTX

REGISTERED

Royal LePage, 5th Floor - 777 Dunsmuir Street P.O. Box 10445, Pacific Centre, Vancouver, BC V7Y 1K4 3 Per inspector

Real Estate Board of Greater Vancouver 2433 Spruce Street, Vancouver, BC V6H 4C8



City of Vancouver

Sheri vanBemmelen Inspection Division Clerk, Permits and Licenses, Community Services 453 W. 12th Ave. Vancouver, BC VSY 1V4 = 604.873.7601 fax:873.7100

sheri_van_bemmelen@city.vancouver.bc.ca

June 9, 2000

Harbourview Electric Limited 1-5707 Sidley Street Burnaby, B.C., V5J 5E5

RE: EL438450 1200 West 73rd Avenue

As the holder of the above-noted Electrical Permit, please be advised that we have no record of your request for inspection within the last 180 day period.

The BC Electrical Safety Regulation (BC Reg. 487/95) Section 30(4) states:

- 4. The registered representative of a registered electrical contractor holding a regular permit must submit a request for inspection at least once in every 180 day period, by delivering a declaration form to the regulatory authority having jurisdiction, that:
 - certifies that the registered representative has physically inspected the electrical installation;
 - b. states that the electrical installation is safe; and
 - c. reports of the present status of the electrical installation.

Therefore, you are ordered to provide the required declaration by June 23, 2000. Also to provide access for the District Electrical Inspector. Our fax number is 871-6367.

Failure to comply with this order may result in the cancellation of your permit privileges in the City of Vancouver in accordance with Section 5.2(d) of the City of Vancouver Electrical By-law. Further disciplinary action may also be taken in accordance with the Electrical Safety Regulation.

Yours truly,

nom Bernuh

(A. Z. Tsisserev, P.Eng. City Electrician

AZT/svb



September 18, 2001

PLEASE REFER TO Sheri Amendt, Clerk Typist 11 Inspection Support Services Sheri_amendt@city.vancouver.bc.ca at 873-7601

Sasco Systems Limited 111 - 3070 Norland Avenue Burnaby, B.C., V6B 3A6

RE: EL451958 #850 - 1200 West 73rd Avenue

As the holder of the above-noted Electrical Permit, please be advised that we have no record of your request for inspection within the last 180 day period.

The BC Electrical Safety Regulation (BC Reg. 487/95) Section 30(4) states:

- 4. The registered representative of a registered electrical contractor holding a regular permit must submit a request for inspection at least once in every 180 day period, by delivering a declaration form to the regulatory authority having jurisdiction, that:
 - a. certifies that the registered representative has physically inspected the electrical installation;
 - b. states that the electrical installation is safe; and
 - c. reports of the present status of the electrical installation.

Therefore, you are ordered to provide the required declaration by October 2, 2001. Our fax number is 871-6367.

Failure to comply with this order may result in the cancellation of your permit privileges in the City of Vancouver in accordance with Section 5.2(d) of the City of Vancouver Electrical By-law. Further disciplinary action may also be taken in accordance with the Electrical Safety Regulation.

Yours truly,

annenalt

A. Z. Tsisserev, P.Eng. City Electrician

12

AZT/sa



November 13, 2001

PLEASE REFER TO Sheri Amendt, Clerk Typist 11 Inspection Support Services Sheri_amendt@city.vancouver.bc.ca at 873-7601

BMS Communications Services Limited 6660 McMillan Way Richmond, B.C., V6W 1J7

RE: EL454513 1220- 1200 West 73rd Avenue

As the holder of the above-noted Electrical Permit, please be advised that we have no record of your request for inspection within the last 180 day period.

The BC Electrical Safety Regulation (BC Reg. 487/95) Section 30(4) states:

- The registered representative of a registered electrical contractor holding a regular 4. permit must submit a request for inspection at least once in every 180 day period, by delivering a declaration form to the regulatory authority having jurisdiction, that:
 - certifies that the registered representative has physically inspected the a. electrical installation;
 - states that the electrical installation is safe; and b.
 - reports of the present status of the electrical installation. c.

Therefore, you are ordered to provide the required declaration by November 27, 2001. Our fax number is 871-6367.

Failure to comply with this order may result in the cancellation of your permit privileges in the City of Vancouver in accordance with Section 5.2(d) of the City of Vancouver Electrical By-law. Further disciplinary action may also be taken in accordance with the Electrical Safety Regulation.

Yours truly.

AZT/sa

Amenalt (1)Q

A. Z. Tsisserev, P.Eng. City Electrician



November 13, 2001

PLEASE REFER TO Sheri Amendt, Clerk Typist 11 Inspection Support Services Sheri_amendt@city.vancouver.bc.ca at 873-7601

Sasco Systems Limited 111-3070 Norland Avenue Burnaby, B.C., V6B 3A6

RE: EL453616 #1550 - 1200 West 73rd Avenue

As the holder of the above-noted Electrical Permit, please be advised that we have no record of your request for inspection within the last 180 day period.

The BC Electrical Safety Regulation (BC Reg. 487/95) Section 30(4) states:

- The registered representative of a registered electrical contractor holding a regular 4. permit must submit a request for inspection at least once in every 180 day period, by delivering a declaration form to the regulatory authority having jurisdiction, that:
 - certifies that the registered representative has physically inspected the a. electrical installation;
 - states that the electrical installation is safe; and b.
 - reports of the present status of the electrical installation. с.

Therefore, you are ordered to provide the required declaration by November 27, 2001. Our fax number is 871-6367.

Failure to comply with this order may result in the cancellation of your permit privileges in the City of Vancouver in accordance with Section 5.2(d) of the City of Vancouver Electrical By-law. Further disciplinary action may also be taken in accordance with the Electrical Safety Regulation.

Yours truly,

A. Z. Tsisserev, P.Eng. City Electrician

AZT/sa



November 19, 2001

PLEASE REFER TO Sheri Amendt, Clerk Typist 11 Inspection Support Services Sheri_amendt@city.vancouver.bc.ca at 873-7601

Intech Electric Inc. 604-4425 Halifax Street Burnaby, B.C., V5C 6P2

RE: EL455498 1200 West 73rd Avenue

As the holder of the above-noted Electrical Permit, please be advised that we have no record of your request for inspection within the last 180 day period.

The BC Electrical Safety Regulation (BC Reg. 487/95) Section 30(4) states:

- 4. The registered representative of a registered electrical contractor holding a regular permit must submit a request for inspection at least once in every 180 day period, by delivering a declaration form to the regulatory authority having jurisdiction, that:
 - a. certifies that the registered representative has physically inspected the electrical installation;
 - b. states that the electrical installation is safe; and
 - c. reports of the present status of the electrical installation.

Therefore, you are ordered to provide access for the Electrical Inspector and also to provide the required declaration by December 3, 2001. Our fax number is 871-6367.

Failure to comply with this order may result in the cancellation of your permit privileges in the City of Vancouver in accordance with Section 5.2(d) of the City of Vancouver Electrical By-law. Further disciplinary action may also be taken in accordance with the Electrical Safety Regulation.

Yours truly,

Imenolt

A. Z. Tsisserev, P.Eng. City Electrician

AZT/sa



December 4, 2001

PLEASE REFER TO Sheri Amendt, Clerk Typist 11 Inspection Support Services Sheri_amendt@city.vancouver.bc.ca at 873-7601

Control Solutions Ltd 226-17 Fawcett Road Coquitlam, B.C., V3K 6V2

RE: EL458047 1200 West 73rd Avenue

As the holder of the above-noted Electrical Permit, please be advised that we have no record of your request for inspection within the last 180 day period.

The BC Electrical Safety Regulation (BC Reg. 487/95) Section 30(4) states:

- 4. The registered representative of a registered electrical contractor holding a regular permit must submit a request for inspection at least once in every 180 day period, by delivering a declaration form to the regulatory authority having jurisdiction, that:
 - a. certifies that the registered representative has physically inspected the electrical installation;
 - b. states that the electrical installation is safe; and
 - c. reports of the present status of the electrical installation.

Therefore, you are ordered to provide access for the Electrical Inspector and also provide the required declaration by December 18th, 2001. Our fax number is 871-6367.

Failure to comply with this order may result in the cancellation of your permit privileges in the City of Vancouver in accordance with Section 5.2(d) of the City of Vancouver Electrical By-law. Further disciplinary action may also be taken in accordance with the Electrical Safety Regulation.

Yours tru , Armenolt

A. Z. Tsisserev, P.Eng.

AZT/sa

EL : 004-0/ 3-7595 FAX : 604-87	3-7100	CITY OF V	ANCOUVE	:R 🔃	初
JUNE 02, 2004	PERMIT TYPE	TRE PREVENTIO	N DIVISION PER	МІТ	P FI 402579
EGAL DESCRIPTION LOT C BLK A DL DDITIONAL ADDRESS INFORMATION		PLAN PLAN 15365	(CONT'D)	ADDRESS 1200 W 73RI SPECIFICS	DAV
PPLICATION DATE IPU	URPOSE PROJECT	ALUE	UE PLANS METRIC	PLACE NAME	
JUN 02, 2004 R			NO		
EMPORARY PERMIT DATES		TEMPORARY USE DATES		SUBTYPE	
				144-835-06	5-0000
ONTRACTOR CONTRACTOR COTTON BROS BOE 7502 CHUTTER ST	TREET	TOUCHSTONE PROP MANAGEMENT SERV #107-4585 CANAL	VICES DA WAY	CONTACT 3	
BURNABY		Value average service ranker and	BC V5G 4L6	TEL	BUS.LICENSE CERTIFICATE
	RTIFICATE	FAX CEP	RIFICATE	FAX	CERTIFICATE
D25 If the work cannot Building By-law f D30 Por removal: the liquids removed. permanently scale D40 Tank removal must D45 Written verificat D50 Phone the Distric	ot be completed in th for Protection of the tanks, together with The tanks and pipin ad by capping or plug t comply with subsect tion from contractor ct Fire Inspector at	tamination site, clearant a same day, the owner mm Public and Fire Safety connected piping and di g must be removed from t ging. Ion 4.10.3 of the Vancou to District Fire Inspect 504-873-7595 for an Insp 2. If the inspector is	ust follow the requires on leading off constr- lepensing equipment, of the ground and purged of uver Fire By-law. tor for work complete. pection prior to backf	ments of Section intion sites. Wall have all con- if vapours. The illing. Please a	8.2 of the Vancouver mbustible or flammable pipe ends must be arrange for the
that the site is	not contaminated.	ON AREA (BF) OCC	GENERAL USE	SPECIFICS/LO	
E30 GENERAL OFFICE	SPECIFICS/REFERE		ITEM	SPECIFICS/R	EFERENCE QTY/AMT
2010 OIL TANK		1 GU			
CORRECT, AND DESCRIBE THAT RESPONSIBILITY F INDEMNIFY AND SAVE HA AND EXPENSES OF EVERY	ES A USE, A BUILDING O FOR BY-LAW COMPLIANCE ARMLESS THE CITY OF VA F KIND, IN RESPECT OF	THAT THE INFORMATION C R A WORK WHICH COMPLIES RESTS WITH THE OWNER AN NCOUVER, ITS OFFICIALS, ANYTHING DONE OR NOT DO R THE FAILURE TO OBSERV	WITH ALL RELEVANT BY- D THE OWNER'S EMPLOYEE EMPLOYEES AND AGENTS NNE PURSUANT TO THIS AF	LAWS AND STATUTE S. AGENTS AND CO AGAINST ALL CLAI PLICATION OR FAC	IS. I ACKNOWLEDGE INTRACTORS. I WILL MS. LIABILITIES
CORRECT, AND DESCRIBE THAT RESPONSIBILITY F INDEMNIFY AND SAVE HA NND EXPENSES OF EVERY ENSUING PERMIT, INCLU-	25 A USE, A BUILDING O FOR BY-LAW COMPLIANCE REALESS THE CITY OF VI KIND, IN RESPECT OF IDING NEGLIGENCE AND/O AMOUNT FEE	R A WORK WHICH COMPLIES RESTS WITH THE OWNER AN NCOUVER, ITS OFFICIALS, ANYTHING DONE OR NOT DO	I WITH ALL RELEVANT BY- ID THE OWNER'S EMPLOYEE EMPLOYEES AND AGENTS INE PURSUANT TO THIS AR TE ALL BY-LAWS, ACTS OF AMOUNT SIGNATURE	LAWS AND STATUTE S. AGENTS AND CO AGAINST ALL CLAI PLICATION OR FAC	IS. I ACKNOWLEDGE INTRACTORS. I WILL MS. LIABILITIES
CORRECT, AND DESCRIBE HAT RESPONSIBILITY F INDEMNIFY AND SAVE HA IND EXPENSES OF EVERY INSUING PERMIT, INCLU	25 A USE, A BUILDING O FOR BY-LAW COMPLIANCE REALESS THE CITY OF VI KIND, IN RESPECT OF IDING NEGLIGENCE AND/O AMOUNT FEE	R A WORK WHICH COMPLIES RESTS WITH THE OWNER AN NCOUVER, ITS OFFICIALS, ANYTHING DONE OR NOT DO	INITH ALL RELEVANT BY- ID THE OWNER'S EMPLOYEE EMPLOYEES AND AGENTS INE PURSUANT TO THIS AF 'S ALL BY-LAWS, ACTS OF AMOUNT SIGNATURE DATE	LAWS AND STATUTE S. AGENTS AND CO AGAINST ALL CLAI PLICATION OR FAC RECULATIONS.	IS. I ACKNOWLEDGE INTRACTORS. I WILL INS. LIABILITIES IT SHEET OR

P\$0200.01



Date: AUG 3 1 2004

VIA FAX ONLY (604) 682-3497

Pottinger Gaherty Environmental Consultants Ltd. 1200 - 1185 West Georgia Street Vancouver, BC V6E 4E6

Attention: Graeme Wilson, B.Sc., GIT

Dear Sir:

ECE CITY OF VANCOUVER AUU 3 1 2004 COMMUNITY SERVICE GROUP



THE SHURE

ENVIRONMENTAL PROTECTION BRANCH

Regional File: 26250-20/9102 Victoria File: 26250-20/ NA SITE number: 9102

LICENCES AND INSPECTIONS ENVIRONMENTAL PROTECTION BRANCH

CHECKED ... SEPT 1 2004 APPROVED 12 RO; 1200 VN 73RD AVE FI 402579

Notice of Commencement/Completion of Independent Remediation Re: 1200 West 73rd Avenuc, Vancouver, BC, V6P 6G5 PID: 007-676-352

This letter is to acknowledge receipt of written notice of commencement and completion of independent remediation at the above-referenced site pursuant to section 54(2)(a) of the Environmental Management Act. This letter is for information purposes only and should not be construed as acceptance or approval of independent remediation, discharges associated with remediation, or any remediation methods or practices.

This site has been assigned the provincial SITE identification number shown above and we request that you reference this number in future submissions regarding this site.

Please be advised that any reports or other documentation submitted with your notice of commencement or completion of independent remediation are not reviewed by the ministry. It remains your responsibility to meet the requirements of the Environmental Management Act and regulations (e.g. Contaminated Sites Regulation, Hazardous Waste Regulation, etc.) and to identify and address any human health or environmental impacts, safety issues or impacts on utilities associated with the contamination.

Please note that a soil relocation agreement may be required if contaminated soil from this site is relocated to a receiving site. We refer you to section 55 of the Environmental Management Act and sections 40 through 46 of the Contaminated Sites Regulation which specify requirements with respect to relocation of contaminated soil.

Ministry of Water, Land and Air Protection

Environmental Protection Division Environmental Management Branch Contaminated Sites Program

Mailing/Location Address: 10470 152 Street SURREY BC V3R 0Y3

Telephone: (604) 582-5200 Facsimile: (604) 584-9751 http://www.gov.bc.ca/ http://www.gov.bc.ca/wisp/

-2-

Site ID: 9102

In the event that you determine that one or more substances has migrated, or is likely to have migrated, to a neighbouring property(ies) and is, or likely is, causing contamination of the neighbouring property(ics), you are required to provide written notification to the person or persons who own the neighbouring property(ies) and send a copy to the manager as further explained in sections 57(1) and 60.1 of the Contaminated Sites Regulation. It is your responsibility to also advise any other affected persons (e.g. owners of rights-of-way, utility corridors, easements, etc.).

Should you anticipate a future requirement or desire for an *Environmental Management Act* instrument (c.g. certificate of compliance, approval in principle, etc.) at this site, we recommend that you review all aspects of the government's contaminated sites legislation and supporting guideline documents and protocols to ensure that all required information is collected and documented during the remediation project. Information regarding ministry requirements may be accessed at:

"http://wlapwww.gov.bc.ca/epd/epdpa/contam_sites/index.html".

If you have any questions about this letter, please contact the undersigned at 604-582-5332.

Sincerely,

Ashley Smith Contaminated Sites Technician

CC:

Touchstone Property Management Ltd., 107 - 4585 Canada Way, Burnaby, BC, Fax: 604-662-3631

ASQ Building Ltd., Suite 309C - 896 Cambie Street, Vancouver, BC, V6B 2P6 Hank Uyeyama, City of Vancouver, Fax: 604-873-7963

NAMES OF A DOMESTIC OF A DOMESTIC	173-7100 HE	CITY OF			
JUNE 02, 2004	PERMIT TYPE	FIRE PREVENT			FI 402579
		X PLAN PLAN 1536	5 (CONT'D)	1200 W 73RD AV	
ADDITIONAL ADDRESS INFORMATIC		JECT VALUE ASSESS		SPECIFICS	
JUN 02, 2004	Transfer to the second second		NO	PLACE NAME	
EMPORARY PERMIT DATES		TEMPORARY USE DATES		SUBTYPE	
				0-0RDINATE 144-835-06-000	0
PPUCANT CONTRACTOR COTTON BROS BO 7502 CHUTTER S BURNABY	CONTRACT CONTRACT A CONTRACT	CONTACT2 PROPERTY OWN TOUCHSTONE P MANAGEMENT S #107-4585 CA BURNABY	ROPERTY ERVICES	CONTACT 3	
TEL 604-435-2020 BL	USLICENSE 328393	TEL 604-261-8414 FAX	BUS.LICENSE 1	12.55	LICENSE
010 For fuel dispens 025 If the work cann Building By-law 030 For removel, the liquids removed, permanently seal 040 Tank removal mus 045 Written verifica 050 Phone the Distri innpecion at lea that the site is	HIS PERMIT IS AUTH ing site or known iot be completed in for Protection of tanks, together w The tanks and pi ed by capping or p to comply with subs tion from contract of Fire Inspector at 24 hours in adv a not contaminated.	i the same day, the owne the Public and Fire Saf fith connected piping an ping must be removed fr blugging. Jection 4.10.3 of the Va or to District Fire Ins at 604-873-7595 for an ance. It the inspector	earance from Environmental P or must follow the requireme- rety on fencing off construc- ul dispensing equipment, sha own the ground and purged of incouver Fire By-law. spector for work complete, inspection prior to backfil is not available, photograp	nts of Section 8.2 of tion sites. Il have all combustif vapours. The pipe e ling. Please arrange phs should be taken t	ele or flammable ends must be
GENERAL USE E30 GENERAL OFFICE	SPECIFICS/LOC				and the second second second second
			D ITEM	SPECIFICS/LOCATION SPECIFICS/REFERENCE	
ITEM 2010 OIL TANK APPROVALS REQUIRED B	SPECIFICS/REF	TERENCE QTY/AMT 1 MPLETED INCLUDE :	D GU FIRE INSPECTION	SPECIFICS/REFERENC	
ITEM 2010 OIL TANK APPROVALS REQUIRED B PROCESSED BY: APPLIC	SPECIFICS/REF	TERENCE QTY/AMT 1 MPLETED INCLUDE : .EUNG. PE	D GU ITEM	SPECIFICS/REFERENC	
ITEM 2010 OIL TANK APPROVALS REQUIRED B PROCESSED BY: APPLIC	SPECIFICS/REF	TERENCE QTY/AMT 1 MPLETED INCLUDE : .EUNG. PE	D GU FIRE INSPECTION	SPECIFICS/REFERENC	TE QTY/AMT
ITEM 2010 OIL TANK APPROVALS REQUIRED B PROCESSED BY: APPLIC PERMIT	SPECIFICS/REF	TERENCE QTY/AMT 1 MPLETED INCLUDE : EUNG. PE 5.	D GU FIRE INSPECTION RMIT AUTHORIZED BY R CRITCH	SPECIFICS/REFERENC	TE QTY/AMT

PSD204.01



August 4, 2004 File: 1231-02.01

Via Fax: 604-688-4349 (Original by Mail)

COPY

Touchstone Property Management Ltd. 107 - 4585 Canada Way Burnaby, BC V5G 4L6 Pottinger Gaherty Environmental Consultants Ltd. 1200–1185 West Georgia Scree Vancouver BC V6E 4E6 Tel 604.682 3707 Fax 604.682 3497

Attention: Ching-Lei Lee

RE: REMEDIAL EXCAVATION OF FORMER UNDERGROUND STORAGE TANK BASIN, 1200 WEST 73RD AVENUE, VANCOUVER, BC

Pottinger Gaherty Environmental Consultants Ltd. (PGL) is pleased to provide this report regarding the remedial excavation of a former heating oil underground storage tank (UST) at the above-mentioned site.

This report has been prepared exclusively for the use of Touchstone Property Management Ltd. (Touchstone). It is not suitable for submission to the BC Ministry of Water, Land and Air Protection (MWLAP). A report suitable for MWLAP submission requires additional documentation that adds considerable reporting cost. For due diligence purposes, a report suitable for MWLAP submission is not required; however, if such documentation is required in the future, we can augment this report.

BACKGROUND

The subject site is occupied by an office building at 1200 West 73rd Avenue, Vancouver, BC. The UST was identified on the northeast side of the building and formerly serviced the building with heating fuel. During decommissioning of the tank, a representative from the Vancouver Fire Department inspected the site and suspected (based on their visual observations) that soil contamination may be present. The property manager contacted PGL to oversee remediation of the soil surrounding the UST.

SCOPE OF WORK

On June 2, 2004, Touchstone retained PGL to provide environmental consulting services for the tank-decommissioning project. PGL's responsibilities included directing the remedial excavation, collecting confirmatory soil samples for analysis, submission of a Notification of Independent Remediation and summarizing the work in a report.

Cotton Brothers Contracting Ltd. (Cotton Brothers) acted as the project contractor. Their responsibilities included excavating and removing the UST, preparing the UST for offsite

disposal, excavating and transporting the contaminated soil, assisting with soil sample collection, and backfilling the excavation.

SITE WORK AND FINDINGS

The tank removal occurred on June 2, 2004. Cotton Brothers excavated and removed the tank and all associated piping from the site. PGL was not onsite during the decommissioning of the UST and did not inspect the tank.

PGL inspected the tank hold on the afternoon of June 2, 2004. Five soil samples were collected from the excavation base and four sidewalls. One soil sample was collected from the clean soil (based on visual observations and odour) excavated from above the tank. Soil samples were placed in an ice-packed cooler and were submitted to CanTest Ltd. in Burnaby, BC, for analysis of extractable petroleum hydrocarbons (EPH), the contaminants associated with heating oil.

The initial East Wall Sample (CS-1), West Wall Sample (CS-2), and North Wall Sample (CS-4) exceeded the Contaminated Sites Regulation (CSR) Commercial Level (CL) standard for EPH. This indicated that excavation of contaminated soil was required from the east wall, the west wall (adjacent to the building), and the north wall of the tank hold.

On June 23, 2004, 24.72 tonnes of contaminated soil was excavated from the tank hold. Excavation continued until visual observations and odour indicated that excavation was complete. Confirmatory samples were collected from the new east, west, and north excavation walls and submitted to Cantest for EPH analysis.

The remedial excavation measured 5.0m long by 4.5m wide by 3.3m deep. Tank basin soils consisted of loose brown sand, underlain by light grey, stiff, silty clay. No groundwater was observed in the excavation. At the completion of the project, the excavation was backfilled with the clean soil excavated from above the tank and imported sand fill.

The contaminated soil was loaded into trucks and transferred to the licensed bioremediation facility operated by Sumas Remediation Services Ltd.

A Notification of Independent Remediation (NIR) was filed with the Ministry of Water, Land and Air protection as per the requirements of Section 57 of the CSR.

CONFIRMATORY RESULTS

All final confirmatory soil samples tested below the CSR CL standards applicable to the site. Laboratory analytical results are attached.

CONCLUSIONS

PGL concludes that the remaining soils surrounding the former UST meet CSR CL standards for extractable petroleum hydrocarbons. No further work is required.

2

STANDARD LIMITATIONS

PGL prepared this report for Touchstone Property Management Ltd. exclusively. PGL accepts no responsibility for any damages that may be suffered by third parties as a result of decisions or actions based on this report. The purpose of this report is to provide our client with a summary of the removal of the UST and an assessment of the potential for environmental contamination on the subject property due to the tank. This report is neither an endorsement nor a condemnation of the subject property.

The findings and conclusions are site-specific and were developed in a manner consistent with that level of care and skill normally exercised by environmental professionals currently practicing under similar conditions in the area. PGL accepts no responsibility for any damages that may be suffered by third parties as a result of decisions or actions based on this report.

The project has been conducted using the terms of reference and conditions set forth in our work program. No warranty, express or implied, is made.

The investigation consisted of a screening for potential contamination and, as is true for all environmental investigations, potential remains for the presence of unknown, unidentified, or unforeseen surface or subsurface contamination. More or different investigation may be required if other risks are identified. The data presented in this report is valid for the date of sampling, but site conditions may change with time, as may regulatory requirements/policy. Conclusions and costs are time sensitive, and so this report is designed for present use. The report should not be used after this time without PGL review/approval.

We trust that this meets your needs. If you have any questions, or require clarification, please contact Graeme Wilson or Duncan Macdonald at 604-895-7642 and 604-895-7639, respectively.

POTTINGER GAHERTY ENVIRONMENTAL CONSULTANTS LTD.

Per:

Graeme S. Wilson, B.Sc., GIT Project Staff

GW/AND/sjk P:\1200-1399\1231\r-1231-02-01 UST remed.doc

A. Nick Dayal, A.Sc.T. Senior Consultant

Attachments: Laboratory Reports, Notice of Independent Remediation, Notice of Completion of Independent Remediation

cc: Lieutenant John Poole, Fire and Rescue Service, City of Vancouver 201 – 456 West Broadway Vancouver, BC, V5Y 1R3

3

August 4, 2004 File: 1231-02.01



Pottinger Gaherty

BC Ministry of Water, Land and Air Protection 10470 - 152nd Street Surrey, BC V3R 0Y3

Attention: Ashley Smith Contaminated Sites Technician

RE: NOTICE OF COMPLETION OF INDEPENDENT REMEDIATION -1200 WEST 73RD AVENUE, VANCOUVER, BC

Pottinger Gaherty Environmental Consultants Ltd. (PGL) is providing this notice of completion of independent remediation, on behalf of Touchstone Property Management Ltd., for the subject site. Remediation was completed in July 2004, as requested in PGL's notice of independent remediation of June 17, 2004.

Civic Address:	1200 West 73rd Avenue, Vancouver, BC
Legal description:	LotC BlockA DL318 319 PLN 15365
Owner's name & address:	Touchstone Property Management Ltd. 107-4585 Canada Way Burnaby, BC V5G 4L6
Consultant:	Pottinger Gaherty Environmental Consultants Ltd. 1200 – 1185 West Georgia Street Vancouver, BC V6E 4E6 Graeme Wilson @ 604-895-7642

The site is situated in a commercial neighborhood in Vancouver, BC. One heating oil underground storage tank (UST) was excavated from the northeast corner of the building. Concentrations of extractable petroleum hydrocarbons (EPH) in soil, excavated during UST removal, exceeded the CSR Commercial Land (CL) use standards.

Approximately 25 tonnes of contaminated soil was removed from the site by Cotton Brothers Excavating Ltd. and delivered to the Surnas Remediation treatment facility at 4623 Byrne Road, Burnaby, BC.

Results of confirmatory sampling of the residual soil in the excavation meet CSR CL standards for EPH.

Environmental Consultants Lid. 1200–1185 West Georgia Stree Vancouver BC V6E 4E6 Tel 604.682 3707

Fax 604.682 3497

We trust that this meets your needs. If you have any questions or require clarification, please contact Graeme Wilson or Duncan Macdonald at 604-895-7642 or 604-895-7639, respectively.

POTTINGER GAHERTY ENVIRONMENTAL CONSULTANTS LTD.

Per:

Graeme S. Wilson, B.Sc., GIT Project Staff

A. Nick Dayal, A.Sc.T. Senior Consultant

GW/AND/sjk P:\1200-1399\1231\l-1231-02-01 Notice of Completion.doc

Analysis Report

REPORT ON:	Analysis of Soil Samples
REPORTED TO:	Pottinger Gaherty Ltd. Environmental Consultants Suite 1200 1185 West Georgia Street Vancouver, B.C. V6E 4E6

Att'n: Graeme Wilson

CHAIN OF CUSTODY: PROJECT NAME: PROJECT NUMBER: P.O. NUMBER: 152590 Touchstone 1231-02.01 1231-02.01

NUMBER OF SAMPLES: 6

DATE SUBMITTED: June 3, 2004

REPORT DATE: June 10, 2004

ANTEST

GROUP NUMBER: 50603067

SAMPLE TYPE: Soil

NOTE: Results contained in this report refer only to the testing of samples submitted.

TEST METHODS:

Moisture in Soil - analysis was performed gravimetrically by heating a separate sample portion at 105 C and measuring the weight loss.

Extractable Petroleum Hydrocarbons and Light and Heavy Extractable Petroleum Hydrocarbons in Soil -

analysis was performed using B.C. MOELP CSR-Analytical Method 3 "Extractable Petroleum Hydrocarbons in Solids by GC/FID" and CSR-Analytical Method 6 "Calculation of Light and Heavy Extractable Petroleum Hydrocarbons in Solids or Water (LEPH & HEPH)". The method involves acetone/hexane extraction and GC/FID analysis. EPH components ranging from C10 to C19 and C19 to C32 are quantified against elcosane (n-C20). LEPH & HEPH are calculated by subtraction of specified PAH's.

TEST RESULTS:

(See following pages)

CANTEST LTD. Zhenyong Gao, SC. Coordinator, Trace Organics

Page 1 of 5

CANTEST LTD.

Professional Analytical Services

4606 Canada Way Burnaby, B.C. V5G 1K5

Fax: 604 731 2386

Tel: 604 734 7276

1 800 665 8566

REPORTED TO: Pottinger Gaherty Ltd.



REPORT DATE: June 10, 2004

GROUP NUMBER: 50603067

. 1

Conventional Parameters in Soil

CLIENT SAMPLE IDENTIFICATION:	SAMPLE DATE	CANTEST ID	Moisture
CS-1(East 2.5m)	Jun 2/04	406030286	9.8
CS-2(West 2.5m)	Jun 2/04	406030288	8.2
CS-3(South 2.5m)	Jun 2/04	406030289	8.1
CS-4(North 2.5m)	Jun 2/04	406030290	5.7
CS-5(Base 3.0m)	Jun 2/04	406030291	12.1
SP-1(Comp)	Jun 2/04	406030292	9.9
DETECTION LIMIT			0.1

% = percent

REPORTED TO: Pottinger Gaherty Ltd.



REPORT DATE: June 10, 2004

GROUP NUMBER: 50603067

Extractable Petroleum Hydrocarbons in Soil

SAMPLE DATE	CANTEST ID	EPHs10-19	EPHs19-32
Jun 2/04	406030286	20000	5200
Jun 2/04	406030288	15000	5900
Jun 2/04	406030289	<	<
Jun 2/04	406030290	3800	1700
Jun 2/04	406030291	1400	470
Jun 2/04	406030292	<	<
an a		250	250 µg/g
	DATE Jun 2/04 Jun 2/04 Jun 2/04 Jun 2/04 Jun 2/04	DATE ID Jun 2/04 406030286 Jun 2/04 406030288 Jun 2/04 406030289 Jun 2/04 406030290 Jun 2/04 406030291	DATE ID Jun 2/04 406030286 20000 Jun 2/04 406030288 15000 Jun 2/04 406030289 <

 μ g/g = micrograms per gram, on a dry weight basis. < = Less than detection limit

REPORTED TO: Pottinger Gaherty Ltd.



REPORT DATE: June 10, 2004

GROUP NUMBER: 50603067

Batch Quality Control for Extractable Petroleum Hydrocarbons in Soil (QC# 53027)

Parameter	Blank (ug/g)	Blank Limits	Duplicate (R.P.D.) 406030288	Duplicate Limits
EPHs10-19	< 250	250	6.9	20
EPHs19-32	< 250	250	5.2	20

ug/g = micrograms per gram R.P.D. = Relative Percent Difference

REPORTED TO: Pottinger Gaherty Ltd.



REPORT DATE: June 10, 2004

GROUP NUMBER: 50603067

Batch Quality Control Frequency Summary

EPH (LEPH/HEPH)- Soil Prep (Batch# 53027)

QC Type	No. Samples
Blank	1
Cert Ref Material RTC CRM355	1
Duplicate	1
Method Performance Check Spike	1
Batch Size	17

CHAIN OF C	1.2016 (B. C. S.	Canada Way	Korimini	Cha	TUNE	nu.	Con	5.1	DD					U	6E	4EE	>	Pag	get_	of	_
CANE	ST Bu V5	maby, B.C. G 1K5	Street Address (inc 1200 - 1 Telephone:	luding suite	ID. C	EN	26-14	5	Τ.				utnew ven					RE	RESUL	TS BY:*	-
152590	Tel Fa: Tol	x: 604.731.2386 I Free: 800.665.8566 w.cantest.com	604.687 Contact Name:"	3907	604.	682 Projec	- 34		Mail Add	Name:		ALC: NO.	P.O. Number				(Surcharges May A				
Special Instructions:	AutoFax	AutoEmail	Project Name:	stan	5	12	31-	02.0	21	1 1		r r		17	230	-02.0	1	lourch	larges w	nay Ap	(piy)
Return Cooler Applicable Regulatory Gu BC-CSR Drinking Water	Later Constant of	ners (please specify) ne specify)			sis - Level	s - Level	th	(total / spec.)		Coliform - Total Fecal E.coli F CI SO, NO,	d Nitrita	ase (Total/HC)	PCP (Tri, Tetra and Penta) PCP (Mono and Di)	I		LEPH/HEPH (PAH corrected)			-DO NOT ANALYZE	Number of Containers	Yes No
50603067		Sample ntification*	Date Sampled (D/M/Y)	Sample Type (Matrix)		Soil Metals pH	Conductivity TSS	TDS Alkalinity	BOD COD	Coliform -	Nitrite Nitrate and Nitrite	Oil & Grease	PCP (Tri, PCP (Mo	BETX/VPH	PAH	LEPH/HEF			HOLD - D	Number o	No. useholds?
406030206	CS-1	(EAST25m)	02/06/04	Sou												X					Ves tote ho
NUMBER OF THE OWNER		(WEST 2.5m		1												X					ente mitt
		(SNTH 2.5m														X					
290	CS-4	(NOPIHZ.SM	S /													X					
291	CS-5	(BK56 3.0m	\$													X					le? Nut
392 ⁴	57-1	(ComP)	V	Y												X					rinking Water Sample?
																	_				rinking W
Relinquished by:			Date	Time	Recei	ved by:	KB	to	3	<u> </u>		1	-1	4	Rec	uired Fie	To	tal Number	of Contai	ners:	1
Relinquished by:			Date	Time	Recei	ved by:	NIN	1	/		*										6
Method of Shipment:	-	Waybill No.:		1	Received for La	ab by:	KR	2 3	INF :	3/04	Time	13	0			be paid dire	ctly by our	client;			_
Shipped by:		Shipment Condition:		1	Cooler opened	by:	i des chi	Dat	te		Time			Addr		Name:					_
FOR LABORATORY USE Sample State at Receipt:	ONLY	Cold Frozan	N/A C	comments:		-			E.S.		市市市		555	Cont		-	-	Postal Co	ode:		
2	10	10	eal Intact? Yes	-	n/s	Numb	er ol Cox	olers/SI	hipping	Contain	. :The	<u>.</u>	· ·	Pho	ne:			Fax			

			Analy Şervi
ROMATOGR	MI COVER S	liser	4600 Burr V50
			Fax
Date:	June 10, 200	Υ.	18
Company:	PGL		
Contact:	S. Wilson		
Fax Number:	682-3497	:	
No. Of Pages:	7.	•	
PLEASE FIND THE AT WITH:	TACHED CHROMATOO	BRAMS ASSOCIA	TED
CANTEST Group #	. 506030	067	•
Your Project Name			:
Your Project #	1231-02.01		
Sample Matrix	Soul		· ~ .

If you have any questions or concerns, please do not hesitate to contact one of our Technical Serve Representatives at (604) 734-7276.

14


 $\bar{\tau}_{2}$

Data File D:\HPCHEM\1\DATA\040607B\010F7701.D

: 6/9/04 11:58:22 AM	Seq	. Line	:	77	
: 406030286	1.11.2110	Vial	:	10	È.
; pcn		Inj	:	1	ŝ.
	Inj	Volume	:	2 µ	1
: D:\HPCHEM\1\METHODS\1EPH.M	5.A.C			1	
: 11/27/03 3:07:37 PM by AZL					
: D:\HPCHEM\1\METHODS\!EPH_AP.M					
(modified after loading)					
	: 6/9/04 11:58:22 AM : 406030286 : pcn : D:\HPCHEM\1\METHODS\!EPH.M : 11/27/03 3:07:37 PM by AZL : D:\HPCHEM\1\METHODS\!EPH_AP.M : 6/10/04 7:50:32 AM by pcn (modified after loading)	: 406030286 : pcn Inj : D:\HPCHEM\1\METHODS\1EPH.M : 11/27/03 3:07:37 PM by AZL : D:\HPCHEM\1\METHODS\1EPH_AP.M : 6/10/04 7:50:32 AM by pcn	: 406030286 Vial : pcn Inj Inj Volume : D:\HPCHEM\1\METHODS\1EPH.M : 11/27/03 3:07:37 PM by AZL : D:\HPCHEM\1\METHODS\1EPH_AP.M : 6/10/04 7:50:32 AM by pcn	: 406030286 Vial : : pcn Inj : Inj Volume : : D:\HPCHEM\1\METHODS\1EPH.M : 11/27/03 3:07:37 PM by AZL : D:\HPCHEM\1\METHODS\1EPH_AP.M : 6/10/04 7:50:32 AM by pcn	: 406030286 Vial : 10 : pcn Inj : 1 : D:\HPCHEM\1\METHODS\1EPH.M : 11/27/03 3:07:37 PM by AZL : D:\HPCHEM\1\METHODS\!EPH_AP.M

PGL 50603067

Total Extractable Hydrocarbons. Soils and Waters are extracted using methylene chloride and then analyzed using an HPGC-FID. Calculations are based on an internal standard and reported in ug/L for waters and ug/g for soils.




EPH FID-A 6/10/04 7:50:34 AM pcn

Data File D:\HPCHEM\1\DATA\0406078\009F7501.D

Injection Date	:	6/9/04 11:03:44 AM	See	q.	Line	:	1	75	
Sample Name	:	406030288			vial	:		9	
Acq. Operator	:	pcn			Inj	:		1	
			Inj	Vo	lume	:	2	μT	
Acq. Method	:	D:\HPCHEM\1\METHODS\!EPH.M						2	
Last changed	:	11/27/03 3:07:37 PM by AZL							
Analysis Method	:	D:\HPCHEM\1\METHODS\!EPH_AP.M							
Last changed		6/10/04 7:50:32 AM by pcn							
CANCER SERVICE STR		(modified after loading)							

Total Extractable Hydrocarbons. Soils and Waters are extracted using methylene chloride and then analyzed using an HPGC-FID. Calculations are based on an internal standard and reported in ug/L for waters and ug/g for soils.




EPH FID-A 6/10/04 7:50:57 AM pcn



: 6/9/04 5:47:20 AM	Sec	. Line	:	66	
: 406030289		Vial	:	98	1
; pcn		Inj	:	1	Ř.,
	Inj	volume	:	2 4	1
: D:\HPCHEM\1\METHODS\!EPH.M					
: 6/9/04 3:10:31 AM by pcn					
: D:\HPCHEM\1\METHODS\!EPH_AP.M					
(modified after loading)					
the second of the second	: 6/9/04 3:10:31 AM by pcn : D:\HPCHEM\1\METHODS\!EPH_AP.M : 6/10/04 7:50:32 AM by pcn	: 406030289 : pcn Inj : D:\HPCHEM\1\METHODS\!EPH.M : 6/9/04 3:10:31 AM by pcn : D:\HPCHEM\1\METHODS\!EPH_AP.M : 6/10/04 7:50:32 AM by pcn	: 406030289 vial : pcn Inj Volume : D:\HPCHEM\1\METHODS\!EPH.M : 6/9/04 3:10:31 AM by pcn : D:\HPCHEM\1\METHODS\!EPH_AP.M : 6/10/04 7:50:32 AM by pcn	: 406030289 vial : : pcn Inj : Inj Volume : : D:\HPCHEM\1\METHODS\!EPH.M : 6/9/04 3:10:31 AM by pcn : D:\HPCHEM\1\METHODS\!EPH_AP.M : 6/10/04 7:50:32 AM by pcn	: 406030289 Vial : 98 : pcn Inj : 1 Inj Volume : 2 p : D:\HPCHEM\1\METHODS\!EPH.M : 6/9/04 3:10:31 AM by pcn : D:\HPCHEM\1\METHODS\!EPH_AP.M : 6/10/04 7:50:32 AM by pcn

Total Extractable Hydrocarbons. Soils and Waters are extracted using methylene chloride and then analyzed using an HPGC-FID. Calculations are based on an internal standard and reported in ug/L for waters and ug/g for soils.



EPH FID-A 6/10/04 7:51:28 AM pcn


Page 1 of 2

Sample Name: 406030289

Data File D:\HPCHEM\1\DATA\0406078\006F7101.D

Injection Date	:	6/9/04 8:54:25 AM	Sec	q. Line	:		71
Sample Name		406030290		vial	:		6
Acq. Operator	:	pcn		Inj	:		1
ana in Salari anter			Inj	volume	:	2	μT
Acq. Method	:	D:\HPCHEM\1\METHODS\!EPH.M	100				
Last changed	:	6/9/04 3:10:31 AM by pcn					
Analysis Method	:	D:\HPCHEM\1\METHODS\IEPH_AP.M					
Last changed		6/10/04 7:50:32 AM by pcn					


(modified after loading) Total Extractable Hydrocarbons. Soils and Waters are extracted using methylene chloride and then analyzed using an HPGC-FID. Calculations are based on an internal standard and reported in ug/L for waters and ug/g for soils.



Data File D:\HPCHEM\1\DATA\040607B\004F6801.D

: 6/9/04 7:02:15 AM	Seq	. Line	:	6	8
		Vial	:		4
; pcn		Inj	:		1
	Inj	Volume	:	2	μÌ
: D:\HPCHEM\1\METHODS\!EPH.M					·
: 6/9/04 3:10:31 AM by pcn					
: D:\HPCHEM\1\METHODS\1EPH_AP.M					
(modified after loading)					
	: 6/9/04 7:02:15 AM : 406030291 : pcn : D:\HPCHEM\1\METHODS\!EPH.M : 6/9/04 3:10:31 AM by pcn : D:\HPCHEM\1\METHODS\!EPH_AP.M : 6/10/04 7:50:32 AM by pcn (modified after loading)	: 406030291 : pcn Inj : D:\HPCHEM\1\METHODS\!EPH.M : 6/9/04 3:10:31 AM by pcn : D:\HPCHEM\1\METHODS\!EPH_AP.M : 6/10/04 7:50:32 AM by pcn	: 406030291 Vial : pcn Inj : D:\HPCHEM\1\METHODS\!EPH.M : 6/9/04 3:10:31 AM by pcn : D:\HPCHEM\1\METHODS\!EPH_AP.M : 6/10/04 7:50:32 AM by pcn	: 406030291 Vial : : pcn Inj : Inj Volume : : D:\HPCHEM\1\METHODS\!EPH.M : 6/9/04 3:10:31 AM by pcn : D:\HPCHEM\1\METHODS\!EPH_AP.M : 6/10/04 7:50:32 AM by pcn	: 406030291 Vial : : pcn Inj : Inj Volume : 2 : D:\HPCHEM\1\METHODS\!EPH.M : 6/9/04 3:10:31 AM by pcn : D:\HPCHEM\1\METHODS\!EPH_AP.M : 6/10/04 7:50:32 AM by pcn

Total Extractable Hydrocarbons. Soils and waters are extracted using methylene chloride and then analyzed using an HPGC-FID. Calculations are based on an internal standard and reported in ug/L for waters and ug/g for soils.



EPH FID-A 6/10/04 7:52:00 AM pcn


Page 1 of 2

Sample Name: 406030291

Data File D:\HPCHEM\1\DATA\040607B\007F7201.D

Injection Date	3	6/9/04 9:31:51 AM	Seq	. Line	:		72	
Sample Name	:	406030292	1960	vial			7	
Acq. Operator	:	pcn		Inj	:		1	
			Inj	volume	:	Z	μl	
Acq. Method	:	D:\HPCHEM\1\METHODS\IEPH.M					2	
Last changed	:	6/9/04 3:10:31 AM by pcn						
Analysis Method								
Last changed	:	6/10/04 7:50:32 AM by pcn						
Tante consta		(modified after loading)						

Total Extractable Hydrocarbons. Soils and Waters are extracted using methylene chloride and then analyzed using an HPGC-FID. Calculations are based on an internal standard and reported in ug/L for waters and ug/g for soils.



EPH FID-A 6/10/04 7:52:16 AM pcn

Analysis Report



CANTEST LTD.

Professional Analytical Services

4606 Canada Way Burnaby, B.C. V5G 1K5

Fax: 604 731 2386

Tel: 604 734 7276

1 800 665 8566

REPORT ON:

Analysis of Soil Samples

REPORTED TO:

Pottinger Gaherty Ltd. Environmental Consultants Suite 1200 1185 West Georgia Street Vancouver, B.C. V6E 4E6

Att'n: Mr. Graeme Wilson

CHAIN OF CUSTODY: PROJECT NAME: PROJECT NUMBER:

152570 Touchstone 1231-0201

NUMBER OF SAMPLES: 3

DATE SUBMITTED: June 25, 2004

REPORT DATE: July 5, 2004

GROUP NUMBER: 50625071

SAMPLE TYPE: Soll

NOTE: Results contained in this report refer only to the testing of samples submitted.

TEST METHODS:

Moisture in Soil - analysis was performed gravimetrically by heating a separate sample portion at 105 C and measuring the weight loss.

Extractable Petroleum Hydrocarbons and Light and Heavy Extractable Petroleum Hydrocarbons in Soil -

analysis was performed using B.C. MOELP CSR-Analytical Method 3 "Extractable Petroleum Hydrocarbons in Solids by GC/FID" and CSR-Analytical Method 6 "Calculation of Light and Heavy Extractable Petroleum Hydrocarbons in Solids or Water (LEPH & HEPH)". The method involves acetone/hexane extraction and GC/FID analysis. EPH components ranging from C10 to C19 and C19 to C32 are quantified against elcosane (n-C20). LEPH & HEPH are calculated by subtraction of specified PAH's.

TEST RESULTS:

(See following pages)

CANTEST LTD. Zhenyong Gao, M.Sc. Coordinator, Trace Organics

Page 1 of 5

REPORTED TO: Pottinger Gaherty Ltd.



REPORT DATE: July 5, 2004

GROUP NUMBER: 50625071

Conventional Parameters in Soil

CLIENT SAMPLE IDENTIFICATION:	SAMPLE DATE	CANTEST ID	Moisture
CS-6 West 2.8M	Jun 23/04	406250365	4.9
CS-7 East 2.8M	Jun 23/04	406250366	12.0
CS-8 North 3.0M	Jun 23/04	406250367	20.0
DETECTION LIMIT UNITS			0.1 %

% = percent

REPORTED TO: Pottinger Gaherty Ltd.



REPORT DATE: July 5, 2004

GROUP NUMBER: 50625071

Extractable Petroleum Hydrocarbons in Soil

CLIENT SAMPLE IDENTIFICATION:	SAMPLE DATE			EPHs19-32		
CS-6 West 2.8M	Jun 23/04	406250365	<	<		
CS-7 East 2.8M	Jun 23/04	406250366	<	<		
CS-8 North 3.0M	406250367	<	<			
DETECTION LIMIT	250	250				
UNITS		µg/g	µg/g			

 μ g/g = micrograms per gram, on a dry weight basis. < = Less than detection limit **REPORTED TO:** Pottinger Gaherty Ltd.



REPORT DATE: July 5, 2004

GROUP NUMBER: 50625071

Batch Quality Control for Extractable Petroleum Hydrocarbons in Soil (QC# 53808)

Parameter	Blank (ug/g)	Blank Limits	Duplicate (R.P.D.) 406250364	Duplicate Limits
EPHs10-19	< 250	250	NC	20
EPHs19-32	< 250	250	NC	20

ug/g = micrograms per gram R.P.D. = Relative Percent Difference

NC = Not Calculated. Duplicate sample results were less than the detection limit. Relative Percent Difference calculation is not defined for analyte levels of less than detection limit.

REPORTED TO: Pottinger Gaherty Ltd.



REPORT DATE: July 5, 2004


GROUP NUMBER: 50625071

Batch Quality Control Frequency Summary

EPH (LEPH/HEPH)- Soil Prep (Batch# 53808)

QC Туре	No. Samples
Blank	1
Cert Ref Material RTC CRM355	1
Duplicate	
Method Performance Check Spike	1
Batch Size	17

CHAIN OF	CUSTODY		Pornue	n Cu	1	- 15	2						c .		17		ostal					Pa	ge _	of	-
CAN	EST #	umaby, B.C.	Street Address (included)	uding suite ni	umber):*							C	GEA	City	r.	2.1	VO	5	4	66	٦ſ		-	ULTS	
-	Te	1 004 704 7070	elephone:*		Fax				E-Mail	Addr	ess (R	equir	ed fo	or "Ai	utoEr	nail*	Rep	orts)	6			THE			S
1525	Cond Diametric III 20	ax: 604.731.2386	504-682 Spintact Name:"	-370	7-60	4.6	12.3	197	SL	3.1.	su	e	P	55	2	P	ca	n							
1020	1912/250	ww.cantest.com	Spontact Name:	1, 21	<i>~</i>			1	sampli	er's N	ame:			~			1.					Day	Mo	onth	Year
			Project Name:	0.1	un		act Num			Quota	tion N	umbe	ar:	ν	15	P	0. N	umb	er		-	(Surc	harger	Mav	Apply)
Special Instructions	AutoFax	AutoEmail	autor	ME		12	31-	02	01					_								1			+P-11
Return Cooler	Ship Conta	iners (please specify)									1								()						9
Applicable Regulato	ry Guidelines:				evel	Level			6		E.coll		1011	Penta)				1	corrected)					ALYZ	No
BC-CSR	CCME				evel s - L	Level			eds /		Feca No.						4		H cor			. 1	1	T AN	Sec.
Drinking Water	Other (plea	ise specify) 6 -	40118				N.		(lotal / spec.)		- Total Fecal SO, NO,		Intrin Di	Tetra	no and	Ŧ		DAU	PH (PA					DO NO	Ē.
10/2020	Id	Sample Ientification*	Date Sampled	Sample Type (Matrix)	Total Metals Dissolved Me	Soil Metals	Conductivity	108	Alkalinity BOD	COD	Coliform	Nitrite	Nitrate and Nitrite	Oil & Grease (10tal PCP (Tri. Tetra and	PCP (Mono and Di)	BETX/VPH	VOC	PAH	LEPH/HEPH (PAH					HOLD · DO NOT ANALYZE Number of Containers	NQ: Politis ¹
5-0625071			(D/M/Y)		Põü	in .	ESF	F	2 9	Ö	ΟL	Z	Z (5 ă	ā	ā	3	a p	13					IZ	- Internet
406250365	CS-61	NEST 28M	23/06/04	Soil															X					1	Yes
		EAST 2.8M		1																				1	n yigh
AND ADDRESS OF A DREAM AND ADDREAM AND AND AND AND AND AND ADDREAM AND		NORTH 3.DM																	A					1	purvey us
And an a star of the star		BASE 3.3M																						X١	solu the sitter so
ADDED VISION	SP-Z C		1	V																				XI	Åre. Doe
and the second			V																						ple?
									1		T		1								-				Sam
TO ALL OF						1	11		-		+		1	1	1			1	1		1	-			inking Water Sample?
1. 1000							++		-		1	H	+	-	+			+	+		+				M Bu
						-	++		-		+	\mathbb{H}	+	+	-	$\left \right $		+	+		-	_		_	
														_	1										ã
Relinquished by: Relinquished by:			Date	Time /b	am	eived by					_	_				*	e = F	lequ	iired	Field	Total	Number	of Con	tainers:	5
Method of Shipment:		Waybill No.:	Date	1 made	ecsived for L		k	1 1	late	2	804	Time	ľ	30	-	Y	You w	ill be	e paid	directly by	our cl	lient: [
Shipped by: Kh	14 m	Shipment Condition:			oder opene		N)JA	54	101	Time		-	-	Co	mpa	ny N	ame:						
110	13		CONTRACTOR OF STREET	ATT OF ST	15 0.54		1.0	-	-	Retur		-		-	-	Ad	dress	K	-						
FOR LABORATORY Sample State at Race	to water the strength of the second second			mments:		1=0	SS/C		建金				ALL ALL		TANK AND	Co	ntacl	E.			1	Postal C	lode:		
	Temperature	O	and the second second]n/a	Num	ber of C	oblera	Ship	sing C	ontain	Ø rs :	and the	N-1	the life	Ph	one:					Fax:			





CITY OF VANCOUVER COMMUNITY SERVICES GROUP Licences and Inspections Coordinated By-law Enforcement

> PLEASE REFER TO: Mr. John lacobazzi District Property Use Inspector at 604.871.6628 I.R. No. UI 25842

March 23, 2005

ASQ Building Ltd. 760-1066 West Hastings Street Vancouver, BC V6E 3X2

Digre CD. 62221 EN #:

Dear Sirs:

RE: 1200 West 73rd Avenue

Following inspection, it was determined that an approximate $3.5' \times 5'$ illuminated facia sign reading "Royal LePage" "For Lease" "604-683-3111" has been erected on the southeast elevation of the building at the above location without permit in contravention of the Sign By-law.

To make application for the necessary Sign Permit, a licensed sign contractor must attend this office, sign the application form, submit a photograph of the sign's location, provide two (2) sets of architectural drawings which include a description of the copy or wording of the sign, two (2) sets of engineers structural drawings with a Schedule B-1 and Schedule B-2 may be required, a site plan, and pay the prescribed fees. For further clarification, please contact the Sign Permit Clerk at 604.873.7772 or 604.871.6714.

Your attention is also drawn to Section 13.2.2 of the Vancouver Sign By-law which states in part:

"where any sign has been erected before a permit has been issued for such sign, the fee in Section 13.1 (a), in addition to all other fees shall be \$300.00."

A separate permit may be required for electrical connection.

In accordance with the By-law and to avoid further action, you are to either make application for the required permit as outlined above or remove the illuminated facia sign, described above, within 30 days of the date of this letter.

Yours truly.

Mr. John lacobazzi District Property Use Inspector

JI/jm

Q:\Correspondence\Sign\Z005Archives\03 - March\1200w73(2).doc



1

CITY OF VANCOUVER COMMUNITY SERVICES GROUP Licences and Inspections Coordinated By-law Enforcement

REGISTERED

PLEASE REFER TO: M. Twynstra Manager Property Use Branch at 604.873.7563 I.R. No. UI 25842

March 23, 2005

ASQ Building Ltd. 1600-925 West Georgia Street Vancouver, BC V6C 3L2

les EN

Dear Sirs:

RE: 1200 West 73rd Avenue

Following inspection, it was determined that an approximate 12' x 8' non-illuminated plywood sign reading "Royal LePage" "For Lease" "604-683-3111" has been erected on the roof of the first floor, south portion of the building, at the above location, in contravention of the Sign By-law.

For your information, this type of sign is not permitted in the City of Vancouver in accordance with the Sign By-law.

In accordance with Section 7.1 of the Sign By-law, you are ordered to remove the roof-top sign, described above, within 48 hours of the date of this order.

Failure to comply with this order will result in this matter being referred to the City Prosecutor for the laying of charges.

Yours truly,

P. Teichroeb

Director

JI/jm

Copy: ASQ Building Ltd., 760-1066 West Hastings Street, Vancouver, BC, V6E 3X2

Q:\Correspondence\Sign\2005Archives\03 - March\1200w73rd.doc

2005/03/23 1 PSA550.00 1 Address: 120	PSP150X Pr	cs PRISM Properties => City of Vancouver operty Tax Inquiry Co-ordinate: 144-835-06-0000
Lot code	: 2 AREA (SQUARE FEE	F) Neighbourhood code : 012
Width	:	Postal code : V6P 3E5
Length	:	Zone code :
Area	: 77,537.00	Record status : ACTIVE
Land value	: \$5,272,000 (2004)	Plan number : 15365
Impr value	: \$17,348,000 (2004)	Homeowner grant : No
Number of ow ASQ BUILDING		Legal description: Lot Block Sect Town Ra Plan DL LD

760-1066 HASTINGS ST W VANCOUVER BC V6E 3X2 LOT C BLK A DL 318 & 319 EX PLAN 18082X, 18083X, 18084X & 18085X 13166 19421 LMP22484 (ROW)

F1=Help F2=Print F12=Return

F13=Additional owners



Ministry of Finance Corporate and Personal Property Registries www.corporateonline.gov.bc.ca Mailing Address: PO BOX 9431 Stn Prov Govt. Victoria BC V8W 9V3

Location: 2nd Floor - 940 Blanshard St. Victoria BC 250 356-8626

BC Company Summary

For

ASQ BUILDING LTD.

Date and Time of Search: Currency Date: March 23, 2005 10:50 AM Pacific Time March 04, 2005

ACTIVE

Incorporation Number: Name of Company: Recognition Date: Last Annual Report Filed:

ASQ BUILDING LTD. Incorporated on February 10, 2000 February 10, 2004

BC0601148

In Liquidation: No Receiver: No

REGISTERED OFFICE INFORMATION

Mailing Address: 1600 - 925 W GEORGIA ST VANCOUVER BC V6C 3L2 CANADA Delivery Address: 1600 - 925 W GEORGIA ST VANCOUVER BC V6C 3L2 CANADA

RECORDS OFFICE INFORMATION

Mailing Address: 1600 - 925 W GEORGIA ST VANCOUVER BC V6C 3L2 CANADA Delivery Address: 1600 - 925 W GEORGIA ST VANCOUVER BC V6C 3L2 CANADA

DIRECTOR INFORMATION

Last Name, First Name, Middle Name: ALTMAN, ZELICK

Mailing Address: SUITE 1550 - 11 KING STREET WEST TORONTO ON M5H 4C7 CANADA

Last Name, First Name, Middle Name:

ERIXON, AMY

Mailing Address:

200 E RANDOLPH CHICAGO ILLINOIS USA 60601 CANADA

TORONTO ON M5H 4C7

SUITE 1550 - 11 KING STREET WEST

Delivery Address:

Delivery Address:

200 E RANDOLPH CHICAGO ILLINOIS USA 60601

Last Name, First Name, Middle Name:

MARSHALL, CATHERINE

Mailing Address: 760, 1066 WEST HASTINGS STREET VANCOUVER BC V6E 3X2 CANADA Delivery Address:

760, 1066 WEST HASTINGS STREET VANCOUVER BC V6E 3X2 CANADA

Last Name, First Name, Middle Name: MCWATT, BRYAN

Mailing Address: 509 HOUNSLOW AVE TORONTO ON M2R1J1 Delivery Address: 509 HOUNSLOW AVE TORONTO ON M2R1J1

OFFICER INFORMATION AS AT February 10, 2004

Last Name, First Name, Middle Name: ERIXON, AMY Office(s) Held: (President)

Mailing Address:

200 E RANDOLPH CHICAGO ILLINOIS USA 60601 Delivery Address: 200 E RANDOLPH CHICAGO ILLINOIS USA 60601

Last Name, First Name, Middle Name: Lee, Jeany

Office(s) Held: (Vice President)

Mailing Address: 760, 1066 WEST HASTINGS STREET VANCOUVER BC V6E 3X2 CANADA Delivery Address: 760, 1066 WEST HASTINGS STREET VANCOUVER BC V6E 3X2 CANADA

Last Name, First Name, Middle Name: STEELE, WILLIAM Office(s) Held: (Secretary)

Mailing Address: 3437 ST MARY'S AVE NORTH VANCOUVER BC V7N1X7 Delivery Address: 3437 ST MARY'S AVE NORTH VANCOUVER BC V7N1X7



COMMUNITY SERVICES GROUP Licences and Inspections Inspections

PLEASE REFER TO: Jason Rowley District Electrical Inspector *jason.rowley@vancouver.ca* at 604.873.7601 Office Hours: 1:00 - 1:45pm

February 6, 2008

S.O.S. Security Solutions Ltd. #369 - 7360 137th Street Surrey, BC V3W 1A3

Dear Sirs:

RF-EL504793 1200 West 73rd Avenue #1400

Please be advised that no request for inspection of the electrical work under the scope of the referenced permit has been submitted to this office during a 180-day period, as stated by Section Sections 19(1) and 19(2) of the BC Electrical Safety Regulations.

Please also note that under the provision of Section 5.8 of the City of Vancouver Electrical By-Law that the above permit may no longer be valid if no work has been commenced within 90 days of the date of the permit issuance.

Therefore, in order for this office to revalidate the permit as provided by Section 5.10 of the City of Vancouver Electrical By-Law, a request for inspection must be submitted to the City of Electrician in conformance with Section 6.6 of the City of Vancouver Electrical By-Law and the installation must be made available for inspection as provided by Section 19(6)(a) of the BC Electrical Safety Regulations within 14 days of this letter.

Failure to comply with this letter may result in the cancellation of your permit privileges in the City of Vancouver in accordance with Section 5.2(d) of the City of Vancouver Electrical By-law. Further disciplinary action may also be taken in accordance with the Electrical Safety Regulation.

Yours truly,

A. Z. Tsisserev, P.Eng. Chief Electrical Inspector and City Electrician

AZT/rm

CC:

ASQ Building Ltd. Lasalle Investment Management #1210 - 1066 West Hastings Street Vancouver, BC V6E 3X2



COMMUNITY SERVICES GROUP Licences and Inspections Inspections

PLEASE REFER TO: Jason Rowley District Electrical Inspector *jason.rowley@vancouver.ca* at 604.873.7601 Office Hours: 1:00 - 1:45pm

February 6, 2008

ASQ Building Ltd. Lasalle Investment Management #1210 - 1066 West Hastings Street Vancouver, BC V6E 3X2

Dear Sirs:

RE: EL504793 1200 West 73rd Avenue #1400

Please be advised that no request for inspection of the electrical work under the scope of the referenced permit has been submitted to this office during a 180-day period, as stated by Section Sections 19(1) and 19(2) of the BC Electrical Safety Regulations.

Please also note that under the provision of Section 5.8 of the City of Vancouver Electrical By-Law that the above permit may no longer be valid if no work has been commenced within 90 days of the date of the permit issuance.

Therefore, in order for this office to revalidate the permit as provided by Section 5.10 of the City of Vancouver Electrical By-Law, a request for inspection must be submitted to the City of Electrician in conformance with Section 6.6 of the City of Vancouver Electrical By-Law and the installation must be made available for inspection as provided by Section 19(6)(a) of the BC Electrical Safety Regulations within 14 days of this letter.

Failure to comply with this letter may result in the cancellation of your permit privileges in the City of Vancouver in accordance with Section 5.2(d) of the City of Vancouver Electrical By-law. Further disciplinary action may also be taken in accordance with the Electrical Safety Regulation.

Yours truly,

A. Z. Tsisserev, P.Eng. Chief Electrical Inspector and City Electrician

AZT/rm

cc:

S.O.S. Security Solutions Ltd. #369 - 7360 137th Street Surrey, BC V3W 1A3



PLEASE REFER TO: J. Rowley District Electrical Inspector jason.rowley@vancouver.ca at 604.873.7920

July 25, 2012

Arwest Electric Paul Chiasson 5271 Elgin Street Vancouver BC V5W 3J9

Dear Sir/Madam:

RE: 1200 West 73rd Avenue - Unit #340 Electrical Permit No. EL528448

Please be advised that no request for inspection of the electrical work under the scope of the referenced permit has been submitted to this office during a 180-day period, as stated by Section Sections 19(1) and 19(2) of the BC Electrical Safety Regulations.

Please also note that under the provision of Section 5.8 of the City of Vancouver Electrical By-Law that the above permit may no longer be valid if no work has been commenced within 90 days of the date of the permit issuance.

Therefore, in order for this office to revalidate the permit as provided by Section 5.10 of the City of Vancouver Electrical By-Law, a request for inspection must be submitted to the City of Electrician in conformance with Section 6.6 of the City of Vancouver Electrical By-Law and the installation must be made available for inspection as provided by Section 19(6)(a) of the BC Electrical Safety Regulations within 14 days of this letter.

Failure to comply with this letter may result in the cancellation of your permit privileges in the City of Vancouver in accordance with Section 5.2(d) of the City of Vancouver Electrical By-law. Further disciplinary action may also be taken in accordance with the Electrical Safety Regulation.

Yours truly,

Buchannon, for

D. Buchannon for Director of Licences & Inspections, and City Electrician

To: J. ROWICY IG, Bawn Date:

/dlb

cc: J. Rowley - District Electrical Inspector



PLEASE REFER TO: Jason Rowley District Electrical Inspector csg.inspectin@vancouver.ca at 604.873.7920 Office Hours: 1:00 - 1:45 p.m.

February 14, 2013

Troy Life & Fire Safety Limited Protection Incendie Troy Ltee 43775 Industrial Way Chilliwack, B.C. V2R 4L2

Diary? No..... Yes..

EN #:....

Dear Sir/Madam:

RE: EL526749 1200 West 73rd Avenue

Please be advised that no request for inspection of the electrical work under the scope of the referenced permit has been submitted to this office during a 180-day period, as stated by Section Sections 19(1) and 19(2) of the BC Electrical Safety Regulations.

Please also note that under the provision of Section 5.8 of the City of Vancouver Electrical By-Law that the above permit may no longer be valid if no work has been commenced within 90 days of the date of the permit issuance.

Therefore, in order for this office to revalidate the permit as provided by Section 5.10 of the City of Vancouver Electrical By-Law, a request for inspection must be submitted to the City of Electrician in conformance with Section 6.6 of the City of Vancouver Electrical By-Law and the installation must be made available for inspection as provided by Section 19(6)(a) of the BC Electrical Safety Regulations within 14 days of this letter.

Failure to comply with this letter may result in the cancellation of your permit privileges in the City of Vancouver in accordance with Section 5.2(d) of the City of Vancouver Electrical By-law. Further disciplinary action may also be taken in accordance with the Electrical Safety Regulation.

Yours truly,

or,

G. Bawn for Director of Licences & Inspections, and City Electrician

1200 W 73rd Av -E101st Ltr. docx



PLEASE REFER TO: Jason Rowley at 604.873.7920

May 28, 2013

Fibernet Services Ltd. Unit #116 - 2323 Boundary Road Vancouver, B.C. V5M 4V8

Dear Sir/Madam:

RE: EL519751 1200 West 73rd Avenue - Unit #215

Diary? No..... Yes. To: J. Rowler

EN #:.....

As the holder of the above-noted Electrical Permit, please be advised that we have no record of your request for inspection within the last 180-day period.

The BC Electrical Safety Regulation Section 19(1) states:

- If a person holds an electrical installation permit, the field safety representative named on the permit must request an inspection at least once in every 180 day period.
 - (3) On the completion of each phase of electrical work under an installation permit, the field safety representative named on the permit must request an inspection.
 - (6) After reviewing a request under subsection (1) or (3), the regulatory authority may require
 - (a) an inspection, or
 - (b) a declaration that the work performed under the permit complies with the Act and the regulations.

Therefore, you are requested to provide the above stated declaration by June 11, 2013. Our fax number is 604.873.7100.


Failure to comply with this letter may result in the cancellation of your permit privileges in the City of Vancouver in accordance with Section 5.2(d) of the City of Vancouver Electrical By-law. Further disciplinary action may also be taken in accordance with the Electrical Safety Regulation.

Yours truly,

W. White Deputy City Electrician Manager of Trades Inspection

cc: Jason Rowley, District Electrical Inspector 1200 W 73rd Av - E196 1st ltr.docx


Home	Main Search	PC Building	Permits Addresses	Insp Sch	AMANDA	Mechanical	Tracking	More System	IS 🕨
Addre	ss 1200	to	W 73RD AV			Search			
lote	ypes								
		Note Type	e			Number o	f notes f	or this permit	
1	09 - INTERNA	L NOTES	1						
Notes	19 E							and the second second	
	Number		Title			Included?	List seq	Updated By	Date Updated
	081 E	NV PROTECT	ION INSPECTION	1.1.1			081 E	ROBERTSON	30 Mar 2010
Sept	1/04:- Re: FI4	402579:- Rec	eived a copy of lette	er from the	Ministry o	of Water, Lar	nd and Ai	Protection for	r the above
refer	enced site Re:	Notice of Co	mmencement/Compl	etion of Inc	dependent	Remediation).		
Feb2	5/10 BU44714	3 for #604 de	ental offices of DrsMi	tchell and	Hastings.	An amalgam	separato	r is to be insta	lled. X-ray
-			work. BU approved.						
		and the second s	ental office of Dr Jar	nos Landric	ian Inc. A	amalgam s	onarator	(the Liberty BO	SS by MARS
				nes canung	juit file. Al	r amaigan se	eparator	(the Liberty DO	DO DY MARD
Biom	ed Processes I	nc)to be inst	alled.						



🖹 BY - PROSEC	CUTION	PROSECUTION	01 - OPEN 08	Apr 2005
Action Details	and the second second		The second s	and the second of
Date	Action by	Action	Action specifics	Reference
08 Apr 2005	P HAYES	060 - OPEN GROUP	7	+
08 Apr 2005	P HAYES	183 - RECEIVE INFO	- SIGN	IR - UI26107
03 May 2005	P HAYES	420 - INFRACTION CLEAR	- REMOVED	IR - UI26107
🖹 EN - ENFOR	CEMENT	COMMUNITY SERV/P&D	10 - CLEARED 23	Mar 2005 11 Jul 2005
Action Details	A CONTRACTOR OF THE OWNER	And the Real Property lies and	100 C 100 C 200 C 200	
Date	Action by	Action	Action specifics	Reference
23 Mar 2005	J MOREE	060 - OPEN GROUP	-	-
23 Mar 2005	J MOREE	849 - PUI ENFORCMNT	A20 - PUI SIGN	EN - 023664
23 Mar 2005	J MOREE	835 - X-REFERENCE IR	- EN023664	IR - UI25842
23 Mar 2005	J MOREE	849 - PUI ENFORCMNT	A20 - PUI SIGN	EN - 023665
23 Mar 2005	J MOREE	835 - X-REFERENCE IR	- EN023665	IR - UI25842
11 Jul 2005	K MORGAN	859 - CLEAR PUI ENFORCMT	A20 - PUI SIGN	EN - 023665
11 Ju <mark>l</mark> 2005	K MORGAN	859 - CLEAR PUI ENFORCMT	A20 - PUI SIGN	EN - 023664
11 Jul 2005	K MORGAN	069 - REVIEW COMPLETE		

	DING INSPECTN	BI11 BUILDING INSP	01 - OPEN 08 Jul 2	005
Action Details Date	Action by	Action	Action specifics	Reference
08 Jul 2005	C PRYCE	060 - OPEN GROUP		+
27 Apr 2006	F HILL	700 - COMPLAINT	19 - WWOP FEES REQ'D	-
27 Apr 2006	F HILL	991 - NOTE	- UNIT # 170 PODIUM	+
27 Apr 2006	FHILL	991 - NOTE	- FRAMNG BEFORE PERM	+
16 Jul 2012	V LE.	810 - RECEIVE COMPLAINT	045 - UNSAFE CONDITION	-
16 Jul 2012	V LE	800 - SCHEDULE INSPECT N	- SEE COMPLAINT	DT - 120718
18 Jul 2012	L ROBERTS	991 - NOTE	- CALLED COMLAINANT	÷
18 Jul 2012	L ROBERTS	991 - NOTE	- LEFT MESSAGE	
18 Jul 2012	L ROBERTS	991 - NOTE	- WENT TO AIRPORT	
18 Jul 2012	L ROBERTS	991 - NOTE	- I DID NOT SEE ANY	
18 Jul 2012	L ROBERTS	991 - NOTE	- FOUNDATION OR	4
18 Jul 2012	L ROBERTS	991 - NOTE	- PROBLEMS WITH THE	-
18 Jul 2012	L ROBERTS	991 - NOTE	- CRACKING IN WALLS	•
18 Jul 2012	L ROBERTS	700 - COMPLAINT	69 - NO ACTION REQUIRED	
26 Jul 2016	E MAH	810 - RECEIVE COMPLAINT	060 - SITE COMPLAINT	-
26 Jul 2016	EMAH	814 - INVSTGTN & ENFORCM		2
26 Jul 2016	E MAH	704 - FILE MANAGER	- MIKE MCDIARMID	-

02 Aug 2016	M MCDIARMID	800 - SCHEDULE INSPECTN	- COMPLAINT UNSAFE	DT - 160803
04 Aug 2016	M CARSTAIRS	991 - NOTE	- SEE DOMINO NO	NT - ISSUE
8 61 - ELEC	TRICAL INSPECT	EI16 ELECTRICAL INSP	01 - OPEN 21 Dec 3	1999
Action Details			and the second	
Date	Action by	Action	Action specifics	Reference
21 Dec 1999	J GILL	060 - OPEN GROUP		
21 Dec 1999	J GILL	830 - REFER INFRACTION	ELWW - ELECTRICAL WWOP	-
21 Dec 1999	J GILL	991 - NOTE	- VALUE \$500/PER SW	-
21 Dec 1999	J GILL	991 - NOTE	- SUITE #400	-
21 Dec 1999	S VAN BEMMELEN	991 - NOTE	- UNIT #350 DATA	
21 Dec 1999	S VAN BEMMELEN	991 - NOTE	- CABLING PER SW	-
21 Dec 1999	S VAN BEMMELEN	830 - REFER INFRACTION	ELWW - ELECTRICAL WWOP	IR - ???
07 Jan 2000	D FLEMING	991 - NOTE	- SUITE #350 ONLY	
07 Jan 2000	D FLEMING	860 - CLEAR INFRACTION	ELWW - ELECTRICAL WWOP	
27 Jun 2000	D FLEMING.	991 - NOTE	- WWP PAID FOR #400	-
03 Jun 2004	RTUTTLE	860 - CLEAR INFRACTION	ELWW - ELECTRICAL WWOP	IR - ???
23 Aug 2005	K BILINSKY	770 - GIVE INFO / ADVICE	22 - PERMIT/LICENSE REQ	8
23 Aug 2005	K BILINSKY	991 - NOTE	- APLYING FOR NEW	EL - ANNUAL
31 Aug 2005	K BILINSKY	740 - PROGRESS / RECHECK	69 - NO ACTION REQUIRED	EL - 495484
31 Aug 2005	K BILINSKY	991 - NOTE	- ANNUAL PERMIT RECD	4



10 (p) 12220	IT OT IS IT O			
10 Apr 1996	H CHIANG	R26 - LETTER/ORDER REQD	- ILLEGAL BANNER	IR - 314530
01 May 1996	H CHIANG	A20 - SIGN	05 - RE-CHECK	
01 May 1996	H CHIANG	R62 - INFORMATION RECVD	-	-
23 May 1996	H CHIANG	A20 - SIGN	05 - RE-CHECK	7
23 May 1996	H CHIANG	R63 - INFRACTION CLEAR	-	IR - 320309

14 Mar 2005	J IACOBAZZI	840 - COMPLAINT	A20 - PUI SIGN	EN - 023664
14 Mar 2005	J JACOBAZZI	842 - ROUTINE	A20 - PUI SIGN	EN - 023665
14 Mar 2005	J IACOBAZZI	R26 - LETTER/ORDER REQD	- ROOF TOP SIGN	IR - UI25842
14 Mar 2005	J IACOBAZZI	R26 - LETTER/ORDER REQD	- FACIA SIGN	IR - UI25842
06 Apr 2005	J IACOBAZZI	A20 - SIGN	05 - RE-CHECK	EN - 023664
06 Apr 2005	J IACOBAZZI	R71 - REFERRED	- TO P HAYES 4 PROSC	IR - UI26107
03 May 2005	J IACOBAZZI	A20 - SIGN	05 - RE-CHECK	EN - 023664
03 May 2005	J IACOBAZZI	R63 - INFRACTION CLEAR	- ROOF TOP SIGN RMVD	-
03 May 2005	J IACOBAZZI	A20 - SIGN	05 - RE-CHECK	EN - 023665
03 May 2005	J IACOBAZZI	R63 - INFRACTION CLEAR	- FACIA SGN REMVD	
03 May 2005	J IACOBAZZI	850 - CLEAR COMPLAINT	A20 - PUI SIGN	EN - 023664
03 May 2005	J IACOBAZZI	852 - CLEAR ROUTINE	A20 - PUI SIGN	EN - 023665
THE REPORT OF MANAGEMENT	Contraction and the			

22 Sep 2011	A BUCHANAN	840 - COMPLAINT	A03 - PUI BUSNSS LICENSE	EN - 073500
22 Sep 2011	A BUCHANAN	R10 - VERBAL ORDER	- NO BL POLICE ENQUI	-
23 Sep 2011	A BUCHANAN	850 - CLEAR COMPLAINT	A03 - PUI BUSNSS LICENSE	EN - 073500
23 Sep 2011	A BUCHANAN	R64 - NO VIOLATION	- AT 400-601WBROADW	-
02 Mar 2012	A BUCHANAN	852 - CLEAR ROUTINE	A03 - PUI BUSNSS LICENSE	EN - 041177
20 Aug 2014	M MACKIE	843 - ROUTINE OPEN/CLEAR	A03 - PUI BUSNSS LICENSE	BL - 130656

81 - ENV F	PROTECTN INSPN	ENV PROTECTION	01 - OPEN 01 Sep 2004				
Action Details		and the second	and the second				
Date	Action by	Action	Action specifics	Reference			
01 Sep 2004	H UYEYAMA	060 - OPEN GROUP		-			
01 Sep 2004	H UYEYAMA	N12 - SOIL ASSESSMENT	01 - ROUTINE	-			
01 Sep 2004	H UYEYAMA	R62 - INFORMATION RECVD	- FROM MWLAP	FI - 402579			
01 Sep 2004	H UYEYAMA	993 - SEE INTERNAL NOTES	+	÷			
25 Feb 2010	D ROBERTSON	N30 - APPLICATION	01 - ROUTINE	BU - 447143			
25 Feb 2010	D ROBERT SON	R90 - ACCEPTED	- #604 AIRPORT SQUAR				
25 Feb 2010	D ROBERT SON	993 - SEE INTERNAL NOTES	- DENTAL OFFICE				
30 Mar 2010	D ROBERT SON	N30 - APPLICATION	01 - ROUTINE	BU - 447448			
30 Mar 2010	D ROBERT SON	R90 - ACCEPTED	- #603 AIRPORT SQUAR	-			
30 Mar 2010	D ROBERTSON	993 - SEE INTERNAL NOTES	- DENTAL OFFICE	-			