

File No.: 04-1000-20-2017-438

February 8, 2017

s.22(1)

Dear s.22(1)

Re: **Request for Access to Records under the Freedom of Information and Protection of Privacy Act (the "Act")**

I am responding to your request of November 7, 2017 for:

In or around 2009, there was a large water-main break on West 16th Avenue at approximately Trafalgar Street, Vancouver, BC. Request is for all documents relating to water main ruptures in 2009 on 16th Avenue between Macdonald Street and Larch Street in the possession of the City, including documents and/or reports relating to any maintenance or other work being conducted near the location of the water-main break at the time of the break and all documents related to the cause of the failure and the timeline of repairs and any assessments or investigation of damage to surrounding properties.

All responsive records are attached. Some information in the records has been severed, (blacked out), under s.22(1) of the Act. You can read or download this section here: http://www.bclaws.ca/EPLibraries/bclaws_new/document/ID/freeside/96165_00

Please note: some information in the records has been marked as 'Address not responsive to the request' as these records refer to addresses not within the specified area of your request.

Engineering Staff confirmed that City records are limited as your request appears to be related to a water main pipe belonging to Metro Vancouver and not the City of Vancouver. However, a City crew did attend near the specified area of your request on December 8, 2009 to investigate a water leak.


Under section 52 of the Act you may ask the Information & Privacy Commissioner to review any matter related to the City's response to your request. The Act allows you 30 business days from the date you receive this notice to request a review by writing to: Office of the Information & Privacy Commissioner, info@oipc.bc.ca or by phoning 250-387-5629.

If you request a review, please provide the Commissioner's office with: 1) the request number assigned to your request (#04-1000-20-2017-438); 2) a copy of this letter; 3) a copy of your original request for information sent to the City of Vancouver; and 4) detailed reasons or grounds on which you are seeking the review.

Please do not hesitate to contact the Freedom of Information Office at foi@vancouver.ca if you have any questions.

Yours truly,

Cobi Falconer, FOI Case Manager, for

A handwritten signature in black ink, appearing to read 'Cobi Falconer', written over a faint, illegible background.

Barbara J. Van Fraassen, BA
Director, Access to Information & Privacy

Barbara.vanfraassen@vancouver.ca
453 W. 12th Avenue Vancouver BC V5Y 1V4
Phone: 604 .873.7999
Fax: 604.873.7419

Encl.

:ma



Service Request # R 200256 Lagan's ECM Update

Request Type* WCheckForLeakCFL Water Check For Leak (CFL)

Sub Type Incident Date 2009/12/07 15:20 Last 311 Update, where applicable

Call Date 2009/12/07 15:18 Crew Assign Date 2009/12/08 08:01

Request Date 2009/12/07 15:18 Crew ID 1070 Water - Crew 1070 Creator

Reviewed 2010/04/14 14:44 Crew Contact s. 22(1) CHRIS FERNQUIST Dispatcher

Initiated By Alt Crew Contact Alt Dispatcher

Follow-Up Date / / :

Charges Explained

Information **Call Details** Inspection Log Attachments Associations Schedules Audit Log Lagan eForm

Call Duration 00:01:28 # of Calls 1

Taken By s. 22(1) NADINE SABBERTON

Customer Contact Requested Notify Customer Regarding Service Request Progress

Contact

Name s. 22(1) Contact Phone s. 22(1)

First, MI Title Foreign Alternate Phone - - x

Address Fax - - x

City Pager - - x PIN

State/Province E-mail

ZIP/PC Country Contact Type NotOwner



Service Request # R 200256 Lagan's ECM Update

Request Type* WCheckForLeakCFL Water Check For Leak (CFL)

Sub Type Incident Date 2009/12/07 15:20 Last 311 Update, where applicable

Call Date 2009/12/07 15:18 Crew Assign Date 2009/12/08 08:01

Request Date 2009/12/07 15:18 Crew ID 1070 Water - Crew 1070 Creator

Reviewed 2010/04/14 14:44 Crew Contact S 22(1) CHRIS FERNQUIST Dispatcher

Initiated By All Crew Contact Alt Dispatcher

Follow-Up Date / / :

Charges Explained

Information Call Details Inspection **Log** Attachments Associations Schedules Audit Log Lagan eForm

Service Request Log Results (1 records)

Log Type ▲	Entered By	Entered By Name	Start Date	To	Comments
<input type="checkbox"/> InspResult	S 22(1)	NADINE SABBERTON	2009/12/08 12:49		Referred to Metro Vancouver (GVRD)

Work Slip

SAP Charge #	Address & Location: 2600 - 2699 W 16TH AV COVAV				Responsible	
					Water Operations	
Work Order #	Work Order Activity				Created Date	
30132	Main - Leak(2600 W 16TH 800mm GVWD)				2009/12/07	
Group Project #	Problem	Sub Activity	Assigned To	Crew ID		
1	MetroLeak		CHRIS FERNQUIST	1070		
Work Order Comments: Pool of water on middle boulevard, water escaping on road. Leak on GVWD 800mm main CFL in road - REFERED TO METRO VANCOUVER - LEAK ON 800MM MAIN						
Reference #1					Billable?	
Reference #2					N	
Collection Agency		Collection Method		Zone	Beat	
Service Request #	R200256 (Water Check For Leak (CFL))					
Contact Name			Contact Phone		Contact Type	
s. 22(1)			s. 22(1)		NotOwner	
Asset Type	Asset ID #	B.U.N	Status	Asset Area	Map # (Facet)	District
()						
Asset Details:						
Safety & Asset Notes:						
PM Schedule	Last Completed Work Order					
	;					
Crew Comments						
Note that Hansen shows this Work Order as already completed						
Work Completed Date: 2009/12/08			Print Name:		Crew ID:	

Lagan E-Form

Case Details

Water Operation Record 83

Operations **Lookup Num:**

Num	Status	Created	Date Received	Time Received		
9018045	Completed	08-Dec-2009	08-Dec-2009	10:30 AM	<input type="button" value="Graphics"/>	<input type="button" value="Details"/>

From	To	Street	Cross	Place Name
2625	0	W 16TH AV	STEPHENS ST	

Area	To Area	Requested By	Reference No.	Last Name	First Name	Telephone
		Water		Ferquist	Chris	

Details	Chrg Exp	Account	Total
			\$0.00

Meters	S/N:	WSA #	Side:	Hydrants	ID:	Old ID:	Permit:	Make:	Line:
	0								

Make:	Model:	Size:	Fire Only:	Di:	From Corner:	To Ctrl Valve:	Map:	Colour:

Meter Loc:	RR/TP:	In Commission:	Date O/C:	O/C Reason:	Remark:

Task	Facility Type	Id #	Priority	Work Order	Crew	Employee	Trouble	Remedy	Part	Status
Leak Check	Main		As Sched		1070	Ferquist, C.		Referral - GVF	Main	Completed
			As Sched							

Comments: Date Task Completed: 08-Dec-2009

Document Search Summary - FOI 2017-438

Date	Location	WO #	Description	Crew
Dec 2/09	16th Ave W & Trafalgar	80052089	b/o bus pads	83
Address not responsive to the request				
Dec 2/09	16th Ave W & Trafalgar	50018431	b/o s/w	83
Address not responsive to the request				
Dec 04/09	16th ave & Trafalgar	80052089	grade #9 grind roots and set forms for bus pads	83
Dec 04/09	16th ave & Trafalgar	50018431	breakout s/w chop roots grade #9 and set forms	83
Address not responsive to the request				
Dec 7/09	16th Ave W & Trafalgar	80052089	poured, set and finished concrete	83
Address not responsive to the request				
Dec 7/09	16th Ave W & Trafalgar	50018430	poured, set and finished 3 stones	83
Address not responsive to the request				
Dec 14/09	16th ave & Trafalgar	80052089	strip top soil and seed, clean up all materials	83
Dec 14/09	16th Ave & Trafalgar	80052089	strip/topsoil and seed	78
Dec 7/09	16th Ave & Trafalgar	80052089	helped crew 53	73

Weather

Sunny am sunny pm

Date: December 2, 2009



A/A 910 344 964 MT

Streets Operations Daily Crew Report

Crew # **83**
 Field Supervisor **Cavaliere 690-7362**
 Superintendent **Taryn Scollard**
 Hours of Work 7:00 AM - 3:30 PM

(signed)
(signed)

Work Order # and Hours


1	2	3	4	5	6
8052089	8052085	8052086	8052098	8052096	50018431

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem. Code	1	2	3	4	5	6
s. 22(1)	G. Anderson	B2171		6000			1.5	1.5	1.5	1	1	1.5
	R. Cavaliere	A1152		6000			1	1.5	1.5	1	1	2
	S. Cerminara	C1193	P74	6000	4R-370				3		3	2
	A. Mannarino	A1928	P74	6000	4R-370		1	1	2	1	2	1
	G. Melvor		P16	6000	4R-370				3		3	2
	M. Skinner			6000			1	1	2	1	1	2

Equipment Description	Equipment ID	Running Hours					
TRUCK, PICKUP, LIGHT	A1152	1	1.5	1.5	1	1	2
TRUCK, DUMP, 1 YARD	A1928	1	1	2	1	2	1
TRAILER, OFFICE/WORK, 6-11 MAN	A2727	1					
TANDEM TRUCK	Ateeq Trucking Ltd.						
CONSTRUCTION, LOADER BACKHOE, MEDIUM	B2171	1.5	1.5	1.5	1	1	1.5
TRUCK, DUMP, 3 YARD	C1193			3		3	2
COMPRESSOR, TRAILER, 185 CFM	C2228	1	1	2	1	1	2
Concrete Forms	C22480			1			
SAW, CUT-OFF, HANDHELD, GAS, MEDIUM, 16"	V11777	1	1	2	1	2	1
COMPACTION, PLATE, NON-REV, VIBRATING, GAS, LIGHT	V11910	1	1	2	1	2	1
Toilets		1					
Flashers							
Dumps (Nat. Yds. Only)	Yds Dumped						

Location 1	Material	Amount	Comments
50052089 16 of TRAFALGAR			BRAKE OUT BUS PADS
Dump:		Location:	
Site Safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input checked="" type="checkbox"/> Barricades <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>			
Signage Used:			By: (Initials)
Activity Code		Units Completed	Measurement

Address not responsive to the request



Location 6	Material	Amount	Comments
50018431 16 of TRAFALGAR			BRAKE OUT 9/03
Dump:		Location:	
Site Safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input checked="" type="checkbox"/> Barricades <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>			
Signage Used:			By: (Initials)
Activity Code		Units Completed	Measurement

Weather

Sunny am Sunny pm

Date: December 4, 2009



A/A 910356770

Streets Operations Daily Crew Report

Crew # 83

Field Supervisor Cavaliere 690-7362

Superintendent Taryn Scollard

Hours of Work 7:00 AM - 3:30 PM

Work Order # and Hours

1	2	3	4	5	6
80052089	50018031	80052095	80052096		

(signed) [Signature]
(signed) [Signature]

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem. Code	1	2	3	4	5	6
s. 22(1)	R. Cavaliere	A1152		6000			2	2	2	2		
	S. Cerminara	C1193		6000			2	2	2	2		
	A. Mannarino	A1928	P74	6000	61-320		2	2	2	2		
	G. Melvor	3	P16	6000	61-320		2	2	2	2		

✓
✓
✓
✓
M+

Equipment Description	Equipment ID	Running Hours					
TRUCK, PICKUP, LIGHT	A1152	2	2	2	2		
TRUCK, DUMP, 1 YARD	A1928	2	2	2	2		
TRAILER, OFFICE/WORK, 6-11 MAN	A2727	1					
TRUCK, DUMP, 3 YARD	C1193	2	2	2	2		
COMPRESSOR, TRAILER, 185 CFM	C2228	2	2	2	2		
Concrete Forms	C22480		1				
SAW, CUT-OFF, HANDHELD, GAS, MEDIUM, 16"	V11777	2	2	2	2		
COMPACTION, PLATE, NON-REV, VIBRATING, GAS, LIGHT	V11910	2	2	2	2		
Toilets		1	1				
Flashers							
Dumps (Nat. Yds. Only)	Yds Dumped						

Location 1 80052089 TRAFALGAN #9 2.6 TON GRADE #9 GRIND
ROOTS & SET FORMS
for Best Peds

Material: #9 Amount: 2.6 TON Comments: GRIND ROOTS & SET FORMS for Best Peds

Dump: _____ Location: _____

Site Safety when Departing Location: Cones Snow Fence Tape Barricades Ramps Flashers Delineators

Signage Used: _____ By: _____ (Initials)

Activity Code: _____ Units Completed: _____ Measurement: _____

Location 2 50918431 TRAFALGAN BREAKOUT GRIND
ROOTS & SET FORMS

Material: _____ Amount: _____ Comments: BREAKOUT w/ chop ROOTS GRIND #9 & SET FORMS

Dump: _____ Location: _____

Site Safety when Departing Location: Cones Snow Fence Tape Barricades Ramps Flashers Delineators

Signage Used: _____ By: _____ (Initials)

Activity Code: _____ Units Completed: _____ Measurement: _____



Location 5 _____ Material: _____ Amount: _____ Comments: _____

Dump: _____ Location: _____

Site Safety when Departing Location: Cones Snow Fence Tape Barricades Ramps Flashers Delineators

Signage Used: _____ By: _____ (Initials)

Activity Code: _____ Units Completed: _____ Measurement: _____

Location 6 _____ Material: _____ Amount: _____ Comments: _____

Dump: _____ Location: _____

Site Safety when Departing Location: Cones Snow Fence Tape Barricades Ramps Flashers Delineators

Signage Used: _____ By: _____ (Initials)

Activity Code: _____ Units Completed: _____ Measurement: _____

Weather

clear/cold am clear/cold pm



A/A 910360490

Date: December 7, 2009

Streets Operations Daily Crew Report

Crew # 83

Field Supervisor Cavaliere 690-7362

Superintendent Taryn Scollard

Hours of Work 7 AM - 3³⁰ PM

(signed)
(signed)

Work Order # and Hours

1	2	3	4	5	6
60052089	60052085	60052083			

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem. Code	1	2	3	4	5	6
s. 22(1)	R. Cavaliere			7001								
	S. Cerminara	C1193	P74	6000	GR320		4	2	2			
	A. Mannarino	A1928	P74	6000	GR320		2		2			
				5620			4					
	G. McIvor	A1152	P28	6000	GR355		4	2	2			

Equipment Description	Equipment ID	Running Hours					
TRUCK, PICKUP, LIGHT	A1152	1					
TRUCK, DUMP, 1 YARD	A1928	2	4	2			
TRAILER, OFFICE/WORK, 6-11 MAN	A2727	1					
TRUCK, DUMP, 3 YARD	C1193	4	2	2			
COMPRESSOR, TRAILER, 185 CFM	C2228	4	2	2			
Concrete Forms	C22480	4	2	2			
SAW, CUT-OFF, HANDHELD, GAS, MEDIUM, 16"	V11777	4	2	2			
COMPACTION, PLATE, NON-REV, VIBRATING, GAS, LIGHT	V11910	4	2	2			
Toilets		1					
Flashers							
Dumps (Nat. Yds. Only)	Yds Dumped						

Location 1	80052089	Material	Amount	Comments
W16 th @ Trafalgar		Concrete/curb	2.2m ✓	pour set & finished
		1503 15 cal		✓
		Dump:		Location: W16 th & Trafalgar
Site Safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input checked="" type="checkbox"/> Barricades <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>				
Signage Used: Side walk closed By: <i>an</i> (Initials)				
Activity Code		Units Completed		Measurement

Address not responsive to the request

Location 3	50018430	Material	Amount	Comments
W16 th @ Trafalgar		Concrete/curb	0.8m ✓	pour set & finished
		0.8m		15 stones
		Dump:		Location: W16 th & Trafalgar
Site Safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input checked="" type="checkbox"/> Barricades <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>				
Signage Used: Side walk closed By: <i>an</i> (Initials)				
Activity Code		Units Completed		Measurement

Location 4		Material	Amount	Comments
				s.22(1)
		Dump:		Location:
Site Safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricades <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>				
Signage Used: By: (Initials)				
Activity Code		Units Completed		Measurement

Location 5		Material	Amount	Comments
		Dump:		Location:
Site Safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricades <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>				
Signage Used: By: (Initials)				
Activity Code		Units Completed		Measurement

Location 6		Material	Amount	Comments
		Dump:		Location:
Site Safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricades <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>				
Signage Used: By: (Initials)				
Activity Code		Units Completed		Measurement

Weather

cloud am cloud pm



A/A 910 374 503

Date: December 14, 2009

Streets Operations Daily Crew Report

Work Order # and Hours

Crew # 83

Field Supervisor Cavaliere 690-7362

Superintendent Taryn Scollard

Hours of Work 7:20 AM - 3:30 PM

(signed)
(signed)

1	2	3	4	5	6
8052089	8052098	8052088	8052089		

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem. Code	1	2	3	4	5	6
s.22(1)	R. Cavaliere	A1152		6000			2	2	2	2		
	S. Cerminara	C1193	P74	6000	GR-320		2	2	2	2		
	B. Kirk			6000			2	2	2	2		
	G. McIvor	A1928	P74	6000	GR-320		2	2	2	2		
	D. Zemluk			6000			2	2	2	2		

Equipment Description	Equipment ID	Running Hours
TRUCK, PICKUP, LIGHT	A1152	2 2 2 2
TRUCK, DUMP, 1 YARD	A1928	2 2 2 2
TRAILER, OFFICE/WORK, 6-11 MAN	A2727	1
TRUCK, DUMP, 3 YARD	C1193	2 2 2 2
COMPRESSOR, TRAILER, 185 CFM	C2228	2 2 2 2
Concrete Forms	C22480	1
SAW, CUT-OFF, HANDHELD, GAS, MEDIUM, 16"	V11777	2 2 2 2
COMPACTION, PLATE, NON-REV, VIBRATING, GAS, LIGHT	V11910	2 2 2 2
Toilets		1
Flashers		
Dumps (Nat. Yds. Only)	Yds Dumped	

Location 1	Material	Amount	Comments
80052089			
16" TRAFALGAN			STILL TOP SOIL & SEED
			clean up all materials
Dump:		Location:	
Site Safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricades <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>			
Signage Used:			By: (Initials)
Activity Code		Units Completed	Measurement

Address not responsive to the request



Location 4	Material	Amount	Comments
80052099			
16" McDonald			TOP SOIL & SEED
			clean up all materials
Dump:		Location:	
Site Safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricades <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>			
Signage Used:			By: (Initials)
Activity Code		Units Completed	Measurement

Location 5	Material	Amount	Comments
Dump:		Location:	
Site Safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricades <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>			
Signage Used:			By: (Initials)
Activity Code		Units Completed	Measurement

Location 6	Material	Amount	Comments
Dump:		Location:	
Site Safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricades <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>			
Signage Used:			By: (Initials)
Activity Code		Units Completed	Measurement

Weather

Cloudy am Cloudy pm



A/A 910 374 501

Date: December 14, 2009

Streets Operations Daily Crew Report

Crew # **78**
 Field Supervisor **Gleason 690-4734**
 Superintendent **Taryn Scollard**
 Hours of Work 7:00 AM - 3:30 PM

(signed)
(signed)

Work Order # and Hours

1	2	3	4	5	6
<u>80052089</u>	<u>80052098</u>	<u>80052088</u>	<u>50017826</u>	<u>90049735</u>	

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem. Code	1	2	3	4	5	6
s.22(1)	R. Gleason	D1114	P33	6000	GR-365		1.5	1.5	1.5	1.5	2	

Equipment Description	Equipment ID	Running Hours					
TRUCK, PICKUP, LIGHT	D1114	1.5	1.5	1.5	1.5	2	
Toilets							
Flashers							
Dumps (Nat. Yds. Only)	Yds Dumped						

Location 1	Material	Amount	Comments
80052089 16 TH + TRAFALGAR			STRIP/TOPSOIL + SEED
	Dump:		Location:
<i>Site Safety when Departing Location:</i> Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricades <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>			
Signage Used:			By: RL (Initials)
Activity Code		Units Completed	Measurement

Address not responsive to the request



Location 6	Material	Amount	Comments
	Dump:		Location:
<i>Site Safety when Departing Location:</i> Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricades <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>			
Signage Used:			By: (Initials)
Activity Code		Units Completed	Measurement

Weather

7:50 am Sun pm



A/A 910 360 481
910 360 481

Date: December 7, 2009

Streets Operations Daily Crew Report

Work Order # and Hours

Crew # 73

Field Supervisor Bailey 690-5598

(signed)

Superintendent Taryn Scollard

Hours of Work 7 AM - 3:30 PM

(signed)

1	2	3	4	5	6
5001 2811 K 8005 2089					

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem. Code	1	2	3	4	5	6
s.22(1)	Z. Bailey	A1153	P28	6000	GR-355		6	2				
	T. Inacio			7001			-	-				
	M. Skinner			6000			6	2				
	J. Young			7001			-	-				

Equipment Description	Equipment ID	Running Hours
TRUCK, PICKUP, HEAVY	A1153	6 2
TRAILER, OFFICE/WORK, 6-11 MAN	A2728	1
TRUCK, DUMP, 3 YARD	C1133	idle -
TRUCK, DUMP, 1 YARD	C1281	6 2
Concrete Forms	C2248N	1
SAW, CIRCULAR, ELECTRIC, 120V, 7 1/4"	V11170	6 2
BREAKER, ERGO, AIR, 60#	V11282	6 2
COMPACTION, PLATE,	V11293	6 2
GENERATOR, PORT, GAS, 3.0KW, 120V, 1PHASE	V11586	1
Toilets		
Flashers		
Dumps (Nat. Yds. Only)	Yds Dumped	

Location 2 Material Amount Comments

Location 2	Material	Amount	Comments
16th / Trafalgar			helped crew 53
Dump:		Location:	
Site Safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricades <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>			
Signage Used: _____ By: _____ (Initials)			
Activity Code	_____	Units Completed	_____ Measurement _____

Location 3 Material Amount Comments

Location 3	Material	Amount	Comments
Dump:		Location:	
Site Safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricades <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>			
Signage Used: _____ By: _____ (Initials)			
Activity Code	_____	Units Completed	_____ Measurement _____

Location 4 Material Amount Comments

Location 4	Material	Amount	Comments
Dump:		Location:	
Site Safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricades <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>			
Signage Used: _____ By: _____ (Initials)			
Activity Code	_____	Units Completed	_____ Measurement _____

Location 5 Material Amount Comments

Location 5	Material	Amount	Comments
Dump:		Location:	
Site Safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricades <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>			
Signage Used: _____ By: _____ (Initials)			
Activity Code	_____	Units Completed	_____ Measurement _____

Location 6 Material Amount Comments

Location 6	Material	Amount	Comments
Dump:		Location:	
Site Safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricades <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>			
Signage Used: _____ By: _____ (Initials)			
Activity Code	_____	Units Completed	_____ Measurement _____