

File No.: 04-1000-20-2017-518

December 21, 2017

s.22(1)

Dear s.22(1)

Re: Request for Access to Records under the Freedom of Information and Protection of Privacy Act (the "Act")

I am responding to your request of December 14, 2017 for:

Electronic report of the sewer main cleaning and maintenance on Hull Street (located under the street) from January 1, 2007 to November 19, 2017 or the last recorded maintenance done earlier than 2007.

All responsive records are attached.


Under section 52 of the Act you may ask the Information & Privacy Commissioner to review any matter related to the City's response to your request. The Act allows you 30 business days from the date you receive this notice to request a review by writing to: Office of the Information & Privacy Commissioner, info@oipc.bc.ca or by phoning 250-387-5629.

If you request a review, please provide the Commissioner's office with: 1) the request number assigned to your request (#04-1000-20-2017-518); 2) a copy of this letter; 3) a copy of your original request for information sent to the City of Vancouver; and 4) detailed reasons or grounds on which you are seeking the review.

Please do not hesitate to contact the Freedom of Information Office at foi@vancouver.ca if you have any questions.

Yours truly,

Cobi Falconer, FOI Case Manager, for

A handwritten signature in black ink, appearing to read 'Cobi Falconer', written over the typed name.

Barbara J. Van Fraassen, BA
Director, Access to Information & Privacy

Barbara.vanfraassen@vancouver.ca
453 W. 12th Avenue Vancouver BC V5Y 1V4
Phone: 604.873.7999
Fax: 604.873.7419

Encl.

:pm

Work Slip

SAP Charge #	Address & Location: 3500 - 3699 HULL ST COVAV (Rootcut main)			Responsible		
EES236114				Sewer Operations		
Work Order #	Work Order Activity			Created Date		
236114	#MAINTENANCE - ROOT CUTTING(3500 Hull R/C Main)			2011/10/07		
Group Project #	Problem	Sub Activity	Assigned To	Crew ID		
			DAVE LUNDBERG	S_Crew30		
Work Order Comments: 10/07/11 D1347 Martelli/Jackson - could only get 23.7m from E 20th to south., this main needs to be TV'd. 10/07/11 Steve Wood (Dave Lundberg) same crew to try 6' cutter first, will return Tuesday Oct 11th then possibly tv after we see results. 10/18/11 Martelli/Currie D1347 - 100% of main has been rootcut but roots are infiltrating the m/h upstream. m/h upstream need sot have roots removed around the bench. complete						
Reference #1				Billable?		
Reference #2				N		
Collection Agency		Collection Method	Zone	Beat		
Service Request #						
Contact Name		Contact Phone	Contact Type			
Asset Type	Asset ID #	B.U.N	Status	Asset Area	Map # (Facet)	District
Main (C)	410914		IN_SERVICE	CBC10	T15	1
Asset Details: C 200 Millimeter VC 81.68 Meters 7.31% [81.68-200.0 C VC 7.31% 1930];[81.7 - 200 C 7.31% 1930]:						
Safety & Asset Notes:						
PM Schedule	Maint. Schedule	Last Completed Work Order				
6 MONTHS	1	2017/11/24; 924407; Maintenance (3500 Blk of Hull St Plg Mn)				
Crew Comments						
Note that Hansen shows this Work Order as already completed						
Work Completed Date: 2011/10/18		Print Name:		Crew ID:		

Work Slip

SAP Charge #	Address & Location: 3500 - 3699 HULL ST COVAV			Responsible		
				Sewer Operations		
Work Order #	Work Order Activity			Created Date		
365917	Maintenance(Main cleaning per Sewer Des)			2013/01/09		
Group Project #	Problem	Sub Activity	Assigned To	Crew ID		
37432			ALBANO LUIS	S_Crew29		
Work Order Comments: Beatrice Street requires root cutting. Hull Street requires root cutting. Jang: R/C 200c. Heavy roots, solids, debris.						
Reference #1				Billable?		
Reference #2				N		
Collection Agency		Collection Method	Zone	Beat		
Service Request #						
Contact Name		Contact Phone	Contact Type			
Asset Type	Asset ID #	B.U.N	Status	Asset Area	Map # (Facet)	District
Main (C)	410914		IN_SERVICE	CBC10	T15	1
Asset Details: C 200 Millimeter VC 81.68 Meters 7.31% [81.68-200.0 C VC 7.31% 1930];[81.7 - 200 C 7.31% 1930]:						
Safety & Asset Notes:						
PM Schedule	Maint. Schedule	Last Completed Work Order				
6 MONTHS	1	2017/11/24; 924407; Maintenance (3500 Blk of Hull St Plg Mn)				
Crew Comments						
Note that Hansen shows this Work Order as already completed						
Work Completed Date: 2013/01/29		Print Name:		Crew ID:		

Work Slip

SAP Charge #	Address & Location: 3500 - 3599 HULL ST COVAV (3500 BLK HULL)			Responsible		
EES517159				Sewer Operations		
Work Order #	Work Order Activity			Created Date		
517159	Inspection & QC(CCTV MAIN)			2014/07/07		
Group Project #	Problem	Sub Activity	Assigned To	Crew ID		
			KEITH DOHERTY	S_Crew23		
Work Order Comments: CCTV RE - SINK-HOLE, TV Main for sinkhole. No problem with main. Sink hole in road cut, compatcion? Refer back to Streets for repair. Streets advised. Citizen called in about palm sized sinkhole that is several feet deep. YC June 26/14-Sink hole in old road cut. Approx: 1.5'X1.5'X1' deep. Fill with sand & premix. Refer to J. Bruce. July 9/14 - Per Sewers: TV for main found no problem with main, refer back to STS for repair						
Reference #1				Billable?		
Reference #2				N		
Collection Agency		Collection Method	Zone	Beat		
Service Request #	R711118 (Street - General Issue)					
Contact Name		Contact Phone	Contact Type			
Asset Type	Asset ID #	B.U.N	Status	Asset Area	Map # (Facet)	District
Main (C)	422026		IN_SERVICE	CBC10	T15	1
Asset Details: C 250 Millimeter VC 81.38 Meters 3.21% [81.38-250.0 C VC 3.21% 1930]						
Safety & Asset Notes:						
PM Schedule	Maint. Schedule	Last Completed Work Order				
6 MONTHS	1	2014/07/08; 517159; Inspection & QC (CCTV MAIN)				
Crew Comments						
Note that Hansen shows this Work Order as already completed						
Work Completed Date: 2014/07/08			Print Name:	Crew ID:		

Work Slip

SAP Charge #	Address & Location: 3500 - 3599 HULL ST COVAV			Responsible		
EES924407				Sewer Operations		
Work Order #	Work Order Activity			Created Date		
924407	Maintenance(3500 Blk of Hull St Plg Mn)			2017/11/22		
Group Project #	Problem	Sub Activity	Assigned To	Crew ID		
	SBlock	SCUT	ALBANO LUIS			
Work Order Comments: 2017/11/21 Key/Kozak 3581 Hull St. Assist afternoon shift Sarazin, R/C main (5 hrs) Relieve plugged main and back up @ 3581 Hull St. Very heavy roots and solids found' Could only get R/C in 25.6 m from bottom M/H. Tried to R/C from top M/H. Could only get R/C in 3.6 m. Got R/C stuck in main, ended up cutting the hose. Crew is returning Nov. 22, 2017. Complete. H.O. 2017/11/21 Key/Kozak 3500 Hull St. 81.4-81.7 m, R/C main. Roots and solids. Not complete. H.O. 2017/11/22 Key/Kozak R/C main - extremely heavy roots & grease got R/C stuck in top m/h @ 2m, used C1316 Neves crew to						
Reference #1	EES923382 <i>↑ See next page ↑</i>			Billable?		
Reference #2				N		
Collection Agency		Collection Method	Zone	Beat		
Service Request #	R1216290 (Sewage Backup/Flooding)					
Contact Name		Contact Phone	Contact Type			
s.22(1)		s.22(1)	s.22(1)			
Asset Type	Asset ID #	B.U.N	Status	Asset Area	Map # (Facet)	District
Main (C)	410914		IN_SERVICE	CBC10	T15	1
Asset Details: C 200 Millimeter VC 81.68 Meters 7.31% [81.68-200.0 C VC 7.31% 1930];[81.7 - 200 C 7.31% 1930];						
Safety & Asset Notes:						
PM Schedule	Maint. Schedule	Last Completed Work Order				
6 MONTHS	1	2017/11/24; 924407; Maintenance (3500 Blk of Hull St Plg Mn)				
Crew Comments						
Note that Hansen shows this Work Order as already completed						
Work Completed Date: 2017/11/24			Print Name:		Crew ID:	

3500 Hull – Plugged Main Report 2017

(Notes from last work order 924407 was not showing complete comments – copied from w/o report)

2017/11/21 Key/Kozak 3581 Hull St. Assist afternoon shift Sarazin, R/C main (5 hrs) Relieve plugged main and back up @ 3581 Hull St. Very heavy roots and solids found' Could only get R/C in 25.6 m from bottom M/H. Tried to R/C from top M/H. Could only get R/C in 3.6 m. Got R/C stuck in main, ended up cutting the hose. Crew is returning Nov. 22, 2017. Complete. H.O.

2017/11/21 Key/Kozak 3500 Hull St. 81.4-81.7 m, R/C main. Roots and solids. Not complete. H.O.

2017/11/22 Key/Kozak R/C main - extremely heavy roots & grease got R/C stuck in top m/h @ 2m, used C1316 Neves crew to free cutter. got R/C also stuck @ about 26m from bottom m/h need to use C1316 to free cutter. Very heavy root masses in this main needs to have CCTV inspection complete kl

2017/11/23 Key/Kozak could only get R/C in 73.7m from bottom m/h, and 2.7m from top m/h. Extremely heavy root masses got R/C stuck 26m from bottom m/h, used C1316 Neves to free R/C main needs to be CCTV/d not complete kl

2017/11/24 Uncao/Taylor were able to clear the bench of roots in top m/h 81.7 & main is also clear complete kl

2017/11/27 Created 6 month cleaning (Root-cut) schedule #25411 kl

Report Printed from OMS Program

No.	From	To	Street Name	Area	Cross Street	Task	WO #	Crew	Last	First	Tel	Flags	Completed	Place Name	Task Status	Task Priority	Remedy Name	Trouble Name	Facility Type	Footage (m)
109746	3500	0	HULL ST		E 20TH AV	Rodding (A1300)	50000470	1330				- - -	14-Aug-2001		Completed	As Scheduled	Rodded	Solids	Combined Main	81.38
305159	3570	0	HULL ST			Inspection	50000478	1317	s.22(1)		s.22(1)	- - -	23-Apr-2003		Completed	As Scheduled	Cleared	No Trouble Found	Combined Main	81.69
504459	3570	0	HULL ST			Inspection	50015503	C1315				- S -	14-Jun-2005		Completed	As Scheduled	Cleared	No Trouble Found	Combined Main	29.00
605487	3570	0	HULL ST		E 20TH AV	Inspection	50015503	C1315				- S -	30-Jun-2006		Completed	As Scheduled	Cleared	No Trouble Found	Combined Main	81.70
704684	3570	0	HULL ST		E 20TH AV	Inspection	50015503	B1979				- S -	13-Nov-2007		Completed	As Scheduled	Cleared	No Trouble Found	Combined Main	8.84
805630	3570	0	HULL ST		E 20TH AV	Inspection	50015503	A1341				- S -	08-Jul-2008		Completed	As Scheduled	Cleared	No Trouble Found	Combined Main	81.70
9700871	3500	0	HULL ST		E 20TH AV	Rodding (A1300)	EDM10002	1330				- - -	23-Jan-1997		Completed	As Scheduled	Cutter	Roots	Combined Main	81.69