


File No. 04-1000-20-2016-230

July 13, 2016



Re: Request for Access to Records under the Freedom of Information and Protection of Privacy Act (the "Act")

I am responding to your request of June 21, 2016 for:

The following information in regards to uneven sidewalk repair order file #7532606 for 2837 East 54th Avenue, Vancouver:

- 1. The time and date that the call was made to report the condition of the sidewalk;
- 2. Was the call was made by resident or other individual;
- 3. The date and time of repair;
- 4. Particulars of findings including copies of photos regarding the sidewalk condition.

All responsive records are attached. Some information in the records has been severed, (blacked out), under s.22(1) of the Act. You can read or download this section here: http://www.bclaws.ca/EPLibraries/bclaws_new/document/ID/freeside/96165_00

Under section 52 of the Act you may ask the Information & Privacy Commissioner to review any matter related to the City's response to your request. The Act allows you 30 business days from the date you receive this notice to request a review by writing to: Office of the Information & Privacy Commissioner, <u>info@oipc.bc.ca</u> or by phoning 250-387-5629.

If you request a review, please provide the Commissioner's office with: 1) the request number assigned to your request (#04-1000-20-2016-230); 2) a copy of this letter; 3) a copy of your original request for information sent to the City of Vancouver; and 4) detailed reasons or grounds on which you are seeking the review.

Please do not hesitate to contact the Freedom of Information Office at <u>foi@vancouver.ca</u> if you have any questions.

Yours truly,

Barbara J. Van Fraassen, BA Director, Access to Information City Clerk's Department, City of Vancouver Email: <u>Barbara.vanfraassen@vancouver.ca</u> Telephone: 604.873.7999

Encl.

:jb

.



INTOR HANSENS

2016/07/04 12:05

Service Request # R	941804
Lagan's ECM Update	MajorLog
Request Type	RSideWalkRepair Sidewa k - Repair
Sub Type	Sidewa kUneven
Incident Date	2016/04/13 16:34
Call Date	Last 311 Update, where applicable 2016/04/04 16:12
Crew Assign Date	2016/04/05 07:09
Request Date Crew ID	2016/04/04 16:14
	2016/04/05 07:09
Crew Contact	5420 MARCO BIAGINI
Reviewed	yes
Initiated By	
Follow-Up Date	
Charges Explained	no

Information

4
Medium
RO
Streets C
1010075
2016/04/
lagan

ledium O treets Operations 01007532606 016/04/07 16:12

Request Location

toquoot Looutio	
Parcel ID Lane	Asset
Property ID GPS X	0.0000
GPS X GPS Y	
Location	A BA MAN LATING M
Street # Pre Dir	2837
Street Name	E 54TH AV
Suffix	(MA)
Post Dir	
Subdesignation	Address
Cross Street	
Cross Street	
City, Province, Postal Code	Vancouver
	BC
Location	

(No Data)		5		
# Ta Customer	Duration of Calls aken By Contact quested istomer Service rogress	00:00:00 0 yes no 1		
Other C No Data)	alls			
Contact	Name First, MI Title Foreign Address City /Province	s.22(1) no		
Conta	ZIP/PC Country act Phone te Phone Fax Pager	s.22(1)		
	PIN			
Con	PIN E-mail tact Type	Other		
	E-mail tact Type			
Custom	E-mail tact Type er Com	ments		
Custom spection In Sci	E-mail tact Type er Com er Com <u>n</u> spector beduled Due By Started Due By mpleted Due By	5420 MARCO BIAGINI		
Custom spection In Sci Cor R	E-mail tact Type er Com er Com n spector heduled Due By Started Due By soluted Due By esolved Due By solution	5420		
Custom spection In Sci Cor Re Re Service	E-mail tact Type er Com er Com spector heduled Due By Started Due By esolved Due By esolved Due By solution	5420 MARCO BIAGINI 2016/04/05 00:00 39		
Service No Data)	E-mail tact Type er Com spector heduled Due By Started Due By esolved Due By solution Reque	5420 MARCO BIAGINI 2016/04/05 00:00 39 Dispatched to Crew 1		
Service No Data)	E-mail tact Type er Com er Com n spector heduled Due By Started Due By solved Due By solved Due By solution	5420 MARCO BIAGINI 2016/04/05 00:00 39 Dispatched to Crew 1 st Inspections		
Custome spection In Sci Con Re Con Re Service No Data) Dg Service Log	E-mail tact Type er Com spector heduled Due By Started Due By esolved Due By esolved Due By solution Reque Reque Entere	5420 MARCO BIAGINI 2016/04/05 00:00 39 Dispatched to Crew 1 st Inspections 1 st Log Results rd Entered By	Start Date	To Comments
Custome spection In Sci Con Re Service No Data) Dg Service	E-mail tact Type er Com spector heduled Due By Started Due By esolved Due By solution Reque	5420 MARCO BIAGINI 2016/04/05 00:00 39 Dispatched to Crew 1 st Inspections 1 st Log Results	Start Date	To Comments Apr 5/16 - Referred to M. Biagini. Apr 5/16 - Referred to M. Biagini. Apr 5/16 - Went to site, took photo. Will forward to Crew 71 to repair trip hazard M.

Attachments					
Attachments (No Data)					
Associations					
	1				
	1				ï
Linked Servi (No Data)	ce Requ	ests			
Associated V	Vork Or	ders			
Work Order # 735393	Milestone	Activity Schedule Date Completed Date Asset Unit RSwReact 2016/04/06 00:00 Sidewalk 99944	ID		
Associated A (No Data)	Asset Ins	spections			
Associated ((No Data)	Cases				
Request Deta	ils				
Schedules	4				
2	1 1				
Employees (No Data)					
Fleet Equipn	nent				
Plant Equipn (No Data)	nent				
Vehicles (No Data)					
Audit Log					
Audit Log					
Audit Log	1				
	Audit	Normal Lawr	Old	User	Audit
Field Name	Date Time	New Value	Value	ID	Catagory
Inspector	2016/04/05 07 09	5420		TYLER F ELD	Hansen
Review Date	2016/04/05 07 09	05/04/2016 7:09:00 AM	01/01/0001 12 00 00 AM	TYLER F ELD	Hansen
Resolved	2016/04/06 12:42	True	False	TYLER F ELD	Hansen
ResolutionDateTime	2016/04/13 16 34	True	False	Integration	MCloseCase
LaganEForm	2016/04/13 16 34			Integration	IEFormPage
	2016/04/13	(AVLM2, Apr 13 2016 4:33PM) S.22(1) called and asked speak to Risk Management. She said it was in regards to a tripping incident on a City	0		

1.21					
LaganCaseDetails	16:34	sidewalk - she broke her leg. Incident occurred on April 4th, just before 4pm in this location, on the north side of 2800 blk E 5		Integration	MCaseNotes
IncidentDate	2016/04/13 16:34	13/04/2016 4:34 24 PM	04/04/2016 4:14:00 PM	Integration	IIncidDate
ResolutionDateTime	2016/04/13 16:34	True	False	Integration	MCloseCase
IncidentDate	2016/04/13 16:34	13/04/2016 4:34 34 PM	13/04/2016 4 34:24 PM	Integration	IIncidDate
agan eForm.					
Lagan Detail					
		eForm e of sidewalk problem: Uneven			
	2. If Ot	her, provide details:			
	3. Is th	ere a black patch on it? No			
	4. Is it	safe? No			
	an une Ave th	cribe issue in detail (in front of, beside, side of street, etc.): Citize even portion of the sidewalk in between 2837 East 54th Ave a lat is sticking up around an inch or more. She witnessed ano It seems like the panel is separated and uneven an inch from	nd 2857 Eas	t 54th Ial trip	
	6. Is th	is request due to Motor Vehicle Accident? No			
	7. If Ye	es, provide details on license plate number or other details (if know	wn):		
	8. (Doi	n't ask just record - Did caller indicate they want a call back?) No			
	(AV to Risk broke of 280	Case Details LM2, Apr 13 2016 4:33PM) s.22(1) call call call call call call call call	ation, on the r	a k - she orth side	

Wagon Location	National Y	ard					A/A				
5	Stree	ets Operation	s Dail	y Cre	w Repo	ort	Rev.				
Apr	1 06, 2016	SA18 AD9 . 8		/			Wo	rk ord	er#a	nd Ho	urs
Crew #	71	9	/	1.1	Maria	~	1	2	3	4	5
Field Supervisor		604-619-2057	71	A	(signed)	4	3	-0-			
26 			/	9	12		ER 068959	17			
Superintendent	Warco Dia	igini Z	$ \leq $	5//	61 Ø		0	EERD 6897			
1997). (States) a	-		0.	V	(signed)		2	09			
Hours of Work	/	00 AM - 3.	30 PM		D 0 1		E	ER'			
	nployee	Equip #	Activity Type	A/Abs/Stat Code	Pay Scale Group	Prem Code	5	3			
s.22(1) F. Paw	elchak			6000			7	(
F. Cap	pellano			6000			7	1			
T. Faria	3	C1297		6000			2	1			
							† ·	-			
										-	
								-	-		
			_								
	Equipment	Name		Equip	ment ID		Runni	ng Hrs	5		
ANGLE GRINDE	R 4.5, CORDL	ESS	X-ST90	019			17	1			
DRILL & DRIVE	SET		X-ST90	020			7	1			
DRILL, HAMMER			X-ST30				7	(
SAW, RECIPRO			X-ST80			_	7	1	-		
SKIL SAW, COR	and the second se		X-ST20	CONTRACTOR				1			
TRUCK, DUMP,	TAKD		C1297				7	<u> </u>			
Toilets							+			-	
Flashers	0	- 164 <u>0 - 1640 - 16600 - 16600 - 16600 - 1660 - 16600 - 1660 - 1660 - 1660 - 1660 - 16</u>			ne de						
Dumps (National	Yards Only)		Yrds D	umped			1				

pg. 1 of 2

pril 06, 2016 ocation 1	Crew # 71		/isor Mezzomo			
	EERV68	Field Super	Material	Superintendent Amount	Marco Biagini Comments	
34178						
	(<u>{20)</u> 90 ((-(2)90		25		P1#	
4182	$\frac{(1-(2))}{(1-(2))}$		2]			
14180	9(25)9	3/1//-	50			
•						
		1				
			Dump:	Location:		
n safety when I	Departing Location:	Cones			L Denne L Fleets	
	reparting Location.	Cones	Snow Fence	ape Barricad	e Ramps Flashe	
nage Used:						By: (Initias)
tivity Code			Units Completed		Measurement	
cation 2	EERO 68	979	Material	Amount	Comments	
74180	(1-1)				SIW Tr	P
14.00	$\gamma = (1)$				JIW IT	
					· · · · · · · · · · · · · · · · · · ·	
•						
						· · · · ·
	·····					
				andian		
			Dump:	Location:		
	Departing Location:	Cones	Snow Fence T	ape Barricad	e Ramps Flashe	
gnage Used:		—				By: (Initials)
tivity Code			Units Completed		Measurement	
cation 3			Material	Amount	Comments	
						· · · · · · · · · · · · · · · · · · ·
•						
,						
						· · · · · · · · · · · · · · · · · · ·
		-1				
						•
			Dump:	Location:		
an acfatuuban T	Departing Location:	Cones			Elseh	ers Delineators
	repairing Location.	Corres	Snow Fence	ape Barricad	e Ramps Flash	
gnage Used:						By: (Initials)
tivity Code						
livity ooue			Units Completed		Measurement	
			Units Completed Material	Amount	Measurement Comments	
			Material	Amount		
cation 4	Departing Location:	Cones	Material Material Dump:	Amount	Comments	ers Delineators
cation 4	Departing Location:	Cones	Material	Amount Amount	Comments	
n safety when I	Departing Location:	Cones	Material Material Dump: Snow Fence	Amount	Comments	ers Delineators By: (Initials)
In safety when I Inage Used: tivity Code	Departing Location:	Cones	Material Material Dump: Dump: Units Completed	Amount Amount	Comments	
n safety when I nage Used: tivity Code	Departing Location:	Cones	Material Material Dump: Snow Fence	Amount	Comments	
n safety when I nage Used:	Departing Location:	Cones	Material Material Dump: Dump: Units Completed	Amount Amount	Comments	
n safety when I nage Used: tivity Code	Departing Location:	Cones	Material Material Dump: Dump: Units Completed	Amount Amount	Comments	
In safety when I Inage Used: tivity Code	Departing Location:	Cones	Material Material Dump: Dump: Units Completed	Amount Amount	Comments	
cation 4 gn safety when I gnage Used: tivity Code	Departing Location:	Cones	Material Material Dump: Dump: Units Completed	Amount Amount	Comments	
gn safety when I gnage Used: ctivity Code	Departing Location:	Cones	Material Material Dump: Dump: Units Completed	Amount Amount	Comments	
ocation 4	Departing Location:	Cones	Material Material Dump: Dump: Units Completed	Amount Amount	Comments	
gn safety when I gnage Used: ctivity Code	Departing Location:	Cones	Material Material Dump: Dump: Units Completed	Amount Amount	Comments	
gn safety when I gnage Used: ctivity Code	Departing Location:	Cones	Material Material Dump: Dump: Units Completed	Amount Amount	Comments	
gn safety when I gnage Used: ctivity Code	Departing Location:	Cones	Material Material Dump: Dump: Units Completed	Amount Amount	Comments	
gn safety when I gnage Used: ctivity Code	Departing Location:	Cones	Material Material Dump: Dump: Dump: Units Completed Material	Amount Am	Comments	
gn safety when I gnage Used: protectivity Code protection 5		Cones	Material Material Dump: Snow Fence Units Completed Material Dump: Dump: Dump: Dump: Dump:	Amount Amount Amount Amount Amount Amount Location: Amount Amount Location: Amount Location:	Comments Comments Ramps Flash Keasurement Comments	By: (Initials)
in safety when I inage Used: tivity Code cation 5	Departing Location:	Cones	Material Material Dump: Snow Fence Units Completed Material Dump: Dump: Dump: Dump:	Amount Am	Comments Comments Ramps Flash Keasurement Comments	By: (Initials)

Work Order Summary



Work Order #: Asset ID #:	735393 99944	Rsw_Flt_NM 71-2016/4-6		Asphalt Fillet - Sidew	valk
Group Project #:		Rsw_Flt_NM 71-2016/4-6 H AV		Streets Operations	
Operational Statu Service Request: Requested By:	ıs:	Ref #1: : Contact Name: Requested Date	s.22(1) :	Ref #2: Phone#: Initiated Date:	Apr 26, 2016
Assigned Date:	MARCO BIAGINI Apr 06, 2016 Completed Sidewalk Fillet - Non Accomplishment: RS	Assigned To: TONY FAR Crew ID: RMS71 MRN - Crew 71 - April to June wAsFlt		Work Started: Work Completed:	Apr 06, 2016

Work Orders & Accomplishments:

WO#	Result	Completed Date					
735393	Completed	Apr 06, 2016					
Accomplish	nment Date	Description	Quantity	Truck#	Assigned To		Comments
Apr 06	, 2016	Asphalt Fillet - Sidewalk	1	RMS71	TONY FARIA	TF	

Work Area Prefix: R

SAP Network #: EERD70455 Billable: N WBS#: EER-00009-SF-NM-AP

Parent Network:

Cost Summary Estimated Costs Actual Costs Difference Equipment \$0.00 \$0.00 \$0.00 Labour \$0.00 \$0.00 \$0.00 Material \$0.00 \$0.00 \$0.00 Other \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 TOTAL \$0.00 \$0.00 \$0.00



Work Order Summary