



Violation #54





s.22(1) Walls - unfinished drywall repair.

Violation #54



4<sup>th</sup> floor South side (SW) Shower Room: ineffective door lock.

Violation #55



Photo	Description
	2 <sup>nd</sup> floor North side Shower Room: paint on tiles in shower stall. Violation #59
	2 <sup>nd</sup> floor South side Toilet Room: ineffective door lock.  Violation #60



Photo

#### Description

1<sup>st</sup> floor North side Shower Room: damaged walls and peeling paint.

Violation #61



1<sup>st</sup> floor South side Shower Room: dirty upper tile area of shower.

Violation #62



CF Numb	er (	CF-2017-007589	Date of Inspection (yyyy/mm/c	2018/01/30 2018/01/29	
Main Add	lress	917 MAIN STREET, Vancouver, BC		tes and common areas h outstanding violations	
Tenant	Cob	alt Hotel	Number of Storeys 5 + Bas	ement	
Owner	NORTHSTAR INTERNATIONAL MOTOR HOTEL LTD 6626 ANGUS DR VANCOUVER BC V6P 5H9		Permit Number		
Agent	Dar	shan Punia (Manager)	Approved Use of Building/Land	SRA Hotel	
District Z	one	FC-1	Present Use of Building/Land	SRA Hotel	
Business	Licen	se HL-2018-446897			

Reason for Inspection

Recheck of Order dated December 20, 2017

#### Narrative/Observations

January 29 and 30: I conducted a recheck at 1:00 PM of the 62 outstanding violations. Ranjeeva (Ron) Samaranayake, Stanley Michael, Darshan Punia (Manager), and Gudy Sahota were present. Of the 62 outstanding violations, 57 have been corrected.

The following 5 violations remain outstanding:

- 1) \$.22(1) Walls/ceiling remains dirty/unpainted.
- Floor deflection under the carpet has not been repaired.
- Carpet remains damaged and dirty. Photo #1
- Walls and ceiling repairs remain incomplete. Photo #2
- Wall repairs have been completed; however, there is evidence of new water damage to the walls and ceiling. Therefore, the source of the water leak has not been located and the repair has not been completed to satisfaction. Photo #3

<u>NOTE</u>: The tenants in \$.22(1) have been uncooperative in allowing access for the repairs to be done. Cobalt manager Darshan Punia has issued breach letters to the tenants of \$.22(1)

NOTE: The tenant in \$.22( has been relocated to \$.22( on January 30th to facilitate investigation and provide repairs to \$.22(1)

NOTE: The tenant in \$.22( was present and not cooperative so I was unable to take photos.

Further to the required repairs to correct the outstanding violations, voluntary work has been completed to remove the carpets in the hallways and refinish the floors on the 2<sup>nd</sup>-4<sup>th</sup> floors, and to repair and paint walls and trimwork in the hallways on the 1<sup>st</sup>-4<sup>th</sup> floors. The common toilet rooms and shower rooms continue to be maintained in good condition.

Requirements		
Violation of Standards of Maintenance By-law 54	62 Section 21.10	
Recommendations		
Refer for prosecution		
Photos Taken?		
Date Report Made: January 30, 2018	Mike Elliston	
97.1 L <u>. 101. 10</u>	Inspector's Name	

Violation Details	
Violation Number:	Violation:
VI-2017-03442	s.22(1- Floors - floor has area of deflection under carpet
Violation Date:	Standards of Maintenance 5462 - Sec 4.1(12) & (13):
Aug 21, 2017	21.10 Every lodging house owner shall at all times keep or maintain the lodging house:
Violation Type:	(a) in a thoroughly clean and sanitary condition, including windows and
Standards of	lightwells;
Maintenance By-Law No.	(b) free of pests, including insects and rodents;
5462	(c) fixtures and appliances in good working order and repair;
Resolve By:	(d) floors, stairs, doors, walls and windows in good working order and repair; (e) heating system in good working order and repair; and
Resolve by.	(f) sinks, toilets and bathing fixtures in good working order and repair.
Violation Status:	Violation Instructions:
Violation Number:	Violation:
VI-2017-03462	s.22(1) Walls/ceiling - dirty and peeling paint
Violation Date:	Standards of Maintenance By-law 5462 - Sec 21.10:
Jun 27, 2017	21.10 Every lodging house owner shall at all times keep or maintain the lodging house:
Violation Type:	(a) in a thoroughly clean and sanitary condition, including windows and
Standards of	lightwells;
Maintenance By-Law No.	(b) free of pests, including insects and rodents;
5462	(c) fixtures and appliances in good working order and repair;
	(d) floors, stairs, doors, walls and windows in good working order and repair;
Resolve By:	(e) heating system in good working order and repair; and
National State of the State of	(f) sinks, toilets and bathing fixtures in good working order and repair.
Violation Status:	Violation Instructions:

Violation Number:	Violation:
VI-2017-03454	s.22(1) Carpets - damaged and dirty
VI-2017-03434	3.22(1) Carpets - damaged and dirty
Violeties Deter	Chandrade of Maintanana Bulance E4/2 Con 24 40
Violation Date:	Standards of Maintenance By-law 5462 - Sec 21.10:
Jun 27, 2017	21.10 Every lodging house owner shall at all times keep or maintain the
	lodging house:
Violation Type:	(a) in a thoroughly clean and sanitary condition, including windows and
Standards of	lightwells;
Maintenance By-Law No.	(b) free of pests, including insects and rodents;
5462	(c) fixtures and appliances in good working order and repair;
	(d) floors, stairs, doors, walls and windows in good working order and repair;
Resolve By:	(e) heating system in good working order and repair; and
Resolve by.	(f) sinks, toilets and bathing fixtures in good working order and repair.
	(1) sinks, tollers and pathing fixtures in good working order and repair.
Violation Status:	Violation Instructions:
Violation Number:	Violation:
VI-2017-03458	s.22(1) Walls/ceiling - unfinished drywall repair
Violation Date:	Standards of Maintenance By-law 5462 - Sec 21.10:
Sep 26, 2017	21.10 Every lodging house owner shall at all times keep or maintain the
	lodging house:
Violation Type:	(a) in a thoroughly clean and sanitary condition, including windows and
Standards of	lightwells;
Maintenance By-Law No.	(b) free of pests, including insects and rodents;
5462	(c) fixtures and appliances in good working order and repair;
3 102	(d) floors, stairs, doors, walls and windows in good working order and repair;
Resolve By:	(e) heating system in good working order and repair; and
Resolve by.	(f) sinks, toilets and bathing fixtures in good working order and repair.
	(1) silks, tollets and patining fixtures in good working order and repair.
Violation Status:	Violation Instructions:
Violation Status.	Violation instructions,
Violation Number:	Violation:
VI-2017-05070	s.22(1) Walls - water damaged, drywall missing
V1-2017-030/0	walls - water damaged, drywall fillssing
Violation Date:	Standards of Maintonanco By Jaw 5462 Soc 24 40:
	Standards of Maintenance By-law 5462 - Sec 21.10:
Jun 27, 2017	21.10 Every lodging house owner shall at all times keep or maintain the
Violeties Torrer	lodging house:
Violation Type:	(a) in a thoroughly clean and sanitary condition, including windows and
Standards of	lightwells;
Maintenance By-Law No.	(b) free of pests, including insects and rodents;
5462	(c) fixtures and appliances in good working order and repair;
	(d) floors, stairs, doors, walls and windows in good working order and repair;
Resolve By:	(e) heating system in good working order and repair; and
	(f) sinks, toilets and bathing fixtures in good working order and repair.
Violation Status:	Violation Instructions:
<del></del>	




Photo	Description
	S.22(1) View of walls and ceiling showing repaired drywall has again been water damaged.



CF Numb	er C	F-2018-002	836		Date of Inspection (yyyy/	/mm/dd)	2018/03/09
Main Add	iress	917 MAIN	STREET, V	ancouver, BC	Specifics and/or Suite #		Cabaret Pub
Tenant	Coba	alt Hotel /	Cobalt Cal	paret Pub	Number of Storeys		
Owner NORTHSTAR INTERNATIONAL MOTOR HOTEL LTD 6626 ANGUS DR VANCOUVER BC V6P 5H9		Permit Number					
Agent Darshan Punia, manager		Approved Use of Building/Land SRA Hotel/ Cabaret Pub					
District Zone FC-1  Business License HL-2018-446897		Present Use of Building/Land SRA Hotel/ Cabaret Pub					
Business	Licens	- 112 20	18-446897 18-451321				
Reason fo	or Insp	ection E	mail comp	laint			
stage in overflow Today di showed Cabaret inspection	the pring raisigns of Pub a on of t	oub. He control  Terry unclo  Terry inspection  Terry inspection	hecked roo gged the d ion I check verflow wi tage has w and did no	om s.22(1)  Irain with a snake a  ked the sinks in ro- ith a wet floor; the vater-damaged dry- ot see any indication	e floor has been mopped wall. I left the sink tap in on of new water on the ce	on the si on the fl s.22( n 1) w I up Th n s.22(1 <sub>tt</sub> eiling.	nk in room \$.22(1 to be loor of \$.22(1)  as okay but Room \$.22(1)  ne ceiling in the Cobalt
Requiren	nents						
Violation	of St	andards of	Maintenan	ice Bylaw 5462 Sec	tions 14.1 and 16.1		
Recomme	endatio	ons					
14-day o	order t	o R/O to re	pair leak a	and associated wat	er damage		
Photos To			□ No	8	Mike Elliston		
		- 2			Inspector's Name		

Violation Details	
Violation Number:	Violation:
VI-2018-01729	Water-damaged ceiling in the Cobalt Cabaret Pub above the stage.
Violation Date:	Standards of Maintenance By-law 5462 Section 14.1:
Mar 09, 2018	(1) Interior walls and ceilings shall be maintained in good repair and free
The state of the s	from holes, or loose or broken plaster that may create health, fire or
Violation Type:	accident hazards.
Standards of	(2) Surfaces of interior walls and ceilings shall be maintained in a clean and
Maintenance By-Law No.	sanitary condition and plumb within limits acceptable to the City Building
5462	Inspector.
Resolve By:	Violation Instructions:
~	14-day order to R/O to provide repairs to water-damaged ceiling.
Violation Status:	
VI I I VI I	
Violation Number:	Violation:
VI-2018-01744	Water leak presenting at the ceiling above the Cobalt Cabaret Pub stage.
Violation Date:	Standards of Maintenance By-law 5462 Section 16.1:
Mar 09, 2018	(1) All plumbing, including plumbing fixtures, drains, vents, waterpipes,
2000 Q 100 100 X	water closets and connecting lines to the water and sewer systems, shall be
Violation Type:	maintained in good working order and repair, free from leaks or other
Standards of	defects and protected from freezing.
Maintenance By-Law No.	(2) Every hand basin and bathtub, shower and sink shall have an adequate
5462	supply of hot and cold running water and every water closet shall have - 9 -
Resolve By:	an adequate supply of running water. Hot water shall be supplied at a minimum temperature of 120?F (49?C) and a maximum of 140?F (60?C).
Resolve by.	(3) Every room containing a toilet shall have a hand basin located in the
	room, or in an immediately adjoining room.
Violation Status:	(4) All bathing units shall be fully enclosed so as to provide privacy for an
	occupant.
	(5) Rooms containing sanitary facilities shall be maintained in a clean and
	sanitary condition and provided with a smooth surface reasonably impervious
	to water or chipping or cracking on the walls and ceilings.
	(6) Where an existing plumbing system appears to be in good repair, special attention shall be given to:
	(a) prevention of cross-connections between potable water supply and
	washing machine drains, hot water heating lines and any other non-potable water uses.
	(b) removal of unused grease traps,
	(c) cleaning out of sumps, and providing backwater valves,
	(d) providing cleanouts to all drains,
	(e) cleaning out all waste traps,
	(f) replacing damaged waste arms,
	(g) extending all plumbing drain vents to the exterior, and
	(h) capping off all unused pipes and drains that may create a health hazard.
	Violation Instructions:
	14-day order to R/O to locate source of leak and provide repairs.

Photo	Description
	Water-damage drywall on ceiling above the Cobalt Cabaret stage.
ROCA	Room s.22(1) Water turned on full, sink is draining.



CF Number	er CF	-2018-003144	Date of Inspection (yyyy/mm/dd)	2018/03/16	
Main Add	ress	917 MAIN STREET, Vancouver, BC	Specifics and/or Suite # Comm	non areas	
Tenant Cobalt Hotel			Number of Storeys 5 + basem	ent	
Owner NORTHSTAR INTERNATIONAL MOTOR HOTEL LTD 6626 ANGUS DR VANCOUVER BC V6P 5H9		L LTD Angus dr	Permit Number		
Agent Darshan Punia, manager		an Punia, manager	Approved Use of Building/Land	SRA Hotel	
District Zone FC-1		FC-1	Present Use of Building/Land	SRA Hotel	
Business I	License	HL-2018-446897			
Reason fo	r Inspec	ction Routine inspection			
- A	and ceil oilet ro	common washroom area: Water-daing and walls in the common corrido ooms. Both toilet rooms remain oper electrical cover plate in 1 <sup>st</sup> floor sour common corridor: Water-damage o	<ul> <li>The ceiling has been completely n for use.</li> <li>th toilet room.</li> </ul>	removed in one of the	
Requirem	ents				
Violation	of Star	ndards of Maintenance By-law 5462 -	Sec 21.10 (c) & (d)		
Recomme	ndation	s			
14-day or	rder to	R/O			
Photos Ta	ken?	☑ Yes ☐ No			
Date Repo	ort Made	e: March 19, 2018	Mike Elliston		
			Inspector's Name		


Violation Details	
Violation Number:	Violation:
VI-2018-01879	CARTERIA DE LA CARTE DE LA CAR
VI-2018-01879	1st floor Bathroom - Electrical - cover plate missing
Violation Date:	Standards of Maintenance By Jaw 5462 Sec 24 40:
Mar 16, 2018	Standards of Maintenance By-law 5462 - Sec 21.10:
Mar 16, 2016	21.10 Every lodging house owner shall at all times keep or maintain the
W. L. C T	lodging house:
Violation Type:	(a) in a thoroughly clean and sanitary condition, including windows and
Standards of	lightwells;
Maintenance By-Law No.	(b) free of pests, including insects and rodents;
5462	(c) fixtures and appliances in good working order and repair;
2 7 2	(d) floors, stairs, doors, walls and windows in good working order and repair;
Resolve By:	(e) heating system in good working order and repair; and
	(f) sinks, toilets and bathing fixtures in good working order and repair.
GAS IN THE CONTROL OF	STATES OF A STATE OF THE STATE
Violation Status:	Violation Instructions:
	14-day order to R/O
	ALC:
Violation Number:	Violation:
VI-2018-01883	1st floor North Bathroom - water-damaged walls and ceiling
Violation Date:	Standards of Maintenance By-law 5462 - Sec 21.10:
Mar 16, 2018	21.10 Every lodging house owner shall at all times keep or maintain the
2000	lodging house:
Violation Type:	(a) in a thoroughly clean and sanitary condition, including windows and
Standards of	lightwells;
Maintenance By-Law No.	(b) free of pests, including insects and rodents;
5462	(c) fixtures and appliances in good working order and repair;
	(d) floors, stairs, doors, walls and windows in good working order and repair;
Resolve By:	(e) heating system in good working order and repair; and
Service Control of the Park Service Control of the Service Control o	(f) sinks, toilets and bathing fixtures in good working order and repair.
	The Contraction of Contraction Contraction of Contr
Violation Status:	Violation Instructions:
	14-day order to R/O to locate source of leak and repair
	THE CHIEF STREET
Violation Number:	Violation:
VI-2018-01880	1st floor South Bathroom - water-damaged walls and ceiling
Violation Date:	Standards of Maintenance By-law 5462 - Sec 21.10:
Mar 16, 2018	21.10 Every lodging house owner shall at all times keep or maintain the
,	lodging house:
Violation Type:	(a) in a thoroughly clean and sanitary condition, including windows and
Standards of	lightwells;
Maintenance By-Law No.	(b) free of pests, including insects and rodents;
5462	(c) fixtures and appliances in good working order and repair;
	(d) floors, stairs, doors, walls and windows in good working order and repair;
Resolve By:	(e) heating system in good working order and repair; and
	(f) sinks, toilets and bathing fixtures in good working order and repair.
Violation Status:	Violation Instructions:
Violation Status:	
	14-day order to R/O to locate source of leak and repair

Violation Number:	Violation:
VI-2018-01882	1st floor hallway - water-damaged walls and ceiling
Violation Date:	Standards of Maintenance By-law 5462 - Sec 21.10:
Mar 16, 2018	21.10 Every lodging house owner shall at all times keep or maintain the
Mai 10, 2010	lodging house:
Violation Type:	(a) in a thoroughly clean and sanitary condition, including windows and
Standards of	lightwells;
Maintenance By-Law No.	(b) free of pests, including insects and rodents;
5462	(c) fixtures and appliances in good working order and repair;
	(d) floors, stairs, doors, walls and windows in good working order and repair;
Resolve By:	(e) heating system in good working order and repair; and
	(f) sinks, toilets and bathing fixtures in good working order and repair.
Violation Status:	Violation Instructions:
	14-day order to R/O to locate source of leak and repair
Violation Number:	Violation:
VI-2018-01884	4th floor hallway ceiling - water-damaged ceiling
Violation Date:	Standards of Maintenance By-law 5462 - Sec 21.10:
Mar 16, 2018	21.10 Every lodging house owner shall at all times keep or maintain the
	lodging house:
Violation Type:	(a) in a thoroughly clean and sanitary condition, including windows and
Standards of	lightwells;
Maintenance By-Law No.	(b) free of pests, including insects and rodents;
5462	(c) fixtures and appliances in good working order and repair;
	(d) floors, stairs, doors, walls and windows in good working order and repair;
Decelve Du	(e) heating system in good working order and repair; and
Resolve by:	
Resolve By:	(f) sinks, toilets and bathing fixtures in good working order and repair.
	(f) sinks, toilets and bathing fixtures in good working order and repair.
Violation Status:	(f) sinks, toilets and bathing fixtures in good working order and repair.  Violation Instructions:
	(f) sinks, toilets and bathing fixtures in good working order and repair.

Photo	Description
	1st floor Bathroom - Electrical - cover plate missing
	1st floor North Bathroom - water-damaged walls and ceiling; drywall removed from ceiling

Photo	Description
	1st floor South Bathroom - water-damaged walls and ceiling
	1st floor hallway - water-damaged walls and ceiling

Photo	Description
	1st floor hallway - water-damaged walls and ceiling
	4th floor hallway - drywall removed from ceiling





CF Numb	er (	CF-2018-003117	Date of Inspection (yyyy/mm/dd)	2018/03/16
Main Add	iress	917 MAIN STREET, Vancouver, BC	Specifics and/or Suite # \$.22(1	)
Tenant	Cob	alt Hotel	Number of Storeys 5 + basen	nent
Owner	HO <sup>2</sup>	RTHSTAR INTERNATIONAL MOTOR TEL LTD 6 ANGUS DR NCOUVER BC V6P 5H9	Permit Number	
Agent	Dar	shan Punia, manager	Approved Use of Building/Land	SRA Hotel
District Z	one	FC-1	Present Use of Building/Land	SRA Hotel
Business	Licen	se HL-2018-446897		
Reason fo	or Insp	pection Routine inspection		
the smol	ke ala ests - lectri	rm is missing and an electrical cove bedbugs and roaches - Standards of	I see a number of bedbugs and roacher plate is missing.  Maintenance By-law 5462 - Sec 21.10 of Maintenance By-law 5462 - Sec 21	)(b)
		tandards of Maintenance By-Law No.	. 5462 Lodging House Maintenance Sec	ction 21.10(b) & (c)
14-day o	order i	ions to R/O to provide pest control servic to R/O to replace the electrical cove e the smoke alarm		
Photos T	aken?	☑ Yes □ No		
Date Rep	ort Ma	ade: March 16, 2018	Mike Elliston	

Violation Details	
Violation Number:	Violation:
VI-2018-01835	s.22(1) Electrical - cover plate missing
Violation Date:	Standards of Maintenance By-law 5462 - Sec 21.10:
Mar 16, 2018	21.10 Every lodging house owner shall at all times keep or maintain the lodging house:
Violation Type:	(a) in a thoroughly clean and sanitary condition, including windows and
Standards of	lightwells;
Maintenance By-Law No.	(b) free of pests, including insects and rodents;
5462	(c) fixtures and appliances in good working order and repair;
Resolve By:	(d) floors, stairs, doors, walls and windows in good working order and repair; (e) heating system in good working order and repair; and
Resolve by.	(f) sinks, toilets and bathing fixtures in good working order and repair.
Violation Status:	Violation Instructions:
10 2 2 2 10	14-day order to R/O
Violation Number:	Violation:
VI-2018-01834	s.22(1) Pests - bedbugs and roaches
Violation Date:	Standards of Maintenance By-law 5462 - Sec 21.10:
Mar 16, 2018	21.10 Every lodging house owner shall at all times keep or maintain the lodging house:
Violation Type:	(a) in a thoroughly clean and sanitary condition, including windows and
Standards of	lightwells;
Maintenance By-Law No.	(b) free of pests, including insects and rodents;
5462	(c) fixtures and appliances in good working order and repair;
	(d) floors, stairs, doors, walls and windows in good working order and repair;
Resolve By:	(e) heating system in good working order and repair; and
	(f) sinks, toilets and bathing fixtures in good working order and repair.
Violation Status:	Violation Instructions:
	14-day order to R/O

Photo	Description
	s.22(1) Electrical - cover plate missing  Photo 1
	s.22(1) Smoke alarm missing Photo 2

# 453 West 12<sup>th</sup> Avenue, Vancouver BC V5Y 1V4 tel: 604.873.7611

Tenant's Nam

Job Contact:

Address: Postal Code:

Address:

#### PLANNING AND DEVELOPMENT SERVICES **Development** and / or Mailing Address:

**Building** 

**Application Form** 

To help expedite submission of your application, please fill out BOTH sides of this information sheet prior to attending the Application located in the Development and Building Services Centre, Ground Floor, 515 West 10th Avenue (West Annex, City Hall). JOB LOCATION (Correct and complete addressing is important. Complete this section carefully.) Address: Floor Level: 9 Legal Description: Lot(s) Block(s) District Lot(s)\_ Plan Number(s) Are you aware of the presence of any contaminated soils on the subject property? ☐ Yes □No Are you aware of the existence of any contaminated soils studies, reports, soil agreements, or Ministry of Environment orders or letters with respect to the subject property? ☐ Yes □No Is the building being converted to strata-title ownership? ☐ Yes □No Note: If you intend to convert an existing building to strata title ownership, please contact Subdivision and Strata Title staff at 604.871.6627 for information on the strata conversion process in advance of the issuance of any permits. This area must be completed by the person signing the application form ECyou are the: 01 Property Owner Mailing Address: 02 Contractor 03 Certified Professional Postal Code: 04 Design Professional City: 05 Tenant E-mail Address: 06 Agent for Owner 07 Agent for Tenant Phone Number: 08 Consultant Non-profit Association Cert. No: Company Name: 10 Civic Department Business License Account Number: 98 Note: Contractors/design professionals/consultants <u>MUST</u> have a valid Business License to do work in the City of Vancouver. You may obtain current business license account numbers from the Business License Counter. Complete the following for ALL applications Property Owner's Name: City: Address: Phone Number: Postal Code: Is the owner aware of this application?, 🛮 Yes □ No Contractor's Name Address: City: Postal Code: Phone Number: Business License\_Account\_Number

City:

City:

Phone Number

Business License Account Number:

TY OF VANCOLIVER

COMMUNITY SERVICE !!

DEVELOPMENT SERVICE

F	
This application is to: (Check applicable boxes)  001  Construct a new building(s)	Is this a new tenant? Yes No
002 Add to an existing building	What is the existing use? Pub SRO What is the proposed use?
Add to a building and alter the existing portion	What is the proposed use?
004  Add to a building and alter the existing portion 005  Add to a building and change the use	How many storeys?
006 Add to the building, alter existing portion and change	
use 007 ☐ Interior/exterior alterations and change of use	How many levels of underground parking?
008 Enclose an area of an existing building (balcony	How many <u>new</u> rooftop units?
enclosures)  1011 Project/Site Permit	Describe work to be done:
014 Change of use	
015 Retain use	(Complete carefully, Your application will be based on your written description.)
016  Alter grade (raise or lower grade) 022  Alterations to legalize a suite	STRUCTURAL REPAIR
023 Alterations for a new suite	and the second
026   Demolish   Commercial	- Tt
Fire damaged building	
Non-rental one-family dwelling	
☐ Heritage building☐ Residential rental building	,
028 Temporary tents	
030 Construct a garage/carport	
031 Add/alter/demo garage/carport 038 Construct partial - framing, etc.	
040 Excavate - valid for project address et al.	·
041  Move building from another site 042  Move building on the same site	
043 Install a pool, fence, tennis court, boat ramp, sign, or	
similar	
044 ☐ Upgrade seismic and/or sprinkler 045 ☐ Mechanical kitchen exhaust, roof top unit, satellite dish	
046 Prefabricated structure placed on site	
047 Fire damage repair	
048 ☐ Flood damage repair 050 ☐ Landscape only	
053 Building envelope repair	
What is the value of the work proposed? (Include cost of plans, material and labour)	Office Use Only
i' '	
\$ 100,000	
Will any of the following be altered/repaired/installed? Select all that apply:	
· · ·	
☐ Electrical ☐ Gas ☐ Drain Tile	
☐ Plumbing ☐ Sprinkler ☐ Fire Alarm	
Sprinkler Contractor's Name:	
Note: If the sprinkler contractor noted on this application	
changes, please notify the City of Vancouver in writing within 24 hours.	Office Use Only Invoice #
Special Sprinkler Inspection Number SP	BU
special spiritkier inspection number sr	DE
Complete the following for all residential buildings	
'	
Total number of dwelling units:  Existing Proposed	Office Use Only
Total number of housekeeping units:	BU ( WWOP? )
· -	<b> </b>
Total number of sleeping units:	DE
	DT
Complete the following related permit information	BG f/m
Development Permit/Application Number DE	ENV. PROT. Site Profile
Minor Amendment Number DE	SUBTOTAL
Building Permit/Application Number BU	SP
,,	1
	TOTAL
Combined Permit Application Number DB	
describes a use, a building or a work which complies with all relevant by law will not be released to the public except as required by law; however, all	within this document and associated applications and plans is correct, and we and statutes. I understand that personal information contained in this form associated applications and plans will be made publications and plans will be made publications and plans will be made publications and the property of this application or fact sheet or eparting and the property of this application or fact sheet or eparting the property of this application or fact sheet or eparting the property of the pro

SIGNED AT VANCOUVER, B.C. THIS DAY OF COUNTY DOC/2016/081493 (Revised March 2016)

SIGNATURE OF APPLICANT



2348 Yukon Street Vancouver, BC Canada V5Y 3T6 Phone 604 872-1211 Fax 604 872-1274 see@telus.net

Our File No.: \$16-502 November 11, 2016

City of Vancouver 515 West 10th Avenue Vancouver, B.C. V5Z 4A8

**Attention: Plans and Permits** 

Dear Sir:

Re: Cobalt Hotel

917 Main Street, Vancouver, B.C.

- Repair Project - 2016 to 2017

- Building Permit Application

The Owner has retained Spratt Emanuel Engineering Ltd. to design and provide quality assurance services for the above-noted project.

Yours truly,

Mr. Pal Sahota Owner's Appointed Agent

MWE/ke

FEB 0 2 2017

COMMUNITY SERVICE CROUP
DEVELOPMENT SERVICE.

CITY OF VANCOUVER

BP-2017-00582

ACCEPTED

#### **BUILDING BY-LAW 2014 - CITY OF VANCOUVER**

#### SCHEDULE A

Forming Part of Sentence 2.2.7.2.(1), Div. C of the **Building By-law** 

Building Permit No.

#### CONFIRMATION OF COMMITMENT BY OWNER AND COORDINATING REGISTERED PROFESSIONAL

Notes:

- (i) This letter must be submitted before issuance of a building permit.
- This letter is endorsed by: Architectural Institute of B.C., Association of Professional Engineers and Geoscientists of B.C.
- (iii) In this letter the words in italics have the same meaning as in the Building By-law.

Re: Design and Field Review of Construction by a Coordinating Registered Professional

To: The Chief Building Official Cobalt Hotel Name of Project (Print) 917 Main Street, Vancouver, B.C. Address of Project (Print) Legal Description of Project (Print) (Professional's Seal and Signature)

November 3, 2016

Date

The undersigned has retained Spratt Emanuel Engineering Ltd. as a coordinating registered professional to coordinate the design work and field reviews of the registered professionals of record required for this project. The coordinating registered professional shall coordinate the design work and field reviews of the registered professionals of record required for the project in order to ascertain that the design will substantially comply with the Building By-law and other applicable enactments respecting safety and that the construction of the project will substantially comply with the Building By-law and other applicable enactments respecting safety, not including the construction safety aspects.

"field reviews" are defined in the Building By-law to mean those reviews of the work

- (a) at a project site of a development to which a building permit relates, and
- (b) where applicable, at fabrication locations where building components are fabricated for use at the project site

that a registered professional in his or her professional discretion considers necessary to ascertain whether the work substantially complies in all material respects with the plans and supporting documents prepared by the registered professional of record for which the building permit is issued.

The owner and the coordinating registered professional have read Subsection 2.2.7, Division C of the Building By-law. The owner and the coordinating registered professional each acknowledge their responsibility to notify the Chief Building Official of the date the coordinating registered professional ceases to be retained by the owner before the date the coordinating registered professional ceases to be retained or, if that is not possible, then as soon as possible. The coordinating registered professional acknowledges the responsibility to notify the Chief Building Official of the date a registered professional of record ceases to be retained before the date the registered professional of record ceases to be retained or, if that is not possible, then as soon as possible.

1 It is the responsibility of th ofessional to ascertain which registered professionals are required, Building Official.

initial each Schedule B p

FEB 02 2017

**COMMUNITY SERVICE CROUP DEVELOPMENT SERVICES** 

CITY OF VANCOUVER

BP-2017-00582

ACCEPTED

#### **BUILDING BY-LAW 2014 - CITY OF VANCOUVER**

Sch	edul	۵ ما	-0	ontini	ued

Building Permit No.

917 Main Street, Vancouver, B.C.

Project Address

The owner and the coordinating registered professional understand that where the coordinating registered professional or a registered professional of record ceases to be retained at any time during construction, work on the above project will cease until such time as

- (a) a new coordinating registered professional or registered professional of record, as the case may be, is retained, and
- (b) a new letter in the form set out in Schedule A or in the forms set out in Schedules B, as the case may be, is filed with the *Chief Building Official*.

The undersigned coordinating registered professional certifies that he or she is a registered professional as defined in the Building By-law, and agrees to coordinate the design work and field reviews of the registered professionals of record required for the project as outlined in the attached Schedules B including coordination and integration of functional testing of fire protection and life safety systems. (See A-2.2,7.3 in Appendix A.)

Name of Ager

Date

#### **Coordinating Registered Professional**

Mark W. Emanuel, P.Eng.

Coordinating Registered Professional's Name (Print)


2348 Yukon Street

Address (Print)

Vancouver, B.C. V5Y 3T6

604-872-1211

Phone No.



Owner's or Owner's appointed agent's Signature. (If owner is a corporation the signature of a signing officer must be given here. If the signature is that of the agent, a copy of the document that appoints the agent must be attached.)

or Signing Officer if applicable (Print

CITY OF VANCOUVER

BP-2017-00582

ACCEPTED

(If the Coordinating Registered Professional is a member of a firm, complete the following.)

am a member of the

Date

firm Spratt Emanuel Engineering Ltd.

and I sign this letter on behalf of the firm.

November 3, 2016

(Print name of firm)

This letter must be signed by the *owner* or the *owner*'s appointed agent and by the *coordinating registered* professional. An agent's letter of appointment must be attached. If the *owner* is a corporation, the letter must be signed by a signing officer of the corporation and the signing officer must set forth his or her position in the corporation.

The Building By-law defines a registered professional to mean

- (a) a person who is registered or licensed to practise as an architect under the Architects Act, or
- (b) a person who is registered or licensed to practise as a professional engineer under the Engineers and Geoscientists Act.

2 of 2

#### **BUILDING BY-LAW 2014 - CITY OF VANCOUVER**

#### SCHEDULE B

Forming Part of Subsection 2.2.7, Div. C of the Building By-law

Building Permit No.

#### ASSURANCE OF PROFESSIONAL DESIGN AND **COMMITMENT FOR FIELD REVIEW**

- Notes: (i) This letter must be submitted prior to the commencement of construction activities of the components identified below.
  - A separate letter must be submitted by each registered professional of record. This letter is endorsed by: Architectural Institute of B.C., Association of Professional Engineers and
  - Geoscientists of B.C. (iii) In this letter the words in italics have the same meaning as in the Building By-law.

To: The Chief Building Official

Re: Cobalt Hotel

Name of Project (Print)

917 Main Street, Vancouver, B.C.

Address of Project (Print)

Legal Description of Project (Print)

The undersigned hereby gives assurance that the design of the (Initial those of the personal steed below that apply to this registered professional omes will not necessarily be employed on every project.)

**ARCHITECTURAL** 

**STRUCTURAL** 

MECHANICAL

**PLUMBING** 

FIRE SUPPRESSION SYSTEMS

**<b><b> <u>M</u>GEOTECHNI**CAL — temporary

GEOTECHNICAL — permanent

(Professional's estated

November 3, 2016

Date

components of the plans and supporting documents prepared by this registered professional in support of the application for the building permit as outlined below substantially comply with the Building By-law and other applicable enactments respecting safety except for construction safety aspects.

The undersigned hereby undertakes to be responsible for field reviews of the above referenced components during construction as indicated on the "SUMMARY OF DESIGN AND FIELD REVIEW REQUIREMENTS" below.

1 of 4

CITY OF VANCOUVER

BP - 2017 - 0.0582

ACCEPTED

FEB 0 2 2017

**COMMUNITY SERVICE GROUP DEVELOPMENT SERVICES** 

CRP's Initials

#### **BUILDING BY-LAW 2014 - CITY OF VANCOUVER**

Schedule B - Continued

Building Permit No.

917 Main Street, Vancouver, B.C.

Project Address

**Architectural** 

Discipline

The undersigned also undertakes to notify the *Chief Building Official* in writing as soon as possible if the undersigned's contract for *field review* is terminated at any time during *construction*.

I certify that I am a registered professional as defined in the Building By-law.

Mark W. Emanuel, P.Eng.

Registered Professional's Name (Print)


2348 Yukon Street

Address (Print)

Vancouver, B.C. V5Y 3T6

604-872-1211

Phone No.



November 3, 2016

Date

(If the Registered Professional of Record is a member of a firm, complete the following.)

I am a member of the firm Spratt Emanuel Engineering Ltd.

and I sign this letter on behalf of the firm.

(Print name of firm)

Note: The above letter must be signed by a registered professional of record, who is a registered professional. The Building By-law defines a registered professional to mean

(a) a person who is registered or licensed to practise as an architect under the Architects Act, or

(b) a person who is registered or licensed to practise as a professional engineer under the Engineers and Geoscientists Act.

CITY OF VANCOUVER

BP-2017-00582

ACCEPTED

CRP's Initials

#### Amendment: May 7, 2014 **BUILDING BY-LAW 2014 - CITY OF VANCOUVER** Schedule B - Continued Building Permit No. 917 Main Street, Vancouver, B.C. Project Address **Architectural** Discipline SUMMARY OF DESIGN AND FIELD REVIEW REQUIREMENTS bolicable discipline below and cross out and initial only those items not applicable to the project.) ARCHITECTURAL Fire resisting assemblies 1.1 Fire separations and their continuity 1.3 Closures, including tightness and operation 14 Egress systems, including access to exit within suites and floor areas Performance and physical safety features (quardrails, handrails, etc.) Structural capacity of architectural components, including anchorage and seismic restraint 1.6 1.7 Sound control Landseaping, screening and site grading-Provisions for firefighting access 1:10 Access requirements for porsons with 1.11 Elevating devices 1.12 Functional testing of architecturally related fire emergency systems and devices 1.13 Development Permit and conditions therein 14 Interior signage, including acceptable materials. locations 1.15 Review of all applicable shop drawings 1.16 Interior and exterior finishes 1.17 Dampproofing and/or waterproofing 1.18 Roofing and flashings 1.19 Wall cladding systems 1.20 Condensation control and cavity ventilation 1.21 Exterior glazing 1.22 Integration of building envelope components 1.23 Environmental separation requirements (Part 5) November 3, 2016 1-24 Building envelope. Part 10 requirements Date STRUCTURAL Structural capacity of structural components of the building, including anchorage and seismic restraint Structural aspects of deep foundations Review of all applicable shop drawings Structural aspects of unbonded post-tensioned concrete design and construction 2.4 MECHÂNICAL 3.1% HVAC systems and devices, including high building requirements where applicable Fire dampers at required fire separations Continuity of fire separations at HVAC penetrations Functional testing of mechanically related fire emergency systems and devices 3.5 Maintenance manuals for mechanical systems Structural capacity of mechanical components, including anchorage and seismic restraint 3.6 3.7 Review of all applicable shop drawings Mechanical systems, Part 10 requirements CITY OF VANCOUVER CRP's Initial 3 of 4

BP-2017-00582

#### **BUILDING BY-LAW 2014 - CITY OF VANCOUVER**

#### Schedule B - Continued

Building Permit No.

917 Main Street, Vancouver, B.C.

Project Address

#### Architectural

Discipline

#### **PLUMBING**

- 4.1 Roof drainage systems
- 4.2 Site and foundation drainage systems
- Plumbing systems and devices
- Continuity of fire separations at plumbing penetrations
- Functional testing of plumbing related fire emergency systems and devices
- Maintenance manuals for plumbing systems
- Structural capacity of plumbing components, including anchorage and seismic restraint 4.7
- Review of all applicable shop drawings 4.8
- 4.9 Plumbing systems, Part 10 requirements

#### **FIRE SUPPRESSION SYSTEMS**

- Suppression system classification for type of occupancy
- Design coverage, including concealed or special areas
- Compatibility and location of electrical supervision, ancillary alarm and control devices
- Evaluation of the capacity of city (municipal) water supply versus system demands and domestic demand, including pumping devices where necessary
- Qualification of welder, quality of welds and material
- Review of all applicable shop drawings 5.6
- Acceptance testing for "Contractor's Material and Test Certificate" as per NFPA Standards
- 5.8 Maintenance program and manual for suppression systems
  5.9 Structural capacity of sprinkler components, including anchorage and seismic restrain of VANCOUVER
- 5.11 Fire Department connections and hydrant locations
- 5.12 Fire hose standpipes

**ELECTRICAL** 

- 5.13 Freeze protection measures for fire suppression systems
- 5.14 Functional testing of fire suppression systems and devices

BP-2017-00582


- Electrical systems and devices, including high building requirements where applicable
- Continuity of fire separations at electrical penetrations
- Functional testing of electrical related fire emergency systems and devices 6.3
- Electrical systems and devices maintenance manuals
- Structural capacity of electrical components, including anchorage and seismic restraint >
- Clearances from buildings of all electrical utility equipment
- Fire protection of wiring for emergency systems 6.7
- Review of all applicable shop drawings 6.8
- Electrical systems, Part 10 requirements

#### **GEOTECHNICAL** — Temporary

- 7.1 Excavation 7.2 Shorin
- 7.3 Underpinning
- 7.4 Temporary construction dewatering

#### **GEOTECHNICAL** — Permanent

- 8.1 Bearing capacity of the soil
- 8.2 Geotechnical aspects of deep foundations
- Compaction of engineered fill
- Structural considerations of soil, including slope stability and 8.4 seismic loading
- Backfill 8.5
- Permanent dewatering 8.6
- Permanent underpinning



November 3, 2016

#### **BUILDING BY-LAW 2014 - CITY OF VANCOUVER**

#### SCHEDULE B

Forming Part of Subsection 2.2.7, Div. C of the Building By-law

Building Permit No.

#### ASSURANCE OF PROFESSIONAL DESIGN AND **COMMITMENT FOR FIELD REVIEW**

(i) This letter must be submitted prior to the commencement of construction activities of the components identified below. Notes: A separate letter must be submitted by each registered professional of record.

This letter is endorsed by: Architectural Institute of B.C., Association of Professional Engineers

Geoscientists of B.C. (iii) In this letter the words in italics have the same meaning as in the Building By-law.

To: The Chief Building Official

#### The Cobalt Hotel Repairs.

Name of Project (Print) 917 Main St.

Address of Project (Print)

Legal Description of Project (Print)

The undersigned hereby gives assurance that the design of the (Initial those of the items listed below that apply to this registered professional of record. All the disciplines will not necessarily be employed on every project.)

**ARCHITECTURAL** 

STRUCTURAL

MECHANICAL

PLUMBING

FIRE SUPPRÈSSION SYSTEMS

**ELECTRICAL** 

(\) GEOTECHNICAL — temporary

GEOTECHNICAL — permanent

PROVINCE OF BRITISH COLUMBIA DESIGNATED STRUCTURAL ENGINEER

November 24, 2016

Date

CRP's Initials


components of the plans and supporting documents prepared by this registered professional in support of the application for the building permit as outlined below substantially comply with the Building By-law and other applicable enactments respecting safety except for construction safety aspects.

The undersigned hereby undertakes to be responsible for field reviews of the above referenced components during construction as indicated on the "SUMMARY OF DESIGN AND FIELD REVIEW REQUIREMENTS" below.

CITY OF VANCOUVER

BP-2017-00582

ACCEPTED



COMMUNITY SERVICE CROUP DEVELOPMENT SERVICES


#### BUILDING BY-LAW 2014 - CITY OF VANCOUVER

Schedule B - Continued	
	Building Permit No.
	917 Main St.
	Project Address
	Structural
The undersigned also undertakes to notify the Chief Building undersigned's contract for field review is terminated at any t	g Official in writing as soon as possible if the
I certify that I am a registered professional as defined in the	Building By-law.
Andrew B. McLellan Registered Professional's Name (Print)	PROVINGE OF BRITISH COLUMBIA
601 - 625 Fifth Ave., New Westminster, BC.	SAMPELDAM?
Address (Print)	
604 544 1082	DESIGNATED
Phone No.	STRUCTURAL ENGINEER
· · · · · · · · · · · · · · · · · · ·	33333333333
	(Professional's Seal and Signature)
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	November 24, 2016
	Date
(If the Registered Professional of Recordis a member of a f	
I am a member of the firm	(Print name of firm)
Note: The above letter must be signed by a registered profesulding By-law defines a registered professional to mean	essional of record, who is a registered professional. The
(a) apperson who is registered or licensed to practice (b) a person who is registered or licensed to practice Geoscientists Act.	se as an architect under the Architects Act, <i>o</i> r se as a professional engineer under the Engineers and
O,	
CITY OF VANCOUVER	MI I. 1
BP-2017-00582	
ACCEPTED 2 of	f4

	BUILDING BY-LAW 2014 - CITY	OF VANCOUVER
Sch	nedule B - Continued	
		Building Permit No.
		917 Main St.
		Project Address
		Structural
	-	Discipline
	SUMMARY OF DESIGN AND FIELD F	REVIEW REQUIREMENTS
(Initia	al applicable discipline below and cross out and initial only those items	s not applicable to the project.)
	ARCHITECTURAL	
1.1	Fire resisting assemblies	
1.2	Fire separations and their continuity	
1.3	Closures, including tightness and operation	
1.4	Egress systems, including access to exit within suites and flo	
1.5	Performance and physical safety features (guardrails, handra Structural capacity of architectural components, including and	alls, etc.)
1.6 1.7	Sound control	chorage and seismic restraint
	Landscaping, screening and site grading	
	Provisions for firefighting access	
	Access requirements for persons with disabilities	Coccece
1.11	Elevating devices	1 Color State of Color
1.12	Functional testing of architecturally related fire emergency sy	stems and PROVINCE OF BRITISH COLUMBIA
4.40	devices	3
	Development Permit and conditions therein Interior signage, including acceptable materials, dimensions,	AR MA EN MA
1.14	locations	ABOTE AS AND ENGINEER
1.15	Review of all applicable shop drawings	//XX///#EDA/CO
1.16	Interior and exterior finishes	
	Dampproofing and/or waterproofing of walls and slabs below	grade DESIGNATED STRUCTURAL ENGINEER
	Roofing and flashings Wall cladding systems	371
1.13	Condensation control and cavity ventilation	337
1.21	Exterior glazing	(Professional's Seal and Signature)
1.22	Integration of building envelope components	
	Environmental separation requirements (Part 5)	November 24, 2016
	Building envelope, Part 10 requirements	Date
189	M STRUCTURAL	
$O_{\frac{1}{21}}$	Structural capacity of structural components of the building, in	ncluding anchorage and seismic restraint
1-22	Structural aspects of deep foundations	morading and relage and belomic reculation
2.3	Review of all applicable shop drawings	
2.4	Structural aspects of unbonded post-tensioned-concrete desi	gn and construction—
	MECHANICAL	
3.1	HVAC systems and devices, including high building requirem	ents where applicable
3.2	Fire dampers at required fire separations	
3.3	Continuity of fire separations at HVAC penetrations	
3.4	Functional testing of mechanically related fire emergency sys	stems and devices
3.5	Maintenance manuals for mechanical systems	11/2
3.6	Structural capacity of mechanical components, including and	horage and seismic restraint
3.7	Review of all applicable shop drawings	
3.8	Mechanical systems, Part 10 requirements	

CITY OF VANCOUVER

BP-2017-00582



#### **BUILDING BY-LAW 2014 - CITY OF VANCOUVER**

Schedule B - Continued Building Permit No. 917 Main St. Project Address Structural Discipline **PLUMBING** Roof drainage systems Site and foundation drainage systems Plumbing systems and devices Continuity of fire separations at plumbing penetrations Functional testing of plumbing related fire emergency systems and devices Maintenance manuals for plumbing systems 4.7 Structural capacity of plumbing components, including anchorage and seismic restraint Review of all applicable shop drawings Plumbing systems, Part 10 requirements **FIRE SUPPRESSION SYSTEMS** 5.1 Suppression system classification for type of occupancy 5.2 Design coverage, including concealed or special areas Compatibility and location of electrical supervision, ancillary alarm and control devices
Evaluation of the capacity of city (municipal) water supply versus system demands and domestic demand, including pumping devices where necessary Qualification of welder, quality of welds and material 5.6 Review of all applicable shop drawings Acceptance testing for "Contractor's Material and Test Certificate" as per NFPA Standards 5.7 Maintenance program and manual for suppression systems 5.9 Structural capacity of sprinkler components, including anchorage and seismic restraint of VANCOUVER

5.10 For partial systems — confirm sprinklers are installed in all areas where required 11 VOF VANCOUVER 5.11 Fire Department connections and hydrant locations 5.12 Fire hose standpipes BP-2017-00582 5.13 Freeze protection measures for fire suppression systems 5.14 Functional testing of fire suppression systems and devices Electrical systems and devices including high building requirements where applicable Continuity of *fire separations* at electrical penetrations

Functional testing of electrical related fire emergency systems and devices

Electrical systems and devices maintenance and devices **ELECTRICAL** 6.1 Electrical systems and devices maintenance manuals Structural capacity of electrical components, including anchorage and seismic restraint Clearances from buildings of all electrical utility equipment 6.6 6.7 Fire protection of wiring for emergency systems PROVINCE OF **BRITISH COLUMBIA** Review of all applicable shop drawings Electrical systems, Part 10 requirements GEOTECHNICAL — Temporary Excavation Shoring) Underpinning DESIGNATED Temporary construction dewatering STRUCTURAL ENGINEER **GEOTECHNICAL** — Permanent Bearing capacity of the soil 8.1 rofessionar's Seal and Signature

8.2 Geotechnical aspects of deep foundations

Compaction of engineered fill

8.4 Structural considerations of soil, including slope stability and seismic loading

8.5 Backfill

8.6 Permanent dewatering

8.7 Permanent underpinning

November 24, 2016



#### **SCHEDULE E-1**



Note: To be submitted with the application for a Building Permit

# BUILDING BY-LAW "OWNER'S UNDERTAKING"

# CITY OF VANCOUVER

The Chief Building Offic	:ia
City of Vancouver	-
453 West 12th Avenue	
Vancouver, B.C.	
V5Y 1V4	,

BP-	2017	-0	0	5	8	ć
-----	------	----	---	---	---	---

November 3, 2016

Oate (Month Day Year

AC(	jep	TED
-----	-----	-----

Dear	Sir.
DCai	JII .

RE:	Property Address	917 Main Street, Vancouver, B.C.	Š,
	, ,		

Building Permit Application No.

In consideration of the City accepting and processing the above application for a building permit, and as required by the Building By-law, the following representations, warranties and indemnities are given to the City.

- 1. (a) If an individual is the owner:
  - ( ) That I am the owner of the above property, or
  - (b) If a corporation is the owner of the property, That NOTOR HOTEL LTD, (DBA COBACT HOTEL LTD) (Name of Corporation)
- 2. The owner will comply with, and cause those employed for this project to comply with all applicable by-laws of the City of Vancouver and other statutes and regulations in force in the City of Vancouver relating to the development, work, undertaking or permission in respect of which this application is made.
- 3. The owner fully understands the requirements herein, and acknowledges full responsibility for carrying out the work, or gives assurance that the work will be carried out, in accordance with all by-laws governing the construction of the building. The owner understands and acknowledges that the issuance of any permit, including an Occupancy Permit, or the inspection or approval or passage of work by the City is not a representation or warranty that any by-law has been complied with and the owner remains responsible at all times to assure compliance. The Owner has read and understands Article 1.3.2.1. and Article 1.4.1.5. of Division C Book I and Book II of the Building By-law which are set out on the reverse side hereof.
- 4. The owner hereby agrees to indemnify and save harmless the City of Vancouver and its employees from all claims, liability, judgments, costs and expenses of every kind including negligence which may result from the failure to comply fully with all by-laws, statutes and regulations relating to any work or undertaking in respect of which this application is made.
- 5. Where used herein the words "work" or "undertaking" in respect of which this application is made, the owner understands this to include all electrical, plumbing, mechanical, gas and other works necessary to complete the contemplated construction.

FEB 0 2 2017

COMMUNITY SERVICE CROUP
DEVELOPMENT SERVICES

Owr	ner's Undertaking (continued)	Property Address 917 Main Street, Vancouver, B.C.
		Building Permit Application No
6.		nese representations, warranties, assurances and indemnities to the City of idertaking is executed by the Owner this 23 day of 12, 2016 (Month) (Year)
	CITY OF V	/ANCOUVER
1.	Where owner is an individual: BP - 2017  Owner's Signature	Witness's Signature
	Owner's Name (PR	Witness's Name (PRINT) Witness's Address
2.	Where owner is a corporation:	THSTAR INTERNATIONAL
	Name of Corporation (DCA)	COBALT HOTE Witness's Signature
	Per: Authorized Signatory	Witness's Name Mark W. Emanuel, P.Eng. (PRINT)
	Name Pal Sahota (PR	Witness's Address 2348 Yukon Street, Vancouver, BC

Building By-law, Division C, Article 1,3,21. Intent

1) This By-Law sets standards in the general public interest. It is enacted and retained on the understanding and specifically expressed condition that it creates no duty whatsoever on the city, the Chief Building Official or any employee of the city to enforce its provisions, and on the further condition that a failure to administer or enforce its provisions, or the incomplete or inadequate administration or enforcement of its provisions, shall not give rise to a cause of action in favour of any person whatsoever. The issuance of any permit, including an occupancy permit, is not a representation, warranty or statement that this By-Law or any other enactment has been complied with, and the issuance thereof in error shall not give rise to a cause of action. Accordingly, words in this By-law defining the responsibilities and authority of the Chief Building Official shall be construed as internal administrative directions which do not create a duty.

### Building By-law, Division C, Article 1.4.1.5. Compliance with By-law and Other Enactments

1) The owner shall comply with this By-law and all other applicable enactments.

2) The owner shall ensure that all work, construction, or occupancy is carried out in accordance with this By-law and all-other applicable enactments.

3) The owner shall ensure that the occupancy of a building or part of a building complies with the occupancy permit.

The issuance of a permit, the acceptance of plans and supporting documents submitted for a permit, or the making of inspections by the Chief Building Official shall not relieve the owner of a building from the full responsibility for carrying out the work or having the work carried out in accordance with this By-law and all other applicable enactments.



Address 7	Main	St
(Property Use)	SRCF-20	017-013186

	Standards of Maintenand	ce By-law No. 5462	Violations
Room No.	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	Window-pane/frame/trim/hardware - repair/replace/clean     Pests-rats/mice/roaches/bedbugs/fruit flies - pest control     Electrical outlets/fixtures/cover plates - repair or replace     Smoke alarm - repair/replace	0
ast are	Air: 24.0°C		
Room No. St Floor Carridot Usel Sed	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	Window-pane/frame/trim/hardware - repair/replace/clean     Pests-rats/mice/roaches/bedbugs/fruit flies - pest control     Electrical outlets/fixtures/cover plates - repair or replace     Smoke alarm - repair/replace □ Sprinkler line - remove items     Clutter/doorway access - 1□ 2□ 3□	0
Room No. 194 Floor South	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	Window-pane/frame/trim/hardware - repair/replace/clean     Pests-rats/mice/roaches/bedbugs/fruit flies - pest control     Electrical outlets/fixtures/cover plates - repair or replace     Smoke alarm - repair/replace	0
Room No.	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	0
NOW!	witer : 52.1°C		
Room No. s.22(1)	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/celling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control☐ Electrical outlets/fixtures/cover plates - repair or replace☐ Smoke alarm - repair/replace☐ Sprinkler line - remove items☐ Clutter/doorway access - 1☐ 2☐ 3☐	2
	Air: 23.62 W	iter 43.22 Radiator not Working	6
Room No. s.22(1)	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	3
	Air : OK Whiter :	No hot water	
Room No.	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	□ Window-pane/frame/trim/hardware - repair/replace/clean     □ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control     □ Electrical outlets/fixtures/cover plates - repair or replace     □ Smoke alarm - repair/replace □ Sprinkler line - remove items     □ Clutter/doorway access - 1□ 2□ 3□	3
	a sink plantonis taps teaks - repair replace unplug	Li Ciutte / 1000 way access - 111 211 311	
Vacant			
No Access			
Inspected			
Notes:	-4. 111-1-1-1-1	2.2.2.2.11	Total
70	TAL VIOLATIONS : 3	5+2+3+2+4	
		14 VIOLATIONS	5



Address 917	Main St
(Property Use)	SRCF-2017-013/86

	Standards of Maintenar	nce By-law No. 5462	Violations
Room No. 2nd Floor Corridor	☐ Carpets/floor/baseboards - repair/replace/clean☐ Walls/ceiling/floors - repair/replace/clean/paint☐ Radiator/Electric baseboard - repair/replace☐ Door-handset/hinges/frame/room# - repair/replace☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	0
best side	- Air : 23.4°C		
Room No.	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	0
Room No. Znd Floor North	☐ Carpets/floor/baseboards - repair/replace/clean☐ Walls/ceiling/floors - repair/replace/clean/paint☐ Radiator/Electric baseboard - repair/replace☐ Door-handset/hinges/frame/room// - repair/replace☐ Sink/plumbing/taps/leaks - repair/replace/unplug☐	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	0
Room No. 2 Floor	☐ Carpets/floor/baseboards - repair/replace/clean ☐ Walls/ceiling/floors - repair/replace/clean/paint ☐ Radiator/Electric baseboard - repair/replace ☐ Door-handset/hinges/frame/room# - repair/replace ☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	0
Mercoci	ages: 53.8°C		
Room No. s.22(1)	□ Carpets/floor/baseboards - repair/replace/clean     □ Walls/ceiling/floors - repair/replace/clean/paint     □ Radiator/Electric baseboard - repair/replace     □ Door-handset/hinges/frame/room# - repair/replace     □ Sink/plumbing/taps/leaks - repair/replace/unplug	<ul> <li>□ Window-pane/frame/trim/hardware - repair/replace/clean</li> <li>□ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control</li> <li>□ Electrical outlets/fixtures/cover plates - repair or replace</li> <li>□ Smoke alarm - repair/replace</li> <li>□ Sprinkler line - remove items</li> <li>□ Clutter/doorway access - 1</li> <li>□ 2</li> <li>□ 3</li> </ul>	7
	Water : 24.7°C	Air = 25.6°C	
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean☐ Walls/ceiling/floors - repair/replace/clean/paint☐ Radiator/Electric baseboard - repair/replace☐ Door-handset/hinges/frame/room# - repair/replace☐ Sink/plumbing/taps/leaks - repair/replace/unplug	□ Window-pane/frame/trim/hardware - repair/replace/clean     □ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control     □ Electrical outlets/fixtures/cover plates - repair or replace     □ Smoke alarm - repair/replace □ Sprinkler line - remove items     □ Clutter/doorway access - 1□ 2□ 3□	1
	Water: 44.1°C A	ir: 24.8°C Kadiator leaks	
Room No.	□ Carpets/floor/baseboards - repair/replace/clean     □ Walls/ceiling/floors - repair/replace/clean/paint     □ Radiator/Electric baseboard - repair/replace     □ Door-handset/hinges/frame/room# - repair/replace     □ Sink/plumbing/taps/leaks - repair/replace/unplug	□ Window-pane/frame/trim/hardware - repair/replace/clean     □ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control     □ Electrical outlets/fixtures/cover plates - repair or replace     □ Smoke alarm - repair/replace □ Sprinkler line - remove items     □ Clutter/doorway access - 1□ 2□ 3□	X
Vacant			L
No Access			
Inspected			
Notes:			Total
-			2



Address 91	Main :	3+_
(Property Use)	SR CF-2017	-013/86

	Standards of Maintenand	ce By-law No. 5462	Violations
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean☐ Walls/ceiling/floors - repair/replace/clean/paint☐ Radiator/Electric baseboard - repair/replace☐ Door-handset/hinges/frame/room# - repair/replace☐ Sink/plumbing/taps/leaks - repair/replace/unplug	□ Window-pane/frame/trim/hardware - repair/replace/clean     □ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control     □ Electrical outlets/fixtures/cover plates - repair or replace     □ Smoke alarm - repair/replace □ Sprinkler line - remove items     □ Clutter/doorway access - 1□ 2□ 3□	0
	Air 123.0°C 4	18ter: 49.1°C	
Room No.  3 Hoar Carridor East Side	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1 ☐ 2 ☐ 3 ☐	0
Room No. 3 Placer Corridor	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	□ Window-pane/frame/trim/hardware - repair/replace/clean     □ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control     □ Electrical outlets/fixtures/cover plates - repair or replace     □ Smoke alarm - repair/replace □ Sprinkler line - remove items     □ Clutter/doorway access - 1□ 2□ 3□	0
	AIV-ZO. C Cu	indow wideoper in corridor)	
Room No. s.22(1)	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	<ul> <li>□ Window-pane/frame/trim/hardware - repair/replace/clean</li> <li>□ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control</li> <li>□ Electrical outlets/fixtures/cover plates - repair or replace</li> <li>□ Smoke alarm - repair/replace</li> <li>□ Sprinkler line - remove items</li> <li>□ Clutter/doorway access - 1 □ 2 □ 3 □</li> </ul>	2
	AIT : 21.5°C W	later: 40.7°C Radiator not working	
Room No. 3 Floor Common Sink	☐ Carpets/floor/baseboards - repair/replace/clean☐ Walls/ceiling/floors - repair/replace/clean/paint☐ Radiator/Electric baseboard - repair/replace☐ Door-handset/hinges/frame/room# - repair/replace☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	0
15.019.11	Water 52,6°C		
Room No.	☐ Carpets/floor/baseboards - repair/replace/clean ☐ Walls/ceiling/floors - repair/replace/clean/paint ☐ Radiator/Electric baseboard - repair/replace ☐ Door-handset/hinges/frame/room# - repair/replace ☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1 ☐ 2 ☐ 3 ☐	1
	Water: 44-1°C		
Room No.	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1 ☐ 2 ☐ 3 ☐	$\times$
Vacant			
No Access			
Inspected			
Notes:			Total
, to coar			
			3



Address 917 Main 54 (Property Use) SR CF-2017-013186

Standards of Maintenance By-law No. 5462			
Room No.	□ Carpets/floor/baseboards - repair/replace/clean     □ Walls/ceiling/floors - repair/replace/clean/paint     □ Radiator/Electric baseboard - repair/replace     □ Door-handset/hinges/frame/room# - repair/replace     □ Sink/plumbing/taps/leaks - repair/replace/unplug	Window-pane/frame/trim/hardware - repair/replace/clean     Pests-rats/mice/roaches/bedbugs/fruit flies - pest control     Electrical outlets/fixtures/cover plates - repair or replace     Smoke alarm - repair/replace	0
last out	- Air Temp 24.6°C		
Room No. 4th Floor Corridor West State	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control☐ Electrical outlets/fixtures/cover plates - repair or replace☐ Smoke alarm - repair/replace☐ Sprinkler line - remove items☐ Clutter/doorway access - 1☐ 2☐ 3☐	0
Room No. s.22(1)	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	1
Room No. 4th Flass Cannan Sink	Carpets/floor/baseboards - repair/replace/clean Walls/ceiling/floors - repair/replace/clean/paint Radiator/Electric baseboard - repair/replace Door-handset/hinges/frame/room# - repair/replace Sink/plumbing/taps/leaks - repair/replace/unplug	Window-pane/frame/trim/hardware - repair/replace/clean     Pests-rats/mice/roaches/bedbugs/fruit flies - pest control     Electrical outlets/fixtures/cover plates - repair or replace     Smoke alarm - repair/replace	0
Room No. 4th Flow SW Shower	□ Carpets/floor/baseboards - repair/replace/clean     □ Walls/ceiling/floors - repair/replace/clean/paint     □ Radiator/Electric baseboard - repair/replace     □ Door-handset/hinges/frame/room# - repair/replace     □ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	1
Room No. 4th Floor SE Storres	Carpets/floor/baseboards - repair/replace/clean  Walls/ceiling/floors - repair/replace/clean/paint  Radiator/Electric baseboard - repair/replace  Door-handset/hinges/frame/room# - repair/replace  Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	0
Room No. s.22(1)	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	0
Vacant	Air: 24.6°C Wai	er:51.5°C	
			10
No Access			
Inspected			
Notes:	11		Total
A	H Harry " West w	side corridor radiators	2

SPRYING SPRING BED BUGS. SPARYING s 22() (Bed buyy), Næd mattress. D Pough -( Bed bugs) (Bed bugs) (Bed Bugs) Bose Bug) Bed Bry (Bed Bus) Bed By Coun Bed Brig Cocaro (Roches. Red Bu (11) Bed Ang. MIZE Muce. Mice, Recht, Bed Bus - Rock (6) (7) Bedinne, Roches. 13 Friday 9-30 Am

mice, Boches

Pest Control V3H 6Y9  Since 1924 Because We Care	604 395-8115		/1/2016 A0575849 *
SERVICE ADDRESS / ADRESSE DE SERVICE  COBALT HOTEL 917 NAIN ST VANCOUVER, BC V&A 2V8  CONTACT  MANN PESTS / PARASITES  SERVICE INSTRUCTIONS / INSTRUCTIONS DE SERVICE	COBALT 769 HA VANCOU	HOTEL ASTINGS ST E IVER, BC ANA 685-2825	TYPE FREQ EST Q.A. C/S O 01 32 N
STANDARD IPM CONTROL	PROGRAM: INTERIOR H SERVICE DITIONAL \$125+GST OMS \$55 FOR IPM P	EACH	
LOCATION PEST ACTIVACTIVE ACTIVACTIVE CONTRACTIVE CONT	IVITY / STRUCTURAL AND/OR SANITATION CONDI VITEV CONDITIONS SANITAIBES & STRUCTURALE	TITIONS CORRECTIVE ACTION CORRECTION CORRECT	CODE#
Servande Ser	work alor dean de for post for post for post for post for post for post for post	AC CONS	magation partiant
Rodents search for for Protect your indoors. Talk to 1-888-949-4949 Abelipe CERT	estControl.com	oday!	Alogi
CUSTOMER NAME / NOM DU CLIENT  CUSTOMER SIGNATURE SIGNATURE DU CUSTOMER SIGNATURE SIGNATURE DU CUSTOMER SIGNATURE SIGNATUR	SERVICED BY / SERVICE ASSISTED	ON SOME	SERVICE CHARGE FRAIS DE SERVICE G.S.T./H.S.T. T.P.S. P.S.T. T.V.Q. TOTAL



#### COMMUNITY SERVICES Licences and Inspections Property Use Inspections

# **Property Use SRA Inspection Report**

SR No.CF-2017-007589

Property Address	Name of Building	Inspection Date (yy/mm/dd)
917 MAIN ST	COBALT	17/06/26227
Business Licence (B/L) Number	Special Notes on B/L	Security/Video
HL 17-119352	NONE	TYes No 6 CAMERAS
Pest Management Company	Number of Units	SRA Tenant Register
ABELL PEST CONTROL	<b>28</b> 99	24-hr Tenant Check
Owner Information	Building Representative	Inspectors Attending
NORTHSTAR INTERNATIONAL	Mar: Mr. SS. MANIN	PUI: MIKE ELLISTON
MOTOR HOTEL LTD	604-685-2825	BECKY INNES
(SAHOTA)	Ph# COULDEST LIVANAGE	Ph# -
Ph# 604-261-0510	Pn# 604-838-4487	Ph#604-871-6968
Common Areas: bathrooms / ha	ills / kitchens / lighting / ele	evator / stairs / storage rooms
4th FLOOR = 2	T SHOWER/TUB	SHOWER TUB SINK
3rd Floor = 3	Y	0
2nd Floor = 2		
IST FLOOR = 2	1	
All floors - provide pro All floors - provide pro All floors - remark or	remove faint of remove black (mold? per shoups bine in a box security compact	
Recommendations:	be determined (Li	censed for 88 rm since 199
All noted deficiencies must be corre	ected by Accost 14th	2017
Hand delivered to Mr. Man	(Signed)	Total # Violations 94
For Manager or Supervisor Use Only		
	Manager/Superviso	r

Lic & Insp - 5005a (Revised June 2013) RT: Mike Ellisten / Lice 3/17



Address 117	MAIN ST
(Property Use)	SRCF-2017-007589

	Standards of Maintenar	nce By-law No. 5462	Violations
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean☐ Walls/ceiling/floors - repair/replace/clean/paint☐ Radiator/Electric baseboard - repair/replace☐ Door-handset/hinges/frame/room# - repair/replace☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	1
Room No. s.22(1)	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door/handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	1
Room No. s.22(1)	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	1
Room No. s.22(1)	□ Carpets/[loor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	2
	LOCATE WATER L	ENC	
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean☐ Walls/ceiling/floors - repair/replace/clean/paint☐ Radiator/Electric baseboard - repair/replace☐ Door-handset/hinges/frame/room# - repair/replace☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	E.
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean ☐ Walls/ceiling/floors _ repair/replace/clean/paint ☐ Radiator/Electric baseboard - repair/replace ☐ Door-handset/hinges/frame/room# - repair/replace ☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control☐ Electrical outlets/fixtures/cover plates - repair or replace☐ Smoke alarm - repair/replace☐ Sprinkler line - remove items☐ Clutter/doorway access - 1☐ 2☐ 3☐	1
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean☐ Walls/ceiling/floors - repair/replace/clean/paint☐ Radiator/Electric baseboard - repair/replace☐ Door-handset/hinges/frame/room# - repair/replace☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	1
Vacant			
No Access			
Inspected	s.22(1)		
Notes:			Total
77722			0
			0



Address	7 MAIN	ST

SRA ANNUAL INSPECTION REPORT (Property Use) SR CF - 2017 - 2015 Standards of Maintenance By-law No. 5462 Violations □ Carpets/floor/baseboards - repair/replace/clean □ Window-pane/frame/trim/hardware - repair/replace/clean Room No. Pests-rats/mice/roaches/bedbugs/fruit flies - pest control Walls/ceiling/floors - repair/replace/clean/paint Radiator/Electric baseboard - repair/replace Electrical outlets/fixtures/cover plates - repair or replace s.22(1) Door-handset/hinges/frame/room# - repair/replace Smoke alarm - repair/replace ☐ Sprinkler line - remove items □ Sink/plumbing/taps/leaks - repair/replace/unplug ☐ Clutter/doorway access - 1☐ 2☐ 3☐ ☐ Carpets/floor/baseboards - repair/replace/clean □ Window-pane/frame/trim/hardware - repair/replace/clean Room No. Walls/ceiling/floors - repair/replace/clean/paint Pests-rats/mice/roaches/bedbugs/fruit flies - pest control Radiator/Electric baseboard - repair/replace Electrical outlets/fixtures/cover plates - repair or replace s.22(1)□ Door-handset/hinges/frame/room# - repair/replace Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐ ☐ Sink/plumbing/taps/leaks (repair/replace/unplug ☐ Carpets/floor/baseboards - repair/replace/clean ☐ Window-pane/frame/trim/hardware - repair/replace/clean Room No. □ Walls/ceiling/floors repair/replace/clean/paint Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Radiator/Electric baseboard - repair/replace Electrical outlets/fixtures/cover plates - repair or replace s.22(1)Door-handset/hinges/frame/room# - repair/replace Smoke alarm - repair/replace ☐ Sprinkler line - remove items Clutter/doorway access - 1☐ 2☐ 3☐ □ Sink/plumbing/taps/leaks - repair/replace/unplug HOLES BEHIND CARDE ☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Carpets/floor/baseboards - repair/replace/clean Room No. Pests rats/mice/roaches/bedbugs/fruit flies - pest control □ Walls/ceiling/floors - repair/replace/clean/paint Electrical outlets/fixtures/cover plates - repair or replace □ Radiator/Electric baseboard - repair/replace s.22(1) Smoke alarm - repair/replace ☐ Sprinkler line - remove items Door-handset/hinges/frame/room# - repair/replace ☐ Sink/plumbing/taps/leaks - repair/replace/unplug Clutter/doorway access - 1□ 2□ 3□ ☐ Carpets/floor/baseboards - repair/replace/clean Window-pane/frame/trim/hardware - repair/replace/clean Room No. Walls/ceiling/floors repair/replace/clean/paint Pests-rats/mice/roaches/bedbugs/fruit flies - pest control s.22(1)Radiator/Electric baseboard - repair/replace Electrical outlets/fixtures/cover plates - repair or replace ☐ Door-handset/hinges/frame/room# - repair/replace □ Smoke alarm - repair/replace □ Sprinkler line - remove items □ Sink/plumbing/taps/leaks - repair/replace/unplug ☐ Clutter/doorway access - 1☐ 2☐ 3☐ ☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Carpets/floor/baseboards - repair/replace/clean Room No. ☐ Walls/ceiling/floors - repair/replace/clean/paint Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Radiator/Electric baseboard - repair/replace Electrical outlets/fixtures/cover plates - repair or replace s.22(1) ☐ Door-handset/hinges/frame/room# - repair/replace Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Sink/plumbing/taps/leaks - repair/replace/unplug ☐ Clutter/doorway access - 1☐ 2☐ 3☐ ☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Carpets/floor/baseboards - repair/replace/clean Room No. Walls/ceiling/floors - repair/replace/clean/paint Pests-rats/mice/roaches/bedbugs/fruit flies - pest control Radiator/Electric baseboard - repair/replace Electrical outlets/fixtures/cover plates - repair or replace Smoke alarm - repair/replace ☐ Sprinkler line - remove items Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug ☐ Clutter/doorway access - 1☐ 2☐ 3☐ Vacant No Access s.22(1)Inspected s.22(1)Total Notes: s.22(1)



Address	717	MA	MV	ST	
(Property		SRC	-20	017-6	107589

Standards of Maintenance By-law No. 5462			
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean☐ Walls/ceiling/floors - repair/replace/clean/paint☐ Radiator/Electric baseboard - repair/replace☐ Door-handset/hinges/frame/room# - repair/replace☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1 ☐ 2 ☐ 3 ☐	0
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean☐ Walls/ceiling/floors - repair/replace/clean/paint☐ Radiator/Electric baseboard - repair/replace☐ Door-handset/hinges/frame/room# - repair/replace☐ Sink/plumbing/taps/leaks _ repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	1
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean☐ Walls/ceiling/floors - repair/replace/clean/paint☐ Radiator/Electric baseboard - repair/replace☐ Door handset/hinges/frame/room# repair/replace☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1 ☐ 2 ☐ 3 ☐	1
	GAS		
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean ☐ Walls/ceiling/floors - repair/replace/clean/paint ☐ Radiator/Electric baseboard - repair/replace ☐ Door-handset/hinges/frame/room# - repair/replace ☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	1
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean ☐ Walls/ceiling/floors - repair/replace/clean/paint ☐ Radiator/Electric baseboard - repair/replace ☐ Door-handset/hinges/frame/room# - repair/replace ☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests¹ rats/mice (roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1 ☐ 2 ☐ 3 ☐	1
Room No. \$.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean ☐ Walls/ceiling/floors repair/replace/clean/paint ☐ Radiator/Electric baseboard - repair/replace ☐ Door-handset/hinges/frame/room# - repair/replace ☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	1
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean ☐ Walls/ceiling/floors - repair/replace/clean/paint ☐ Radiator/Electric baseboard - repair/replace ☐ Door-handset/hinges/frame/room# - repair/eplace ☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	2
Vacant	WALL DON'T WAN	Kelocate terrait ! Temp	(1)
ACTOR AND A TOTAL OF			
No Access			
Inspected	s.22(1)		
Notes: s.2	2(1) = R-1-R1	temo reboute temait.	Total
	- Flendrical Page	temp repeate terreit	7
-			/



Address 917	MAIN	ST
(Property Use)	CONF-70	7-107500

Standards of Maintenance By-law No. 5462			
Room No. s.22(1)	☐ Walls/ceiling/floors - repair/replace/clean/paint ☐ Radiator/Electric baseboard - repair/replace ☐ Door-handset/hinges/frame/room# - repair/replace ☐ S	Window-pane/frame/trim/hardware - repair/replace/clean Pests-rats/mice/roaches/bedbugs/fruit flies - pest control Electrical outlets/fixtures/cover plates - repair or replace Smoke alarm - repair/replace	1
Room No. s.22(1)	□ Walls/ceiling/floors - repair/replace/clean/paint       □ Radiator/Electric baseboard - repair/replace       □ Boor-handset/hinges/frame/room# - repair/replace       □ Soor-handset/hinges/frame/room# - repair/replace	Window-pane/frame/trim/hardware - repair/replace/clean Pests-rats/mice/roaches/bedbugs/fruit flies - pest control Electrical outlets/fixtures/cover plates - repair or replace Smoke alarm - repair/replace	2
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean ☐/Walls/ceiling/floors (repair/replace/clean/paint) ☐ Radiator/Electric baseboard - repair/replace ☐ Door-handset/hinges/frame/room# - repair/replace ☐ S	Window-pane/frame/trim/hardware - repair/replace/clean Pests/rats/mice/roaches/bedbugs/fruit flies - pest control Electrical outlets/fixtures/cover plates - repair or replace Smoke alarm / repair/replace	2
Room No. s.22(1)	□ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ B □ Door-handset/hinges/frame/room# - repair/replace □ S	Window-pane/frame/trim/hardware - repair/replace/clean Pests-rats/mice/roaches/bedbugs/fruit flies - pest control Electrical outlets/fixtures/cover plates - repair or replace Smoke alarm - repair/replace Sprinkler line - remove items Clutter/doorway access - 1 2 3	0
Room No. s.22(1)	□ Walls/ceiling/floors - repair/replace/clean/paint □ f □ Radiator/Electric baseboard - repair/replace □ E □ Door-handset/hinges/frame/room# - repair/replace □ S	Window-pane/frame/trim/hardware - repair/replace/clean Pests-rats/mice/poaches/bedbugs/fruit flies - pest control Electrical outlets/fixtures/cover plates - repair or replace Smoke alarm - repair/replace	1
Room No. s.22(1)	☐ Walls/ceiling/floors - repair/replace/clean/paint ☐ Radiator/Electric baseboard - repair/replace ☐ Boor-handset/hinges/frame/room# - repair/replace ☐ S	Window-pane/frame/trim/hardware - repair/replace/clean Pests-rats/mice/roaches/bedbugs/fruit flies - pest control Electrical outlets/fixtures/cover plates - repair or replace 5moke alarm - repair/replace	1
Room No. s.22(1)	□ Walls/ceiling/floors - repair/replace/clean/paint       □ / I         □ Radiator/Electric baseboard - repair/replace       □ E         □ Door-handset/hinges/frame/room# - repair/replace       □ Sink/plumbing/taps/leaks - repair/replace/unplug       □ C	Window-pane/frame/trim/hardware - repair/replace/clean Pests-rats/mice/roaches/bedbugs/fruit flies - pest control Electrical outlets/fixtures/cover plates - repair or replace Smoke alarm - repair/replace	Ī
Vacant	ZZU New bei	B leave Drucing	
No Access			
Inspected	s.22(1) s.22(1)		
Notes.22(1		OT DIA	Total
	occipancy.	of Jone. Retroft prior	8



Address 91	MAIN	ST
(Property Use)	SRCF-74	17-007589

Standards of Maintenance By-law No. 5462			
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean ☐ Walls/ceiling/floors - repair/replace/clean/paint ☐ Radiator/Electric baseboard - repair/replace ☐ Door-handset/hinges/frame/room# - repair/replace ☐ Sink/plumbing/taps/leaks - repair/replace/unplug	□ Window-pane/frame/trim/hardware - repair/replace/clean     □ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control     □ Electrical outlets/fixtures/cover plates - repair or replace     □ Smoke alarm - repair/replace □ Sprinkler line - remove items     □ Clutter/doorway access - 1□ 2□ 3□	I
	AMS - Clear of again	bally	
Room No. s.22(1)	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1 ☐ 2 ☐ 3 ☐	3
Room No. s.22(1)	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	□ Window-pane/frame/trim/hardware - repair/replace/clean     □ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control     □ Electrical outlets/fixtures/cover plates - repair or replace     □ Smoke alarm - repair/replace □ Sprinkler line - remove items     □ Clutter/doorway access - 1□ 2□ 3□	3
		Kanne ext. colds.	
Room No. s.22(1)	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	1
ROOM NO.	☐ Carpets/floor/baseboards - repair/replace/clean ☐ Walls/ceiling/floors - repair/replace/clean/paint ☐ Radiator/Electric baseboard - repair/replace ☐ Door handset/hinges/frame/room# - repair/replace ☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	2
	MENITOK!		100
Room No.	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/loaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	2
	BAIND SINK.		
Room No. s.22(1)	□ Carpets/floor/baseboards - repair/replace/clean □ (Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	2
Vacant			
Yacant	224		
No Access			
Inspected	s.22(1)	s.22(1)	- 19
	-610-6		1.274
Notes:			Total
			14



Address 917 MAIN ST (Property Use) SRCF-2017-2015

	Standards of Maintenan	ice By-law No. 5462	Violations
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean ☐ Walls/ceiling/floors - repair/replace/clean/paint ☐ Radiator/Electric baseboard - repair/replace ☐ Door-handset/hinges/frame/room# - repair/replace ☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	2
	Transport panel above door	TERM	1
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean ☐ Walls/ceiling/floors - repair/replace/clean/paint ☐ Radiator/Electric baseboard - repair/replace ☐ Door-handset/hinges/frame/room# - repair/replace ☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests:rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/(ixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1 ☐ 2 ☐ 3 ☐	3
Room No. s.22(1)	□ Carpets/floor/baseboards - repair/replace/clean □ (Walls/celling/floors - (repair/replace/clean/paint) □ Radiator/Electric basebbard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1 ☐ 2 ☐ 3 ☐	1
	Private Sower		
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean ☐ Walls/ceiling/floors - repair/replace/clean/paint ☐ Radiator/Electric baseboard - repair/replace ☐ Door-handset/hinges/frame/room# - repair/replace ☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1 ☐ 2 ☐ 3 ☐	1
	No HOD ROW		
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean ☐ Walls/ceiting/floors - repair/replace/clean/paint ☐ Radiator/Electric baseboard - repair/replace ☐ Door-handset/hinges/frame/room# - repair/replace ☐ Sink/plumbing/taps/leaks/repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	2
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean☐ Walls/ceiling/floors - repair/replace/clean/paint☐ Radiator/Electric baseboard - repair/replace☐ Door-handset/hinges/frame/room# - repair/replace☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	1
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean ☐ Walls/ceiting/floors - repair/replace/clean/paint ☐ Radiator/Electric baseboard - repair/replace ☐ Door-handset/hinges/frame/room# - repair/replace ☐ Sink/plumbing/taps/leaks - tepair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	2
Vacant			
No Access			
	22(4)		
Inspected	s.22(1)		
Notes:	some security comes	from roomor box it.	Total



Address 917 MAIN ST (Property Use) SR 97-2017-00158

	Standards of Maintenar	nce By-law No. 5462	Violations
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean ☐ Walls/ceiting/floors - repair/replace/clean/paint ☐ Radiator/Electric baseboard - repair/replace ☐ Door-handset/hinges/frame/room# - repair/replace ☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	2
	NO DZO		
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean☐ Walls/ceiling/floors - repair/replace/clean/paint☐ Radiator/Electric baseboard - repair/replace☐ Door-handset/hinges/frame/room# - repair/replace☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	1
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean ☐ Walls/celling/floors - repair/replace/clean/paint ☐ Radiator/Electric baseboard - repair/replace ☐ Door-handset/hinges/frame/room# - repair/replace ☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit ffies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	2
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean ☐ Walls/ceiling/floors - repair/replace/clean/paint ☐ Radiator/Electric baseboard - repair/replace ☐ Door-handset/hinges/frame/room#_repair/replace ☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	2
Room No. s.22(1)	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors (repair/replace/clean/paint) □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	□ Window-pane/frame/trim/hardware - repair/replace/clean     □ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control     □ Electrical outlets/fixtures/cover plates - repair or replace     □ Smoke alarm - repair/replace □ Sprinkler line - remove items     □ Clutter/doorway access - 1□ 2□ 3□	2
	Mogrationes on cating	Jual Texp. relastes	
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean☐ Walls/ceiling/floors - repair/replace/clean/paint☐ Radiator/Electric baseboard - repair/replace☐ Door-handset/hinges/frame/room# - repair/replace☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1 ☐ 2 ☐ 3 ☐	1
	NO HOT HED		
Room No. s.22(1)	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Doop handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	1
	GAP IN FRANCE		4
Vacant	The state of the s		
No Access			
Inspected	#_ s.22(1)		
Notes:	- H		Total
Notes: s.22	- Report/report	unit; lebrate territ	Total
	EVICTION! NOTICE	it haited	11



Address 917 MAIN ST

(Property Use) SR <u>CF-2017-00758</u>

	Standards of Maintenan	ce By-law No. 5462	Violations
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean☐ Walls/ceiling/floors - repair/replace/clean/paint☐ Radiator/Electric baseboard - repair/replace☐ Door-handset/hinges/frame/room# - repair/replace☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1 ☐ 2 ☐ 3 ☐	0
		Remove umboela	
Room No. s.22(1)	Carpets/floor/baseboards - repair/replace/clean Walls/ceiling/floors - repair/replace/clean/paint Radiator/Electric baseboard - repair/replace Door-handset/hinges/frame/room# - repair/replace Sink/plumbing/taps/leaks - repair/replace/unplug	□ Window-pane/frame/trim/hardware - repair/replace/clean     □ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control     □ Electrical outlets/fixtures/cover plates - repair or replace     □ Smoke alarm - repair/replace □ Sprinkler line - remove items     □ Clutter/doorway access - 1□ 2□ 3□	1
	* Remove security cames	a from from ox box itleadifies	)
Room No. s.22(1)	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1 ☐ 2 ☐ 3 ☐	2
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean ☐ Walls/ceiling/floors - repair/replace/clean/paint ☐ Radiator/Electric baseboard - repair/replace ☐ Door-handset/hinges/frame/room# - repair/replace ☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	2
	100		
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean ☐ Walls/ceiling/floors - repair/replace/clean/paint ☐ Radiator/Electric baseboard - repair/replace ☐ Door/handset/hinges/frame/room# - repair/replace ☐ Sint/plumbing/taps/fleaks - repair/replace/unplug	□ Window-pane/frame/trim/hardware - repair/replace/clean     □ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control     □ Electrical outlets/fixtures/cover plates - repair or replace     □ Smoke alarm - repair/replace □ Sprinkler line - remove items     □ Clutter/doorway access - 1□ 2□ 3□	3
	dell-closes		
Room No. s.22(1)	Carpets/floor/baseboards - repair/replace/clean Walls/ceiling/floors - repair/replace/clean/paint Radiator/Electric baseboard - repair/replace Door-handset/hinges/frame/room# - repair/replace Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1 ☐ 2 ☐ 3 ☐	ı
	The state of the s		
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean☐ Walls/ceiling/floors - repair/replace/clean/paint☐ Radiator/Electric baseboard - repair/replace☐ Door-handset/hinges/frame/room# - repair/replace☐ Sink/plumbing/taps/leaks - repair/replace/unplug	□ Window-pane/frame/trim/hardware - repair/replace/clean     □ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control     □ Etectrical/outlets/fixtures/cover plates - repair or replace     □ Smoke alarm - repair/replace □ Sprinkler line - remove items     □ Clutter/doorway access - 1□ 2□ 3□	2
Vacant			
No Access			
Inspected	s.22(1)		
Notes: #	to be writed a	a end of Ine	Total
	complete and to	erling report E point	11



Address 91	7 MAIN	ST
(Property Use)	SRCF-2017	-00750

	Standards of Maintenance By-law No. 5462	Violations
Room No. s.22(1)	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/Ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug □ Window-pane/frame/trim/hardware - repair/replace/clean □ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control □ Electrical outlets/fixtures/cover plates - repair or replace □ Smoke alarm - repair/replace □ Sprinkler line - remove items □ Clutter/doorway access - 1□ 2□ 3□	1
VACANT Room No.	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door/handset/hinges/frame/room# - repair/replace □ Sinto/plumbing/taps/leaks - repair/replace/unplug □ Clutter/doorway access - 1□ 2□ 3□	2
Room No. s.22(1)	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug □ Window-pane/frame/trim/hardware - repair/replace/clean □ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control □ Electrical outlets/fixtures/cover plates - repair or replace □ Smoke alarm - repair/replace □ Sprinkler line - remove items □ Clutter/doorway access - 1□ 2□ 3□	1
Room No. s.22(1)	□ Carpets/floor/baseboards / repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room// - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug □ Clutter/doorway access - 1□ 2□ 3□	1
Room No. s.22(1)	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sirik/plumbing/taps/leaks - repair/replace/unplug □ Sirik/plumbing/taps/leaks - repair/replace/unplug □ Window-pane/frame/trim/hardware - repair/replace/clean □ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control □ Electrical outlets/fixtures/cover plates - repair or replace □ Smoke alarm - repair/replace □ Sprinkler line - remove items □ Clutter/doorway access - 1□ 2□ 3□	1
Room No. s.22(1)	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug □ Clutter/doorway access - 1□ 2□ 3□	2:
Room No. s.22(1)	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug □ Window-pane/frame/trim/hardware - repair/replace/clean □ Pests rats/mice/reaches/bedbugs/fruit flies - pest control □ Electricatioutlets/fixtures/cover plates - repair or eplace □ Smoke alarm - repair/replace □ Sprinkler line - remove items □ Clutter/doorway access - 1□ 2□ 3□	-2
Vacant No Access	410	
Inspected	s.22(1) s.22(1)	
Notes:	2.44(1)	Total
notes:		10



Address 917 MAIN ST

(Property Use) SR CF-2017-00158

Jana	Standards of Maintenance	ce By-law No. 5462	Violation
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean ☐ Walls/ceiling/floors - repair/replace/clean/paint ☐ Radiator/Electric baseboard - repair/replace ☐ Door-handset/hinges/frame/room# - repair/replace ☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Rests rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	1
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean☐ Walls/ceiling/floors - repair/replace/clean/paint☐ Radiator/Electric baseboard - repair/replace☐ Door-handset/hinges/frame/room# - repair/replace☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	1
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean ☐ Walls/ceiling/floors - repair/replace/clean/paint ☐ Radiator/Electric baseboard - repair/replace ☐ Door/handset/hinges/frame/room# - repair/replace ☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	1
Room No. s.22(1)	□ Carpets/floor/baseboards - repair/replace/clean □ Walls/ceiling/floors - repair/replace/clean/paint □ Radiator/Electric baseboard - repair/replace □ Door-handset/hinges/frame/room# - repair/replace □ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates > repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	2
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean ☐ Walls/ceiling/floors - repair/replace/clean/paint ☐ Radiator/Electric baseboard - repair/replace ☐ Door-handset/hinges/frame/room# - repair/replace ☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line = remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	1
	F/E/SOUDS(NOT	hollow and	
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean ☐ Walls/ceiling/floors - repair/replace/clean/paint ☐ Radiator/Electric baseboard - repair/replace ☐ Door handset/ninges/frame/room# - repair/replace ☐ Sink/plumbing/paps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm - repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	2
	self-closes		
Room No. s.22(1)	☐ Carpets/floor/baseboards - repair/replace/clean☐ Walls/ceiling/floors - repair/replace/clean/paint☐ Radiator/Electric baseboard - repair/replace☐ Door-handset/hinges/frame/room# - repair/replace☐ Sink/plumbing/taps/leaks - repair/replace/unplug	☐ Window-pane/frame/trim/hardware - repair/replace/clean ☐ Pests-rats/mice/roaches/bedbugs/fruit flies - pest control ☐ Electrical outlets/fixtures/cover plates - repair or replace ☐ Smoke alarm _repair/replace ☐ Sprinkler line - remove items ☐ Clutter/doorway access - 1☐ 2☐ 3☐	0
Vacant			/ 4
No Access			
Inspected	s.22(1)		
The same of	5-22(1)		#32 W
Notes:			Total
			9



### MEMORANDUM - PROSECUTION REFERRAL

February 8, 2018

TO: File

COPY: Mike Elliston

FROM: Sherry Martel

By-law Enforcement Coordinator

SUBJECT: 917 Main Street CF-2017-007589

Charges have been referred to the By-law Prosecutor regarding:

Failing to comply with our order of December 20, 2017 to correct all of the 62 deficiencies ON OR BEFORE JANUARY 22, 2018.

- \*\*\* Photos included
- \*\*\* Registered Mail delivery receipts included
- \*\*\* Five deficiencies are outstanding (57 of 62 have been corrected).

Sherry Martel /sm



#### DEVELOPMENT, BUILDINGS AND LICENSING

#### **REGISTERED AND REGULAR MAIL**

PLEASE REFER TO:

Adrian Cashato
Building Inspector
at 604.871.6141
adrian.cashato@vancouver.ca
CF-2017-012422

# ORDER

October 13, 2017

Northstar International Motor Hotel Ltd. 917 Main Street Vancouver, BC V6A 2V8

Northstar International Motor Hotel Ltd. 6626 Angus Drive Vancouver, BC V6P 5H9

Dear Sir/Madam:

RE: 917 Main Street - Cobalt Hotel (and also 915 Main Street)

A recent inspection was carried out by a Building Inspector and a Property Use Inspector and the following violations were reported, in contravention of the Building By-law as follows:

1. Evidence of water ingress in the center, east/west hallways was found on all floor levels. Recent wall and ceiling repairs have taken place, making accurate diagnoses difficult.

Note: A Building Permit will be required to commence exploratory work to locate the source of the water leak.

To apply for the required Building Permit, please contact our Enquiry Centre at 604.873.7611 for further information regarding permit and/or plan submission requirements or to schedule an appointment with an Enquiry Centre Officer.

In accordance with Article 1.5.4.2. of Division C of the Building By-law, YOU ARE ORDERED TO:

1. **IMMEDIATELY** commence any repair work (paint, wall and ceiling repair) in all common hallways throughout the building with aquaboard in a temporary nature to maintain fire stopping, but can be easily removed for inspection and repair of the plumbing system; **AND** 

- 2. Obtain the required Building Permit to commence exploratory work to locate the source of the water leak ON OR BEFORE OCTOBER 27, 2017; AND
- 3. Hire a Mechanical Engineer to do an assessment of the water and plumbing system including the heating system throughout the building, and to provide a report of the full review of the plumbing and heating system in the building ON OR BEFORE NOVEMBER 14, 2017.

Note: Trades Permits and/or additional Building Permits may be required to make the necessary repairs.

FAILURE TO COMPLY WITH THIS ORDER WILL RESULT IN THIS MATTER BEING REFERRED TO THE CITY PROSECUTOR FOR THE LAYING OF CHARGES AND WILL NOT ABSOLVE YOU FROM COMPLYING.

If you have any questions regarding this Order, please contact Adrian Cashato, Building Inspector, at 604.871.6141 or by email to adrian.cashato@vancouver.ca.

Yours truly,

P. Ryan, M. Sc., P. Eng. Chief Building Official and

Director, Building Code and Policy

AC/ss

Copy: Posted on building



Mailing Address: PO Box 9431 Stn Prov Govt Victoria BC V8W 9V3

www.corporateonline.gov.bc.ca

Location: 2nd Floor - 940 Blanshard Street Victoria BC 1 877 526-1526

# **BC Company Summary**

For

# NORTHSTAR INTERNATIONAL MOTOR HOTEL LTD.

Date and Time of Search:

October 12, 2017 02:46 PM Pacific Time

**Currency Date:** 

September 28, 2017

#### **ACTIVE**

**Incorporation Number:** 

BC0255124

Name of Company:

NORTHSTAR INTERNATIONAL MOTOR HOTEL LTD.

35.

Recognition Date:

Incorporated on September 24, 1982

In Liquidation: No

Last Annual Report Filed:

September 24, 2016

Receiver: No

#### DISSOLUTION/RESTORATION INFORMATION

Filing/Event

**Date of Filing** 

**Full Restoration** 

April 30, 1987

Dissolved - Failure to File

February 14, 1986

#### REGISTERED OFFICE INFORMATION

Mailing Address:

915-917 MAIN STREET., VANCOUVER BC V6A 2V8

CANADA

**Delivery Address:** 

915-917 MAIN STREET., **VANCOUVER BC V6A 2V8** 

CANADA

#### RECORDS OFFICE INFORMATION

Mailing Address:

6626 ANGUS STREET. VANCOUVER BC V6P 5H9

CANADA

Delivery Address:

6626 ANGUS DRIVE

VANCOUVER BC V6P 5H9

CANADA

#### **DIRECTOR INFORMATION**

Last Name, First Name, Middle Name:

SAHOTA, PARKASH

Mailing Address:

6626 ANGUS DRIVE

VANCOUVER BC V6P5H9

**Delivery Address:** 

6626 ANGUS DRIVE

**VANCOUVER BC V6P5H9** 

Last Name, First Name, Middle Name:

SINGH, GURDYAL

**Mailing Address:** 

6626 ANGUS DRIVE

VANCOUVER, BC V6P5H9

**Delivery Address:** 

6626 ANGUS DRIVE

VANCOUVER, BC V6P5H9

OFFICER INFORMATION AS AT September 24, 2016

Last Name, First Name, Middle Name:

SINGH, GURDYAL

Office(s) Held: (President, Secretary)

Mailing Address:

6626 ANGUS DRIVE

VANCOUVER, BC V6P5H9

**Delivery Address:** 

6626 ANGUS DRIVE

VANCOUVER, BC V6P5H9

Folio: 190-601-27-0000

Civic: 915 MAIN ST

Size: 12566.25 SQUARE FEET

Pid: 015-642-640

Legal: LT 4 BLK 23 PL VAP184 DL 196 NWD

Owner: NORTHSTAR INTERNATIONAL MOTOR

HOTEL LTD 6626 ANGUS DR

VANCOUVER BC V6P 5H9

(K62904L)

**Attribute** 

ACTUAL USE MANUAL CLASS

**NEIGHBOURHOOD** PULL LIST

SCHOOL DISTRICT

Value 056

Description

MF - RESIDENTIAL HOTEL

C761

Beer Parlour/Hotel

030

NC030

999 MULTI-C MULTI-CLASS

39

CITY OF VANCOUVER

Title Search Report

Title: GD24362

Printed: Oct. 12, 2017 2:48 PM

Application for registration received on: Feb. 21, 1990

Entered on: Mar. 28, 1990

Declared value: From Title:

Taxation Authority: City of Vancouver

#### REGISTERED OWNERS IN FEE SIMPLE

NORTHSTAR INTERNATIONAL MOTOR HOTEL LTD. Inc. No:

(INC. NO. 255124) 6626 ANGUS DRIVE VANCOUVER,

B.C.

#### **PARCELS**

Parcel Identifier: 015642640

Short Legal Description: S/184///23//4

**Description of Land:** 

LOT 4 BLOCK 23 DISTRICT LOT 196 PLAN 184

#### **LEGAL NOTATIONS**

No legal notations

#### **CHARGES**

Charge Number: 199668M

Date registered: Dec. 21, 1954

Nature: EASEMENT AND INDEMNITY AGREEMENT

Owner: CITY OF VANCOUVER

Remarks:

INTER ALIA

#### City Notes:

· One commercial crassing over sidewalk and boulevard

City Charge Type: EIA City EIA Type: Crossing

- \* Caution -- all charges may not be shown or appear in order of priority
- \* Current information only -- no cancelled information shown



#### REGISTERED AND REGULAR MAIL

October 17, 2017

PLEASE REFER TO:
M. Elliston
Property Use Inspector
at 604.871.6968
mike.elliston@vancouver.ca
CF-2017-012471

# **ORDER**

Northstar International Motor Hotel Ltd. 915 - 917 Main Street Vancouver BC V6A 2V8

Northstar International Motor Hotel Ltd. 6626 Angus Drive Vancouver BC V6P 5H9

Dear Sir/Madam:

RE: 917 Main Street and also 915 Main Street - Cobalt Hotel

During an inspection carried out a Property Use Inspector on September 26, 2017, the inspector observed pest control issues and maintenance issues in various rooms in your building at the above location.

The above is in contravention of the Standards of Maintenance By-law #5462.

The Standards of Maintenance (SofM) By-law sets out a variety of requirements for lodging houses. In particular, section 21.10 reads:

- 21.10 Every lodging house owner shall at all times keep or maintain the lodging house:
- (a) in a thoroughly clean and sanitary condition, including windows and lightwells;
- (b) free of pests, including insects and rodents;
- (c) fixtures and appliances in good working order and repair;
- (d) floors, stairs, doors, walls and windows in good working order and repair;
- (e) heating system in good working order and repair; and
- (f) sinks, toilets and bathing fixtures in good working order and repair.

#### The inspector noted:

```
s.22(1)
                    Pests (bedbugs) - provide pest control services. (SofM 21.10 (b))
1.
2.
                    Pests (roaches) - provide pest control services. (SofM 21.10 (b))
3.
                    Pests (bedbugs) - provide pest control services. (SofM 21.10 (b))
                    Pest infested mattress is not in a clean and sanitary condition
4.
                    new mattress to be provided. (SofM 21.15)
5.
                    Pests (bedbugs) - provide pest control services. (SofM 21.10 (b))
                    Pests (bedbugs) - provide pest control services. (SofM 21.10 (b))
6.
                    Pests (bedbugs) - provide pest control services. (SofM 21.10 (b))
7.
                    Pests (mice) - provide pest control services. (SofM 21.10 (b))
8.
9.

    Pests (mice) - provide pest control services. (SofM 21.10 (b))

10.
                 - Mouse holes in baseboards - holes to be repaired. (SofM 21.10 (d))
11.

    Pests (mice and roaches) -provide pest control services. (SofM 21.10 (b))

12.

    Mouse holes under sink - holes to be repaired. (SofM 21.10 (d))

13.
                    Pests (bedbugs and roaches) - provide pest control services. (SofM 21.10 (b))
14.

    Pests (mice) - provide pest control services. (SofM 21.10 (b))

15.

    Mouse holes in baseboards & behind radiator - holes to be repaired (SofM 21.10 (d))

16.

    Pests (mice and roaches) -provide pest control services. (SofM 21.10 (b))

17.
                  - Mouse holes in walls - holes to be repaired. (SofM 21.10 (d))
18.
                 - Pests (mice and roaches) -provide pest control services. (SofM 21.10 (b))
19.
                  - Mouse holes in walls - holes to be repaired. (SofM 21.10 (d))
```

Therefore, in accordance with Subsection 23.2 of the Standards of Maintenance By-law, you are <u>ordered</u> to:

- 1. CORRECT ALL MAINTENANCE DEFICIENCIES DETAILED ABOVE (item nos. 4, 10, 12, 15, 17 & 19); AND
- 2. PROVIDE THE PROPERTY USE INSPECTOR WITH DOCUMENTATION FROM A CERTIFIED PEST CONTROL TREATMENT COMPANY OUTLINING THE PEST CONTROL TREATMENT SERVICES CURRENTLY BEING CARRIED OUT IN THE ABOVE ROOMS (items nos. 1, 2, 3, 5, 6, 7, 8, 9, 11, 13, 14, 16, & 18) IN THE BUILDING AT THE ABOVE LOCATION:

on or before OCTOBER 27<sup>TH</sup>, 2017.

# FAILURE TO COMPLY WITH THIS ORDER WILL RESULT IN THIS MATTER BEING REFERRED TO THE CITY PROSECUTOR FOR THE LAYING OF CHARGES.

If you have any questions regarding this Order, please contact Mr. E. Elliston, Property Use Inspector at 604.871.6968 or via email to <a href="mike.elliston@vancouver.ca">mike.elliston@vancouver.ca</a>.

Yours truly,

Yours truly,

P. Ryan, M. Sc., P. Eng. Chief Building Official and Director, Building Code and Policy

ME/dlb

Kathryn Holm, P. Eng. Chief Licence Inspector and Director of Licences and Inspections .



Mailing Address: PO Box 9431 Stn Prov Govt Victoria BC V8W 9V3 www.corporateonline.gov.bc.ca

2nd Floor - 940 Blanshard Street Victoria BC

1 877 526-1526

# **BC Company Summary**

For

### NORTHSTAR INTERNATIONAL MOTOR HOTEL LTD.

Date and Time of Search:

October 16, 2017 01:24 PM Pacific Time

**Currency Date:** 

PT 924

September 28, 2017

#### **ACTIVE**

**Incorporation Number:** 

BC0255124

Name of Company:

NORTHSTAR INTERNATIONAL MOTOR HOTEL LTD.

Recognition Date:

Incorporated on September 24, 1982

In Liquidation: No

**Last Annual Report Filed:** 

September 24, 2016

Receiver:

Nο

#### DISSOLUTION/RESTORATION INFORMATION

ALCOHOL: NO.

Filing/Event

**Date of Filing** 

**Full Restoration** 

April 30, 1987

Dissolved - Failure to File

February 14, 1986

#### REGISTERED OFFICE INFORMATION

**Mailing Address:** 

915-917 MAIN STREET.,

VANCOUVER BC V6A 2V8

CANADA

**Delivery Address:** 

915-917 MAIN STREET:, VANCOUVER BC V6A 2V8

CANADA

#### RECORDS OFFICE INFORMATION

**Mailing Address:** 

6626 ANGUS STREET

**VANCOUVER BC V6P 5H9** 

CANADA

**Delivery Address:** 

6626 ANGUS DRIVE

**VANCOUVER BC V6P 5H9** 

CANADA

# DIRECTOR INFORMATION

Last Name, First Name, Middle Name:

SAHOTA, PARKASH

**Mailing Address:** 

6626 ANGUS DRIVE

**VANCOUVER BC V6P5H9** 

**Delivery Address:** 

6626 ANGUS DRIVE

VANCOUVER BC V6P5H9

Last Name, First Name, Middle Name:

SINGH, GURDYAL

Mailing Address:

6626 ANGUS DRIVE VANCOUVER, BC V6P5H9 **Delivery Address:** 

6626 ANGUS DRIVE

VANCOUVER, BC V6P5H9

### OFFICER INFORMATION AS AT September 24, 2016

Last Name, First Name, Middle Name:

SINGH, GURDYAL

Office(s) Held: (President, Secretary)

**Mailing Address:** 

6626 ANGUS DRIVE

VANCOUVER, BC V6P5H9

**Delivery Address:** 

6626 ANGUS DRIVE

VANCOUVER, BC V6P5H9

Folio: 190-601-27-0000 Civic: 915 MAIN ST

Size: 12566.25 SQUARE FEET

Pid: 015-642-640

Legal: LOT 4 BLOCK 23 PLAN VAP184 DISTRICT LOT 196

NEW WESTMINSTER LOT 2, BLOCK 23, PLAN VAP184,

DISTRICT LOT 196, NEW WESTMINSTER LAND

DISTRICT, COBALT HOTEL.

**Owner: NORTHSTAR INTERNATIONAL MOTOR** 

HOTEL LTD 6626 ANGUS DR

VANCOUVER BC V6P 5H9

(K62904L)



#### DEVELOPMENT, BUILDINGS AND LICENSING

#### REGISTERED AND REGULAR MAIL

PLEASE REFER TO:

M. Elliston
Property Use Inspector
at 604.871.6968
mike.elliston@vancouver.ca
CF-2017-013186

# **ORDER**

November 14, 2017

Northstar International Motor Hotel Ltd. 915 - 917 Main Street Vancouver BC V6A 2V8

Northstar International Motor Hotel Ltd. 6626 Ángus Drive Vancouver BC V6P 5H9

Dear Sir/Madam:

RE: 917 Main Street and also 915 Main Street - Cobalt Hotel

On October 31, 2017, our inspection services carried out an inspection in your building at the above location and reported that the hot water system and the heating system are not in compliance with Section 21.4 and Section 21.10 of the Standards of Maintenance (SofM) Bylaw, respectively, which state:

Section 21.4 - Every lodging house operator shall provide:

(a) that, where this By-law requires plumbing fixtures to have hot water, such fixtures shall be connected to a service water heating facility which provides water at a temperature range of 120°F (49°C) and a maximum of 140°F (60°C) at all times at each fixture.

Section 21.10 - Every lodging house owner shall at all times keep or maintain the lodging house:

- (c) fixtures and appliances in good working order and repair;
- (e) heating system in good working order and repair.

The following violations were reported:

- Hot water not working, water in both taps runs cold. Violation of SofM 21.4 (a) Hot water tap 43.2°C. Violation of SofM 21.4 (a) 2. 3. Radiator not working. Violation of SofM 21.10 (c) & (e) Hot water tap 24.7°C. Violation of SofM 21.4 (a) 4. Hot water tap 44.1°C. Violation of SofM 21.4 (a) 5. Hot water tap 40.7°C. Violation of SofM 21.4 (a) 6. Violation of SofM 21.10 (c) & (e) 7. Radiator not working.
- 3rd Floor South Side Bathtub Hot water tap 44.1°C. Violation of SofM 21.4 (a)

Hot and cold water taps do not work.

- 10. 4th Floor SW Shower No hot water (only cold). Violation of SofM 21.4 (a)
- 11. 1st Floor West Side Corridor Radiator not working. Violation of SofM 21.10 (c) & (e)
- 12. 2nd Floor West Side Corridor Radiator not working. Violation of SofM 21.10 (c) & (e)
- 13. 3rd Floor West Side Corridor Radiator not working. Violation of SofM 21.10 (c) & (e)
- 4th Floor West Side Corridor Radiator not working. Violation of SofM 21.10 (c) & (e)

Therefore, in accordance with Subsection 23.2 of the Standards of Maintenance By-law, you are ordered to IMMEDIATELY:

1. Correct all the deficiencies detailed above (item nos. 1 thru 14).

FAILURE TO COMPLY WITH THIS ORDER WILL RESULT IN THIS MATTER BEING REFERRED TO THE CITY PROSECUTOR FOR THE LAYING OF CHARGES. THIS MAY RESULT IN SIGNIFICANT FINES BEING LEVIED AGAINST YOU AND WILL NOT ABSOLVE YOU FROM COMPLYING.

If you have any questions, please contact Mr. M. Elliston, Property Use Inspector, at 604.871.6968 or via email to mike.elliston@vancouver.ca.

Yours truly.

8.

Yours truly.

P. Ryan, M. Sc., P. Eng. Chief Building Official and

Director, Building Code and Policy

Kathryn Holm, P. Eng. Chief Licence Inspector and

Director of Licences and Inspections

Violation of SofM 21.4 (a)

ME/dlb



Mailing Address: PO Box 9431 Stn Prov Govt Victoria BC V8W 9V3 www.corporateonline.gov.bc.ca

Location: 2nd Floor - 940 Blanshard Street Victoria BC 1 877 526-1526

# **BC Company Summary**

For

### NORTHSTAR INTERNATIONAL MOTOR HOTEL LTD.

Date and Time of Search:

November 07, 2017 08:19 AM Pacific Time

**Currency Date:** 

October 17, 2017

### **ACTIVE**

**Incorporation Number:** 

BC0255124

Name of Company:

NORTHSTAR INTERNATIONAL MOTOR HOTEL LTD.

**Recognition Date:** 

Incorporated on September 24, 1982

In Liquidation: No

Last Annual Report Filed:

September 24, 2016

Receiver: No

### DISSOLUTION/RESTORATION INFORMATION

Filing/Event

**Date of Filing** 

**Full Restoration** 

April 30, 1987

Dissolved - Failure to File

February 14, 1986

#### REGISTERED OFFICE INFORMATION

**Mailing Address:** 

915-917 MAIN STREET., VANCOUVER BC V6A 2V8

CANADA

**Delivery Address:** 

915-917 MAIN STREET., VANCOUVER BC V6A 2V8

**CANADA** 

#### RECORDS OFFICE INFORMATION

**Mailing Address:** 

6626 ANGUS STREET, VANCOUVER BC V6P 5H9

CANADA

**Delivery Address:** 

6626 ANGUS DRIVE

VANCOUVER BC V6P 5H9

CANADA

# DIRECTOR INFORMATION

Last Name, First Name, Middle Name:

SAHOTA, PARKASH

**Mailing Address:** 

6626 ANGUS DRIVE

VANCOUVER BC V6P5H9

**Delivery Address:** 

6626 ANGUS DRIVE

VANCOUVER BC V6P5H9

Last Name, First Name, Middle Name:

SINGH, GURDYAL

**Mailing Address:** 

6626 ANGUS DRIVE VANCOUVER, BC V6P5H9 **Delivery Address:** 

6626 ANGUS DRIVE

VANCOUVER, BC V6P5H9

OFFICER INFORMATION AS AT September 24, 2016

Last Name, First Name, Middle Name:

SINGH, GURDYAL

Office(s) Held: (President, Secretary)

Mailing Address:

6626 ANGUS DRIVE

VANCOUVER, BC V6P5H9

**Delivery Address:** 

6626 ANGUS DRIVE

VANCOUVER, BC V6P5H9

BC0255124 Page: 2 of 2

Folio: 190-601-27-0000

Civic: 915 MAIN ST

Size: 12566.25 SQUARE FEET

Pid: 015-642-640

Legal: LOT 4 BLOCK 23 PLAN VAP184 DISTRICT LOT 196

NEW WESTMINSTER LOT 2, BLOCK 23, PLAN VAP184,

DISTRICT LOT 196, NEW WESTMINSTER LAND

DISTRICT, COBALT HOTEL.

Owner: NORTHSTAR INTERNATIONAL MOTOR

HOTEL LTD 6626 ANGUS DR

VANCOUVER BC V6P 5H9

(K62904L)

· '	•	
	ž.	
	. Î	
	,	
		46
•		
		the state of
		* J.
		in the second of
		in the second of
		And December 1997 And December

CITY OF VANCOUVER

Title Search Report

Title: K62904

Printed: Nov. 7, 2017 8:18 AM

Application for registration received on: Sep. 30, 1982

Entered on: Mar. 28, 1990

Declared value: From Title: J58006

Taxation Authority: City of Vancouver

#### REGISTERED OWNERS IN FEE SIMPLE

NORTHSTAR INTERNATIONAL MOTOR HOTEL LTD. Inc. No:

(INC. NO. 255124) 6626 ANGUS DRIVE VANCOUVER,

B.C.

#### **PARCELS**

Parcel Identifier: 015642623

Short Legal Description: S/184///23//2

**Description of Land:** 

LOT 2 BLOCK 23 DISTRICT LOT 196 PLAN 184

#### **LEGAL NOTATIONS**

No legal notations

#### **CHARGES**

Charge Number: 199668M Date registered: Dec. 21, 1954

Nature: EASEMENT AND INDEMNITY AGREEMENT

Owner: CITY OF VANCOUVER

Remarks:

• INTER ALIA

City Notes:

One commercial crassing over sidewalk and boulevard

City Charge Type: EIA City EIA Type: Crossing

- \* Caution -- all charges may not be shown or appear in order of priority
- \* Current information only -- no cancelled information shown