



File No.: 04-1000-20-2018-228

May 9, 2018

s.22(1)

Dear s.22(1)

Re: Request for Access to Records under the Freedom of Information and Protection of Privacy Act (the "Act")

I am responding to your request of April 17, 2018 for:

Any documents related to an oil tank removal project at 6138 Angus Drive, Vancouver. Date Range: January 1, 2000 to April 17, 2018

All responsive records are attached. Some information in the records has been severed, (blacked out), under s.22(1) of the Act. You can read or download this section here: http://www.bclaws.ca/EPLibraries/bclaws new/document/ID/freeside/96165 00

Under section 52 of the Act you may ask the Information & Privacy Commissioner to review any matter related to the City's response to your request. The Act allows you 30 business days from the date you receive this notice to request a review by writing to: Office of the Information & Privacy Commissioner, info@oipc.bc.ca or by phoning 250-387-5629.

If you request a review, please provide the Commissioner's office with: 1) the request number assigned to your request (#04-1000-20-2018-228); 2) a copy of this letter; 3) a copy of your original request for information sent to the City of Vancouver; and 4) detailed reasons or grounds on which you are seeking the review.

Yours truly,

Barbara J. Van Fraassen, BA Director, Access to Information & Privacy

<u>Barbara.vanfraassen@vancouver.ca</u> 453 W. 12th Avenue Vancouver BC V5Y 1V4

*If you have any questions, please email us at foi@vancouver.ca and we will respond to you as soon as possible. Or you can call the FOI Case Manager at 604.871.6584.

Encl.

:ma

453 WEST 12TH VANCOUVER, B.C. V5Y 1V4 TEL: 604-873-7595 FAX: 604-873-7100

CITY OF VANCOUVER

JUNE 22, 2015	PERMIT TYPE	IRE PREVEN	NTION DIVIS	ION PERI	MIT	P FI 412357
LEGAL DESCRIPTION LT 2 BLK 3 E ADDITIONAL ADDRESS INFORM	PL VAP5279 DL 526	NWD PLAN VAI	P5279 (con	z'd)	6138 ANGU	IS DRIVE
		4.2659				
JUN 22, 2015	PURPOSE PROJECT VI	ILUE ASS	ESSED VALUE	PLANS METRIC	PLACE NAME	
TEMPORARY PERMIT DATES		TEMPORARY USE DATES		NO	SUBTYPE	
					CO-ORDINATE	
			<u> </u>		120-758-1	.8-0000
CONTRACTOR TANKTECH ENVI C/O IAN GROVE BOX 5612 SQUAMISH	IRONMENTAL SERVICE ES BC V8B 0C2	CONTACT 2 PROPERTY OF S.22(1) VANCOUVER	WNER BC		CONTACT 3	
TEL 604-880-9007 FAX 604-628-2266	BUS.LICENSE 326305 CERTIFICATE	TEL FAX	BUS.LICENSE CERTIFICATE		TEL FAX	BUS.LICENSE CERTIFICATE
PERMIT CONDITIONS 001 THE WORK UNDER 020 Clearance is a 1030 For removal: 1 liquids removal permanently se 040 Tank removal n 055 New tank insta 910 Construction n 1 This permit (a) Work at (b) Work at (b) Work As 2. Inspection 3. The premise Work Safe a 4. Contractor 5. If the soil 6. Backfill wi 7. Underground 8. Environment GENERAL USE D30 ONE-FAM DWELL	THIS PERMIT IS AUTHORIZ required from the Enginee the tanks, together with each tanks, together with ed. The tanks and piping saled by capping or plugg must comply with subsectiallation must comply with must be carried out in cot will become incomplete ithorized by the permit has been substantially dis is required by Vanccuver es shall be kept in safe and City By-laws. Or homeowner must be on I surrounding the storage the clean soil required. It storage tank removal shall Final Closure Report	ED PURSUANT TO TH ring Department, connected piping must be removed ing. on 4.10.3 of the Part 4 of the Va mpliance with the if any of the fol as not commenced continued for a p Fire and Rescue manner with guard site for the insp tank is contamin all be done in ac and clearance req N AREA (SF) INCLUDE:	Streets Division and dispensing from the ground from the ground Vancouver Fire By provisions of clowing condition within 90 days period of 90 days Services. Its, shoring, etc. pection by the Vanted, the soil is cordance with gauired.	equipment, sh and purged o By-law. law. Noise Control ns are not me from the date as required ancouver Fire shall be repl bod engineeri JSE	all have all confivations. The By-law No. 65: t: of issuance. by the Occupation and Rescue Seaced with clear	ombustible or flammable e pipe ends must be 55 tional Health, rvices. n fill.
is open 7 days message line i AS OWNER OR OWNERS CORRECT, AND DESCR THAT RESPONSIBILIT INDEMNIFY AND SAVE AND EXPENSES OF EV.	Pection call 3-1-1 from a week from 7AM to 10PM is 604-873-7058. For inf is 604-873-7058. For in	THAT THE INFORMATION OF ITS OFFICENTIAL OFF	TION CONTAINED W MPLIES WITH ALL NER AND THE OWNE CIALS, EMPLOYEES NOT DONE PURSUAN	ithin This Do RELEVANT BY-I T'S EMPLOYEES AND AGENTS AT	G Inspections 1 3-1-1 Centre. COMMENT AND ASS AWS AND STATUT AGAINST ALL CLA PLICATION OF FA REGULATIONS.	SOCIATED PLANS IS SES. I ACKNOWLEDGE CONTRACTORS. I WILL NIMS, LIABILITIES
				DATE	SEE APPL	ICATION
				ISSUED BY	R PRASAD	
NVOICE: 782572		TOTAL	6200.00	FOR THE	FIRE CHI	EF



Environmental Branch must be obtained.

FIRE AND RESCUE SERVICES

FIRE PREVENTION DIVISION #306 - 456 W. Broadway VANCOUVER, B.C. V5Y 1R3

TANK REMOVAL Permit Application

FI 412357

Permit Applicant: (please print) Name: _Tanktech Environmental Services Ltd. Address: _Box 5612 City: Squmaish Postal Code: V8B 0C2 Phone: _604-880-9007 Contractor Business License No: _326305	Property Owner: (please print) Name:
Owner Other Specify: Use of Property Site Plan Building Potential State Stat	
Remove tank(s) on site. Capacity (gal/L) Permit Conditions and Notes: 201 THE WORK UNDER THIS PERMIT IS AUTHORIZED PURSUANT 230 For removal: the tanks, together with connected piping a flammable liquids removed. The tanks and piping must b ends must be permanently sealed by capping or plugging. 240 Tank removal must comply with subsection 4.10.3 of the 210 Construction must be carried out in compliance with the 211 This permit shall expire if: (a) Work authorized by the permit has not commenced	TO THE FIRE BY-LAW. Indicate the dispensing equipment, shall have all combustible or elemented from the ground and purged of vapors. The pipe vancouver Fire By-law. Provisions of Noise Control By-law No. 6555.
Safety Regulation and city by-laws. 3. Environmental Final Closure Report and clearance required. 4. Backfill with clean soil required. 5. Underground storage tank removal shall be done in accommodate to the inspection by the Valditional Notes: 15 To book an inspection call 3-1-1 from within Vancouver,	iod of 90 days. , shoring, etc. as required by the Occupational Health and uired. cordance with good engineering practice. ancouver Fire and Rescue Services. or 604-873-7000 from outside Vancouver. The 3-1-1 Centre r. Also, our 24 hour Building Inspections booking request





FIRE AND RESCUE SERVICES FIRE PREVENTION DIVISION

NOTICE TO PROPERTY OWNER

June 23, 2015

s.22(1)

6138 ANGUS DR VANCOUVER BC V6M 3P3

Dear Property Owner,

RE: 6138 ANGUS DRIVE

Our office has received an application for a Fire Permit to remove an Underground Storage Tank (UST), at the above noted address. The City of Vancouver Fire By-Law (section 4.10.3) requires underground storage tanks that have been abandoned or have been out of service for two (2) years, be removed. It also requires that contaminated soil be removed and backfilled with clean fill.

It is our intention to inform all property owners of the correct process to ensure that all work is completed as outlined in the current City Bylaws, and that property owners are aware of their duties, responsibilities, and benefits under the Fire Permit system. If the work is incomplete and/or fails to meet the conditions of the Fire Permit, the permit will remain open which could prevent issuance of future permits from the City, until all Fire Permit conditions are met. Property owners applying for a rezoning, development or building permit will be asked to disclose the presence or absence of an underground storage tank on the subject property, and home owners may be required to provide documentation that an underground storage tank was removed correctly. It is important to note that a Fire Permit for tank removal issued by the Fire Prevention Division must be obtained **prior** to any work starting. All conditions noted on the Fire Permit must be adhered to and completed within 90 days. Any permits not completed within this time frame will expire and a new application and additional fees may be required. A Closure Report must be submitted to the Environmental Contamination Team upon removal of the tank and soil testing for contamination. Once this report has been received and confirmation is provided that all contaminated soil was removed as per the by-law and backfill has been completed, the Fire Permit will be closed.

The City recommends that a qualified environmental consultant be contracted to oversee the tank removal process and to confirm that any contaminated soils are properly removed. The consultant can assist in preparing the final Closure Report. We cannot recommend specific contractors or consultants; however, you should ensure they have a license to operate in the City of Vancouver, have Worksafe BC coverage, and appropriate insurance. Please ensure that the tank removal company you have contracted completes all appropriate documentation.

As a home owner, it is in your best interest to ensure that the company you have contracted to remove your tank completes all the necessary steps in this process. If you have any questions please refer to the City of Vancouver Fire & Rescue Services Website: http://vancouver.ca/home-property-development/tank-removal-or-abandonment-permit.aspx, or contact 311 for more information.





REAL ESTATE AND FACILITIES MANAGEMENT Environmental Planning

BULLETIN 2014-002-ECT

June, 2015

RESIDENTIAL UNDERGROUND STORAGE TANK REMOVAL

The City of Vancouver (the City) has prepared this bulletin that supersedes the "Residential Underground Storage Tank Removal" bulletin issued in May 2014. The bulletin summarizes applicable By-laws and regulations, general underground storage tank (UST) removal activities, and reporting requirements.

RESIDENTIAL UNDERGROUND STORAGE TANK BACKGROUND

Prior to natural gas becoming available in Vancouver in the early 1960s, most homes in Vancouver were heated by furnace oil. Furnace oil was primarily stored in Underground Storage Tanks (USTs) because aboveground tanks were not permitted. These USTs were typically small (1,125-1,350L), located in residence back-yards, and in close proximity to the furnace.

The estimated life-expectancy of USTs is about 20 to 25 years as they are susceptible to damage from corrosion. If damaged, furnace oil can be released into the ground causing contamination and potentially spreading via groundwater and vapours through preferred pathways (e.g., utility corridors, building perimeter drains).

BY-LAW REQUIREMENTS

The City's Fire By-law No. 8191 (sec.4.10.3) and Sewer and Watercourse By-law No. 8093 (sec.5.3) require that tanks which will not be reused or have been out of service for 2 years shall be removed. If the Fire Chief determines it impractical to remove the tank then it shall be emptied and filled with an inert material. Decommissioning in-place does not exempt any requirements (e.g., soil sampling) unless warranted for safety reasons.

The By-laws require that contaminated soils be removed and backfilled with clean fill. This work is often done in conjunction with tank removal activities; however it's not mandatory. Residual contamination will be noted and these soils must be removed concurrent with future site redevelopment. The City relies on the BC Contaminated Sites Regulation (CSR) and Environmental Management Act (EMA) for the definition of contaminated soil and its appropriate management/disposal.

UNDERGROUND STORAGE TANK REMOVAL PROCESS

A tank removal permit issued by the Fire Prevention Department must be obtained prior to any tank removal/decommissioning work. The Fire Prevention Office is at Suite 306, 456 West Broadway (telephone 311). A copy of the permit will be kept in the City's Permits and License's data resource centre. All conditions noted on the tank removal permit must be followed. Failure to meet these conditions could impact issuance of future permits until all tank removal permit conditions are met.

It is strongly recommended that consultants and contractors experienced in UST removals be contracted to conduct the work. The City cannot recommend specific contractors/consultants; however, property owners should ensure the contractors/consultants have a valid City of Vancouver business license, WorkSafeBC coverage, and appropriate insurance. Experienced contractors have a good understanding of what's required for safe and effective UST removals. They have access to licensed haulers and disposal firms to assist in liquid and solid waste disposal in order to ensure compliance with applicable provincial and municipal regulations. For information/reference only, some typical procedures for tank removal include:

- . Dipping the tank to determine if there is any remaining oil.
- Pumping/draining oil and disposing at an approved disposal/recycling facility.
- Assessing the tank for explosive conditions.
- Assessing the need for additional personal protective equipment.
- If necessary, purging combustible vapours with a venturi or dry ice.
- Once safe (e.g., <10% LEL) conditions are achieved, the tank and all associated piping can be excavated.
- · Inspecting the tank for visual evidence of damage or leaks.
- · Cleaning (e.g., dry-scraping) the tank and proper disposal of sludge offsite.
- Rendering the tank unfit for future use (e.g., cut, crushed) and proper offsite recycling/disposal.
- Observing (e.g., observations, soil gas measurements) if there is potential soil or groundwater contamination. Smelling soils to assess presence/absence of contamination MUST be avoided. Proper PPE must be followed in accordance with WorkSafeBC guidelines.
- If contamination is suspected, the environmental consultant will direct the contractor to remove suspect soils from the bottom and sides the tank-hold.
- Offsite disposal of suspect/confirmed contaminated soils at a facility licensed/approved to receive contaminated soil.
- Collecting soil samples to confirm the target level of cleanup is achieved. A minimum of
 five soil samples must be collected; one from each sidewall and base of the excavation.
 Samples must be analyzed by a CALA¹-approved laboratory for suspect contaminants of
 concern. Sampling should be conducted in accordance with BC Ministry of Environment
 (MOE) Technical Guidance Document 1.
- If necessary, submit notifications to the MOE.

The above bullet list is not comprehensive and is provided for reference only. It should not be relied upon as complete or prescriptive about UST removal procedures. If the scope of work expands and exceeds your expected costs, it's recommended you pause work and seek a second opinion.

The City recommends a qualified environmental consultant be contracted to oversee the tank removal contractor and to confirm contaminated soils are properly assessed and removed/disposed. The consultant provides expertise that can result in effective management of contamination and sampling in accordance to industry practices/guidelines. The consultant can assist in preparing the Final Tank Removal/Closure Report which must be signed by a qualified professional (e.g., P.Eng, P.Geo, RPBio, PAg, and ASCT) as defined by the BC Ministry of Environment¹.

Offsite Migration

The MOE requires that if during any stage of the work, it is confirmed or there is reason to believe that contaminants have migrated onto a neighbouring property (including City property such as roads), the owner of the neighbouring property must be notified within 15 days by the responsible person (e.g., source land owner) by issuing a Notice of Likely or Actual Offsite Migration (NOM). The responsible person must provide a NOM consistent with sections 57 and 60.1 of the EMA CSR.

Upon receipt of a NOM, the City will issue a letter to the source owner requesting additional information (e.g., contaminants, analytical results) and a proposed work plan to delineate and/or remediate contamination.

¹ Canadian Association of Laboratory Accreditation Inc.

REPORTING REQUIREMENTS

The City's Final Tank Removal/Closure Report template is provided with the permit and must be submitted electronically to the Environmental Contamination Team upon completion of the work (ust.reporting@vancouver.ca). The report requires information such as: site sketch; tank information; disposal work completed; field observations; soil sampling completed and analytical results. Additional supporting information such as laboratory certificates of analysis and sample chain of custody must be attached to the report. A "Conclusion Statement" must be completed and stamped by a qualified professional, as defined by the BC MOE..

COMPLIANCE

Once the Final Tank Removal/Closure Report has been received and confirmation is provided that all contamination was removed as per Bylaws/applicable legislation, the permit will be completed. Failure to comply with permit conditions will result in the permit being closed as incomplete. The presence of residual contamination will result in a note in city records that the site must be remediated at the time of redevelopment.

Residential property owners applying for a Development/Building Permit may be required to disclose the presence/absence of a UST on the subject property. A homeowner may be required to either provide documentation that a UST was removed and no soil contamination remains, or have the UST/contamination removed as a permit condition.

The City does not inspect, warrant or provide any assurance whatsoever that a UST or potential contamination was or has been removed in accordance with any standards.

Failure to meet any of the requirements in this bulletin may result in a stop work order.

For additional information regarding the UST Removal/Permitting process please contact 311 or refer to the City's website.