

File No.: 04-1000-20-2018-294

June 25, 2018

s.22(1)

Dear s.22(1)

Re: **Request for Access to Records under the Freedom of Information and Protection of Privacy Act (the "Act")**

I am responding to your request of May 28, 2018 for:

Reports that speak to fixing the damages made to a pole at 5th or 6th Avenue of Main Street that had to be repaired due to a Motor Vehicle Accident on March 19, 2013.

All responsive records are attached. Some information in the records has been severed, (blacked out), under s.15(1)(l) and s.22(1) of the Act. You can read or download this section here: http://www.bclaws.ca/EPLibraries/bclaws_new/document/ID/freeside/96165_00

Under section 52 of the Act, and within 30 business days of receipt of this letter, you may ask the Information & Privacy Commissioner to review any matter related to the City's response to your FOI request by writing to: Office of the Information & Privacy Commissioner, info@oipc.bc.ca or by phoning 250-387-5629.

If you request a review, please provide the Commissioner's office with: 1) the request number (#04-1000-20-2018-294); 2) a copy of this letter; 3) a copy of your original request; and 4) detailed reasons why you are seeking the review.

Yours truly,



Barbara J. Van Fraassen, BA
Director, Access to Information & Privacy

*Barbara.vanfraassen@vancouver.ca
453 W. 12th Avenue Vancouver BC V5Y 1V4*

*If you have any questions, please email us at foi@vancouver.ca and we will respond to you as soon as possible. Or you can call the FOI Case Manager at 604.871.6584.

Encl.

:ma



Work Order Summary

Work Order #: 386796 **T_TO_MVA_Main at 6th** **Sign**
Asset ID #: **MRN Repair** **Motor Vehicle Accident**
Group Project #: **Traffic Operations**
Location: E 5TH AV at MAIN ST
Operational Status: **Ref #1: :** **Ref #2:**
Service Request: 557069 **Contact Name:** Ecomm/VPD **Phone#:** s.15(1)(l)
Requested By: Vancouver Police Department **Requested Date:** Mar 19, 2013 **Initiated Date:** Mar 19, 2013

Assigned By: DAN ELFORD **Assigned To:** SANTINO SCARDILLO/ALEX CALDERON
Assigned Date: Mar 20, 2013 **Crew ID:** T_D1664 **Work Started:** Mar 19, 2013
Result: Completed **Work Completed:** Mar 20, 2013

Comments:

Main St at 6th Ave: S/E/C - Stop sign down
Please verify location.

VPD in s.22(1) reported to 311 Mar 19, 2013 at 4:08 pm.

Streets Ops Andrew reports that location is Main at 6th, s/e/c, and stop sign was completed removed. He placed a temp sign.

Work Completed: Mar 20/13:confirming address as E 6th at Main; replaced damaged sleeve, 10' pipe and stop sign. 1 hr incl return to yard for supplies: SS AC D1664.

Work Orders & Accomplishments:

WO#	Result	Completed Date
386796	Completed	Mar 20, 2013

TEOBSN:

Date	Location	Item Code Description	Quantity	Truck#	Assigned To	Reason	Comments
	2100-2200 MAIN ST & 0		0				
	100-199 E 6TH AV & 0		0				

Work Area Prefix: L **SAP Network #:** EEL386796 **WBS#:** EEL-00008-02

Parent Network: **Billable:** Y

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$14.54	-\$14.54
Labour	\$0.00	\$83.60	-\$83.60
Material	\$0.00	\$82.81	-\$82.81
Other	\$0.00	\$0.00	\$0.00
TOTAL	<u>\$0.00</u>	<u>\$180.95</u>	<u>-\$180.95</u>