

File No.: 04-1000-20-2019-722

December 11, 2019

s.22(1)

Dear s.22(1)

Re: **Request for Access to Records under the Freedom of Information and Protection of Privacy Act (the "Act")**

I am responding to your request of November 14, 2019 for:

**Copy of inspection report # 152343 (cited on Work Order Summary Nos. 997998 and 997999) and any associated documents.**

All responsive records are attached. Some information in the records has been severed, (blacked out), under s.22(1) of the Act. You can read or download these sections here: [http://www.bclaws.ca/EPLibraries/bclaws\\_new/document/ID/freeside/96165\\_00](http://www.bclaws.ca/EPLibraries/bclaws_new/document/ID/freeside/96165_00).

Under section 52 of the Act you may ask the Information & Privacy Commissioner to review any matter related to the City's response to your request. The Act allows you 30 business days from the date you receive this notice to request a review by writing to: Office of the Information & Privacy Commissioner, [info@oipc.bc.ca](mailto:info@oipc.bc.ca) or by phoning 250-387-5629.

If you request a review, please provide the Commissioner's office with: 1) the request number assigned to your request (#04-1000-20-2019-722); 2) a copy of this letter; 3) a copy of your original request for information sent to the City of Vancouver; and 4) detailed reasons or grounds on which you are seeking the review.

Please do not hesitate to contact the Freedom of Information Office at [foi@vancouver.ca](mailto:foi@vancouver.ca) if you have any questions.

Yours truly,



**Barbara J. Van Fraassen, BA**  
**Director, Access to Information & Privacy**

[Barbara.vanfraassen@vancouver.ca](mailto:Barbara.vanfraassen@vancouver.ca)  
453 W. 12th Avenue Vancouver BC V5Y 1V4

\*If you have any questions, please email us at [foi@vancouver.ca](mailto:foi@vancouver.ca) and we will respond to you as soon as possible. Or you can call the FOI Case Manager at 604.871.6584.

Encl.

:kt

Wagon Location **Manitoba Yard**

A/A 919763257

### Streets Operations Daily Crew Report

Rev. \_\_\_\_\_

July 23, 2018

Work order # and Hours

Crew # **63**

Field Supervisor **Mezzomo 604-619-2057**

Superintendent **Marco Biagini**

Hours of Work 7 AM - 3:30 PM

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem Code	1	2	3	4	5
s.22(1)	G. Fiskilis	C1287	P74	6000	GR-320		1	1	1		
s.22(1)	K. Green			6000			1	1	1		
Equipment Name			Equipment ID			Running Hrs					
TRUCK, DUMP, 1 YARD			C1287			1 6 1					
Toilets			Number of			0					
Flashers			Number of								
Dumps (National Yards Only)			Yrds Dumped								







# Work Order Summary

**Work Order #:** 997998      Boulevard Hazard  
**Asset ID #:** 97360  
**Group Project #:** 77896      RSw\_Fit\_NM 63-2018      Streets Operations  
**Location:** 2500 - 2599 COLUMBIA ST  
**Operational Status:**      **Ref #1:** :      **Ref #2:**  
**Service Request:**      **Contact Name:**      **Phone#:**  
**Requested By:**      **Requested Date:**      **Initiated Date:** Jul 19, 2018

**Assigned By:**      **Assigned To:** KONSTANTINOS FISKILIS  
**Assigned Date:** Jul 19, 2018      **Crew ID:** RMS63      **Work Started:**  
**Result:** Completed      **Work Completed:** Jul 23, 2018

**Comments:** **Where:** 10 meters N of Civic SPL 2520  
**Hazard:** Sidewalk Trip  
**Comments:**  
  
 This work order created by inspection # 152343  
 Inspector: 28125 (MARK ANDRUK)  
 Inspected Date: 19/07/2018 10:33:21 AM

## Work Orders & Accomplishments:

WO#	Result	Completed Date				
997998	Completed	Jul 23, 2018				
Accomplishment Date	Description	Quantity	Truck#	Assigned To	Comments	
Jul 23, 2018	Asphalt Fillet - Sidewalk	2	RMS63	KONSTANTINOS FISKILIS	SE	

**Work Area Prefix:** R      **SAP Network #:** EERD77896      **WBS#:** EER-00009-SF-NM-AP  
**Parent Network:**      **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
<b>TOTAL</b>	<b><u>\$0.00</u></b>	<b><u>\$0.00</u></b>	<b><u>\$0.00</u></b>



# Work Order Summary

**Work Order #:** 997999      Boulevard Hazard  
**Asset ID #:** 97360  
**Group Project #:** 77896      RSw\_Fit\_NM 63-2018      Streets Operations  
**Location:** 2500 - 2599 COLUMBIA ST  
**Operational Status:**      **Ref #1:** :      **Ref #2:**  
**Service Request:**      **Contact Name:**      **Phone#:**  
**Requested By:**      **Requested Date:**      **Initiated Date:** Jul 19, 2018

**Assigned By:**      **Assigned To:** KONSTANTINOS FISKILIS  
**Assigned Date:** Jul 19, 2018      **Crew ID:** RMS63      **Work Started:**  
**Result:** Completed      **Work Completed:** Jul 23, 2018

**Comments:** 
 Where: 9 meters N of Civic SPL 2520  
 Hazard: Sidewalk Trip  
 Comments:  
  
 This work order created by inspection # 152343  
 Inspector: 28125 (MARK ANDRUK)  
 Inspected Date: 19/07/2018 10:33:42 AM

### Work Orders & Accomplishments:

WO#	Result	Completed Date				
997999	Completed	Jul 23, 2018				
Accomplishment Date	Description	Quantity	Truck#	Assigned To	Comments	
Jul 23, 2018	Asphalt Fillet - Sidewalk	3	RMS63	KONSTANTINOS FISKILIS	SE	

**Work Area Prefix:** R      **SAP Network #:** EERD77896      **WBS#:** EER-00009-SF-NM-AP  
**Parent Network:**      **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
<b>TOTAL</b>	<u>\$0.00</u>	<u>\$0.00</u>	<u>\$0.00</u>

# Street Work Slip

<b>SAP Network #</b>	<b>Address</b>	2500 - 2599 COLUMBIA ST 2500 COLUMBIA ST E	<b>District</b>	<b>Lane/Street Side</b>
EERD77896			N11	
<b>Work Order #</b>	<b>WO Short Description</b>			<b>Reason</b>
997998	Boulevard Hazard			
<b>Activity Type</b>		<b>Sub Activity Type</b>	<b>Problem</b>	<b>Method</b>
Boulevard Hazard				

**SAFETY WARNING:**

**WARRANTIES:**

<b>GP #</b>	77896	<b>Ref #1</b>		<b>Ref #2</b>		<b>SR #</b>	
<b>Incident Date</b>	<b>Created Date</b>	<b>Crew ID</b>	<b>Assigned To</b>		<b>Assigned Addl</b>	<b>Responsibility</b>	
	Jul 19, 2018	RMS63	KONSTANTINOS EISENBERG			RO	
<b>Asset Category</b>		<b>SideWalk Type</b>		<b>Material</b>	<b>StreetSide</b>		
Sidewalk Sidewalk		Sidewalk		Concrete	E		

**JOB DETAILS**

Where: 10 meters N of Civic SPL 2520  
 Hazard: Sidewalk Trip  
 Comments:

This work order created by inspection # 152343  
 Inspector: 28125 (MARK ANDRUK)  
 Inspected Date: 19/07/2018 10:33:21 AM

<b>Assigned By</b>	<b>Assigned Date</b>	<b>Assigned Time</b>	<b>Arrival Date</b>	<b>Arrival Time</b>
	Jul 19, 2018	13:37		

**COMPLETED WORK DETAILS e.g. Measurements, quantity, type of material, what work performed and location**

<b>Completed Date</b>	<b>Completed Time</b>	<b>Crew</b>	<b>Truck #</b>	<b>Print Name</b>	<b>Signature</b>
Jul 23, 2018	00:00				

# Street Work Slip

<b>SAP Network #</b>	<b>Address</b>	2500 - 2599 COLUMBIA ST 2500 COLUMBIA ST E	<b>District</b>	<b>Lane/Street Side</b>
EERD77896			N11	
<b>Work Order #</b>	<b>WO Short Description</b>			<b>Reason</b>
997999	Boulevard Hazard			
<b>Activity Type</b>		<b>Sub Activity Type</b>	<b>Problem</b>	<b>Method</b>
Boulevard Hazard				

**SAFETY WARNING:**

**WARRANTIES:**

<b>GP #</b>	77896	<b>Ref #1</b>		<b>Ref #2</b>		<b>SR #</b>	
<b>Incident Date</b>	<b>Created Date</b>	<b>Crew ID</b>	<b>Assigned To</b>		<b>Assigned Addl</b>	<b>Responsibility</b>	
	Jul 19, 2018	RMS63	KONSTANTINOS EIOZILIC			RO	
<b>Asset Category</b>		<b>SideWalk Type</b>		<b>Material</b>	<b>StreetSide</b>		
Sidewalk Sidewalk		Sidewalk		Concrete	E		

**JOB DETAILS**

Where: 9 meters N of Civic SPL 2520  
 Hazard: Sidewalk Trip  
 Comments:

This work order created by inspection # 152343  
 Inspector: 28125 (MARK ANDRUK)  
 Inspected Date: 19/07/2018 10:33:42 AM

<b>Assigned By</b>	<b>Assigned Date</b>	<b>Assigned Time</b>	<b>Arrival Date</b>	<b>Arrival Time</b>
	Jul 19, 2018	13:37		

**COMPLETED WORK DETAILS e.g. Measurements, quantity, type of material, what work performed and location**

<b>Completed Date</b>	<b>Completed Time</b>	<b>Crew</b>	<b>Truck #</b>	<b>Print Name</b>	<b>Signature</b>
Jul 23, 2018	00:00				