

File No.: 04-1000-20-2020-423

September 15, 2020

s.22(1)

Dear s.22(1)

Re: **Request for Access to Records under the Freedom of Information and Protection of Privacy Act (the "Act")**

I am responding to your request of August 4, 2020 for:

Records regarding the maintenance and repair of the north side of West 12th Avenue between Burrard Street and Cypress Street, including: work order summaries, reports, complaints, and measurements. Date range: January 1, 2016 to August 1, 2020.

All responsive records are attached. Some information in the records has been severed, (blacked out), under s.22(1) of the Act. You can read or download this section here: http://www.bclaws.ca/EPLibraries/bclaws_new/document/ID/freeside/96165_00.

Under section 52 of the Act you may ask the Information & Privacy Commissioner to review any matter related to the City's response to your request. The Act allows you 30 business days from the date you receive this notice to request a review by writing to: Office of the Information & Privacy Commissioner, info@oipc.bc.ca or by phoning 250-387-5629.

If you request a review, please provide the Commissioner's office with: 1) the request number assigned to your request (#04-1000-20-2020-423); 2) a copy of this letter; 3) a copy of your original request for information sent to the City of Vancouver; and 4) detailed reasons or grounds on which you are seeking the review.

Please do not hesitate to contact the Freedom of Information Office at foi@vancouver.ca if you have any questions.

Yours truly,

Cobi Falconer, FOI Case Manager, for

[Signature on file]

Barbara J. Van Fraassen, BA
Director, Access to Information & Privacy

Barbara.vanfraassen@vancouver.ca

453 W. 12th Avenue Vancouver BC V5Y 1V4

*If you have any questions, please email us at foi@vancouver.ca and we will respond to you as soon as possible. Or you can call the FOI Case Manager at 604.871.6584.

Encl.

:kt

FOI - 2020-423 - Cut Sheet Records

CUTNO	WONUM	CLIENTCODE	ASSET_CASTNO	ASSET_CASTNAME	UNITDESC	RATECODE	UNITEST1	CREWID1	STATUSCODE1	BILLDATE1	COMPDTM
690208	690208	WATER	1800	W 12TH AV	1800 W 12TH AV N	210	18.08	RMG95	Completed	24-Dec-15	5/12/2016



2020/08/17 08:57

Class

Service Request # R	1630856
Request Type	RSideWalkRepair
Request type description	Sidewalk - Repair
Request Date	2020/06/15 12:34
Call Date	2020/06/15 12:33
Lagan's ECM Update	IncidentDate
Incident Date	2020/06/15 12:35
Crew Assign Date	2020/06/15 12:52
Crew ID	RMS88
Crew Contact	5409
Alt Crew Contact	
Follow-Up Date	2020/06/15 12:41
Reviewed	yes
Sub Type	xSidewalkBrokeInjury
	RICHARD BRUCE
Charges Explained	Last 311 Update, where applicable
Initiated By	no
	Road Maintenance Sidewalk 88
	Creator
	Dispatcher
	Alt Dispatcher
Alert State	None
	No Alert

nformation

Information

Zone	
Area description	
Sub-area	
Sub-area description	
Beat	
District description	
Auto Beat	
Priority	4
Priority description	Medium
Responsibility	RO
Responsibility description	Streets Operations
Project	
Project description	
311 Case #	101014093309
Source	
Due Date	2020/06/22 12:33
Ext Reference #	
Ref Type	
Lagan CSR Name	lagan
Method	
Designation	
Frequency	
Cleaning Zone	

Request Location

Asset	
Parcel ID	
Property ID	
Lane	
GPS X	0.0000
GPS Y	0.0000

Location

Address type	Address
Street #	1815
Pre Dir	

Street Name W 12TH AV
 Suffix (MA)
 Post Dir
 Subdesignation
 Cross Street
 Street 2 Name
 Street 2 Suffix
 Street 2 Post
 Direction
 Cross Street
 Street 3 Name
 Street 3 Suffix
 Street 3 Post
 Direction
 City, Province, Vancouver
 Postal Code
 State BC
 Postal Code
 Location

Incident Details

Dispatched to B1203 on Jun 15/20 *photos requested*
 Internal Notes

Call Details

Call Duration 00:00:00
 # of Calls 0
 Taken By
 Taken by name
 Customer Contact
 Requested yes
 Notify Customer
 Regarding Service no
 Request Progress

Contact

Name Wright
 First, MI Kevin
 Middle Initial
 Title
 Foreign no
 Address
 City
 State/Province
 ZIP/PC
 Country

Contact Phone 604-871-6306
 Alternate Phone
 Fax
 Pager
 PIN
 E-mail kevin.wright@vancouver.ca
 Contact Type Other

Customer Comments

Wright, Kevin

Other Calls

(No Data)

Inspection

Inspector s.22(1)
 Inspector name RICHARD BRUCE
 Scheduled
 Due By
 Started
 Due By
 Completed
 Due By
 Resolved 2020/06/15 00:00
 Due By
 Resolution 10

Resolution description
 Estimated days to complete 0
 Resident Notified
Service Request Inspections
 (No Data)

Log**Service Request Log Results**

Log Type Entered By Entered By Name Start Date To Comments

Lagan ECM 33609 CHERRY COHEN 2020/06/15 12:53 2020/06/15 12:53 Dispatched to B1203 on Jun 15/20 *photos requested*
 ResolComm 29516 BRENDA AROMIN

Attachments**Attachments**

(No Data)

Associations**Linked Service Requests**

(No Data)

Associated Work Orders

Work Order # Milestone Activity Schedule Date Completed Date Asset Unit ID

1211619 RSwReact 2020/06/15 00:00 Sidewalk 105041

Associated Asset Inspections

(No Data)

Associated Cases

(No Data)

Request Details

(Tab Not Loaded)

Schedules**Employees**

(No Data)

Fleet Equipment

(No Data)

Plant Equipment

(No Data)

Vehicles

(No Data)

Usage Readings

(Tab Not Loaded)

Audit Log**Audit Log****Audit Log**

Field Name Audit Date Time New Value Old Value User ID Audit Catagory

IncidentDate	2020/06/15 12:35	15/06/2020 12:35:13 PM	15/06/2020 12:34:23 PM	Integration SERVICE	IncidentDate
Review Date	2020/06/15 12:41	15/06/2020 12:41:00 PM	01/01/0001 12:00:00 AM	CHERRY COHEN	Hansen
Inspector	2020/06/15 12:53	5409		CHERRY COHEN	Hansen
Crew Id	2020/06/15 12:53	RMS88		CHERRY COHEN	Hansen
Resolved	2020/06/17 10:57	True	False	BRENDA AROMIN	Hansen

Lagan eForm**Lagan Detail**

1. Type of sidewalk problem: **Broken Causing Personal Injury****

2. If Other, provide details:

3. Is there a black patch on it?**No**

4. Is it safe?**No**

5. Describe issue in detail (in front of, beside, side of street, etc.):**Via Tell Us Online: Location is sidewalk in front of 1815 W 12 Ave. There is a panel separation and settlement that needs repair. A claimant s.22(1) tripped on the existing asphalt fillet. Thanks very much and please call if any questions arise.**

6. Is this request due to Motor Vehicle Accident?**Unknown**

7. If Yes, provide details on license plate number or other details (if known):

8. (Don't ask just record - Did caller indicate they want a call back?)**No**

Lagan eForm
Lagan Case Details

Wagon Location **Manitoba Yard**

A/A **917650543**

Streets Operations Daily Crew Report

Rev. _____

August 11, 2016

Work order # and Hours

Crew # **66**
Field Supervisor **Mezzomo 604-619-2057**
Superintendent **Enrico Santamaria**

(signed)

(signed)

1	2	3	4	5
FEED 71774	FEED 627152	FEED 71774		

Hours of Work **7:00** AM - **3:30** PM

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem Code	1	2	3	4	5
s.22(1)	M. Boudreau			6000			2.0	1.0	5.0		
s.22(1)	M. Anstice	C1276	P74	6000	GR-320		2.0	1.0	5.0		
s.22(1)	P. Georgeleos			6000			2.0	1.0	5.0		
Equipment Name			Equipment ID		Running Hrs						
TRUCK, DUMP, 1 YARD			C1276		2.0	1.0	5.0				
Toilets											
Flashers											
Dumps (National Yards Only)			Yrds Dumped								

City of Vancouver - FOI 2020-423 - Page 7 of 20

Wagon Location Manitoba Yard

A/A 920932532

Streets Operations Daily Crew Report

Rev.

August 02, 2019

Work order# and Hours

Crew # 67
Field Supervisor Mezzomo 604-619-2057
Superintendent Jim Bruce

(signed)
(signed)

1	2	3	4	5
FERD81900	FER1042931	FERD84685		

Hours of Work 7:00 AM - 3:30 PM

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem Code	1	2	3	4	5
s.22(1)	W. Andrade	B1203		6000			2	2	4		
s.22(1)	L. Colbourne			6000			2	2	4		
Equipment Name			Equipment ID		Running Hrs						
TRUCK, DUMP, 1 YARD			B1203		2 2 4						
Toilets			Number of		0						
Flashers			Number of								
Dumps (National Yards Only)			Yrds Dumped								

August 02, 2019 Crew # 67 Field Supervisor Mezzomo Superintendent Jim Bruce

Location 1	EEA081900	Material	Amount	Comments
1500 blk Arbutus- 12		#36	230 T	P/H
SR# 1489365- 3				
Dump:		Location:		
Sign safety when Departing Location:		Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>		
Signage Used:		By: (Initials)		
Activity Code		Units Completed	Measurement	

Location 2	EEA1042931	Material	Amount	Comments
2900 - 3600 blk W. 10m				checked C/Bs cleared leaves / debris as required
Dump:		Location:		
Sign safety when Departing Location:		Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>		
Signage Used:		By: (Initials)		
Activity Code		Units Completed	Measurement	

Location 3	EEA084865	Material	Amount	Comments
SR# 1489544-11				
1886 W 12-4 2221 W 16-4		#36	1.00 T	S/N Fillet
1882 W 12-5 2225 W 16-2				
1876 W 12-3				
1868 W 12-5				
1861 W 12-5				
1862 W 12-3				
1856 W 12-1				
2207 W 16-4				
Dump:		Location:		
Sign safety when Departing Location:		Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>		
Signage Used:		By: (Initials)		
Activity Code		Units Completed	Measurement	

Location 4		Material	Amount	Comments
Dump:		Location:		
Sign safety when Departing Location:		Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>		
Signage Used:		By: (Initials)		
Activity Code		Units Completed	Measurement	

Location 5		Material	Amount	Comments
Dump:		Location:		
Sign safety when Departing Location:		Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>		
Signage Used:		By: (Initials)		
Activity Code		Units Completed	Measurement	

Wagon Location **Manitoba Yard**

A 921903022

Streets Operations Daily Crew Report

Rev. _____

June 15, 2020

Work order # and Hours

Crew # **67**
Field Supervisor **Mezzomo 604-619-2057**
Superintendent **Jim Bruce**



(signed)


(signed)

1	2	3	4	5
400 39231	EPD086269	EPD086111	EPD 1042539	EPD 1154468

Hours of Work 7:00 AM - 3:30 PM

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem Code	1	2	3	4	5
s.22(1)	M. Skinner			6000			1	3	2	1	1
s.22(1)	W. Andrade	B1203		6000			1	3	2	1	1
Equipment Name			Equipment ID			Running Hrs					
TRUCK, DUMP, 1 YARD			B1203			1	3	2	1	1	
Toilets			Number of			0					
Flashers			Number of								
Dumps (National Yards Only)			Yrds Dumped								

ENTERED

Comments

Activity Code	Units Completed	Measurement
---------------	-----------------	-------------

Wagon Location **Manitoba Yard**

Streets Operations Daily Crew Report

June 17, 2020

Crew # 67

Field Supervisor Mezzomo 604-619-2057

Superintendent **Jim Bruce**

A/A

921915881

Rev.

Work order $\frac{12}{10}$ and Hours

Hours of Work 7:00 AM - 3:30 PM

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem Code	11	12	13	14
s.22(1)	D. Gubert			6000			1	1	1	5
s.22(1)	W. Andrade	B1203		6000			1	1	1	5
Equipment Name			Equipment ID			Running Hrs				
TRUCK, DUMP, 1 YARD			B1203			1 1 1 5				
Toilets			Number of			0				
Flashers			Number of							
Dumps (National Yards Only)			Yrds Dumped							

N6 ¹² @ Oak	#36	.16T	Fillet around valve box
	Dump:	Location:	

Sign safety when Departing Location:		Cones <input type="checkbox"/>		Snow Fence <input type="checkbox"/>		Tape <input type="checkbox"/>		Barricade <input type="checkbox"/>		Ramps <input type="checkbox"/>		Flashers <input type="checkbox"/>		Delineators <input type="checkbox"/>	
Signage Used:												By: _____		(Initials)	
Activity Code						Units Completed						Measurement			

[illegible]

		Dump:		Location:	
Sign safety when Departing Location:		<input type="checkbox"/> Cones	<input type="checkbox"/> Snow Fence	<input type="checkbox"/> Tape	<input type="checkbox"/> Barricade
Signage Used:		<input type="checkbox"/> Ramps	<input type="checkbox"/> Flashers	<input type="checkbox"/> Delineators	<input type="checkbox"/>
		By:			(Initials)
Activity Code		Units Completed		Measurement	

[illegible]

Dump:		Location:	
Sign safety when Departing Location:	Cones <input type="checkbox"/>	Snow Fence <input type="checkbox"/>	Tape <input type="checkbox"/>
	Barricade <input type="checkbox"/>	Ramps <input type="checkbox"/>	Flashers <input type="checkbox"/>
	Delineators <input type="checkbox"/>		
Signage Used:	By: (Initials)		
Activity Code	Units Completed	Measurement	

Location 4	EPR 086269		Material	Amount	Comments
1630845-6	1211130-1	1211054-1			1211053-1
1211194-1	1211129-1	1211062-2	#36	1.40T	1211032-1
1211156-1	1211133-1	1211095-1			1211029-1
1211102-2	1211135-2	1211096-1			1211023-1
1211101-1	1211076-5	1211099-1			1211017-1
1211103-1	1211073-4	1211059-1			1211018-1
1211104-1	1211069-1	1211049-1			1210995-1
1211105-3	1211078-1	1211051-1			1211041-1

121107-1		1211060-1		1211052-1		Dump:		Location:		1211044-2	
Sign safety when Departing Location:		Cones		<input type="checkbox"/>		Snow Fence		<input type="checkbox"/>		Tape	
		<input type="checkbox"/>						<input type="checkbox"/>		Barricade	
								<input type="checkbox"/>		Ramps	
								<input type="checkbox"/>		Flashers	
								<input type="checkbox"/>		Delineators	
								<input type="checkbox"/>			
Signage Used:										By: (Initials)	
Activity Code						Units Completed				Measurement	

[illegible]

	Dump:	Location:												
Sign safety when Departing Location:	Cones	<input type="checkbox"/>	Snow Fence	<input type="checkbox"/>	Tape	<input type="checkbox"/>	Barricade	<input type="checkbox"/>	Ramps	<input type="checkbox"/>	Flashers	<input type="checkbox"/>	Delineators	<input type="checkbox"/>
Signage Used:											By:	(Initials)		
Activity Code			Units Completed			Measurement								

May 12, 2016 Crew # 95 Field Supervisor Wright Superintendent Vince Santorelli

Location 1	EER454274	Material	Amount	Comments
1835 W. 12 690208				
2835 Yew 658726 + 658720				Dug out - Back filled w/
3039 W. 15 670235				
3076 W. 15 670772				Soil + Seed
3346 W. 10 725068				
Dump:		Location:		
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>				
Signage Used: By: (Initials)				
Activity Code		Units Completed	Measurement	

Location 2	EER355060	Material	Amount	Comments
NATYD				Prepared work
				Issued encroachments
Dump:		Location:		
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>				
Signage Used: By: (Initials)				
Activity Code		Units Completed	Measurement	

Location 3		Material	Amount	Comments
Dump:		Location:		
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>				
Signage Used: By: (Initials)				
Activity Code		Units Completed	Measurement	

Location 4		Material	Amount	Comments
Dump:		Location:		
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>				
Signage Used: By: (Initials)				
Activity Code		Units Completed	Measurement	

Location 5		Material	Amount	Comments
Dump:		Location:		
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>				
Signage Used: By: (Initials)				
Activity Code		Units Completed	Measurement	

Work Order Summary

Work Order #: 770467 Boulevard Hazard Asphalt Fillet - Sidewalk
Asset ID #: 105041 Sidewalk - General (Reactive)
Group Project #: 71774 RSw_Flt_NM 66-2016/8-12 Streets Operations
Location: 1800 - 1899 W 12TH AV
Operational Status: **Ref #1:** : **Ref #2:**
Service Request: **Contact Name:** **Phone#:**
Requested By: **Requested Date:** **Initiated Date:** Aug 08, 2016

Assigned By: MARCO BIAGINI **Assigned To:** MARK ANSTICE
Assigned Date: Aug 09, 2016 **Crew ID:** RMS66 **Work Started:**
Result: Completed **Work Completed:** Aug 11, 2016

Comments:

Where: At Civic WPL 1875
 Hazard: Sidewalk Trip
 Comments:

This work order created by inspection # 107540
 Inspector s.22(1) (BENJAMIN HICKEY)
 Inspected Date: 08/08/2016 1:34:47 PM

Work Orders & Accomplishments:

WO#	Result	Completed Date				
770467	Completed	Aug 11, 2016				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Aug 11, 2016		Asphalt Fillet - Sidewalk	1	RMS66	MARK ANSTICE	1875 - LV

Work Area Prefix: R **SAP Network #:** EERD71774 **WBS#:** EER-00009-SF-NM-AP
Parent Network: **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
TOTAL	<u>\$0.00</u>	<u>\$0.00</u>	<u>\$0.00</u>

Work Order Summary

Work Order #: 1113849 RSw_Flt_NM 67-2019
Asset ID #: 105041
Group Project #: 84685 RSw_Flt_NM 67-2019 Streets Operations
Location: 1800 - 1899 W 12TH AV
Operational Status: **Ref #1:** : **Ref #2:**
Service Request: **Contact Name:** **Phone#:**
Requested By: **Requested Date:** **Initiated Date:** Aug 07, 2019

Assigned By: RICHARD BRUCE **Assigned To:** WALTER ANDRADE
Assigned Date: Aug 07, 2019 **Crew ID:** RMS67 **Work Started:**
Result: Completed **Work Completed:** Aug 02, 2019

Comments: 2019 - Sidewalk Fillets - Non-MRN - Crew 67
 Accomplishment: RSwAsFlt

Work Orders & Accomplishments:

WO#	Result	Completed Date				
1113849	Completed	Aug 02, 2019				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Aug 02, 2019		Asphalt Fillet - Sidewalk	26	RMS67	WALTER ANDRADE	EE

Work Area Prefix: R **SAP Network #:** EERD84685 **WBS#:** EER-00009-SF-NM-AP
Parent Network: **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
TOTAL	\$0.00	\$0.00	\$0.00

Work Order Summary

Work Order #: 1211129 Boulevard Hazard
Asset ID #: 105041
Group Project #: 86269 RSw_Flt_NM 67-2020 Streets Operations
Location: 1800 - 1899 W 12TH AV
Operational Status: **Ref #1:** : **Ref #2:**
Service Request: **Contact Name:** **Phone#:**
Requested By: **Requested Date:** **Initiated Date:** Jun 16, 2020

Assigned By: RICHARD BRUCE **Assigned To:** WALTER ANDRADE
Assigned Date: Jun 16, 2020 **Crew ID:** RMS67 **Work Started:**
Result: Completed **Work Completed:** Jun 17, 2020

Comments:
 Where: 2 meters W of Civic 1865
 Hazard: Sidewalk Trip
 Comments:

 This work order created by inspection # 194171
 Inspector **s.22(1)** (MEHDI YAZDANI)
 Inspected Date: 16/06/2020 12:01:40 PM

Work Orders & Accomplishments:

WO#	Result	Completed Date				
1211129	Completed	Jun 17, 2020				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Jun 17, 2020		Asphalt Fillet - Sidewalk	1	RMS67	WALTER ANDRADE	AC

Work Area Prefix: R **SAP Network #:** EERD86269 **WBS#:** EER-00009-SF-NM-AP
Parent Network: **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
TOTAL	\$0.00	\$0.00	\$0.00

Work Order Summary

Work Order #: 1211130 Boulevard Hazard
Asset ID #: 105041
Group Project #: 86269 RSw_Flt_NM 67-2020 Streets Operations
Location: 1800 - 1899 W 12TH AV
Operational Status: **Ref #1:** : **Ref #2:**
Service Request: **Contact Name:** **Phone#:**
Requested By: **Requested Date:** **Initiated Date:** Jun 16, 2020

Assigned By: RICHARD BRUCE **Assigned To:** WALTER ANDRADE
Assigned Date: Jun 16, 2020 **Crew ID:** RMS67 **Work Started:**
Result: Completed **Work Completed:** Jun 17, 2020

Comments:
 Where: 3 meters W of Civic 1865
 Hazard: Sidewalk Trip
 Comments:

 This work order created by inspection # 194171
 Inspector **s.22(1)**(MEHDI YAZDANI)
 Inspected Date: 16/06/2020 12:02:00 PM

Work Orders & Accomplishments:

WO#	Result	Completed Date				
1211130	Completed	Jun 17, 2020				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Jun 17, 2020		Asphalt Fillet - Sidewalk	1	RMS67	WALTER ANDRADE	AC

Work Area Prefix: R **SAP Network #:** EERD86269 **WBS#:** EER-00009-SF-NM-AP
Parent Network: **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
TOTAL	\$0.00	\$0.00	\$0.00

Work Order Summary

Work Order #: 1211619 RSw_Flt_NM 67-2020
Asset ID #: 105041
Group Project #: 86269 RSw_Flt_NM 67-2020 Streets Operations
Location: 1800 - 1899 W 12TH AV
Operational Status: **Ref #1:** : **Ref #2:**
Service Request: 1630856 **Contact Name:** Kevin Wright **Phone#:** 604-871-6306
Requested By: **Requested Date:** **Initiated Date:** Jun 15, 2020

Assigned By: RICHARD BRUCE **Assigned To:** WALTER ANDRADE
Assigned Date: Jun 15, 2020 **Crew ID:** RMS67 **Work Started:**
Result: Completed **Work Completed:** Jun 15, 2020

Comments: Crew 68 - Sidewalk Fillets - MRN | Accomplishment Code: RSwAsFlt

Work Orders & Accomplishments:

WO#	Result	Completed Date				
1211619	Completed	Jun 15, 2020				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Jun 15, 2020		Asphalt Fillet - Sidewalk	1	RMS67	WALTER ANDRADE	BA - 1815

Work Area Prefix: R **SAP Network #:** EERD86269 **WBS#:** EER-00009-SF-NM-AP
Parent Network: **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
TOTAL	\$0.00	\$0.00	\$0.00