

File No.: 04-1000-20-2020-588

December 18, 2020

s.22(1)

Dear s.22(1)

Re: **Request for Access to Records under the Freedom of Information and Protection of Privacy Act (the "Act")**

I am responding to your request of October 29, 2020 for:

Records regarding the north sidewalk of the 1600 block of East 2nd Avenue, specifically: inspection; complaints; and, maintenance. Date range: January 1, 2018 to October 28, 2020.

All responsive records are attached. Some information in the records has been severed, (blacked out), under s.22(1) of the Act. You can read or download this section here: http://www.bclaws.ca/EPLibraries/bclaws_new/document/ID/freeside/96165_00.

Under section 52 of the Act you may ask the Information & Privacy Commissioner to review any matter related to the City's response to your request. The Act allows you 30 business days from the date you receive this notice to request a review by writing to: Office of the Information & Privacy Commissioner, info@oipc.bc.ca or by phoning 250-387-5629.

If you request a review, please provide the Commissioner's office with: 1) the request number assigned to your request (#04-1000-20-2020-588); 2) a copy of this letter; 3) a copy of your original request for information sent to the City of Vancouver; and 4) detailed reasons or grounds on which you are seeking the review.

Please do not hesitate to contact the Freedom of Information Office at foi@vancouver.ca if you have any questions.

Yours truly,

Cobi Falconer, FOI Case Manager, for

[Signature on file]

Barbara J. Van Fraassen, BA
Director, Access to Information & Privacy

Barbara.vanfraassen@vancouver.ca

453 W. 12th Avenue Vancouver BC V5Y 1V4

*If you have any questions, please email us at foi@vancouver.ca and we will respond to you as soon as possible. Or you can call the FOI Case Manager at 604.871.6584.

Encl.

:kt

Sidewalk and Boulevard History Report

Sidewalk: 107309 1600 E 2ND AV N

Activity From:

Activity To:

Address: 1600 to 1699 E 2ND AV

Street Side: N

Maintenance: COV Engineering

District: N19

Owner: COVAV

Encroachment: Y

Inspections	Type	Assign To	Complete Date	Hazard Reported	WO Created	Location
183466	RSwHazard	RUPERT GUFFEY	Tue, Apr 7, 2020			
162500	RSwHazard	RUPERT GUFFEY	Mon, May 27, 2019			
141546	RSwHazard	PAUL CHAN	Tue, May 8, 2018	Sidewalk Trip	974278	Opposite Pole # 4/66
				Sidewalk Trip	974280	Opposite Civic WPL 1616
117564	RSwHazard	MARK ANDRUK	Thu, Apr 27, 2017	Sidewalk Separation	859374	11 meters W of Civic WPL 1623
				Sidewalk Tree Base	859377	1 meters W of 2nd tree west of Commercial
93640	RSwHazard	RAUL ARMENDARIZ RODRIGUEZ	Wed, Apr 13, 2016	Sidewalk Trip	731064	At 1st tree w/o commercial
				Sidewalk Trip	731067	At Civic 1623
				Sidewalk Trip	731069	At 1st tree e/o cotton
69824	RSwHazard	REZ EHSANI	Tue, Mar 3, 2015	Sidewalk Trip	584718	4 meters E of 2nd tree W of Commercial, Longitudinal
				Sidewalk Trip	584719	5 meters W of Civic WPL 1661
				Sidewalk Trip	584722	Near 3rd tree E of Cotton
42742	RSwHazard	PHILIP MEW	Mon, Mar 10, 2014	Sidewalk Trip	484006	Opposite Pole # 2/66 near the postal box
				Sidewalk Trip	484007	Opposite Pole # 4/66
19242	RSwHazard	RAYMOND SOLIMAN	Mon, Feb 18, 2013			

W.O.#	Activity	Assign To	Complete Date	Accomplishments	Accomplishment Date
1149362	RSwReact	DAVID WOODS	Wed, Dec 4, 2019	Asphalt Fillet - Sidewalk	Wed, Dec 4, 2019
974280	RInsp_Blvd	KONSTANTINOS FISKILIS	Wed, May 16, 2018	Asphalt Fillet - Sidewalk	Wed, May 16, 2018
974278	RInsp_Blvd	KONSTANTINOS FISKILIS	Wed, May 16, 2018	Asphalt Fillet - Sidewalk	Wed, May 16, 2018
859377	RInsp_Blvd	TONY FARIA	Wed, May 3, 2017	Asphalt Fillet - Sidewalk	Wed, May 3, 2017
859374	RInsp_Blvd	TONY FARIA	Wed, May 3, 2017	Asphalt Fillet - Sidewalk	Wed, May 3, 2017
731069	RInsp_Blvd	ERNESTO PERDOMO	Tue, Apr 19, 2016	Asphalt Fillet - Sidewalk	Tue, Apr 19, 2016
731067	RInsp_Blvd	ERNESTO PERDOMO	Tue, Apr 19, 2016	Asphalt Fillet - Sidewalk	Tue, Apr 19, 2016

Sidewalk and Boulevard History Report

731064	RInsp_Blv	ERNESTO PERDOMO	Tue, Apr 19, 2016	Asphalt Fillet - Sidewalk	Tue, Apr 19, 2016
584722	RInsp_Blv	FRANCO MAZZOCCHIO	Mon, Mar 9, 2015	Asphalt Fillet - Sidewalk	Mon, Mar 9, 2015
584719	RInsp_Blv	FRANCO MAZZOCCHIO	Mon, Mar 9, 2015	Asphalt Fillet - Sidewalk	Mon, Mar 9, 2015
584718	RInsp_Blv	FRANCO MAZZOCCHIO	Mon, Mar 9, 2015	Asphalt Fillet - Sidewalk	Mon, Mar 9, 2015
484007	RInsp_Blv	ERNESTO PERDOMO	Tue, Mar 11, 2014	Asphalt Fillet - Sidewalk	Tue, Mar 11, 2014
484006	RInsp_Blv	ERNESTO PERDOMO	Tue, Mar 11, 2014	Asphalt Fillet - Sidewalk	Tue, Mar 11, 2014
269407	RInsp_Blv	MORENO AGOSTI	Mon, Feb 6, 2012	Asphalt Fillet - Sidewalk	Mon, Feb 6, 2012
269400	RInsp_Blv	MORENO AGOSTI	Mon, Feb 6, 2012	Surface Patch - Sidewalk	Tue, Feb 7, 2012
269396	RInsp_Blv	MORENO AGOSTI	Mon, Feb 6, 2012	Asphalt Fillet - Sidewalk	Mon, Feb 6, 2012
89477	RSwPlanned		Sat, Dec 31, 2011		
78712	RInspBlvd	DOMENIC CARNOVALE	Sat, Feb 5, 2011	Asphalt Fillet - Sidewalk	Thu, Jan 13, 2011
78711	RInspSdWk	DOMENIC CARNOVALE	Sat, Feb 5, 2011	Asphalt Fillet - Sidewalk	Thu, Jan 13, 2011
78707	RInspBlvd	DOMENIC CARNOVALE	Sat, Feb 5, 2011	Asphalt Fillet - Sidewalk	Thu, Jan 13, 2011
78706	RInspSdWk	DOMENIC CARNOVALE	Sat, Feb 5, 2011	Asphalt Fillet - Sidewalk	Thu, Jan 13, 2011

Service Requests	Request Type	Assign To	Resolved Date	W. O #	Log Notes	Log Date	Log By
1550656	RSideWalkRepair	RICHARD BRUCE	Wed, Dec 4, 2019		Dispatched to C1271 on Dec 4/19 *Photos Requested*	Wed, Dec 4, 2019	SAMSON ARMSTRONG-WARR
						Thu, Dec 5, 2019	BRENDA AROMIN
646169	RStRepair	RICHARD BRUCE	Mon, Nov 25, 2013		Nov. 25/13 - Follow-Behind crew on site today to complete cuts (Crew 61). -Crew 4, P. Barbosa 	Mon, Nov 25, 2013	MELISSA PIO RODA
					Dispatched to Streets Truck C1135 for investigation and repair at 8:25 on Nov 22/13	Fri, Nov 22, 2013	SCOTT ALSOP
					Nov. 25/13 - Referred to J. Bruce 	Mon, Nov 25, 2013	MELISSA PIO RODA
					Crew Called back 8:57 looking for more info, read the SR to them. Crew called again 9:03, advised the road at this loaction is closed (signs and barricades placed). Location is ready for paving crew. No further action required.	Fri, Nov 22, 2013	SCOTT ALSOP
					Nov. 22/13 - (1661 E 2nd Av) Cut in road - put Road Closed sign on both sides of the road. Ready for black. -Crew 68, R. Aheer 	Mon, Nov 25, 2013	MELISSA PIO RODA
526344	RSideWalkRepair	RONALD HAMILTON	Mon, Nov 26, 2012		NOV 26/12-dispatched to 1287 and he said that he will take a pic of the incident and give it to thomas .G	Mon, Nov 26, 2012	TONY DEMELO

Sidewalk and Boulevard History Report

Associated Address Requests	Request Type	Assign To	Resolved Date	Associated Address	W. O #	Log Notes	Log Date	Log By
1643756	RUrbanIssues	STUART MCMILLAN	Tue, Jul 14, 2020	COMMERCIAL DRIVE and E 2ND AV		Jul 14/20 - Commercial & E. 2nd - He is no longer there. - Crew 502 Jul 14/20 - Referred to S McMillan	Thu, Jul 16, 2020 Tue, Jul 14, 2020	TYLER FIELD TYLER FIELD
1641000	RConstComplaint	JASON AZUELOS	Thu, Aug 6, 2020	COTTON DRIVE and E 2ND AV		Jul 8/20 - Referred to J Azuelos Aug 6/20 - Cotton & E. 2nd - No signs at location. Must have been picked up. - I adams	Wed, Jul 8, 2020 Wed, Aug 12, 2020	TYLER FIELD TYLER FIELD
1431040	RGeneralIssue		Mon, Apr 1, 2019	s.22(1)		Apr 1/19 - 1623 E. 2nd - License plates of cars recorded. WM has been dispatched to deal with the issue.- NY Dispatch Log, Sanitation Dispatched to Sanitation.	Tue, Apr 2, 2019 Mon, Apr 1, 2019	TYLER FIELD CHRISTINA GALLOVICH
1318808	RSideWalkRepair	BILL VISTAUNET	Tue, Jul 24, 2018	COMMERCIAL DRIVE and E 2ND AV		Jul 24/18- (B. Vistaunet) Have marked sections of SW for renewal on the N/S of 1500 and 1600 E 2nd. Development on upcoming developments on this street. Jul 23/18 - Referred to B. Vistaunet.	Thu, Jul 26, 2018 Mon, Jul 23, 2018	SARAH KIM SARAH KIM
1146143	RGeneralIssue		Fri, Jun 23, 2017	s.22(1)		Jun 22/17 - Referred to Street Design Explained to s.22(1) that City policy does not allow the installation of bollards in lanes with a few exceptions (to protect gas meters, for example). The property owner may install bollards on their property at their expense.	Thu, Jun 22, 2017 Fri, Jun 23, 2017	TYLER FAHMI HENRY FEDERAU
878047	RSideWalkRepair	MARCO BIAGINI	Wed, Oct 14, 2015	s.22(1)		Dispatched to Streets Truck C1116 on Oct 14/15 at 12:50 Oct 14/15 - Sidewalk inspection. Safety gear moved. Replaced safety gear and made safe - Crew 71	Wed, Oct 14, 2015 Fri, Oct 16, 2015	OLIVER THOMAS TYLER FAHMI
870288	RTreesVegetation	VINCE SANTORELLI	Thu, Sep 24, 2015	s.22(1)		<P>Sept 24/15 - Refer to Street Trees, whole block is overgrown and needs to be trimmed. - B. Whynott</P><P>Emailed 311 to refer case to Street Trees.</P> Sept 23/15 - Referred to V. Santorelli.	Thu, Sep 24, 2015 Wed, Sep 23, 2015	TYLER FIELD TYLER FIELD
779362	RStRepair	BILL VISTAUNET	Mon, Feb 23, 2015	s.22(1)		Feb. 23/15 - We will get to this sub-district within the next 2 months. False information given due to re-scheduling. Called and informed s.22(1) -B. Vistaunet Jan 21/15 - Referred to B. Vistaunet.	Tue, Feb 24, 2015 Wed, Jan 21, 2015	MELISSA PIO RODA TYLER FIELD
749329	RStRepair	BILL VISTAUNET	Fri, Oct 24, 2014	s.22(1)		Oct. 24/14 - Old curb and gutter cut. (Will check when I get back to the office.) Crew 83 will do the repairs in the next 3 -4 weeks. s.22(1) was called. -S. Girling Oct 22/14 - Referred to B. Vistaunet.	Fri, Oct 24, 2014 Wed, Oct 22, 2014	MELISSA PIO RODA TYLER FIELD
428432	RGeneralIssue		Fri, Jan 13, 2012	1630 E 2ND AV		Dispatched Salt Truck 1961	Fri, Jan 13, 2012	JAN JONES



2020/11/06 14:17

Class

Service Request # R	1550656
Request Type	RSideWalkRepair
Request type description	Sidewalk - Repair
Request Date	2019/12/04 11:59
Call Date	2019/12/04 11:58
Lagan's ECM Update	MajorLog
Incident Date	2019/12/04 12:01
Crew Assign Date	2019/12/04 12:08
Crew ID	RMS88
Crew Contact	s.22(1)
Alt Crew Contact	
Follow-Up Date	2019/12/04 12:04
Reviewed	yes
Sub Type	xSidewalkBrokeInjury
	RICHARD BRUCE
Charges Explained	Last 311 Update, where applicable
Initiated By	no
	Road Maintenance Sidewalk 88
	Creator
	Dispatcher
	Alt Dispatcher
Alert State	None
	No Alert

nformation

Information

Zone	
Area description	
Sub-area	
Sub-area description	
Beat	
District description	
Auto Beat	
Priority	4
Priority description	Medium
Responsibility	RO
Responsibility description	Streets Operations
Project	
Project description	
311 Case #	101013565865
Source	
Due Date	2019/12/11 11:58
Ext Reference #	
Ref Type	
Lagan CSR Name	lagan
Method	
Designation	
Frequency	
Cleaning Zone	

Request Location

[illegible]

Location

Address type	Range
Street #	1600
to	1699

Pre Dir
Street Name E 2ND AV
Suffix -Range
Post Dir
Subdesignation COVAV
Cross Street
Street 2 Name
Street 2 Suffix
Street 2 Post
Direction
Cross Street
Street 3 Name
Street 3 Suffix
Street 3 Post
Direction
City, Province, Postal Code Vancouver
Province BC
Postal Code
Location

Incident Details

Dispatched to Crew #65 on Dec 4/19 *Photos Requested*
Internal Notes

Call Details

Call Duration 00:00:00
of Calls 0
Taken By
Taken by name
Customer Contact
Requested yes
Notify Customer
Regarding Service no
Request Progress

Contact

Name HUNG
First, MI BELINDA
Middle Initial
Title
Foreign no
Address
City
State/Province
ZIP/PC
Country

Contact Phone 604-871-6065
Alternate Phone
Fax
Pager
PIN
E-mail
Contact Type Other

Customer Comments

HUNG, BELINDA

Other Calls

(No Data)

Inspection

Inspector s.22(1)
Inspector name RICHARD BRUCE
Scheduled
Due By
Started
Due By
Completed
Due By
Resolved 2019/12/04 00:00
Due By

Resolution 10
 Resolution description Service Provided
 Estimated days to complete 0
 Resident Notified
Service Request Inspections
 (No Data)

Log

Service Request Log Results

Log Type	Entered By	Start Date	To	Entered By Name	Comments
Lagan ECM	KOL09	2019/12/04 12:07	2019/12/04 12:07	SAMSON ARMSTRONG-WARR	Dispatched to C1271 on Dec 4/19 *Photos Requested*
ResolComm	29516			BRENDA AROM N	

Attachments

Attachments
 (No Data)

Associations

Linked Service Requests

(No Data)

Associated Work Orders

Work Order #	Milestone	Activity	Schedule Date	Completed Date	Asset	Unit ID
1149362		RSwReact	2019/12/04 00:00		Sidewalk	107309

Associated Asset Inspections

(No Data)

Associated Cases

(No Data)

Request Details

(Tab Not Loaded)

Schedules

Employees

(No Data)

Fleet Equipment

(No Data)

Plant Equipment

(No Data)

Vehicles

(No Data)

Usage Readings

(Tab Not Loaded)

Audit Log

Audit Log

Audit Log

Field Name	Audit Date Time	New Value	Old Value	User ID	Audit Catagory
LaganCaseDetails	2019/12/04 12:01	Risk Management file number 20192352		Integration SERVICE	MCaseNotes
IncidentDate	2019/12/04 12:01	04/12/2019 12:01:05 PM	04/12/2019 11:59:35 AM	Integration SERVICE	IncidentDate
Review Date	2019/12/04 12:04	04/12/2019 12:04:00 PM	01/01/0001 12:00:00 AM	SAMSON ARMSTRONG-WARR	Hansen
Inspector	2019/12/04 12:08	s.22(1)		SAMSON ARMSTRONG-WARR	Hansen
Crew Id	2019/12/04 12:08	RMS88		SAMSON ARMSTRONG-WARR	Hansen
Resolved	2019/12/05 14:09	True	False	BRENDA AROM N	Hansen

Lagan eForm

Lagan Detail

Risk Management file number 20192352

1. Type of sidewalk problem: **Broken Causing Personal Injury****

2 If Other, provide details

3 Is there a black patch on it?No

4 Is it safe?No

5 Describe issue in detail (in front of, beside, side of street, etc) Per Risk Management Risk management has been advised of a trip and fall injury that occurred on October 12, 2019 by s.22(1) s.22(1) was allegedly walking eastbound on the north sidewalk of the 1600 block of E 2nd Avenue (just east of the intersection with Cotton Drive) when s.22(1) ripped and fell on an uneven portion of the sidewalk s.22(1) suffered multiple injuries I attended the location today and found a couple of panels that were not in standard one while walking in the eastbound direction and the other while walking in the westbound direction They are the two panels on the north sidewalk of the 1600 block of E 2nd Avenue by the private steps and by the 3rd boulevard tree east of the intersection with Cotton Drive Please have staff check the location Thank you

6 Is this request due to Motor Vehicle Accident?No

7 If Yes, provide details on license plate number or other details (if known)

8 (Don't ask just record Did caller indicate they want a call back?)No

Lagan eForm

Lagan Case Details

Wagon Location **Manitoba Yard**

A/A 919534460

Streets Operations Daily Crew Report

Rev. _____

May 16, 2018

Work order # and Hours

Crew # **63**
Field Supervisor **Mezzomo 604-619-2057**
Superintendent **Marco Biagini**

[Signature]
(signed)
[Signature]
(signed)

Hours of Work 7 AM - 3:30 PM

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem Code	1	2	3	4	5
s.22(1)	G. Fiskilis	C1287	P74	6000	GR-320		EEED77884	EEED77896			
							2	6			
s.22(1)	K. Green			6000			2	6			
Equipment Name			Equipment ID			Running Hrs					
TRUCK, DUMP, 1 YARD			C1287			2 6					
Toilets			Number of								
Flashers			Number of								
Dumps (National Yards Only)			Yrds Dumped								

ENTERED LF

May 16, 2018 Crew # 63 Field Supervisor Mezzomo Superintendent Marco Biagini

Location 1	EERD77884	Material	Amount	Comments
		#36	1.16 TONS	- S/W TRIPS (MRN)
	974292-1			
	974293-1			
	974308-1			
	974310-1			
			.26 TON	
		Dump:	Location:	
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>				
Signage Used: By: G.F. (Initials)				
Activity Code		Units Completed	Measurement	

Location 2	EERD7789A	Material	Amount	Comments
	974902-1	974283-3		- S/W TRIPS.
	974904-3	974285-3		
	974917-1	974315-1		
	974916-1	974287-1		
	974921-1	974294-2		
	974924-1	974281-3	.9 TON	
	974925-4	974289-1		
	974278-3			
	974280-2			
		Dump:	Location:	
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>				
Signage Used: By: G.F. (Initials)				
Activity Code		Units Completed	Measurement	

Location 3		Material	Amount	Comments
		Dump:	Location:	
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>				
Signage Used: By: (Initials)				
Activity Code		Units Completed	Measurement	

Location 4		Material	Amount	Comments
		Dump:	Location:	
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>				
Signage Used: By: (Initials)				
Activity Code		Units Completed	Measurement	

Location 5		Material	Amount	Comments
		Dump:	Location:	
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>				
Signage Used: By: (Initials)				
Activity Code		Units Completed	Measurement	

Wagon Location **Manitoba Yard**

A/A 921316327 *up*
Rev. _____

Streets Operations Daily Crew Report

December 04, 2019

Work order # and Hours

Crew # **65**
Field Supervisor **Mezzomo 604-619-2057**
Superintendent **Jim Bruce**

(signed)
ja

(signed)

Hours of Work 7 AM - 3:30 PM

							1	2	3	4	5
Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem Code	EER1042931				
s.22(1)	M. Boudreau			6000			4	2	1	1	
s.22(1)	D. Woods	C1271		6000			4	2	1	1	
Equipment Name							Equipment ID				
TRUCK, DUMP, 1 YARD							C1271				
							4	2	1	1	
Toilets							Number of				
Flashers							Number of				
Dumps (National Yards Only)							Yrds Dumped				

December 04, 2019 Crew # 65 Field Supervisor Mezzomo Superintendent Jim Bruce

Location 1	EER1042931	Material	Amount	Comments
Facet B11-108 to 122				CB inspection/cleaning issues
" A8-645074				
SWC Renfrew + m's G.I.I				
1550512				
Dump:		Location:		
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>				
Signage Used: By: (Initials)				
Activity Code		Units Completed	Measurement	
Location 2	EER081898	Material	Amount	Comments
4517 Elgin 1549760		#36	2.43mg	Polluter
LX700 E Hastings (5)				
L152916 E 6th (2)				
L1E 2200 Renfrew (1)				
1628 Garden (4)				
Dump:		Location:		
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>				
Signage Used: By: (Initials)				
Activity Code		Units Completed	Measurement	
Location 3	EER084687	Material	Amount	Comments
2305 E 1st (1)		#36	.08mg	Fillet
N151600 E 2nd (2) 1550656				
Dump:		Location:		
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>				
Signage Used: By: (Initials)				
Activity Code		Units Completed	Measurement	
Location 4	EER1042937	Material	Amount	Comments
SEC Commercial + N. Grandview				
1550197				
Dump:		Location:		
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>				
Signage Used: By: (Initials)				
Activity Code		Units Completed	Measurement	
Location 5		Material	Amount	Comments
Dump:		Location:		
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>				
Signage Used: By: (Initials)				
Activity Code		Units Completed	Measurement	

Work Order Summary

Work Order #: 974278 Boulevard Hazard
Asset ID #: 107309
Group Project #: 77896 RSw_Flt_NM 63-2018 Streets Operations
Location: 1600 - 1699 E 2ND AV
Operational Status: **Ref #1:** : **Ref #2:**
Service Request: **Contact Name:** **Phone#:**
Requested By: **Requested Date:** **Initiated Date:** May 08, 2018

Assigned By: MARCO BIAGINI **Assigned To:** KONSTANTINOS FISKILIS
Assigned Date: May 08, 2018 **Crew ID:** RMS63 **Work Started:**
Result: Completed **Work Completed:** May 16, 2018

Comments:

Where: Opposite Pole # 4/66
 Hazard: Sidewalk Trip
 Comments: beside a tree

This work order created by inspection # 141546
 Inspector: s.22(1)(PAUL CHAN)
 Inspected Date: 08/05/2018 1:00:34 PM

Work Orders & Accomplishments:

WO#	Result	Completed Date				
974278	Completed	May 16, 2018				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
May 16, 2018		Asphalt Fillet - Sidewalk	3	RMS63	KONSTANTINOS FISKILIS	BA

Work Area Prefix: R **SAP Network #:** EERD77896 **WBS#:** EER-00009-SF-NM-AP
Parent Network: **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
TOTAL	<u>\$0.00</u>	<u>\$0.00</u>	<u>\$0.00</u>

Work Order Summary

Work Order #: 974280 Boulevard Hazard
Asset ID #: 107309
Group Project #: 77896 RSw_Flt_NM 63-2018 Streets Operations
Location: 1600 - 1699 E 2ND AV
Operational Status: **Ref #1:** : **Ref #2:**
Service Request: **Contact Name:** **Phone#:**
Requested By: **Requested Date:** **Initiated Date:** May 08, 2018

Assigned By: MARCO BIAGINI **Assigned To:** KONSTANTINOS FISKILIS
Assigned Date: May 08, 2018 **Crew ID:** RMS63 **Work Started:**
Result: Completed **Work Completed:** May 16, 2018

Comments: Where: Opposite Civic WPL 1616
 Hazard: Sidewalk Trip
 Comments: beside a tree. also further west. second tree

This work order created by inspection # 141546
 Inspector: s.22(1)(PAUL CHAN)
 Inspected Date: 08/05/2018 1:02:27 PM

Work Orders & Accomplishments:

WO#	Result	Completed Date				
974280	Completed	May 16, 2018				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
May 16, 2018		Asphalt Fillet - Sidewalk	2	RMS63	KONSTANTINOS FISKILIS	BA

Work Area Prefix: R **SAP Network #:** EERD77896 **WBS#:** EER-00009-SF-NM-AP
Parent Network: **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
TOTAL	<u>\$0.00</u>	<u>\$0.00</u>	<u>\$0.00</u>

Work Order Summary

Work Order #: 1149362 RSw_Flt_NM 65-2019
Asset ID #: 107309
Group Project #: 84683 RSw_Flt_NM 65-2019 Streets Operations
Location: 1600 - 1699 E 2ND AV
Operational Status: **Ref #1:** : **Ref #2:**
Service Request: 1550656 **Contact Name:** BELINDA HUNG **Phone#:** 604-871-6065
Requested By: **Requested Date:** **Initiated Date:** Dec 05, 2019

Assigned By: RICHARD BRUCE **Assigned To:** DAVID WOODS
Assigned Date: Dec 05, 2019 **Crew ID:** RMA65 **Work Started:**
Result: Completed **Work Completed:** Dec 04, 2019

Comments: 2019 - Sidewalk Fillets - Non-MRN - Crew 65
 Accomplishment: RSwAsFlt

Work Orders & Accomplishments:

WO#	Result	Completed Date				
1149362	Completed	Dec 04, 2019				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Dec 04, 2019		Asphalt Fillet - Sidewalk	2	RMA65	DAVID WOODS	BA

Work Area Prefix: R **SAP Network #:** EERD84683 **WBS#:** EER-00009-SF-NM-AP
Parent Network: **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
TOTAL	\$0.00	\$0.00	\$0.00