

File No.: 04-1000-20-2021-195

May 25, 2021

s.22(1)

Dear s.22(1)

Re: **Request for Access to Records under the Freedom of Information and Protection of Privacy Act (the "Act")**

I am responding to your request of **April 7, 2021** for:

**Records regarding the sidewalk on the south side of the 2800-block of West 16th Avenue, specifically: 1) The inspection report from May 27, 2019, and 2) Any repairs from December 21, 2019 to April 7, 2021.**

All responsive records are attached. Some information in the records has been severed, (blacked out), under s.22(1) of the Act. You can read or download this section here: [http://www.bclaws.ca/EPLibraries/bclaws\\_new/document/ID/freeside/96165\\_00](http://www.bclaws.ca/EPLibraries/bclaws_new/document/ID/freeside/96165_00)

Under section 52 of the Act, and within 30 business days of receipt of this letter, you may ask the Information & Privacy Commissioner to review any matter related to the City's response to your FOI request by writing to: Office of the Information & Privacy Commissioner, [info@oipc.bc.ca](mailto:info@oipc.bc.ca) or by phoning 250-387-5629.

If you request a review, please provide the Commissioner's office with: 1) the request number (#04-1000-20-2021-195); 2) a copy of this letter; 3) a copy of your original request; and 4) detailed reasons why you are seeking the review.

Yours truly,

[Signature on file]

**Barbara J. Van Fraassen, BA**  
**Director, Access to Information & Privacy**

[Barbara.vanfraassen@vancouver.ca](mailto:Barbara.vanfraassen@vancouver.ca)  
453 W. 12th Avenue Vancouver BC V5Y 1V4

\*If you have any questions, please email us at [foi@vancouver.ca](mailto:foi@vancouver.ca) and we will respond to you as soon as possible. Or you can call the FOI Case Manager at 604.871.6584.

Encl.

:aa



2021/05/20 14:05

## Inspection

*Inspection Number* 162801  
*Inspection Type* RSwHazard  
     *Sidewalk*  
     *Asset ID* 100291  
*Asset Length* 0.0000  
*Length Unit of Measure* &nbsp;  
*Asset Width* 0.0000  
*Width Unit of Measure* &nbsp;  
*Program* H-2018-2019  
     Hazard Inspection Program 2018-2019  
     2800 W 16TH AV S  
     2800 to 2899  
     W 16TH AV

## Information

### Inspection Information

*Initiated Date*  
*Initiated By*  
*Scheduled Date*  
*Expire Date*  
*Responsibility* YK  
*Assigned To* 32342  
*Group Inspection* 7396  
     *Project*  
     *Source*  
     *Reference #*  
         Budget Number  
*Budget Number*  
*Priority*  
*Problem*

*Start Date*  
*Completed Date* 2019/05/27 09:39  
*Completed By* 32342  
*Cancel Inspection* no

## Indexes

(No Data)

## Associations

### Associated Service Requests

(No Data)

## Resource Usage

Delete Selected Usage

### Resource Usage

(No Data)

## Schedules

### Employees

(No Data)

### Fleet Equipment

(No Data)

### Plant Equipment

(No Data)

### Vehicles

(No Data)

**Attachments****Attachments**

(No Data)

**Comments**

Comments

**SWHazardDetails****Sidewalk Hazards****Hazard**

(No Data)

**SWSegHazardDetails****Segment Hazards****Hazard**

(No Data)

**SWAssetDetails***Popup Value* 2*Popup Attribute* SWCR2019*Popup Value***Asset Details***Text Attribute**Date Attribute**Text Value**Number**Value* 0.00*Value* 0.00*Date Value**Number**Program* H-2018-2019

Hazard Inspection Program 2018-2019

*Popup Attribute*

Wagon Location **Manitoba Yard**

A/A 92 1755707

**Streets Operations Daily Crew Report**

Rev. \_\_\_\_\_

April 20, 2020

Work order # and Hours

Crew # **67**  
Field Supervisor **Mezzomo 604-619-2057**  
Superintendent **Jim Bruce**

(signed) \_\_\_\_\_  
(signed) \_\_\_\_\_

Hours of Work 7:00 AM - 3:30 PM

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem Code	1	2	3	4	5
s.22(1)	G. Lindsay			6000			2	1	1	1	2
s.22(1)	W. Andrade	B1203		6000			2	1	1	1	2
Equipment Name			Equipment ID			Running Hrs					
TRUCK, DUMP, 1 YARD			B1203			2 1 1 1 2					
Toilets			Number of			0					
Flashers			Number of								
Dumps (National Yards Only)			Yrds Dumped								

16  
1  
1

ENTERED



City of Vancouver - FOI 2021-195 - Page 4 of 21

Wagon Location **Manitoba Yard**

A/A 921573574

**Streets Operations Daily Crew Report**

Rev. \_\_\_\_\_

March 02, 2020

Work order # and Hours

Crew # **67**  
Field Supervisor **Mezzomo 604-619-2057**  
Superintendent **Jim Bruce**

  
\_\_\_\_\_  
(signed)  
  
\_\_\_\_\_  
(signed)

1	2	3	4	5
FEA 286111	FEA 086269	FEA 1042940	FEA 1042939	

Hours of Work 7:00 AM - 3:30 PM

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem Code	1	2	3	4	5
s.22(1)	W. Andrade	B1203		6000			3	2	1	2	
s.22(1)	L. Colbourne			6000			3	2	1	2	
Equipment Name			Equipment ID			Running Hrs					
TRUCK, DUMP, 1 YARD			B1203			3 2 1 2					
Toilets			Number of			0					
Flashers			Number of								
Dumps (National Yards Only)			Yrds Dumped								

S



Sign safety when Departing Location:		Cones	<input type="checkbox"/>	Snow Fence	<input type="checkbox"/>	Tape	<input type="checkbox"/>	Barricade	<input type="checkbox"/>	Ramps	<input type="checkbox"/>	Flashers	<input type="checkbox"/>	Delineators	<input type="checkbox"/>
Signage Used:		By: _____ (Initials)													
Activity Code	_____		Units Completed	_____		Measurement	_____								

Sign safety when Departing Location:		Cones		<input type="checkbox"/>	Snow Fence		<input type="checkbox"/>	Tape		<input type="checkbox"/>	Barricade		<input type="checkbox"/>	Ramps		<input type="checkbox"/>	Flashers		<input type="checkbox"/>	Delineators		<input type="checkbox"/>			
Signage Used:																						By:		(Initials)	
Activity Code						Units Completed								Measurement											

Sign safety when Departing Location:		<input type="checkbox"/> Cones	<input type="checkbox"/> Snow Fence	<input type="checkbox"/> Tape	<input type="checkbox"/> Barricade	<input type="checkbox"/> Ramps	<input type="checkbox"/> Flashers	<input type="checkbox"/> Delineators	<input type="checkbox"/>
Signage Used:									By: (Initials)
Activity Code		Units Completed			Measurement				

Sign safety when Departing Location:		Cones		<input type="checkbox"/>	Snow Fence		<input type="checkbox"/>	Tape		<input type="checkbox"/>	Barricade		<input type="checkbox"/>	Ramps		<input type="checkbox"/>	Flashers		<input type="checkbox"/>	Delineators		<input type="checkbox"/>
Signage Used:																						
		By: (Initials)																				
Activity Code						Units Completed								Measurement								

Sign safety when Departing Location:		Cones		<input type="checkbox"/>	Snow Fence		<input type="checkbox"/>	Tape		<input type="checkbox"/>	Barricade		<input type="checkbox"/>	Ramps		<input type="checkbox"/>	Flashers		<input type="checkbox"/>	Delineators		<input type="checkbox"/>
Signage Used:		By: _____ (Initials)																				
Activity Code						Units Completed								Measurement								



Wagon Location Manitoba Yard

A/A 921614797 *ways*  
Rev. \_\_\_\_\_

Streets Operations Daily Crew Report

March 06, 2020

Work order # and Hours

Crew # 67  
Field Supervisor Mezzomo 604-619-2057  
Superintendent Jim Bruce

(signed) <i>[Signature]</i>	1	2	3	4	5
(signed) <i>[Signature]</i>	3	5			

Hours of Work 7:00 AM - 3:30 PM

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem Code	1	2	3	4	5
s.22(1)	D. Gubert			6000			3	5			
s.22(1)	W. Andrade	B1203		6000			3	5			
Equipment Name			Equipment ID			Running Hrs					
TRUCK, DUMP, 1 YARD			B1203			3 5					
Toilets			Number of			0					
Flashers			Number of								
Dumps (National Yards Only)			Yrds Dumped								

Activity Code	Units Completed	Measurement



March 12, 2019 Crew # 67 Field Supervisor Mezzomo Superintendent Jim Bruce

Location 1	Material	Amount	Comments
SP# 1122116			Picket up box of screws dropped on road
Dump:		Location:	
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>			
Signage Used: By: (Initials)			
Activity Code	Units Completed	Measurement	

Location 2	Material	Amount	Comments
SP# 1122346	#36	.20T	SW Filet MPV
Dump:		Location:	
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>			
Signage Used: By: (Initials)			
Activity Code	Units Completed	Measurement	

Location 3	Material	Amount	Comments
SP# 1422290			checked 900 & 1000 bK Canada Place Rd no PTH's found
Dump:		Location:	
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>			
Signage Used: By: (Initials)			
Activity Code	Units Completed	Measurement	

Location 4	Material	Amount	Comments
#200 bK Bidwell	#36	.10T	Filet 1/4" wheel chair ramp for crew # 51.
Dump:		Location:	
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>			
Signage Used: By: (Initials)			
Activity Code	Units Completed	Measurement	

Location 5	Material	Amount	Comments
SP# 1421545- 6	#36	2.21T	PTH
1421067- 6			
1421371- 10			
2000 bK Tolmie - 9			
1900 bK Tolmie 11			
4500 bK N 47- 3			
2570 N .16T- 1.0m x 1.0m			
Dump:		Location:	
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>			
Signage Used: By: (Initials)			
Activity Code	Units Completed	Measurement	

Wagon Location **Manitoba Yard**

A/A 921646646-cc



**Streets Operations Daily Crew Report**

Rev. \_\_\_\_\_

March 17, 2020

Work order # and Hours

Crew # **67**  
Field Supervisor **Mezzomo 604-619-2057**  
Superintendent **Jim Bruce**

  
\_\_\_\_\_  
(signed)  
  
\_\_\_\_\_  
(signed)

1	2	3	4	5
6:2086269	6:2086111			

Hours of Work 7:00 AM - 3:30 PM

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem Code	1	2	3	4	5
s.22(1)	G. Lindsay			6000			2	6			
s.22(1)	W. Andrade	B1203		6000			2	6			
Equipment Name			Equipment ID			Running Hrs					
TRUCK, DUMP, 1 YARD			B1203			2 6					
Toilets			Number of			0					
Flashers			Number of								
Dumps (National Yards Only)			Yrds Dumped								

ENTERED



City of Vancouver - FOI 2021-195 - Page 11 of 21

Wagon Location **Manitoba Yard**

A/A 921697780-cc

**Streets Operations Daily Crew Report**

Rev. \_\_\_\_\_

March 31, 2020

Work order # and Hours

Crew # **67**  
Field Supervisor **Mezzomo 604-619-2057**  
Superintendent **Jim Bruce**

  
\_\_\_\_\_  
(signed)  
  
\_\_\_\_\_  
(signed)

1	2	3	4	5
FEH1012939	FEH1154468	FEH178611	FEH186269	

Hours of Work 7.00 AM - 3.30 PM

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem Code	1	2	3	4	5
s.22(1)	G. Lindsay			6000			1	1	2	4	
s.22(1)	W. Andrade	B1203		6000			1	1	2	4	
Equipment Name			Equipment ID			Running Hrs					
TRUCK, DUMP, 1 YARD			B1203			1	1	2	4		
Toilets			Number of			0					
Flashers			Number of								
Dumps (National Yards Only)			Yrds Dumped								

ENTERED



Comments

Activity Code	Units Completed	Measurement
---------------	-----------------	-------------

# Work Order Summary

**Work Order #:** 1175752      RRw\_Pothole\_NM 67-2020  
**Asset ID #:** W 16TH AV  
**Group Project #:** 86111      RRw\_Pothole\_NM 67-2020      Streets Operations  
**Location:** 2800 - 2899 W 16TH AV  
**Operational Status:**      **Ref #1:** :      **Ref #2:**  
**Service Request:** 1581981      **Contact Name:** s.22(1)      **Phone#:** s.22(1)  
**Requested By:**      **Requested Date:**      **Initiated Date:** Mar 04, 2020

**Assigned By:** RICHARD BRUCE      **Assigned To:** WALTER ANDRADE  
**Assigned Date:** Mar 02, 2020      **Crew ID:** RMS67      **Work Started:**  
**Result:** Completed      **Work Completed:** Mar 02, 2020

**Comments:** Crew 67 - Potholes - Non-MRN | Accomplishment Code: RRwPothole

## Work Orders & Accomplishments:

WO#	Result	Completed Date				
1175752	Completed	Mar 02, 2020				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Mar 02, 2020		Pothole Repair	3	RMS67	WALTER ANDRADE	BA

**Work Area Prefix:** R      **SAP Network #:** EERD86111      **WBS#:** EER-00008-PR-NM-GN  
**Parent Network:**      **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
<b>TOTAL</b>	<u>\$0.00</u>	<u>\$0.00</u>	<u>\$0.00</u>



# Work Order Summary

**Work Order #:** 1178224      RRw\_Pothole\_NM 67-2020  
**Asset ID #:** W 16TH AV  
**Group Project #:** 86111      RRw\_Pothole\_NM 67-2020      Streets Operations  
**Location:** 2800 - 2899 W 16TH AV  
**Operational Status:**      **Ref #1:** :      **Ref #2:**  
**Service Request:** 1590886      **Contact Name:** s.22(1)      **Phone#:** s.22(1)  
**Requested By:**      **Requested Date:**      **Initiated Date:** Mar 11, 2020

**Assigned By:** RICHARD BRUCE      **Assigned To:** WALTER ANDRADE  
**Assigned Date:** Mar 06, 2020      **Crew ID:** RMS67      **Work Started:**  
**Result:** Completed      **Work Completed:** Mar 06, 2020

**Comments:** Crew 67 - Potholes - Non-MRN | Accomplishment Code: RRwPothole

## Work Orders & Accomplishments:

WO#	Result	Completed Date				
1178224	Completed	Mar 06, 2020				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Mar 06, 2020		Pothole Repair	6	RMS67	WALTER ANDRADE	AH - 2803

**Work Area Prefix:** R      **SAP Network #:** EERD86111      **WBS#:** EER-00008-PR-NM-GN  
**Parent Network:**      **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
<b>TOTAL</b>	<u>\$0.00</u>	<u>\$0.00</u>	<u>\$0.00</u>

# Work Order Summary

**Work Order #:** 1181853      RSw\_Flt\_NM 67-2020  
**Asset ID #:** 100291  
**Group Project #:** 86269      RSw\_Flt\_NM 67-2020      Streets Operations  
**Location:** 2800 - 2899 W 16TH AV  
**Operational Status:**      **Ref #1:** :      **Ref #2:**  
**Service Request:** 1593806      **Contact Name:** s.22(1)      **Phone#:**  
**Requested By:**      **Requested Date:**      **Initiated Date:** Mar 19, 2020

**Assigned By:**      **Assigned To:**  
**Assigned Date:**      **Crew ID:**      **Work Started:**  
**Result:** Completed      **Work Completed:** Mar 17, 2020

**Comments:** Crew 67 - Sidewalk Fillets - Non-MRN | Accomplishment Code: RSwAsFit

## Work Orders & Accomplishments:

WO#	Result	Completed Date				
1181853	Completed	Mar 17, 2020				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Mar 17, 2020		Asphalt Fillet - Sidewalk	3	RMS67	WALTER ANDRADE	AC

**Work Area Prefix:** R      **SAP Network #:** EERD86269      **WBS#:** EER-00009-SF-NM-AP  
**Parent Network:**      **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
<b>TOTAL</b>	<u>\$0.00</u>	<u>\$0.00</u>	<u>\$0.00</u>

# Work Order Summary

**Work Order #:** 1181855      RSw\_Flt\_NM 67-2020  
**Asset ID #:** 101875  
**Group Project #:** 86269      RSw\_Flt\_NM 67-2020      Streets Operations  
**Location:** 2800 - 2899 W 16TH AV  
**Operational Status:**      **Ref #1:** :      **Ref #2:**  
**Service Request:**      **Contact Name:**      **Phone#:**  
**Requested By:**      **Requested Date:**      **Initiated Date:** Mar 19, 2020

**Assigned By:**      **Assigned To:**  
**Assigned Date:**      **Crew ID:**      **Work Started:**  
**Result:** Completed      **Work Completed:** Mar 17, 2020

**Comments:** Crew 67 - Sidewalk Fillets - Non-MRN | Accomplishment Code: RSwAsFit

## Work Orders & Accomplishments:

WO#	Result	Completed Date				
1181855	Completed	Mar 17, 2020				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Mar 17, 2020		Asphalt Fillet - Sidewalk	3	RMS67	WALTER ANDRADE	AC - 2861

**Work Area Prefix:** R      **SAP Network #:** EERD86269      **WBS#:** EER-00009-SF-NM-AP  
**Parent Network:**      **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
<b>TOTAL</b>	<u>\$0.00</u>	<u>\$0.00</u>	<u>\$0.00</u>



# Work Order Summary

**Work Order #:** 1181856      RSw\_Flt\_NM 67-2020  
**Asset ID #:** 100291  
**Group Project #:** 86269      RSw\_Flt\_NM 67-2020      Streets Operations  
**Location:** 2800 - 2899 W 16TH AV  
**Operational Status:**      **Ref #1:** :      **Ref #2:**  
**Service Request:**      **Contact Name:**      **Phone#:**  
**Requested By:**      **Requested Date:**      **Initiated Date:** Mar 19, 2020

**Assigned By:**      **Assigned To:**  
**Assigned Date:**      **Crew ID:**      **Work Started:**  
**Result:** Completed      **Work Completed:** Mar 17, 2020

**Comments:** Crew 67 - Sidewalk Fillets - Non-MRN | Accomplishment Code: RSwAsFit

## Work Orders & Accomplishments:

WO#	Result	Completed Date				
1181856	Completed	Mar 17, 2020				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Mar 17, 2020		Asphalt Fillet - Sidewalk	3	RMS67	WALTER ANDRADE	AC - 2868

**Work Area Prefix:** R      **SAP Network #:** EERD86269      **WBS#:** EER-00009-SF-NM-AP  
**Parent Network:**      **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
<b>TOTAL</b>	<u>\$0.00</u>	<u>\$0.00</u>	<u>\$0.00</u>



# Work Order Summary

**Work Order #:** 1185452      Roadway Hazard  
**Asset ID #:** W 16TH AV  
**Group Project #:** 86269      RSw\_Flt\_NM 67-2020      Streets Operations  
**Location:** 2800 - 2899 W 16TH AV  
**Operational Status:**      **Ref #1:** :      **Ref #2:**  
**Service Request:**      **Contact Name:**      **Phone#:**  
**Requested By:**      **Requested Date:**      **Initiated Date:** Mar 30, 2020

**Assigned By:** RICHARD BRUCE      **Assigned To:** WALTER ANDRADE  
**Assigned Date:** Mar 30, 2020      **Crew ID:** RMS67      **Work Started:**  
**Result:** Completed      **Work Completed:** Mar 31, 2020

**Comments:** Where: At Civic 2803 Multiple trips & gaps at bus stop  
 Hazard: Curb Trip  
 Comments:

This work order created by inspection # 183838  
 Inspector: 32932 (BRUCE MCDONALD)  
 Inspected Date: 30/03/2020 11:24:05 AM

## Work Orders & Accomplishments:

WO#	Result	Completed Date				
1185452	Completed	Mar 31, 2020				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Mar 31, 2020		Asphalt Fillet - Sidewalk	4	RMS67	WALTER ANDRADE	AC

**Work Area Prefix:** R      **SAP Network #:** EERD86269      **WBS#:** EER-00009-SF-NM-AP  
**Parent Network:**      **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
<b>TOTAL</b>	<u>\$0.00</u>	<u>\$0.00</u>	<u>\$0.00</u>

# Work Order Summary

**Work Order #:** 1185469      Boulevard Hazard  
**Asset ID #:** 100291  
**Group Project #:** 86269      RSw\_Flt\_NM 67-2020      Streets Operations  
**Location:** 2800 - 2899 W 16TH AV  
**Operational Status:**      **Ref #1:** :      **Ref #2:**  
**Service Request:**      **Contact Name:**      **Phone#:**  
**Requested By:**      **Requested Date:**      **Initiated Date:** Mar 30, 2020

**Assigned By:** RICHARD BRUCE      **Assigned To:** WALTER ANDRADE  
**Assigned Date:** Mar 30, 2020      **Crew ID:** RMS67      **Work Started:**  
**Result:** Completed      **Work Completed:** Mar 31, 2020

**Comments:**  
 Where: At Pole # 8-28  
 Hazard: Sidewalk Separation  
 Comments:

This work order created by inspection # 183767  
 Inspector: 32932 (BRUCE MCDONALD)  
 Inspected Date: 30/03/2020 11:46:26 AM

## Work Orders & Accomplishments:

WO#	Result	Completed Date				
1185469	Completed	Mar 31, 2020				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Mar 31, 2020		Asphalt Fillet - Sidewalk	1	RMS67	WALTER ANDRADE	AC

**Work Area Prefix:** R      **SAP Network #:** EERD86269      **WBS#:** EER-00009-SF-NM-AP  
**Parent Network:**      **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
<b>TOTAL</b>	<b>\$0.00</b>	<b>\$0.00</b>	<b>\$0.00</b>

# Work Order Summary

**Work Order #:** 1191703      **RRw\_Pothole\_NM** 67-2020  
**Asset ID #:** W 16TH AV  
**Group Project #:** 86111      **RRw\_Pothole\_NM** 67-2020      Streets Operations  
**Location:** 2800 - 2899 W 16TH AV  
**Operational Status:**      **Ref #1:** :      **Ref #2:**  
**Service Request:**      **Contact Name:**      **Phone#:**  
**Requested By:**      **Requested Date:**      **Initiated Date:** Apr 21, 2020

**Assigned By:** RICHARD BRUCE      **Assigned To:** WALTER ANDRADE  
**Assigned Date:** Apr 20, 2020      **Crew ID:** RMS67      **Work Started:**  
**Result:** Completed      **Work Completed:** Apr 20, 2020

**Comments:** Crew 67 - Potholes - Non-MRN | Accomplishment Code: RRwPothole

## Work Orders & Accomplishments:

WO#	Result	Completed Date				
1191703	Completed	Apr 20, 2020				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Apr 20, 2020		Pothole Repair	3	RMS67	WALTER ANDRADE	AC

**Work Area Prefix:** R      **SAP Network #:** EERD86111      **WBS#:** EER-00008-PR-NM-GN  
**Parent Network:**      **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
<b>TOTAL</b>	<u>\$0.00</u>	<u>\$0.00</u>	<u>\$0.00</u>