

File No.: 04-1000-20-2021-317

September 14, 2021

s.22(1)

Dear s.22(1)

Re: **Request for Access to Records under the Freedom of Information and Protection of Privacy Act (the "Act")**

I am responding to your request of June 16, 2021 for:

**Record of all inspections and repairs regarding the 3400 block of East Hastings Street, (City of Vancouver File No. 20201376.) Date range: January 1, 2015 to November 10, 2020.**

All responsive records are located on an FTP site, (FTP instructions are included in the accompanying email). Some information in the records has been severed, (blacked out), under s.22(1) of the Act. You can read or download this section here:

[http://www.bclaws.ca/EPLibraries/bclaws\\_new/document/ID/freeside/96165\\_00](http://www.bclaws.ca/EPLibraries/bclaws_new/document/ID/freeside/96165_00)

Under section 52 of the Act, and within 30 business days of receipt of this letter, you may ask the Information & Privacy Commissioner to review any matter related to the City's response to your FOI request by writing to: Office of the Information & Privacy Commissioner, [info@oipc.bc.ca](mailto:info@oipc.bc.ca) or by phoning 250-387-5629.

If you request a review, please provide the Commissioner's office with: 1) the request number (#04-1000-20-2021-317); 2) a copy of this letter; 3) a copy of your original request; and 4) detailed reasons why you are seeking the review.

Yours truly,

[Signature on file]

**Barbara J. Van Fraassen, BA**  
**Director, Access to Information & Privacy**

[Barbara.vanfraassen@vancouver.ca](mailto:Barbara.vanfraassen@vancouver.ca)  
453 W. 12th Avenue Vancouver BC V5Y 1V4

\*If you have any questions, please email us at [foi@vancouver.ca](mailto:foi@vancouver.ca) and we will respond to you as soon as possible. Or you can call the FOI Case Manager at 604.871.6584.

:ftp

:ma



2021/08/19 13:34

## Class

Service Request # R 792075  
 Request Type RGeneralIssue  
 Request type description Street - General Issue  
 Request Date 2015/03/02 09:37  
 Call Date 2015/03/02 09:32  
 Last 311 Update MajorLog  
 Incident Date 2015/03/03 14:25  
 Crew Assign Date  
 Crew ID  
 Crew Contact  
 Alt Crew Contact  
 Follow-Up Date 2015/03/03 08:20  
 Reviewed yes  
 Sub Type Other  
 Last 311 Update, where applicable  
 Initiated By  
 Charges Explained no  
 Creator  
 Dispatcher  
 Alt Dispatcher  
 Alert State None  
 No Alert

## Information

## Information

Zone  
 Area description  
 Sub-area  
 Sub-area description  
 Beat  
 District description  
 Auto Beat  
 Priority 4  
 Priority description Medium  
 Responsibility RD  
 Responsibility description Street Design  
 Project  
 Project description  
 Source  
 Due Date 2015/04/13 09:32  
 Ext Reference #  
 Ref Type  
 Method  
 Designation  
 Frequency  
 Cleaning Zone

## Request Location

Asset &nbsp;     
 Parcel ID  
 Property ID  
 GPS X 0.0000  
 GPS Y 0.0000  
 Lane

## Location

Address type Address  
 Street # 3444  
 Pre Dir  
 Street Name E HASTINGS ST  
 Suffix (MA)  
 Post Dir  
 Subdesignation  
 Cross Street

Street 2 Name  
 Street 2 Suffix  
 Street 2 Post  
 Direction  
 Cross Street  
 Street 3 Name  
 Street 3 Suffix  
 Street 3 Post  
 Direction  
 City, Province, Postal Code  
 State BC  
 Postal Code  
 Location

## Incident Details

Internal Notes

## Call Details

Call Duration 00:00:00  
 # of Calls 0  
 Taken By  
 Taken by name  
 Customer Contact  
 Requested yes  
 Notify Customer  
 Regarding Service no  
 Request Progress  
 Warning: please use the Other Calls grid to add new contacts, otherwise the results may be unexpected.

## Contact

Name s.22(1)  
 First, MI  
 Middle Initial  
 Title  
 Contact Type Other  
 Foreign no  
 Address s.22(1) E HASTINGS ST  
 City Vancouver  
 State/Province BC  
 ZIP/PC s.22(1)  
 Country  
 Contact Phone s.22(1)  
 E-mail  
 Alternate Phone  
 Fax  
 Pager

(No Data)

## Customer Comments

s.22(1)

## Other Calls

(No Data)

## Inspection

Inspector  
 Inspector name  
 Scheduled  
 Due By  
 Started  
 Due By  
 Completed  
 Due By  
 Resolved 2015/03/03 09:02  
 Due By  
 Resolution 32  
 Resolution description Incorrect Queue Allocation  
 Resident Notified  
 Estimated days to complete 0

## Service Request Inspections

(No Data)

## Log

## Service Request Log Results

Log Type Entered By Start Date To

Lagan ECM s:22(1)

2015/03/03 07:22

Entered By Name Comments

TYLER F ELD

Mar 3/15 - Refer to Street Design. - J. Durnford

ResolComm s:22(1)

2015/03/03 09:03 HENRY FEDERAU

This appears to be a request for modification of an existing median on an arterial street. Email sent to 311 Ops requesting a new case/SR be created for Strategic Transportation and/or Traffic Management. Tried calling s:22(1) without success.

## Attachments

## Attachments

(No Data)

## Associations

## Linked Service Requests

(No Data)

## Associated Work Orders

(No Data)

## Associated Asset Inspections

(No Data)

## Associated Cases

(No Data)

## Request Details

(Tab Not Loaded)

## Schedules

## Employees

(No Data)

## Fleet Equipment

(No Data)

## Plant Equipment

(No Data)

## Vehicles

(No Data)

## Usage Readings

(Tab Not Loaded)

## Audit Log

## Audit Log

## Audit Log

Field Name	Audit Date Time	New Value	Old Value	User ID	Audit Category
Review Date	2015/03/03 07:17	03/03/2015 7:17:00 AM	01/01/0001 12:00:00 AM	TYLER FIELD	Hansen
Responsibility	2015/03/03 07:22	RD	RO	TYLER FIELD	Hansen
Review Date	2015/03/03 07:22	01/01/0001 12:00:00 AM	03/03/2015 7:17:00 AM	TYLER FIELD	Hansen
Review Date	2015/03/03 08:20	03/03/2015 8:20:00 AM	01/01/0001 12:00:00 AM	HENRY FEDERAU	Hansen
ResolutionDateTime	2015/03/03 14:25	True	False	Integration	MCloseCase
Responsibility	2015/03/03 14:25	WARNING: 311 case responsibility is RO		Integration	MResp
LaganEForm	2015/03/03 14:25			Integration	IEFormPage
LaganCaseDetails	2015/03/03 14:25	Please call s:22(1) back. Thank you. — (SAN11, Mar 3 2015 2:22PM) Created new case 101005917356	Please call s:22(1) back. Thank you.	Integration	MCaseNotes
IncidentDate	2015/03/03 14:25	03/03/2015 2:25:14 PM	02/03/2015 9:37:00 AM	Integration	IncidentDate

## 311 Case Info

## Lagan Detail

Please call s.22(1) back. Thank you. — (SAN11, Mar 3 2015 2:22PM) Created new case 101005917356

1. Type of Inquiry: \*Other - Non-Emergency

2. If Other, provide details: Would like to see the city extend an already present median or put up some sort of divider.

3. Describe the issue in detail: \*There is a Mcdonalds located at 3444 E Hastings. When you come out of the parking lot you can only turn east on E Hastings. There is not an option to turn west, and there is a median in the centre of the road. s.22(1) says that people are coming out of the Mcdonalds parking lot, turning east on Hastings and then doing a u-turn to head west on E Hastings where the median ends. Its not to far from the exit of the Mcdonalds parking lot. s.22(1) says that there are probably 100 cars a day doing this, there has been accidents and he said someone died this morning because these cars are doing u-turns where they shouldn't be. He would like to see the median extended or some sort of dividers put up to stop people from doing this u-turns and creating very unsafe conditions. s.22(1) would like a call back asap. s.22(1) across from the Mcdonalds and sees this go on all day long.

4. Is this request due to Motor Vehicle Accident? \* No

5. If Yes, provide details on license plate number or other details (if known):

6. (Don't ask just record - Did caller indicate they want a call back?) \* Yes

311 Case Form

311 notes and details

Notes to 311  
Notes to Citizen

311 Case # 101005909330  
Case creator lagan



2021/08/19 13:33

## Class

Service Request # R 845925  
 Request Type RGeneralIssue  
 Request type description Street - General Issue  
 Request Date 2015/07/27 10:11  
 Call Date 2015/07/27 10:10  
 Last 311 Update MajorLog  
 Incident Date 2015/07/27 10:17  
 Crew Assign Date 2015/07/27 10:33  
 Crew ID  
 Crew Contact [REDACTED]  
 Alt Crew Contact  
 Follow-Up Date 2015/07/27 10:33  
 Reviewed yes  
 Sub Type xEmergency  
 MARCO BIAGINI  
 Last 311 Update, where applicable  
 Initiated By  
 Charges Explained no  
 Creator  
 Dispatcher  
 Alt Dispatcher  
 Alert State None  
 No Alert

## Information

## Information

Zone  
 Area description  
 Sub-area  
 Sub-area description  
 Beat  
 District description  
 Auto Beat  
 Priority 4  
 Priority description Medium  
 Responsibility RO  
 Responsibility description Streets Operations  
 Project  
 Project description  
 Source  
 Due Date 2015/09/07 10:10  
 Ext Reference #  
 Ref Type  
 Method  
 Designation  
 Frequency  
 Cleaning Zone

## Request Location

Asset &nbsp;     
 Parcel ID  
 Property ID  
 GPS X 0.0000  
 GPS Y 0.0000  
 Lane

## Location

Address type Address  
 Street # 3423  
 Pre Dir  
 Street Name E HASTINGS ST  
 Suffix (MA)  
 Post Dir  
 Subdesignation

Cross Street  
 Street 2 Name  
 Street 2 Suffix  
 Street 2 Post  
 Direction  
 Cross Street  
 Street 3 Name  
 Street 3 Suffix  
 Street 3 Post  
 Direction  
 City, Province,  
 Postal Code  
 State  
 Postal Code  
 Location

Vancouver

BC

## Incident Details

Dispatched to Streets Truck C1297 July 27/15 10:35  
 Internal Notes

## Call Details

Call Duration 00:00:00  
 # of Calls 0  
 Taken By  
 Taken by name  
 Customer Contact  
 Requested yes  
 Notify Customer  
 Regarding Service no  
 Request Progress

Warning: please use the Other Calls grid to add new contacts, otherwise the results may be unexpected.

## Contact

Name 2015 July  
 First, MI Anonymous  
 Middle Initial  
 Title  
 Contact Type Other  
 Foreign no  
 Address  
 City  
 State/Province  
 ZIP/PC  
 Country  
 Contact Phone  
 E-mail  
 Alternate Phone  
 Fax  
 Pager

(No Data)


## Customer Comments

2015 July, Anonymous

## Other Calls

(No Data)

## Inspection

Inspector  22(1)  
 Inspector name MARCO BIAGINI  
 Scheduled  
 Due By  
 Started  
 Due By  
 Completed  
 Due By  
 Resolved 2015/07/27 00:00  
 Due By  
 Resolution 10  
 Resolution description Service Provided  
 Resident Notified  
 Estimated days to 0

complete  
Service Request Inspections  
(No Data)

## Log

## Service Request Log Results

Log Type Entered By Start Date To Entered By Name Comments

Lagan ECM	s.22(1)	2015/07/27 10:36	LEWIS GIBSON	Dispatched to Streets Truck C1297 July 27/15 10:35
ResolComm	s.22(1)	2015/07/28 10:41	TYLER FAHMI	Jul 27/15 - Broken information sign. Made safe and waited for owner - Crew 71

## Attachments

Attachments  
(No Data)

## Associations

Linked Service Requests

(No Data)

Associated Work Orders

(No Data)

Associated Asset Inspections

(No Data)

Associated Cases

(No Data)

## Request Details

(Tab Not Loaded)

## Schedules

Employees

(No Data)

Fleet Equipment

(No Data)

Plant Equipment

(No Data)

Vehicles

(No Data)

## Usage Readings

(Tab Not Loaded)

## Audit Log

## Audit Log

## Audit Log

Field Name	Audit Date Time	New Value	Old Value	User ID	Audit Catagory
LaganCaseDetails	2015/07/27 10:17	Called in by citizen s.22(1) who hung up while on hold, i was unable to reach him again to get his last name to add contact details for this case. — (Jaw27, Jul 27 2015 10:16AM) 10:16am called out to s.22(1) and provided hansen number.	Called in by citizen s.22(1) who hung up while on hold, i was unable to reach him again to get his last name to add contact details for this case.	Integration	MCasNotes
IncidentDate	2015/07/27 10:17	27/07/2015 10:17:41 AM	27/07/2015 10:11 36 AM	Integration	IncidentDate
Inspector	2015/07/27 10:33	s.22(1)		LEWIS GIBSON	Hansen
Review Date	2015/07/27 10:33	27/07/2015 10:33:00 AM	01/01/0001 12:00:00 AM	LEWIS GIBSON	Hansen
Resolved	2015/07/28 10:41	True	False	TYLER FAHMI	Hansen

## 311 Case Info

## Lagan Detail

Called in by citizen s.22(1) who hung up while on hold, i was unable to reach him again to get his last name to add contact details for this case. — (Jaw27, Jul 27 2015 10:16AM)  
10:16am called out to s.22(1) and provided hansen number.

1. Type of Inquiry: **\*Other - Emergency\***

2. If Other, provide details:

3. Describe the issue in detail: **\*There is an informational construction light up sign on E Hastings across from the Macdonalds restaurant that has been placed on the sidewalk but too close to the road side and "looks" like it has been hit by a bus or vehicle. Glass pane has come loose.**

4. Is this request due to Motor Vehicle Accident? **\* Unknown**

5. If Yes, provide details on license plate number or other details (if known):

6. (Don't ask just record - Did caller indicate they want a call back?) **\*No**

311 Case Form

311 notes and details


Notes to 311  
Notes to Citizen

311 Case # 101006517674  
Case creator lagan



2021/08/25 12:02

## Class

Service Request # R 853568  
 Request Type RGeneralIssue  
 Request type description Street - General Issue  
 Request Date 2015/08/12 14:47  
 Call Date 2015/08/12 14:46  
 Last 311 Update  
 Incident Date 2015/08/12 14:47  
 Crew Assign Date 2015/08/13 07:13  
 Crew ID  
 Crew Contact   
 Alt Crew Contact  
 Follow-Up Date 2015/08/13 07:14  
 Reviewed yes  
 Sub Type Other  
 MARCO BIAGINI  
 Last 311 Update, where applicable  
 Initiated By  
 Charges Explained no  
 Creator  
 Dispatcher  
 Alt Dispatcher  
 Alert State None  
 No Alert

## Information

## Information

Zone  
 Area description  
 Sub-area  
 Sub-area description  
 Beat  
 District description  
 Auto Beat  
 Priority 4  
 Priority description Medium  
 Responsibility RO  
 Responsibility description Streets Operations  
 Project  
 Project description  
 Source  
 Due Date 2015/09/23 14:46  
 Ext Reference #  
 Ref Type  
 Method  
 Designation  
 Frequency  
 Cleaning Zone

## Request Location

Asset &nbsp;     
 Parcel ID  
 Property ID  
 GPS X 0.0000  
 GPS Y 0.0000  
 Lane

## Location

Address type Intersection  
 Pre Dir  
 Street Name CASSIAR ST  
 Suffix -Inter  
 Post Dir  
 Compass Dir  
 Cross Street

Street 2 Name E HASTINGS ST  
 Street 2 Suffix  
 Street 2 Post  
 Direction  
 Cross Street  
 Street 3 Name  
 Street 3 Suffix  
 Street 3 Post  
 Direction  
 City, Province, Vancouver  
 Postal Code  
 Province BC  
 Postal Code  
 Location  
 Street # 300  
 to 400  
 Subdesignation COVAV

## Incident Details

Internal Notes

## Call Details

Call Duration 00:00:00  
 # of Calls 0  
 Taken By  
 Taken by name  
 Customer Contact  
 Requested yes  
 Notify Customer  
 Regarding Service no  
 Request Progress  
 Warning: please use the Other Calls grid to add new contacts, otherwise the results may be unexpected.

## Contact

Name s.22(1)  
 First, MI  
 Middle Initial  
 Title  
 Contact Type Other  
 Foreign no  
 Address  
 City  
 State/Province  
 ZIP/PC  
 Country  
 Contact Phone s.22(1)  
 E-mail  
 Alternate Phone  
 Fax  
 Pager

(No Data)

## Customer Comments

s.22(1)

## Other Calls

(No Data)

## Inspection

Inspector s.22(1)  
 Inspector name MARCO BIAGINI  
 Scheduled  
 Due By  
 Started  
 Due By  
 Completed  
 Due By  
 Resolved 2015/08/20 00:00  
 Due By  
 Resolution 39  
 Resolution description Dispatched to Crew  
 Resident Notified

Estimated days to  
complete 0

## Service Request Inspections

(No Data)

## Log

### Service Request Log Results

Log Type Entered By Start Date To Entered By Name Comments

Lagan ECM	<span style="background-color: #f08080;">s.22(1)</span>	2015/08/13 07:14	TYLER F ELD	Aug 13/15 - Referred to M. Biagini.
ResolComm	<span style="background-color: #f08080;">s.22(1)</span>	2015/08/20 15:17	TYLER F ELD	Aug 20/15 - Went to site. Will forward to Crew 75 to arrange for grinder to come out to remove concrete. - M. Biagini
ResolComm	<span style="background-color: #f08080;">s.22(1)</span>	2015/09/09 13:15	TYLER FAHMI	Sept 4/15 - Removed spilled concrete from mid lane on 3500 E Hastings at Cassiar - Crew 75

## Attachments

### Attachments

(No Data)

## Associations

### Linked Service Requests

(No Data)

### Associated Work Orders

Work Order #	Milestone	Activity	Schedule Date	Completed Date	Asset	Unit ID
665344		RRwReact	2015/09/04 00:00		Street Segment	E HASTINGS ST

### Associated Asset Inspections

(No Data)

### Associated Cases

(No Data)

## Request Details

(Tab Not Loaded)

## Schedules

### Employees

(No Data)

### Fleet Equipment

(No Data)

### Plant Equipment

(No Data)

### Vehicles

(No Data)

## Usage Readings

(Tab Not Loaded)

## Audit Log

### Audit Log

#### Audit Log

Field Name	Audit Date	Time	New Value	Old Value	User ID	Audit Catagory
Inspector	2015/08/13 07:14		<span style="background-color: #f08080;">s.22(1)</span>		TYLER FIELD	Hansen
Review Date	2015/08/13 07:14		13/08/2015 7:14 00 AM	01/01/0001 12 00:00 AM	TYLER FIELD	Hansen
Resolved	2015/08/20 15:17		True	False	TYLER FIELD	Hansen

## 311 Case Info

### Lagan Detail

Case created with help of mentor T.T

1. Type of Inquiry: **\*Other - Non-Emergency**

2. If Other, provide details:

3. Describe the issue in detail: **\*There are sections on the road that have dried up cement going eastbound on E Hastings St between Cassiar St and Boundary Road. It has been**

there for a year or two, and is uneven for cars driving.

4. Is this request due to Motor Vehicle Accident?\* **Unknown**

5. If Yes, provide details on license plate number or other details (if known):

6. (Don't ask just record - Did caller indicate they want a call back?)\***No**

311 Case Form

311 notes and details

Notes to 311

Notes to Citizen

311 Case # 101006589780

Case creator lagan



2021/08/19 13:37

## Class

Service Request # R 1103533  
 Request Type RStRepair  
 Request type description Street - Repair  
 Request Date 2017/03/14 10:19  
 Call Date 2017/03/14 10:17  
 Last 311 Update  
 Incident Date 2017/03/14 10:19  
 Crew Assign Date 2017/03/14 13:53  
 Crew ID  
 Crew Contact [REDACTED]  
 Alt Crew Contact  
 Follow-Up Date 2017/03/14 13:54  
 Reviewed yes  
 Sub Type BrokeConcrtCurbGut  
 MARCO BIAGINI  
 Last 311 Update, where applicable  
 Initiated By  
 Charges Explained no  
 Creator  
 Dispatcher  
 Alt Dispatcher  
 Alert State None  
 No Alert

## Information

## Information

Zone  
 Area description  
 Sub-area  
 Sub-area description  
 Beat  
 District description  
 Auto Beat  
 Priority 4  
 Priority description Medium  
 Responsibility RO  
 Responsibility description Streets Operations  
 Project  
 Project description  
 Source  
 Due Date 2017/03/17 10:17  
 Ext Reference #  
 Ref Type  
 Method  
 Designation  
 Frequency  
 Cleaning Zone

## Request Location

Asset &nbsp;     
 Parcel ID  
 Property ID  
 GPS X 0.0000  
 GPS Y 0.0000  
 Lane

## Location

Address type Address  
 Street # 3423  
 Pre Dir  
 Street Name E HASTINGS ST  
 Suffix (MA)  
 Post Dir  
 Subdesignation

Cross Street  
 Street 2 Name  
 Street 2 Suffix  
 Street 2 Post  
 Direction  
 Cross Street  
 Street 3 Name  
 Street 3 Suffix  
 Street 3 Post  
 Direction  
 City, Province, Vancouver  
 Postal Code  
 State BC  
 Postal Code  
 Location

## Incident Details

Internal Notes

## Call Details

Call Duration 00:00:00  
 # of Calls 0  
 Taken By  
 Taken by name  
 Customer Contact  
 Requested yes  
 Notify Customer  
 Regarding Service no  
 Request Progress  
 Warning: please use the Other Calls grid to add new contacts, otherwise the results may be unexpected.

## Contact

Name s.22(1)  
 First, MI  
 Middle Initial  
 Title  
 Contact Type Other  
 Foreign no  
 Address s.22(1) E HASTINGS ST  
 City Vancouver  
 State/Province BC  
 ZIP/PC s.22(1)  
 Country  
 Contact Phone s.22(1)  
 E-mail  
 Alternate Phone  
 Fax  
 Pager

(No Data)

## Customer Comments

s.22(1)

## Other Calls

(No Data)

## Inspection

Inspector s.22(1)  
 Inspector name MARCO BIAGINI  
 Scheduled  
 Due By  
 Started  
 Due By  
 Completed  
 Due By  
 Resolved 2017/03/20 00:00  
 Due By  
 Resolution 10  
 Resolution description Service Provided  
 Resident Notified  
 Estimated days to complete 0

## Service Request Inspections

(No Data)

## Log

## Service Request Log Results

Log Type Entered By Start Date To Entered By Name Comments

Lagan ECM	8:22(1)	2017/03/14 13:54	TYLER FAHMI	Mar 14/17 - Referred to M Biagini
ResolComm	8:22(1)	2017/03/21 13:55	SARAH KIM	Mar 20/17- Crew 70 (B. Harper) Filled 2 SW fillets.

## Attachments

## Attachments

(No Data)

## Associations

## Linked Service Requests

(No Data)

## Associated Work Orders

Work Order # Milestone Activity Schedule Date Completed Date Asset Unit ID

855224	RSwReact	2017/03/20 00:00	Sidewalk	100976
--------	----------	------------------	----------	--------

## Associated Asset Inspections

(No Data)

## Associated Cases

(No Data)

## Request Details

(Tab Not Loaded)

## Schedules

## Employees

(No Data)

## Fleet Equipment

(No Data)

## Plant Equipment

(No Data)

## Vehicles

(No Data)

## Usage Readings

(Tab Not Loaded)

## Audit Log

## Audit Log

## Audit Log

Field Name Audit Date Time New Value Old Value User ID Audit Catagory

Inspector	2017/03/14 13:54	8:22(1)			TYLER FAHMI	Hansen
Review Date	2017/03/14 13:54	14/03/2017 1:54 09 PM	01/01/0001 12 00:00 AM		TYLER FAHMI	Hansen
Resolved	2017/03/21 13:55	True	False		SARAH K M	Hansen

## 311 Case Info

## Lagan Detail

1. Type of repair: **Broken Concrete Curb/Gutter**
2. If Other, provide details:
3. Location: **Street**
4. Describe issue and location in detail: **3 ft long broken curb on the west side of 300 Cassiar adjacent to the big blvd directly across from the lane entrance of the address. The barricades on the blvd are also broken and it was reported separately.**
5. What direction were you travelling? **South**

6. Is this request due to Motor Vehicle Accident?**No**

7. If Yes, provide details on license plate number or other details (if known):

8. (Don't ask just record - Did caller indicate they want a call back?)**No**

311 Case Form

311 notes and details

*Notes to 311*  
*Notes to Citizen*

311 Case # 101009269924

Case creator lagan



2021/08/19 13:25

## Class

Service Request # R 1127074  
 Request Type RPotholeRepair  
 Request type Pothole Repair  
 description  
 Request Date 2017/05/09 14:13  
 Call Date 2017/05/09 14:13  
 Last 311 Update MajorLog  
 Incident Date 2017/05/23 13:44  
 Crew Assign Date 2017/05/10 08:49  
 Crew ID  
 Crew Contact [REDACTED]  
 Alt Crew Contact  
 Follow-Up Date 2017/05/09 14:24  
 Reviewed yes  
 Sub Type xPotholeStreet  
 MARCO BIAGINI  
 Last 311 Update, where applicable  
 Initiated By  
 Charges Explained no  
 Creator  
 Dispatcher  
 Alt Dispatcher  
 Alert State None  
 No Alert

## Information

## Information

Zone  
 Area description  
 Sub-area  
 Sub-area description  
 Beat  
 District description  
 Auto Beat  
 Priority 4  
 Priority description Medium  
 Responsibility RO  
 Responsibility description Streets Operations  
 Project  
 Project description  
 Source  
 Due Date 2017/05/12 14:13  
 Ext Reference #  
 Ref Type  
 Method  
 Designation  
 Frequency  
 Cleaning Zone

## Request Location

Asset &nbsp;     
 Parcel ID  
 Property ID  
 GPS X 0.0000  
 GPS Y 0.0000  
 Lane

## Location

Address type Range  
 Street # 3400  
 to 3499  
 Pre Dir  
 Street Name E HASTINGS ST  
 Suffix -Range  
 Post Dir

Subdesignation COVAV  
 Cross Street  
 Street 2 Name  
 Street 2 Suffix  
 Street 2 Post  
 Direction  
 Cross Street  
 Street 3 Name  
 Street 3 Suffix  
 Street 3 Post  
 Direction  
 City, Province, Postal Code Vancouver  
 Province BC  
 Postal Code  
 Location -app version: 2.31 original address: 3491 East Hastings Street

### Incident Details

Dispatched out to Afternoon Shift on May 9/17  
 May 9/17 - 3491 E. Hastings - Premixed p/h. Referred to M. Biagini. - Crew 503  
 Internal Notes

### Call Details

Call Duration 00:00:00  
 # of Calls 0  
 Taken By  
 Taken by name  
 Customer Contact  
 Requested yes  
 Notify Customer  
 Regarding Service no  
 Request Progress  
 Warning: please use the Other Calls grid to add new contacts, otherwise the results may be unexpected.

### Contact

Name s.22(1)  
 First, MI  
 Middle Initial  
 Title  
 Contact Type Owner  
 Foreign no  
 Address  
 City  
 State/Province  
 ZIP/PC  
 Country  
 Contact Phone s.22(1)  
 E-mail  
 Alternate Phone  
 Fax  
 Pager

(No Data)

### Customer Comments

s.22(1)

### Other Calls

(No Data)

### Inspection

Inspector s.22(1)  
 Inspector name MARCO BIAGINI  
 Scheduled  
 Due By  
 Started  
 Due By  
 Completed  
 Due By  
 Resolved 2017/05/18 00:00  
 Due By  
 Resolution 10  
 Resolution Service Provided  
 description

Resident Notified  
Estimated days to  
complete 0

## Service Request Inspections

(No Data)

### Log

#### Service Request Log Results

Log Type Entered By Start Date To Entered By Name Comments

Lagan ECM		2017/05/09 14:24	FAT MA LEE	Dispatched out to Afternoon Shift on May 9/17
Lagan ECM		2017/05/10 08:49	TYLER F ELD	May 9/17 - 3491 E. Hastings - Premixed p/h. Referred to M. Biagini. - Crew 503

### Attachments

#### Attachments

(No Data)

### Associations

#### Linked Service Requests

(No Data)

#### Associated Work Orders

Work Order #	Milestone	Activity	Schedule Date	Completed Date	Asset	Unit ID
867629		RRwReact	2017/05/18 00:00		Street Segment	E HASTINGS ST

#### Associated Asset Inspections

(No Data)

#### Associated Cases

(No Data)

### Request Details

(Tab Not Loaded)

### Schedules

#### Employees

(No Data)

#### Fleet Equipment

(No Data)

#### Plant Equipment

(No Data)

#### Vehicles

(No Data)

### Usage Readings

(Tab Not Loaded)

### Audit Log

#### Audit Log

##### Audit Log

Field Name	Audit Date Time	New Value	Old Value	User ID	Audit Catagory
Review Date	2017/05/09 14:24	09/05/2017 2:24 38 PM	01/01/0001 12:00:00 AM	FAT MA LEE	Hansen
Inspector	2017/05/09 14:25			FAT MA LEE	Hansen
Crew Id	2017/05/09 14:25	REM504		FAT MA LEE	Hansen
Review Date	2017/05/09 14:25	09/05/2017 2:24 00 PM	09/05/2017 2:24 38 PM	FAT MA LEE	Hansen
Inspector	2017/05/10 08:49			TYLER FIELD	Hansen
Crew Id	2017/05/10 08:49		REM504	TYLER FIELD	Hansen
Resolved	2017/05/23 13:41	True	False	Niamh MCGEE	Hansen
ResolutionDateTime	2017/05/23 13:44	True	False	Integration SERVICE	MCloseCase
LaganEForm	2017/05/23 13:44			Integration SERVICE	IEFormPage
LaganCaseDetails	2017/05/23 13:44	Comment updated.	Comment updated.	Integration SERVICE	MCaseNotes
IncidentDate	2017/05/23 13:44	23/05/2017 1:44 53 PM	09/05/2017 2:13 00 PM	Integration SERVICE	IIncidDate

### 311 Case Info

## Lagan Detail

PS Description: pothole at northwest corner of Hastings and Skeena intersection on Hastings St right lane. concrete slab missing a deep corner. right turn vehicles from Skeena to Hastings all trying to avoid it by swings into middle lane. it is a driving hazard.

PS#: 2620197

Click images below to expand



<http://www.publicstuff.com/request/view/2620197>

What is the size of the pothole? **Medium - 30-60 cm (12-24 in)**

What is the depth of the pothole? **Large - greater than 10 cm (4 in)**

Pothole location: **Street (including bike lane)**

**Unknown**

**No**

311 Case Form

311 notes and details

*Notes to 311*

*Notes to Citizen*

311 Case # 101009517579

Case creator PublicStuff



2021/08/19 13:24

## Class

Service Request # R 1133945  
 Request Type RStRepair  
 Request type description Street - Repair  
 Request Date 2017/05/26 10:26  
 Call Date 2017/05/26 10:25  
 Last 311 Update  
 Incident Date 2017/05/26 10:26  
 Crew Assign Date 2017/05/29 07:03  
 Crew ID  
 Crew Contact [REDACTED]  
 Alt Crew Contact  
 Follow-Up Date 2017/05/29 07:03  
 Reviewed yes  
 Sub Type CrackHumpInStreet  
 MARCO BIAGINI  
 Last 311 Update, where applicable  
 Initiated By  
 Charges Explained no  
 Creator  
 Dispatcher  
 Alt Dispatcher  
 Alert State None  
 No Alert

## Information

## Information

Zone  
 Area description  
 Sub-area  
 Sub-area description  
 Beat  
 District description  
 Auto Beat  
 Priority 4  
 Priority description Medium  
 Responsibility RO  
 Responsibility description Streets Operations  
 Project  
 Project description  
 Source  
 Due Date 2017/05/31 10:25  
 Ext Reference #  
 Ref Type  
 Method  
 Designation  
 Frequency  
 Cleaning Zone

## Request Location

Asset &nbsp;     
 Parcel ID  
 Property ID  
 GPS X 0.0000  
 GPS Y 0.0000  
 Lane

## Location

Address type Range  
 Street # 3400  
 to 3499  
 Pre Dir  
 Street Name E HASTINGS ST  
 Suffix -Range  
 Post Dir

Subdesignation COVAV  
 Cross Street  
 Street 2 Name  
 Street 2 Suffix  
 Street 2 Post  
 Direction  
 Cross Street  
 Street 3 Name  
 Street 3 Suffix  
 Street 3 Post  
 Direction  
 City, Province, Postal Code Vancouver  
 Province BC  
 Postal Code  
 Location

## Incident Details

Internal Notes

## Call Details

Call Duration 00:00:00  
 # of Calls 0  
 Taken By  
 Taken by name  
 Customer Contact  
 Requested yes  
 Notify Customer  
 Regarding Service no  
 Request Progress

Warning: please use the Other Calls grid to add new contacts, otherwise the results may be unexpected.

## Contact

Name s.22(1)  
 First, MI  
 Middle Initial  
 Title  
 Contact Type Other  
 Foreign no  
 Address  
 City  
 State/Province  
 ZIP/PC  
 Country  
 Contact Phone s.22(1)  
 E-mail  
 Alternate Phone  
 Fax  
 Pager

(No Data)

## Customer Comments

s.22(1)

## Other Calls

(No Data)

## Inspection

Inspector s.22(1)  
 Inspector name MARCO BIAGINI  
 Scheduled  
 Due By  
 Started  
 Due By  
 Completed  
 Due By  
 Resolved 2017/05/29 00:00  
 Due By  
 Resolution 24  
 Resolution description Investigation found no issue  
 Resident Notified  
 Estimated days to 0

*complete*  
**Service Request Inspections**  
 (No Data)

**Log****Service Request Log Results**

Log Type Entered By Start Date To Entered By Name Comments

Lagan ECM	<span style="color: red;">5.22(1)</span>	2017/05/29 07:03	TYLER F ELD	May 29/17 - Referred to M. Biagini.
ResolComm	LAG66	2017/05/30 11:46	Niamh MCGEE	MAY 29/17 - No issues found. - F Mezzomo

**Attachments****Attachments**

(No Data)

**Associations****Linked Service Requests**

(No Data)

**Associated Work Orders**

(No Data)

**Associated Asset Inspections**

(No Data)

**Associated Cases**

(No Data)

**Request Details**

(Tab Not Loaded)

**Schedules****Employees**

(No Data)

**Fleet Equipment**

(No Data)

**Plant Equipment**

(No Data)

**Vehicles**

(No Data)

**Usage Readings**

(Tab Not Loaded)

**Audit Log****Audit Log****Audit Log**

Field Name	Audit Date Time	New Value	Old Value	User ID	Audit Catagory
------------	-----------------	-----------	-----------	---------	----------------

Inspector	2017/05/29 07:03	<span style="color: red;">5.22(1)</span>		TYLER FIELD	Hansen
Review Date	2017/05/29 07:03	29/05/2017 7:03 31 AM	01/01/0001 12:00:00 AM	TYLER FIELD	Hansen
Resolved	2017/05/30 11:46	True	False	Niamh MCGEE	Hansen

**311 Case Info****Lagan Detail**

1. Type of repair: **Cracks or Humps in Street or Lane**
2. If Other, provide details:
3. Location: **Street**
4. Describe issue and location in detail: **Dried concrete on E Hastings, centre lane, between Cassiar and Boundary. This was spilled previously and never removed, has been here for a year or so. Citizen was unable to state if it's causing an issue, just that the street should be flat and smooth.**
5. What direction were you travelling? **East**

6. Is this request due to Motor Vehicle Accident?**No**

7. If Yes, provide details on license plate number or other details (if known):

8. (Don't ask just record - Did caller indicate they want a call back?)**No**

311 Case Form

311 notes and details

*Notes to 311*  
*Notes to Citizen*

311 Case # 101009598356

Case creator lagan



2021/08/19 13:36

## Class

Service Request # R 1326516  
 Request Type RSideWa kRepair  
 Request type Sidewalk - Repair  
 description  
 Request Date 2018/08/05 11:16  
 Call Date 2018/08/05 11:16  
 Last 311 Update MajorLog  
 Incident Date 2018/08/08 14:57  
 Crew Assign Date 2018/08/07 00:00  
 Crew ID  
 Crew Contact [REDACTED]  
 Alt Crew Contact  
 Follow-Up Date 2018/08/07 00:00  
 Reviewed yes  
 Sub Type SidewalkUneven  
 MARCO BIAGINI  
 Last 311 Update, where applicable  
 Initiated By  
 Charges Explained no  
 Creator  
 Dispatcher  
 Alt Dispatcher  
 Alert State None  
 No Alert

## Information

## Information

Zone  
 Area description  
 Sub-area  
 Sub-area description  
 Beat  
 District description  
 Auto Beat  
 Priority 4  
 Priority description Medium  
 Responsibility RO  
 Responsibility Streets Operations  
 description  
 Project  
 Project description  
 Source  
 Due Date 2018/08/09 08:30  
 Ext Reference #  
 Ref Type  
 Method  
 Designation  
 Frequency  
 Cleaning Zone

## Request Location

Asset &nbsp;     
 Parcel ID  
 Property ID  
 GPS X 0.0000  
 GPS Y 0.0000  
 Lane

## Location

Address type Address  
 Street # 3495  
 Pre Dir  
 Street Name E HASTINGS ST  
 Suffix (MA)  
 Post Dir  
 Subdesignation

Cross Street  
 Street 2 Name  
 Street 2 Suffix  
 Street 2 Post  
 Direction  
 Cross Street  
 Street 3 Name  
 Street 3 Suffix  
 Street 3 Post  
 Direction

City, Province, Vancouver

Postal Code

State BC

Postal Code

Location -app version: 2.31 original address: 3495 BC-7A alias: 3495 BC-7A full: 3495 E HASTINGS ST,  
 VANCOUVER, BC

## Incident Details

Aug 7/18 - Referred to M Biagini Aug 7/18 - No issues found. - F Mezzomo  
 Internal Notes

## Call Details

Call Duration 00:00:00

# of Calls 0

Taken By

Taken by name

Customer Contact yes

Requested

Notify Customer

Regarding Service no

Request Progress

Warning: please use the Other Calls grid to add new contacts, otherwise the results may be unexpected.

## Contact

Name No Name (ps)

First, MI No Name

Middle Initial

Title

Contact Type Owner

Foreign no

Address

City

State/Province

ZIP/PC

Country

Contact Phone

E-mail Anonymous@Anonymous.ca

Alternate Phone

Fax

Pager

(No Data)

## Customer Comments

No Name No Name (ps)

## Other Calls

(No Data)

## Inspection

Inspector § 22(1)

Inspector name MARCO BIAGINI

Scheduled

Due By

Started

Due By

Completed

Due By

Resolved 2018/08/07 00:00

Due By

Resolution 24

Resolution description Investigation found no issue

Resident Notified

Estimated days to  
complete 0

## Service Request Inspections

(No Data)

## Log

### Service Request Log Results

Log Type Entered By Start Date To

Entered By Name Comments

Lagan ECM	s:22(1)	2018/08/07 00:39	2018/08/07 00:39	SARAH KIM	Aug 7/18 - Referred to M Biagini
ResolComm	s:22(1)	2018/08/08 00:28	2018/08/08 00:28	TYLER FAHMI	Aug 7/18 - No issues found. - F Mezzomo

## Attachments

### Attachments

(No Data)

## Associations

### Linked Service Requests

(No Data)

### Associated Work Orders

(No Data)

### Associated Asset Inspections

(No Data)

### Associated Cases

(No Data)

## Request Details

(Tab Not Loaded)

## Schedules

### Employees

(No Data)

### Fleet Equipment

(No Data)

### Plant Equipment

(No Data)

### Vehicles

(No Data)

## Usage Readings

(Tab Not Loaded)

## Audit Log

### Audit Log

#### Audit Log

Field Name	Audit Date Time	New Value	Old Value	User ID	Audit Catagory
IncidentDate	2018/08/05 11:16	05/08/2018 11:16:45 AM	05/08/2018 11:16 26 AM	Integration SERVICE	IIcidDate
Inspector	2018/08/07 07 31	s:22(1)		SARAH K M	Hansen
Resolved	2018/08/08 14:49	True	False	TYLER FAHMI	Hansen
ResolutionDateTime	2018/08/08 14 57	True	False	Integration SERVICE	MCloseCase
IncidentDate	2018/08/08 14 57	08/08/2018 2:57:44 PM	05/08/2018 11:16:45 AM	Integration SERVICE	IIcidDate

## 311 Case Info

### Lagan Detail

PS Description: Cracks and even areas on both Hastings and Sheena.

PS#: 4632240

Click images below to expand



<http://www.publicstuff.com/request/view/4632240>

1. Type of sidewalk problem: **Uneven**
2. If Other, provide brief description:
3. Is there a black patch on it? **No**
4. Is it safe? **No**
5. Describe issue in detail (in front of, beside, side of street, etc.): **Not Applicable**
6. Is this request due to Motor Vehicle Accident? **Unknown**
8. (Don't ask just record - Did caller indicate they want a call back?): **No**


311 Case Form  
311 notes and details

Notes to 311  
Notes to Citizen  
311 Case # 101011677343  
Case creator PublicStuff



2021/08/19 13:35

## Class

Service Request # R 1330865  
 Request Type RSideWa kRepair  
 Request type Sidewalk - Repair  
 description  
 Request Date 2018/08/14 14:25  
 Call Date 2018/08/14 14:24  
 Last 311 Update IncidDate  
 Incident Date 2018/08/14 14:26  
 Crew Assign Date 2018/08/14 00:00  
 Crew ID  
 Crew Contact   
 Alt Crew Contact  
 Follow-Up Date 2018/08/14 00:00  
 Reviewed yes  
 Sub Type SidewalkCracked  
 BILL VISTAUNET  
 Last 311 Update, where applicable  
 Initiated By  
 Charges Explained no  
 Creator  
 Dispatcher  
 Alt Dispatcher  
 Alert State None  
 No Alert

## Information

## Information

Zone  
 Area description  
 Sub-area  
 Sub-area description  
 Beat  
 District description  
 Auto Beat  
 Priority 4  
 Priority description Medium  
 Responsibility RO  
 Responsibility Streets Operations  
 description  
 Project  
 Project description  
 Source  
 Due Date 2018/08/17 14:24  
 Ext Reference #  
 Ref Type  
 Method  
 Designation  
 Frequency  
 Cleaning Zone

## Request Location

Asset &nbsp;     
 Parcel ID  
 Property ID  
 GPS X 0.0000  
 GPS Y 0.0000  
 Lane

## Location

Address type Address  
 Street # 3495  
 Pre Dir  
 Street Name E HASTINGS ST  
 Suffix (MA)  
 Post Dir  
 Subdesignation

Cross Street  
 Street 2 Name  
 Street 2 Suffix  
 Street 2 Post  
 Direction  
 Cross Street  
 Street 3 Name  
 Street 3 Suffix  
 Street 3 Post  
 Direction  
 City, Province, Vancouver  
 Postal Code  
 State BC  
 Postal Code  
 Location

## Incident Details

Aug 14/18 - Referred to B Vistaunet  
 Internal Notes

## Call Details

Call Duration 00:00:00  
 # of Calls 0  
 Taken By  
 Taken by name  
 Customer Contact  
 Requested yes  
 Notify Customer  
 Regarding Service no  
 Request Progress

Warning: please use the Other Calls grid to add new contacts, otherwise the results may be unexpected.

## Contact

Name s.22(1)  
 First, MI  
 Middle Initial  
 Title  
 Contact Type Other  
 Foreign no  
 Address  
 City  
 State/Province  
 ZIP/PC  
 Country  
 Contact Phone s.22(1)  
 E-mail  
 Alternate Phone  
 Fax  
 Pager

(No Data)

## Customer Comments

s.22(1)

## Other Calls

(No Data)

## Inspection

Inspector s.22(1)  
 Inspector name BILL VISTAUNET  
 Scheduled  
 Due By  
 Started  
 Due By  
 Completed  
 Due By  
 Resolved 2018/08/15 00:00  
 Due By  
 Resolution 24  
 Resolution description Investigation found no issue  
 Resident Notified  
 Estimated days to 0

complete

## Service Request Inspections



(No Data)

## Log

## Service Request Log Results

Log Type Entered By Start Date To

Entered By Name Comments

Lagan ECM		2018/08/14 00:32	2018/08/14 00:32	SARAH KIM	Aug 14/18 - Referred to B Vistaunet
ResolComm		2018/08/16 15:28		SARAH KIM	Aug 15/18- (B. Vistaunet) No evidence of any issues at this location.

## Attachments

## Attachments

(No Data)

## Associations

## Linked Service Requests

(No Data)

## Associated Work Orders

(No Data)

## Associated Asset Inspections

(No Data)

## Associated Cases

(No Data)

## Request Details

(Tab Not Loaded)

## Schedules

## Employees

(No Data)

## Fleet Equipment

(No Data)

## Plant Equipment

(No Data)

## Vehicles

(No Data)


## Usage Readings

(Tab Not Loaded)

## Audit Log

## Audit Log

## Audit Log

Field Name	Audit Date Time	New Value	Old Value	User ID	Audit Catagory
IncidentDate	2018/08/14 14 26	14/08/2018 2:26 20 PM	14/08/2018 2:25 34 PM	Integration SERVICE	IncidentDate
Inspector	2018/08/14 15:19			SARAH K M	Hansen
Resolved	2018/08/16 15 28	True	False	SARAH K M	Hansen

## 311 Case Info

## Lagan Detail

1. Type of sidewalk problem: **Cracked**

2. If Other, provide details:

3. Is there a black patch on it? **No**4. Is it safe? **No**

5. Describe issue in detail (in front of, beside, side of street, etc.): **Sidewalk along the East and South side of this property (Hastings & Skeena) is cracked and uneven, causing a tripping hazard**

6. Is this request due to Motor Vehicle Accident?**No**

7. If Yes, provide details on license plate number or other details (if known):

8. (Don't ask just record - Did caller indicate they want a call back?)**No**

311 Case Form

311 notes and details

*Notes to 311*  
*Notes to Citizen*

311 Case # 101011720454

Case creator lagan



Service Request # R	1400294
Request Type	RStRepair
Request type description	Street - Repair
Request Date	2019/01/18 11:40
Call Date	2019/01/18 11:40
Last 311 Update	MajorLog
Incident Date	2019/01/29 07:29
Crew Assign Date	2019/01/23 00:00
Crew ID	
Crew Contact	2311
Alt Crew Contact	
Follow-Up Date	
	2019/01/21 00:00
Reviewed	yes
Sub Type	BrokeConcrtCurbGut
	RICHARD BRUCE
	Last 311 Update, where applicable
Initiated By	
Charges Explained	no
	Creator
	Dispatcher
	Alt Dispatcher
Alert State	None
	No Alert

## Information

Zone	
Area description	
Sub-area	
Sub-area description	
Beat	
District description	
Auto Beat	
Priority	4
Priority description	Medium
Responsibility	RO
Responsibility description	Streets Operations
Project	
Project description	
Source	
Due Date	2019/01/23 11:40
Ext Reference #	
Ref Type	
Method	
Designation	
Frequency	
Cleaning Zone	

Asset	
Parcel ID	
Property ID	
GPS X	0.0000
GPS Y	0.0000
Lane	

Address type	Address
Street #	3444
Pre Dir	
Street Name	E HASTINGS ST
Suffix	(MA)
Post Dir	
Subdesignation	

Cross Street  
 Street 2 Name  
 Street 2 Suffix  
 Street 2 Post  
 Direction  
 Cross Street  
 Street 3 Name  
 Street 3 Suffix  
 Street 3 Post  
 Direction

City, Province, Vancouver

Postal Code

State BC

Postal Code

Location -app version: 2.31 original address: 3444 E Hastings St alias: 3444 E HASTINGS ST full: 3444 E HASTINGS ST, VANCOUVER, BC

## Incident Details

Jan 21/19 - Referred to B Vistaunet Jan 21/19 - Concrete curb repair will be done when crew next in subdistrict. Refer to J Bruce to have asphalt repair in the interim - B Vistaunet | Jan 23/19 - Referred to J Bruce  
 Internal Notes

## Call Details

Call Duration 00:00:00

# of Calls 0

Taken By

Taken by name

Customer Contact

yes

Requested

Notify Customer

Regarding Service

no

Request Progress

Warning: please use the Other Calls grid to add new contacts, otherwise the results may be unexpected.

## Contact

Name s.22(1)  
 First, MI  
 Middle Initial  
 Title  
 Contact Type Owner  
 Foreign no  
 Address s.22(1)  
 City Vancouver  
 State/Province BC  
 ZIP/PC s.22(1)  
 Country  
 Contact Phone s.22(1)  
 E-mail  
 Alternate Phone  
 Fax  
 Pager

(No Data)

## Customer Comments

s.22(1)

## Other Calls

(No Data)

## Inspection

Inspector s.22(1)  
 Inspector name RICHARD BRUCE  
 Scheduled  
 Due By  
 Started  
 Due By  
 Completed  
 Due By  
 Resolved 2019/01/25 00:00  
 Due By  
 Resolution 10  
 Resolution Service Provided

description  
Resident Notified  
Estimated days to  
complete 0

## Service Request Inspections

(No Data)

### Log

#### Service Request Log Results

Log Type	Entered By	Start Date	To	Entered By Name	Comments
Lagan ECM		2019/01/21 00:13	2019/01/21 00:13	TYLER F ELD	Jan 21/19 - Referred to B Vistaunet
Lagan ECM		2019/01/23 00:04	2019/01/23 00:04	TYLER FAHMI	Jan 21/19 - Concrete curb repair will be done when crew next in subdistrict. Refer to J Bruce to have asphalt repair in the interim - B Vistaunet   Jan 23/19 - Referred to J Bruce
ResolComm				BRENDA AROM N	

### Attachments

(Tab Not Loaded)

### Associations

#### Linked Service Requests

(No Data)

#### Associated Work Orders

Work Order #	Milestone	Activity	Schedule Date	Completed Date	Asset Unit ID
1052346		RSwReact	2019/01/25 00:00		Sidewalk 99532

#### Associated Asset Inspections

(No Data)

#### Associated Cases

(No Data)

### Request Details

(Tab Not Loaded)

### Schedules

#### Employees

(No Data)

#### Fleet Equipment

(No Data)

#### Plant Equipment

(No Data)

#### Vehicles

(No Data)

### Usage Readings

(Tab Not Loaded)

### Audit Log

#### Audit Log

#### Audit Log


Field Name	Audit Date Time	New Value	Old Value	User ID	Audit Catagory
Inspector	2019/01/21 08:20			TYLER FIELD	Hansen
Inspector	2019/01/23 10:55			TYLER FAHMI	Hansen
Resolved	2019/01/29 07:26	True	False	BRENDA AROMIN	Hansen
ResolutionDateTime	2019/01/29 07:29	True	False	Integration SERVICE	MCloseCase
IncidentDate	2019/01/29 07:29	29/01/2019 7:29 52 AM	18/01/2019 11:40 32 AM	Integration SERVICE	IncidentDate

### 311 Case Info

#### Lagan Detail

PS#: 5473366

Click images below to expand



<http://www.publicstuff.com/request/view/5473366>

1. Type of repair:\* **Curb repair**

3. Location:\* **Street**

4. Describe issue and location in detail:\* **A chunk of curb in the bus zone by McDonald's is missing.**

8. (Don't ask just record - Did caller indicate they want a call back?) **Unknown**

311 Case Form

311 notes and details

Notes to 311

Notes to Citizen

311 Case # 101012395230

Case creator PublicStuff



2021/08/19 13:35

## Class

Service Request # R 1552368  
 Request Type RPotholeRepair  
 Request type Pothole Repair  
 description  
 Request Date 2019/12/08 19:31  
 Call Date 2019/12/08 19:31  
 Last 311 Update MajorLog  
 Incident Date 2019/12/09 09:24  
 Crew Assign Date  
 Crew ID  
 Crew Contact  
 Alt Crew Contact  
 Follow-Up Date 2019/12/08 20:17  
 Reviewed yes  
 Sub Type xPotholeStreet  
 Last 311 Update, where applicable  
 Initiated By  
 Charges Explained no  
 Creator  
 Dispatcher  
 Alt Dispatcher  
 Alert State None  
 No Alert

## Information

## Information

Zone  
 Area description  
 Sub-area  
 Sub-area description  
 Beat  
 District description  
 Auto Beat  
 Priority 4  
 Priority description Medium  
 Responsibility RO  
 Responsibility description Streets Operations  
 Project  
 Project description  
 Source  
 Due Date 2019/12/16 08:30  
 Ext Reference #  
 Ref Type  
 Method  
 Designation  
 Frequency  
 Cleaning Zone

## Request Location

Asset &nbsp;     
 Parcel ID  
 Property ID  
 GPS X 0.0000  
 GPS Y 0.0000  
 Lane

## Location

Address type Address  
 Street # 3495  
 Pre Dir  
 Street Name E HASTINGS ST  
 Suffix (MA)  
 Post Dir  
 Subdesignation  
 Cross Street

Street 2 Name  
 Street 2 Suffix  
 Street 2 Post  
 Direction  
 Cross Street  
 Street 3 Name  
 Street 3 Suffix  
 Street 3 Post  
 Direction  
 City, Province,  
 Postal Code  
 State  
 Postal Code

Vancouver

BC

Location -app version: 2.31 original address: Westbound E Hastings St @ Skeena St alias:  
 WESTBOUND E HASTINGS ST @ SKEENA ST full: 3495 E HASTINGS ST, VANCOUVER,  
 BC

## Incident Details

Internal Notes

## Call Details

Call Duration 00:00:00

# of Calls 0

Taken By

Taken by name

Customer Contact

Requested yes

Notify Customer

Regarding Service no

Request Progress

Warning: please use the Other Calls grid to add new contacts, otherwise the results may be unexpected.

## Contact

Name No Name (ps)

First, MI No Name

Middle Initial

Title

Contact Type Owner

Foreign no

Address

City

State/Province

ZIP/PC

Country

Contact Phone

E-mail Anonymous@Anonymous.ca

Alternate Phone

Fax

Pager

(No Data)

## Customer Comments

No Name No Name (ps)

## Other Calls

(No Data)

## Inspection

Inspector

Inspector name

Scheduled

Due By

Started

Due By

Completed

Due By

Resolved 2019/12/09 09:17

Due By

Resolution 24

Resolution description Investigation found no issue

Resident Notified

Estimated days to 0

*complete*  
Service Request Inspections  
(No Data)

## Log

## Service Request Log Results

Log Type Entered By Start Date To

Entered By Name Comments

Lagan ECM	NatYdPM	2019/12/08 20:17	National Yards Night Shift	Dispatched to Sanitation/Dan on 08Dec19 @20 20. LPR
ResolComm	<b>S.22(1)</b>	2019/12/09 09:17 2019/12/09 09:17	STEVE ELFORD	Sanitation Night Shift - No Fault Found

## Attachments

## Attachments

(No Data)

## Associations

## Linked Service Requests

(No Data)

## Associated Work Orders

(No Data)

## Associated Asset Inspections

(No Data)

## Associated Cases

(No Data)

## Request Details

(Tab Not Loaded)

## Schedules

## Employees

(No Data)

## Fleet Equipment

(No Data)

## Plant Equipment

(No Data)

## Vehicles

(No Data)

## Usage Readings

(Tab Not Loaded)

## Audit Log

## Audit Log

## Audit Log

Field Name	Audit Date Time	New Value	Old Value	User ID	Audit Catagory
IncidentDate	2019/12/08 19 32	08/12/2019 7:32:19 PM	08/12/2019 7:31:46 PM	Integration SERVICE	IncidentDate
Review Date	2019/12/08 20:17	08/12/2019 8:17 00 PM	01/01/0001 12 00:00 AM	National Yards Night Shift	Hansen
Resolved	2019/12/09 09:17	True	False	STEVE ELFORD	Hansen
ResolutionDateTime	2019/12/09 09 24	True	False	Integration SERVICE	MCloseCase
LaganEForm	2019/12/09 09 24			Integration SERVICE	IEFormPage
LaganCaseDetails	2019/12/09 09 24	Comment updated.	Comment updated.	Integration SERVICE	MCaseNotes
IncidentDate	2019/12/09 09 24	09/12/2019 9:24 51 AM	08/12/2019 7:32 00 PM	Integration SERVICE	IncidentDate

## 311 Case Info

## Lagan Detail

PS Description: very big crack, my motorcycle tire almost got caught

PS#: 7178240

Click images below to expand



<http://www.publicstuff.com/request/view/7178240>

1. Pothole location: **Street (including bike lane)\*\***
2. What is the size of the pothole? **Medium - 30-60 cm (12-24 in)**
3. What is the depth of the pothole? **Large - greater than 10 cm (4 in)**
6. What part of lane or shoulder is the pothole located?
7. What direction were you travelling?
9. Is this request due to Motor Vehicle Accident? **Unknown**
11. (Don't ask just record - Did caller indicate they want a call back?): **No**


311 Case Form  
311 notes and details

Notes to 311  
Notes to Citizen  
311 Case # 101013577387  
Case creator PublicStuff



2021/08/19 14:27

## Class

Service Request # R 1661801  
 Request Type RStRepair  
 Request type description Street - Repair  
 Request Date 2020/08/18 10:14  
 Call Date 2020/08/18 10:13  
 Last 311 Update MajorLog  
 Incident Date 2020/08/18 10:19  
 Crew Assign Date 2020/08/19 00:00  
 Crew ID RMS88  
 Crew Contact   
 Alt Crew Contact  
 Follow-Up Date 2020/08/19 00:00  
 Reviewed yes  
 Sub Type BrokeConcrtCurbGut  
 RICHARD BRUCE  
 Last 311 Update, where applicable  
 Initiated By  
 Charges Explained no  
 Road Maintenance Sidewalk 88  
 Creator  
 Dispatcher  
 Alt Dispatcher  
 Alert State None  
 No Alert

## Information

## Information

Zone  
 Area description  
 Sub-area  
 Sub-area description  
 Beat  
 District description  
 Auto Beat  
 Priority 4  
 Priority description Medium  
 Responsibility RO  
 Responsibility description Streets Operations  
 Project  
 Project description  
 Source  
 Due Date 2020/08/25 10:13  
 Ext Reference #  
 Ref Type  
 Method  
 Designation  
 Frequency  
 Cleaning Zone

## Request Location

Asset &nbsp;     
 Parcel ID  
 Property ID  
 GPS X 0.0000  
 GPS Y 0.0000  
 Lane

## Location

Address type Address  
 Street # 3450  
 Pre Dir  
 Street Name E HASTINGS ST  
 Suffix (SE)  
 Post Dir

Subdesignation  
 Cross Street  
 Street 2 Name  
 Street 2 Suffix  
 Street 2 Post  
 Direction  
 Cross Street  
 Street 3 Name  
 Street 3 Suffix  
 Street 3 Post  
 Direction  
 City, Province,  
 Postal Code  
 State BC  
 Postal Code  
 Location

Vancouver

BC

## Incident Details

Aug 19/20 - Referred to J Bruce  
Internal Notes

## Call Details

Call Duration 00:00:00  
 # of Calls 0  
 Taken By  
 Taken by name  
 Customer Contact  
 Requested yes  
 Notify Customer  
 Regarding Service no  
 Request Progress

Warning: please use the Other Calls grid to add new contacts, otherwise the results may be unexpected.

## Contact

Name s.22(1)  
 First, MI  
 Middle Initial  
 Title  
 Contact Type Other  
 Foreign no  
 Address  
 City  
 State/Province  
 ZIP/PC  
 Country  
 Contact Phone s.22(1)  
 E-mail  
 Alternate Phone  
 Fax  
 Pager

(No Data)

## Customer Comments

s.22(1)

## Other Calls

(No Data)

## Inspection

Inspector s.22(1)  
 Inspector name RICHARD BRUCE  
 Scheduled  
 Due By  
 Started  
 Due By  
 Completed  
 Due By  
 Resolved 2020/08/20 00:00  
 Due By  
 Resolution 10  
 Resolution description Service Provided  
 Resident Notified

Estimated days to  
complete 0

## Service Request Inspections

(No Data)

## Log

### Service Request Log Results

Log Type Entered By Start Date To

Entered By Name Comments

Lagan ECM s:22(1) 2020/08/19 00:08 2020/08/19 00:08 TYLER F ELD Aug 19/20 - Referred to J Bruce  
ResolComm s:22(1) ASHLEY CHANDRA

## Attachments

### Attachments

(No Data)

## Associations

### Linked Service Requests

(No Data)

### Associated Work Orders

Work Order #	Milestone	Activity	Schedule Date	Completed Date	Asset	Unit ID
1228688		RRwReact	2020/08/20 00:00		Street Segment	E HASTINGS ST

### Associated Asset Inspections

(No Data)

### Associated Cases

(No Data)

## Request Details

(Tab Not Loaded)

## Schedules

### Employees

(No Data)

### Fleet Equipment

(No Data)

### Plant Equipment

(No Data)

### Vehicles

(No Data)

## Usage Readings

(Tab Not Loaded)

## Audit Log

### Audit Log

#### Audit Log

Field Name	Audit Date Time	New Value	Old Value	User ID	Audit Catagory
LaganCaseDetails	2020/08/18 10:19	2020/08/18 10:18:45 ~~~ Caitlin Chanroux ~~~ Photo attached.	Photo attached.	Integration SERVICE	MCaseNotes
IncidentDate	2020/08/18 10:19	18/08/2020 10:19:26 AM	18/08/2020 10:14:10 AM	Integration SERVICE	IncidentDate
Inspector	2020/08/19 07:30	s:22(1)		TYLER FIELD	Hansen
Resolved	2020/08/24 07:32	True	False	ASHLEY CHANDRA	Hansen

## 311 Case Info

### Lagan Detail

2020/08/18 10:18:45 ~~~ Caitlin Chanroux ~~~ Photo attached.

1. Type of repair: **Broken Concrete Curb/Gutter**

2. If Other, provide details:

3. Location: **Shoulder**

4. Describe issue and location in detail: "Risk management received notification of an injury when a woman stepped off the sidewalk onto the road and into a pothole at/near 3450 E Hastings St. I attended the location and observed a small pit in the gutter of the roadway (photo attached). Out of an abundance of caution, please advise Streets Ops of the incident and location for their review."

5. What direction were you travelling? **East**

6. Is this request due to Motor Vehicle Accident? **No**

7. If Yes, provide details on license plate number or other details (if known): **n/a**

8. (Don't ask just record - Did caller indicate they want a call back?) **No**

311 Case Form

311 notes and details

Notes to 311  
Notes to Citizen

311 Case # 101014281401

Case creator lagan

Wagon Location **Manitoba Yard**

A/A

916262234-4C

## Streets Operations Daily Crew Report

Rev.

April 24, 2015

Work order # and Hours

Crew # 67

Field Supervisor **Mezzomo** 604-619-2057

**Superintendent**     **Marco Biagini**

### Hours of Work

AM - 3:30 PM

[illegible]

April 24, 2015 Crew # 67 Field Supervisor Mezzomo Superintendent Marc Diagini  
 Location 1 EER560714 Material Amount Comments

R 807709	#36	1.5 TONS	- USED 3 BAGS ABSORBAL & WHEEL BARREL OF SAND.
	Dump:	Location:	
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>			
Signage Used: By: G.F. (Initials)			
Activity Code	Units Completed	Measurement	

Location 2 EER560720	Material	Amount	Comments
R 807866			- UNPLUGGED FLOODED C.B. N/S
	Dump:	Location:	
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>			
Signage Used: By: G.F. (Initials)			
Activity Code	Units Completed	Measurement	

Location 3 EERD55688	Material	Amount	Comments
599875 (1) ✓			- CURB TRIP.
		.05 TON ✓	
	Dump:	Location:	
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>			
Signage Used: By: G.F. (Initials)			
Activity Code	Units Completed	Measurement	

Location 4 EERD55695	Material	Amount	Comments
599856 (1) ✓ 599831 (2) ✓			- CURB TRIPS (MRN)
		.1 TON ✓	
	Dump:	Location:	
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>			
Signage Used: By: G.F. (Initials)			
Activity Code	Units Completed	Measurement	

Location 5 EERD55738	Material	Amount	Comments
599809 (4) ✓ 599813 (3) ✓ 599861 (2) ✓ 599829 (4) ✓ 599820 (5) ✓			- S/W TRIPS (MRN)
		.5 TON ✓	
	Dump:	Location:	
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>			
Signage Used: By: G.F. (Initials)			
Activity Code	Units Completed	Measurement	

Location 6 EERD57270	Material	Amount	Comments
599877 (2) ✓ 599878 (1) ✓ 599886 (1) ✓ 599887 (1) ✓ 599876 (1) ✓ 599880 (1) ✓ 599879 (2) ✓			- S/W TRIPS.
		.7 TON ✓	
	Dump:	Location:	
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>			
Signage Used: By: G.F. (Initials)			
Activity Code	Units Completed	Measurement	

Location 7	Material	Amount	Comments
599817 (2) ✓ 599805 (1) ✓		.15 TON ✓	- P/H'S FILL (MRN) G.F.



July 20, 2015

Crew #

502Field Supervisor

McMillan

Superintendent

Ken Brown

Location 1

EEL 560395

Material

Amount

Comments

VARIOUS LOCATIONS  
CHECK ON & CLEAN UP AFTER  
TRANSIENTS

HASTINGS  
6 LOADS

Dump:

Location:

Sign safety when Departing Location: Cones ☐ Snow Fence ☐ Tape ☐ Barricade ☐ Ramps ☐ Flashers ☐ Delineators ☐

Signage Used:

By: (Initials)

Activity Code Units Completed Measurement

Location 2 Material Amount Comments

Dump:

Location:

Sign safety when Departing Location: Cones ☐ Snow Fence ☐ Tape ☐ Barricade ☐ Ramps ☐ Flashers ☐ Delineators ☐

Signage Used:

By: (Initials)

Activity Code Units Completed Measurement

Location 3 Material Amount Comments

Dump:

Location:

Sign safety when Departing Location: Cones ☐ Snow Fence ☐ Tape ☐ Barricade ☐ Ramps ☐ Flashers ☐ Delineators ☐

Signage Used:

By: (Initials)

Activity Code Units Completed Measurement

Location 4 Material Amount Comments

Dump:

Location:

Sign safety when Departing Location: Cones ☐ Snow Fence ☐ Tape ☐ Barricade ☐ Ramps ☐ Flashers ☐ Delineators ☐

Signage Used:

By: (Initials)

Activity Code Units Completed Measurement

Location 5 Material Amount Comments

Dump:

Location:

Sign safety when Departing Location: Cones ☐ Snow Fence ☐ Tape ☐ Barricade ☐ Ramps ☐ Flashers ☐ Delineators ☐

Signage Used:

By: (Initials)

Activity Code Units Completed Measurement

Location 6 Material Amount Comments

Dump:

Location:

Sign safety when Departing Location: Cones ☐ Snow Fence ☐ Tape ☐ Barricade ☐ Ramps ☐ Flashers ☐ Delineators ☐

Signage Used:

By: (Initials)

Activity Code Units Completed Measurement

Wagon Location    National Yard

A/A 9/6542112

## Streets Operations Daily Crew Report

Rev. +916545402

July 27, 2015

Work order # and Hours

Crew # 71

Field Supervisor **Mezzomo** 604-619-2057

Superintendent **Marco Biagini**

Hours of Work 7.00 AM - 3.50 PM

[illegible]

Equipment Name	Equipment ID	Running Hrs							
ANGLE GRINDER 4.5, CORDLESS	X-ST9019	/	/	2	2	1	1		
DRILL & DRIVE SET	X-ST9020	/	/	2	2	1	1		
DRILL, HAMMER 18V	X-ST3013	/	/	2	2	1	1		
SAW, RECIPROCATING 18V	X-ST8011	/	/	2	2	1	1		
SKIL SAW, CORDLESS	X-ST2002	/	/	2	2	1	1		
TRUCK, DUMP, 1 YARD	C1297	/	/	2	2	1	1		

ENTERED

July 27, 2015

Crew #

71Field Supervisor

Mezzomo

Superintendent

Marco Biagini

Location 1

eerD58442

Material

Amount

Comments

1.44 + 1.03

200 BIK S/S E 20th (3)  
600 S/S E 18th (2)

#36

.3

S/W TRIPS

Sign safety when Departing Location:

Cones

Snow Fence

Tape

Barricade

Ramps

Flashers

Delineators

Signage Used:

By:

(Initials)

Activity Code

Units Completed

Measurement

Location 2

eerD58799

Material

Amount

Comments

500 E 20th

#36

29 meters

SKIN Patch on Road

40

89 meters

2.0

89 meters long 2 foot wide.

1 HR.

Sign safety when Departing Location:

Cones

Snow Fence

Tape

Barricade

Ramps

Flashers

Delineators

Signage Used:

By:

(Initials)

Activity Code

Units Completed

Measurement

Location 3

eer367652

Material

Amount

Comments

SR. 845 906

2200 Yukon St E/Sc

MISSING CB LTD

it was inside pulled  
it out and replaced it

2300 Yukon E/Sc

SR 845 912

replaced. 2 HRS

Sign safety when Departing Location:

Cones

Snow Fence

Tape

Barricade

Ramps

Flashers

Delineators

Signage Used:

By:

(Initials)

Activity Code

Units Completed

Measurement

Location 4

eer560777

Material

Amount

Comments

3423 East Hastings  
SR. 845 925Broken information  
Sign on Side walk.

2 HRS

Sign safety when Departing Location:

Cones

Snow Fence

Tape

Barricade

Ramps

Flashers

Delineators

Signage Used:

By:

(Initials)

Activity Code

Units Completed

Measurement

Location 5

eerD58436

Material

Amount

Comments

600 BIK 18th Ave

(1)

#36

.22.

pot Holes

2586 E 10th St SR 845 114 (2)

1 HR

Sign safety when Departing Location:

Cones

Snow Fence

Tape

Barricade

Ramps

Flashers

Delineators

Signage Used:

By:

(Initials)

Activity Code

Units Completed

Measurement

Location 6

2005857x

Material

Amount

Comments

SR. 845 954

VPO 137286

1041 E 16th Ave

10 screws

no plywood

Secured The Back

Door with screws

per

Secured The Front

window with screws

Called at 10:41

Franko

Board UP. 1 HR

Sign safety when Departing Location:

Cones

Snow Fence

Tape

Barricade

Ramps

Flashers

Delineators

Signage Used:

By:

(Initials)

Activity Code

Units Completed

Measurement

Wagon Location    **National Yard**

A/A 9165 45 388

## Streets Operations Daily Crew Report

Rev.

July 28, 2015

Work order # and Hours

Crew # 92

Field Supervisor **Whynott** 604-690-7364

**Superintendent Dave Woods**

(signed)

(signed)

### Hours of Work

AM - 7:00 PM 3:30

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem Code	EE	EE
s.22(1)	G. Lindsay			6000			2	6
s.22(1)	J. Kirkpatrick			6000			2	6
s.22(1)	B. Whynott	E1114		6000			2	6
s.22(1)	A. McKillop			6000			2	6
s.22(1)	A. Mannarino	D1155		6000			2	6
s.22(1)	D. Chasse			7001				
	Ember B. Coutlee						2	6

ENTERED  
ECR

Equipment Name	Equipment ID	Running Hrs				
TRUCK, DUMP, 3 YARD	D1155	2	6			
TRUCK, DUMP, 3 YARD	D1160	IDLE				
TRUCK, PICKUP, LIGHT	E1114	2	6			
TURF, TRIMMER, GRASS, GAS, MEDIUM	V31535	2	6			
TURF, TRIMMER, GRASS, GAS, MEDIUM	V31539	2	6			
TURF, TRIMMER, HEDGE, DOUBLE, GAS, 30"	V31138	2	6			
ANSAN LCT.			6.5			
Toilets						
Flashers						
Dumps (National Yards Only)	Yrds Dumped					

City of Vancouver - FOI 2021-317 - Page 52 of 103

Wagon Location **National Yard**

9166 2141

## Streets Operations Daily Crew Report

Rev.

August 21, 2015

Work order # and Hours

Crew # 502

Field Supervisor **McMillan** 604-690-4422

Superintendent **Ken Brown**

(signed)

(signed)

Hours of Work 7:00 AM - 3:30 PM

[illegible]

Equipment Name	Equipment ID	Running Hrs					
SAW, CUT-OFF, HANDHELD, GAS, MEDIUM, 16"	V31336	8	9				
TRUCK, DUMP, 1 YARD	A1244	8	9				
TRUCK, PICKUP, LIGHT	A5547	8	9				
Toilets							
Flashers							
Dumps (National Yards Only)	Yrds Dumped	10 Yrds					

August 21, 2015      Crew #      502Field Supervisor      McMillan      Superintendent      Ken Brown

Location 1	EEL500395	Material	Amount	Comments
HASTINGS		4 LOADS		
		Dump:	Location:	

Sign safety when Departing Location:      Cones      ☐      Snow Fence      ☐      Tape      ☐      Barricade      ☐      Ramps      ☐      Flashers      ☐      Delineators      ☐

Signage Used:      By:      (Initials)

Activity Code      Units Completed      Measurement

Location 2	EEL637192	Material	Amount	Comments
		Dump:	Location:	

Sign safety when Departing Location:      Cones      ☐      Snow Fence      ☐      Tape      ☐      Barricade      ☐      Ramps      ☐      Flashers      ☐      Delineators      ☐

Signage Used:      By:      (Initials)

Activity Code      Units Completed      Measurement

Location 3		Material	Amount	Comments
		Dump:	Location:	

Sign safety when Departing Location:      Cones      ☐      Snow Fence      ☐      Tape      ☐      Barricade      ☐      Ramps      ☐      Flashers      ☐      Delineators      ☐

Signage Used:      By:      (Initials)

Activity Code      Units Completed      Measurement

Location 4		Material	Amount	Comments
		Dump:	Location:	

Sign safety when Departing Location:      Cones      ☐      Snow Fence      ☐      Tape      ☐      Barricade      ☐      Ramps      ☐      Flashers      ☐      Delineators      ☐

Signage Used:      By:      (Initials)

Activity Code      Units Completed      Measurement

Location 5		Material	Amount	Comments
		Dump:	Location:	

Sign safety when Departing Location:      Cones      ☐      Snow Fence      ☐      Tape      ☐      Barricade      ☐      Ramps      ☐      Flashers      ☐      Delineators      ☐

Signage Used:      By:      (Initials)

Activity Code      Units Completed      Measurement

Location 6		Material	Amount	Comments
		Dump:	Location:	

Sign safety when Departing Location:      Cones      ☐      Snow Fence      ☐      Tape      ☐      Barricade      ☐      Ramps      ☐      Flashers      ☐      Delineators      ☐

Signage Used:      By:      (Initials)

Activity Code      Units Completed      Measurement

Wagon Location    National Yard

A/A

916663269

## Streets Operations Daily Crew Report

Rev.

September 04, 2015

Work order # and Hours

Crew # 75

Field Supervisor D'Amato 604-690-5592

Superintendent ~~Marco Biagini~~

Hours of Work

AM - 7:00

PM 3:20

[illegible]

Equipment Name	Equipment ID	Running Hrs
DRILL, COMBI-HAMMER, HANDHELD, ELEC, 120V, 1PHASE	V32182	1.5 7.5 4.0
GENERATOR, PORT, GAS, 3.0KW, 120V, 1PHASE	V31373	1.5 7.5 4.0
SAW, CUT-OFF, HANDHELD, GAS, MEDIUM, 16"	V31329	1.5 7.5 4.0
Skidsteer 2	Tarmac ✓	1.5 7.5 4.0
TOOLS, SCARIFIER, WALKBEHIND	V20673	1.5 7.5 4.0
TOOLS, SCARIFIER, WALKBEHIND	V20760	1.5 7.5 4.0
TRUCK, DUMP, 1 YARD	A5490	1.5 7.5 4.0
<del>TRUCK, VAN, POWER TAILGATE, SINGLE AXLE</del>	<del>A1248</del>	<del>1.5 7.5 4.0</del>
VACUUM, DRY, 10 GALLONS	V12534	1.5 7.5 4.0
Sitter ✓	A5490	1.5 7.5 4.0
Ansam Flag ✓		1.5 7.5 4.0
TARMAC ✓		2.5 4.0
Toilets		
Flashers		
Dumps (National Yards Only)	Yrds Dumped	

Location 1	Material	Amount	Comments
1057 Denman @ Comox #861831 (2)			broken curb, strip forms, remove safety eq. S/W/C
Dump:		Location:	
Sign safety when Departing Location:	Cones	Snow Fence	Tape Barricade Ramps Flashers Delineators
Signage Used:			By: (Initials)
Activity Code	Units Completed	Measurement	
Location 2	Material	Amount	Comments
Hastings @ Cassiar #		10m³	spilled concrete on rd. mid lane. Remove with bobcat grinder
Dump:		Location:	
Sign safety when Departing Location:	Cones	Snow Fence	Tape Barricade Ramps Flashers Delineators
Signage Used:			By: (Initials)
Activity Code	Units Completed	Measurement	
Location 3	Material	Amount	Comments
Marine way @ SE Marine #858004		1.5m³	spilled cement off rd/lane, Remove bobcat grinder
Dump:		Location:	
Sign safety when Departing Location:	Cones	Snow Fence	Tape Barricade Ramps Flashers Delineators
Signage Used:			By: (Initials)
Activity Code	Units Completed	Measurement	
Location 4	Material	Amount	Comments
Dump:		Location:	
Sign safety when Departing Location:	Cones	Snow Fence	Tape Barricade Ramps Flashers Delineators
Signage Used:			By: (Initials)
Activity Code	Units Completed	Measurement	
Location 5	Material	Amount	Comments
Dump:		Location:	
Sign safety when Departing Location:	Cones	Snow Fence	Tape Barricade Ramps Flashers Delineators
Signage Used:			By: (Initials)
Activity Code	Units Completed	Measurement	
Location 6	Material	Amount	Comments
Dump:		Location:	
Sign safety when Departing Location:	Cones	Snow Fence	Tape Barricade Ramps Flashers Delineators
Signage Used:			By: (Initials)
Activity Code	Units Completed	Measurement	

Wagon Location    National Yard

A/A

9/6/66 E 90

## Streets Operations Daily Crew Report

Rev.

September 08, 2015

Work order # and Hours

Crew # 75

Field Supervisor **D'Amato** 604-690-5592

Superintendent     Enrico Santamaria

### Hours of Work

AM -

7:00 PM 3:90

PM

PM 3:10

Emp #	Employee	Equip #	Activity Type	A/Abs Slat Code	Pay Scale Group	Prem Code	N	HL	SL			
s.22(1)	L. D'Amato	A1246		6000			3.5	3	1.5			
s.22(1)	N. Cummings			6000			3.5	3	1.5			
s.22(1)	F. Cappinblano			6000			3.5	3	1.5			

ENTERED

Equipment Name	Equipment ID	Running Hrs					
DRILL, COMBI-HAMMER, HANDHELD, ELEC, 120V, 1PHASE	V32182	3.5	3	1.5			
GENERATOR, PORT, GAS, 3.0KW, 120V, 1PHASE	V31373	3.5	3	1.5			
SAW, CUT-OFF, HANDHELD, GAS, MEDIUM, 16"	V31329	3.5	3	1.5			
TOOLS, SCARIFIER, WALKBEHIND	V20673	3.5	3	1.5			
TOOLS, SCARIFIER, WALKBEHIND	V20760	3.5	3	1.5			
TRUCK, DUMP, 1 YARD	A5490	3.5	3	1.5			
TRUCK, VAN, POWER TAILGATE, SINGLE AXLE	A1246	3.5	3	1.5			
VACUUM, DRY, 10 GALLONS	V12534	3.5	3	1.5			
Toilets							
Flashers							
Dumps (National Yards Only)	Yrds Dumped						

September 08, 2015 Crew # 75Field Supervisor D'Amato Superintendent Enrico Santamaria

Location 1	Material	Amount	Comments
3300 E. HASTINGS		2	Clean CBs of leaves S/S
3400 " "		1	" " " "
3500 " "		2	" " " "
2300 E. Broadway		1	" " " " N/E/K
2300 E. Broadway		1	" " " " S/E/K
1900 " "		1	" " " " N/W/L

Dump: Location:

Sign safety when Departing Location: Cones ☐ Snow Fence ☐ Tape ☐ Barricade ☐ Ramps ☐ Flashers ☐ Delineators ☐

Signage Used: By: (Initials)

Activity Code Units Completed Measurement

Location 2	Material	Amount	Comments
1500 E. Pender			Clean CBs of leaves N/W/K
" " "			" " " " S/W/K
500 Victoria			" " " " E/N/C
" " "			" " " " W/N/K
1800 Powell			" " " " N/S
550 Denman			" " " " N/Center of rd.

Dump: Location:

Sign safety when Departing Location: Cones ☐ Snow Fence ☐ Tape ☐ Barricade ☐ Ramps ☐ Flashers ☐ Delineators ☐

Signage Used: By: (Initials)

Activity Code Units Completed Measurement

Location 3	Material	Amount	Comments
138 E. HASTINGS SR863127		(1)	Fill sink hole with pre-mix S/S 12' x 2' area for Grad 65.

Dump: Location:

Sign safety when Departing Location: Cones ☐ Snow Fence ☐ Tape ☐ Barricade ☐ Ramps ☐ Flashers ☐ Delineators ☐

Signage Used: By: (Initials)

Activity Code Units Completed Measurement

Location 4	Material	Amount	Comments

Dump: Location:

Sign safety when Departing Location: Cones ☐ Snow Fence ☐ Tape ☐ Barricade ☐ Ramps ☐ Flashers ☐ Delineators ☐

Signage Used: By: (Initials)

Activity Code Units Completed Measurement

Location 5	Material	Amount	Comments

Dump: Location:

Sign safety when Departing Location: Cones ☐ Snow Fence ☐ Tape ☐ Barricade ☐ Ramps ☐ Flashers ☐ Delineators ☐

Signage Used: By: (Initials)

Activity Code Units Completed Measurement

Location 6	Material	Amount	Comments

Dump: Location:

Sign safety when Departing Location: Cones ☐ Snow Fence ☐ Tape ☐ Barricade ☐ Ramps ☐ Flashers ☐ Delineators ☐

Signage Used: By: (Initials)

Activity Code Units Completed Measurement

Wagon Location    **National Yard**

A/A

917026516

## Streets Operations Daily Crew Report

Rev.

January 15, 2016

Work order # and Hours

Crew # 503

Field Supervisor    **Emergency Crew**    604-690-5594

Superintendent     **Jeff Eckland**

Hours of Work

330 PM

1200 AM.

[illegible]

28

January 15, 2016 Crew # 503 Field Supervisor Emergency Crew Superintendent Jeff Eckland

Location 1	Material	Amount	Comments
814 RICHARDS.			DROP OFF LICENSE
Log # / SR #R / VPD #			PLATE SLIPS @
Informant:			PARKING ENFORCEMENT.
Time Received:	(Y2HR)		
Time of Arrival:			
Time Completed:			
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input checked="" type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>		
Signage Used:			By: (Initials)
Location 2	Material	Amount	Comments
4227 W 15 <sup>th</sup>			FLOODING: NONE FOUND
Log # / SR #R / VPD # 911499			CHECKED 10 F.O. & L.R.
Informant: NATIONAL DISPATCH.			REPORTED INFO BACK
Time Received: 342 PM.			TO DISPATCH.
Time of Arrival:			
Time Completed:			
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>		
Signage Used:			By: (Initials)
Location 3	Material	Amount	Comments
3543 W 18 <sup>th</sup>			FLOODING: CIB FULL TO TOP
Log # / SR #R / VPD # 911342			WITH DEBRIS. REFERRED
Informant:			TO SEWERS.
Time Received:			
Time of Arrival:			
Time Completed:			
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>		
Signage Used:			By: (Initials)
Location 4	Material	Amount	Comments
3511 W 10 <sup>th</sup>			FLOODING: CIB HALF FULL OF
Log # / SR #R / VPD # 911331			DEBRIS. REFERRED TO
Informant:			SEWERS.
Time Received:			
Time of Arrival:			
Time Completed:			
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>		
Signage Used:			By: (Initials)
Location 5	Material	Amount	Comments
96 E 20 <sup>th</sup>			WATER LEAK.
Log # / SR #R / VPD # 911328			SALT ROAD.
Informant:			
Time Received:			
Time of Arrival:			
Time Completed:			
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>		
Signage Used:			By: (Initials)
Location 6	Material	Amount	Comments
2675 GRANVILLE.			2 S/W TRIPS. 1"
Log # / SR #R / VPD # 911589			4 PICTURES. PREMIX.
Informant: NATIONAL DISPATCH.			REFER TO CREW FOR
Time Received: 538 PM.			HOT MIX
Time of Arrival:			
Time Completed:			
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>		
Signage Used:			By: (Initials)
Location 7	Material	Amount	Comments
1100 BLK KAMLOOPS.			PREMIX 1 PIH.
Log # / SR #R / VPD # 911557			APPROX 2'x2'x2" D.
Informant: NATIONAL DISPATCH.			REFER TO CREW
Time Received: 429 PM.			FOR HOT MIX &
Time of Arrival:			SKIN PATCH.
Time Completed:			
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>		
Signage Used:			By: (Initials)

A/A

## Streets Operations Daily Crew Report

Rev.

January 15, 2016

Work order # and Hours

Crew # 503

Field Supervisor    Emergency Crew    604-690-5594

Superintendent     Jeff Eckland

Hours of Work

330 PM 1200 AM

(signed)

(signed)

[illegible]

Equipment Name	Equipment ID	Running Hrs					
DRILL & DRIVE SET	X-ST9017						
PUMP, DRAIN, SUB, CENTR, PORT, ELEC, 2", 120V, 1PHASE	V21912						
TRUCK, DUMP, 1 YARD	C1116						
Toilets							
Flashers							
Dumps (National Yards Only)	Yrds Dumped						

54

January 15, 2016 Crew # 503 Field Supervisor Emergency Crew Superintendent Jeff Eckland

Location	Material	Amount	Comments
Location 1	EER697099		
Log # / SR #R / VPD #	911603		
Informant:	NATIONAL DISPATCH		
Time Received:	551 PM		
Time of Arrival:			
Time Completed:			
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>		
Signage Used:			By: (Initials)
GRAND VIEW HWY N & WOODLAND DR. PREMIX 3 PHAS IN INTERSECTION. REFER TO CREW FOR HOT MIX.			
Location 2	EER697018		
Log # / SR #R / VPD #	911233		
Informant:	NATIONAL DISPATCH		
Time Received:			
Time of Arrival:			
Time Completed:			
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>		
Signage Used:			By: (Initials)
1693 W 62ND. FLOODING 50% CIB HALF FULL OF DEBRIS. REFERRED TO SEWERS.			
Location 3	EEL258026		
Log # / SR #R / VPD #	911627		
Informant:	NATIONAL DISPATCH		
Time Received:			
Time of Arrival:			
Time Completed:			
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>		
Signage Used:			By: (Initials)
YUKON @ W 2ND & W 4TH STOP SIGN BROKEN OFF. PLACE 3 CONES & TEMP STOP SIGN REFERRED TO TRAFFIC TO REPLACE.			
Location 4	EER697674		
Log # / SR #R / VPD #	911650		
Informant:	NATIONAL DISPATCH		
Time Received:	858 PM		
Time of Arrival:			
Time Completed:			
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>		
Signage Used:			By: (Initials)
199 ROBSON CONT. CLOSED SIW TO WORK ON OVERHEAD SIGN. PLACE CAUTION T SR removed.			
Location 5	EER697677		
Log # / SR #R / VPD #	3495 E. HASTINGS		
Informant:	NATIONAL DISPATCH		
Time Received:			
Time of Arrival:			
Time Completed:			
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>		
Signage Used:			By: (Initials)
CONCRETE SPILL CLEAR TO SIDE OF ROAD REFERRED TO SANI. FOR SWEEPER.			
Location 6			
Log # / SR #R / VPD #			
Informant:			
Time Received:			
Time of Arrival:			
Time Completed:			
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>		
Signage Used:			By: (Initials)
Location 7			
Log # / SR #R / VPD #			
Informant:			
Time Received:			
Time of Arrival:			
Time Completed:			
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>		
Signage Used:			By: (Initials)

Wagon Location **Manitoba Yard**

A/A

**Streets Operations Daily Crew Report**

Rev.

March 20, 2017

Work order # and Hours

Crew # **70**

Field Supervisor **Cut Sheet Inspection 604-690-3208**

(signed)

Superintendent **Marco Biagini**

(signed)

Hours of Work **7** AM - **3:30** PM

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem Code	1	2	3	4	5
s.22(1)	M. Medved			6000			EERD 73662 1	EERD 73661 6	EERD 73664 1		
s.22(1)	B. Harper	X-B1931	P74	6000	GR-320		1	6	1		
Equipment Name			Equipment ID			Running Hrs					
TRUCK, DUMP, 1 YARD			X-B1931			1 6 1					
Toilets											
Flashers											
Dumps (National Yards Only)			Yrds Dumped								

### Comments

Activity Code	Units Completed	Measurement	By:	(Initials)
---------------	-----------------	-------------	-----	------------

Wagon Location National Yard

A/A 10F3

Streets Operations Daily Crew Report

Rev. 918 8/0377

May 09, 2017

Work order # and Hours

Crew # 503

Field Supervisor Emergency Crew 604-690-5594

Superintendent Jim Collins

Hours of Work 3:30 PM - 12:00 AM

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem Code	1	2	3	4	5
5.22(1)	D. McKee	C 1116		6000		05	6	1	.5	.5	
Equipment Name			Equipment ID			Running Hrs					
DRILL & DRIVE SET			X-ST9017			6 1 .5 .5					
DRILL, HAMMER 18V			X-ST3020			6 1 .5 .5					
PUMP, DRAIN, SUB, CENTR, PORT, ELEC, 2", 120V, 1PHASE			V21912			6 1 .5 .5					
SAW, CHAIN, WOOD, GAS, 18"			V31727			6 1 .5 .5					
SAW, CIRCULAR, 18V			X-ST2006			6 1 .5 .5					
TRUCK, DUMP, 1 YARD			C1116			6 1 .5 .5					
Toilets											
Flashers											
Dumps (National Yards Only)			Yrds Dumped								

ENTERED

May 09, 2017 Crew # 503 Field Supervisor Emergency Crew Superintendent Jim Collins

Location 1	Material	Comments
1216 Bute St		Bolts grinded off SW, where bench used to sit.
Log # / SR #R / VPD # 1127022	✓	- Bench is sitting loose
Informant: streets		- There's a new drinking fountain where bench used to sit.
Time Received: 3:30		- Refer to streets
Time of Arrival:		
Time Completed:		- Took 4 pictures
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>	
Signage Used:	By: (Initials)	

Location 2	Material	Comments
1974 Cedar Cres	#35 mix	P/H repair:
Log # / SR #R / VPD # 1127155	✓	Premixed P/H with #35 mix.
Informant: Nat Disp		
Time Received: 4:50		Refer shallow P/H's for hot mix
Time of Arrival:		
Time Completed:		
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>	
Signage Used:	By: (Initials)	

Location 3	Material	Comments
2700 Maple Cres	#35 mix	P/H Repair:
Log # / SR #R / VPD # 1127166	✓	Premixed 7 P/H's with #35 mix
Informant: Nat Disp		
Time Received: 5:20		Refer for Hotmix
Time of Arrival:		
Time Completed:		
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>	
Signage Used:	By: (Initials)	

Location 4	Material	Comments
Fir + W16 W/B	#35 mix	P/H repair:
Log # / SR #R / VPD # 1127165	✓	Premixed 1 P/H with #35 mix
Informant: Nat Disp		
Time Received: 4:52		
Time of Arrival:		
Time Completed:		
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>	
Signage Used:	By: (Initials)	

Location 5	Material	Comments
2700 Trimble N/B	#35 mix	P/H repair:
Log # / SR #R / VPD # 1127157	✓	Premixed 3 P/H's with #35 mix
Informant: Nat Disp		
Time Received: 4:51		Refer for Hotmix
Time of Arrival:		
Time Completed:		
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>	
Signage Used:	By: (Initials)	

Location 6	Material	Comments
2000 Trimble		P/H repair:
Log # / SR #R / VPD # 1127154	✓	Nothing found.
Informant: Nat Disp		
Time Received: 4:49		
Time of Arrival:		
Time Completed:		
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>	
Signage Used:	By: (Initials)	

Wagon Location **National Yard**

A/A 2 of 3

**Streets Operations Daily Crew Report**

Rev. \_\_\_\_\_  
Work order # and Hours

May 09, 2017

Crew # **503**  
Field Supervisor **Emergency Crew 604-690-5594** (signed) \_\_\_\_\_  
Superintendent **Jim Collins** (signed) \_\_\_\_\_

Hours of Work 3:30 PM - 12:00 AM

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem Code	1	2	3	4	5
<b>S.22(1)</b>	D. McKee	<u>C 1116</u>		6000		<u>05</u>					

Equipment Name	Equipment ID	Running Hrs
DRILL & DRIVE SET	X-ST9017	
DRILL, HAMMER 18V	X-ST3020	
PUMP, DRAIN, SUB, CENTR, PORT, ELEC, 2", 120V, 1PHASE	V21912	
SAW, CHAIN, WOOD, GAS, 18"	V31727	
SAW, CIRCULAR, 18V	X-ST2006	
TRUCK, DUMP, 1 YARD	C1116	
Toilets		
Flashers		
Dumps (National Yards Only)	Yrds Dumped	

May 09, 2017

Crew #

503Field Supervisor

Emergency Crew Superintendent

Jim Collins

Location 1

EER815325

Material

Comments

Various		
Log # / SR #R / VPD #		Time
Informant: streets		✓
Time Received: 3:30		✓
Time of Arrival:		Sheets
Time Completed:		
Sign safety when Departing Location:		Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>
Signage Used:		By: (Initials)

Location 2

EER815320

Material

Comments

1956 E Pender		# 35 mix	P/H Repair:
W/B			
Log # / SR #R / VPD # 1127224		✓	Premixed 2 P/H's
Informant: Nat Disp			with # 35 mix
Time Received: 6:52			
Time of Arrival:			
Time Completed:			
Sign safety when Departing Location:		Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>	
Signage Used:		By: (Initials)	

Location 3

EER815320

Material

Comments

3491 Hastings St		# 35 mix	P/H repair:
E.			
Log # / SR #R / VPD # 1127074		✓	Premixed P/H, with
Informant: streets			# 35 mix
Time Received: 3:30			
Time of Arrival:			
Time Completed:			
Sign safety when Departing Location:		Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>	
Signage Used:		By: (Initials)	

Location 4

EER815320

Material

Comments

1803 Kitchener			P/H Repair:
Log # / SR #R / VPD # 1127101		✓	P/H's are completed
Informant: streets			at time of arrival.
Time Received: 3:30			
Time of Arrival:			
Time Completed:			
Sign safety when Departing Location:		Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>	
Signage Used:		By: (Initials)	

Location 5

EER815320

Material

Comments

E 2nd & Nootka		# 35 mix	P/H Repair:
Log # / SR #R / VPD # 1127185		✓	Premixed 2 P/H's
Informant: Nat Disp			with # 35 mix.
Time Received: 6:50			
Time of Arrival:			
Time Completed:			
Sign safety when Departing Location:		Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>	
Signage Used:		By: (Initials)	

Location 6

EER815320

Material

Comments

3450 E 29		# 35 mix	P/H Repair:
Log # / SR #R / VPD # 1127172		✓	Premixed 2 P/H's
Informant: Nat Disp			with # 35 mix
Time Received: 6:41			
Time of Arrival:			
Time Completed:			
Sign safety when Departing Location:		Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>	
Signage Used:		By: (Initials)	

Wagon Location National Yard

A/A 3 of 3

Streets Operations Daily Crew Report

Rev.

May 09, 2017

Work order # and Hours

Crew # 503  
Field Supervisor Emergency Crew 604-690-5594  
Superintendent Jim Collins

1	2	3	4	5

Hours of Work 3:30 PM - 12:00 AM

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem Code
5.22(1)	D. McKee	C1116		6000		05

Equipment Name	Equipment ID	Running Hrs
DRILL & DRIVE SET	X-ST9017	
DRILL, HAMMER 18V	X-ST3020	
PUMP, DRAIN, SUB, CENTR, PORT, ELEC, 2", 120V, 1PHASE	V21912	
SAW, CHAIN, WOOD, GAS, 18"	V31727	
SAW, CIRCULAR, 18V	X-ST2006	
TRUCK, DUMP, 1 YARD	C1116	
Toilets		
Flashers		
Dumps (National Yards Only)	Yrds Dumped	

May 09, 2017 Crew # 503 Field Supervisor Emergency Crew Superintendent Jim Collins

Location 1	Material	Comments
6300 Cartier		P/H Repair:
Log # / SR #R / VPD # 1127216		No P/H's just cracked asphalt from frost heaves.
Informant: Nat Disp		
Time Received: 6:51		
Time of Arrival:		
Time Completed:		
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>	
Signage Used:		By: (Initials)

Location 2	Material	Comments
Highbury & w 18th	1 flasher 2 cones	S/H Hole S/H 4' x 3' x 6" deep, beside Manhole cover.
Log # / SR #R / VPD # 1127229		- Outlined with orange paint.
Informant: Nat Disp		- Placed 1 flasher & 2 cones
Time Received: 7:15		- Refer to asphalt cut crew
Time of Arrival:		
Time Completed:		- Took 4 pic
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>	
Signage Used: EEL864110		By: (Initials)

Location 3	Material	Comments
Commercial & E 11	1 temp stop sign	stop sign down & Placed temp stop sign
Log # / SR #R / VPD # 1127259		- sign
Informant: Nat Disp		Refer to traffic to replace stop sign
Time Received: 9:10		
Time of Arrival:		
Time Completed:		
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>	
Signage Used:		By: (Initials)

Location 4	Material	Comments
2679 Dundas	#35 mix	P/H Repair:
Log # / SR #R / VPD # 1127264		Premixed 2 P/H's with #35 mix
Informant: Nat Disp		
Time Received: 10:22		
Time of Arrival:		
Time Completed:		
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>	
Signage Used:		By: (Initials)

Location 5	Material	Comments
Log # / SR #R / VPD #		
Informant:		
Time Received:		
Time of Arrival:		
Time Completed:		
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>	
Signage Used:		By: (Initials)

Location 6	Material	Comments
Log # / SR #R / VPD #		
Informant:		
Time Received:		
Time of Arrival:		
Time Completed:		
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>	
Signage Used:		By: (Initials)

Wagon Location National Yard

Streets Operations Daily Crew Report

May 18, 2017

A/A 9/1443532  
Rev. +918481242

Work order # and Hours

Crew # 71  
Field Supervisor Mezzomo 604-619-2057  
Superintendent Marco Biagini

*[Signature]*  
(signed)  
*[Signature]*  
(signed)

Hours of Work 7:00 AM - 3:30 PM

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem Code	1	2	3	4	5
s.22(1)	T. Faria	C1297		6000			2	2	1	1	1
s.22(1)	L. Colbourne			6000			2	2	1	1	1
Equipment Name			Equipment ID			Running Hrs					
ANGLE GRINDER 4.5, CORDLESS			X-ST9019			2 2 1 1 1					
DRILL & DRIVE SET			X-ST9020			2 2 1 1 1					
DRILL, HAMMER 18V			X-ST3013			2 2 1 1 1					
SAW, CIRCULAR, 18V			X-ST2002			2 2 1 1 1					
SAW, RECIPROCATING, 18V			X-ST8011			2 2 1 1 1					
TRUCK, DUMP, 1 YARD			B1261			2 2 1 1 1					
TRUCK, DUMP, 1 YARD			C1297			2 2 1 1 1					
Toilets											
Flashers											
Dumps (National Yards Only)			Yrds Dumped								

ENTERED  
11/6

May 18, 2017 Crew # 71 Field Supervisor Mezzomo Superintendent Marco Biagini

Location 1	Material	Amount	Comments
1121411-(1) 1126961-(11)			P/H
1127224-(20) 1123428-(7)			
1120392-(5) 1127264-(11)			
Alexander / Jackson (1)	1130892		
Dump:	Location:		
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>			
Signage Used: By: (Initials)			
Activity Code	Units Completed	Measurement	
Location 2	Material	Amount	Comments
1127674-(1)			P/H m R n
3126 main st	1130734	9 meters	Road patch
Dump:	Location:		
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>			
Signage Used: By: (Initials)			
Activity Code	Units Completed	Measurement	
Location 3	Material	Amount	Comments
main / switchman st	1130744		Recover phone
23 Ave / Belgrade			from C/B
EEW 35716			Bolt cut off lock
			from pole.
Dump:	Location:		
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>			
Signage Used: By: (Initials)			
Activity Code	Units Completed	Measurement	
Location 4	Material	Amount	Comments
200 E 10th Ave	1130685		metal plates on
			road way
Dump:	Location:		
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>			
Signage Used: By: (Initials)			
Activity Code	Units Completed	Measurement	
Location 5	Material	Amount	Comments
LIR 3603 napier st	1130820		missing C/B
			Replaced it
			it fill inside.
Dump:	Location:		
Sign safety when Departing Location: Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>			
Signage Used: By: (Initials)			
Activity Code	Units Completed	Measurement	

Wagon Location National Yard

A/A

Streets Operations Daily Crew Report

Rev.

June 05, 2018

Work order # and Hours

Crew # 503

Field Supervisor Emergency Crew 604-871-6989

(signed)

Superintendent Jim Collins

(signed)

Hours of Work

330 AM - 1200 PM

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem Code	1	2	3	4	5
522(1)	B. Huth	D1116		6000		05	2.5	2	1	1	1
Equipment Name			Equipment ID			Running Hrs					
DRILL & DRIVE SET			X-ST9017			2.5 2 1 1 1					
DRILL, HAMMER 18V			X-ST3020			2.5 2 1 1 1					
PUMP, DRAIN, SUB, CENTR, PORT, ELEC, 2", 120V, 1PHASE			V21912			2.5 2 1 1 1					
SAW, CHAIN, WOOD, GAS, 18"			V31727			2.5 2 1 1 1					
SAW, CIRCULAR, 18V			X-ST2006			2.5 2 1 1 1					
TRUCK, DUMP, 1 YARD			D1116			2.5 2 1 1 1					
Toilets			Number of								
Flashers			Number of								
Dumps (National Yards Only)			Yrds Dumped								

ENTERED

June 05, 2018 Crew # 503 Field Supervisor Emergency Crew Superintendent Jim Collins

Location 1	Material	Comments
2819 W 44th		PREMIX 2 PIHS
Log # / SR #R / VPD # 1297113	(1HR)	REFER TO CREW FOR HOT MIX.
Informant:		
Time Received:		
Time of Arrival:		
Time Completed:		
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>	
Signage Used:		By: (Initials) <i>Marco</i>

Location 2	Material	Comments
VARIOUS		PICK UP & DELIVER ALL MAIL.
Log # / SR #R / VPD #	(2HRS)	
Informant:		
Time Received:		
Time of Arrival:		
Time Completed:		
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>	
Signage Used:		By: (Initials)

Location 3	Material	Comments
241 W. KING EDWARD		CONCRETE SIW PANEL. LOOSE ROCKS ON TREE ROOT. 3 PICTURES. PLACE DELINEATOR. REFER TO CREW TO LEVEL PANEL.
Log # / SR #R / VPD # 1297773	(1/2HR)	
Informant:		
Time Received:		
Time of Arrival:		
Time Completed:		
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>	
Signage Used:		By: (Initials) <i>B. H. V. S. Tourner</i>

Location 4	Material	Comments
2806 W 17th	(1HR)	BRANCHES FROM BUSH BELONGING TO CHEVRON ON W 16th & MACDONALD. BLOCKING VIEW OF STOP SIGN. REFER TO CREW TO CUT BRANCHES OR GIVE ENCROACHMENT NOTICE.
Log # / SR #R / VPD # 101011358386		
Informant:		
Time Received:		
Time of Arrival:		
Time Completed:		
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>	
Signage Used:		By: (Initials) <i>Vince S.</i>

Location 5	Material	Comments
LIN 3100 W. BROADWAY.		USED 2 BARRICADES & 2 FLASHERS WITH CAUTION TAPE TO CLOSE LANE. SINK HOLE. REPORT TO V.P.D. & I.F.D. LANE CLOSED. REPORT INFO TO PENNSBROWL REFERRED TO SANI. TO MONITOR.
Log # / SR #R / VPD # 981783	(1/2HR)	
Informant: ELEC.		
Time Received:		
Time of Arrival:		
Time Completed:		
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>	
Signage Used:		By: (Initials) <i>TO MONITOR</i>

Location 6	Material	Comments
999 CANADA PLACE.		PIH. NONE FOUND.
Log # / SR #R / VPD # 1297810	(1/2HR)	REFER TO DAYSHIFT. TO CONTACT COMPLAINANT.
Informant:		
Time Received:		
Time of Arrival:		
Time Completed:		
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>	
Signage Used:		By: (Initials) <i>Marco</i>

Wagon Location National Yard

A/A 969609593

Streets Operations Daily Crew Report

Rev.

June 05, 2018

Work order # and Hours

Crew # 503

Field Supervisor Emergency Crew 604-871-6989

*Blaire Huth*  
*J. Collins*

Superintendent Jim Collins

Hours of Work 330p AM - 1200 PM

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem Code	1	2	3	4	5
522(1)	B. Huth	D1116		6000		05	05				
Equipment Name			Equipment ID			Running Hrs					
DRILL & DRIVE SET			X-ST9017			.5					
DRILL, HAMMER 18V			X-ST3020			.5					
PUMP, DRAIN, SUB, CENTR, PORT, ELEC, 2", 120V, 1PHASE			V21912			.5					
SAW, CHAIN, WOOD, GAS, 18"			V31727			.5					
SAW, CIRCULAR, 18V			X-ST2006			.5					
TRUCK, DUMP, 1 YARD			D1116			.5					
Toilets			Number of								
Flashers			Number of								
Dumps (National Yards Only)			Yrds Dumped								

ENTERED

June 05, 2018 Crew # 503 Field Supervisor Emergency Crew Superintendent Jim Collins

Location 1	Material	Comments
NIS 3400 BLK E. HASTINGS @ CASSIAR.		PICK UP 2 ABANDONED BARRICADES.
Log # / SR #R / VPD #	(1/2 HR)	
Informant: FOUND		
Time Received:		
Time of Arrival:		
Time Completed:		
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>	
Signage Used:	By: (Initials) <i>BJ</i>	

Location 2	Material	Comments
2608 GRANVILLE.		2600 GRANVILLE. HOLE IN SIW. APPROX: 3" x 5" x 1 1/4" D. TEMP PREMIX.
Log # / SR #R / VPD # 1297888	(1/2 HR)	
Informant:		
Time Received:		REFER TO CREW FOR HOT MIX
Time of Arrival:		Refer to Marco
Time Completed:		
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>	
Signage Used:	By: (Initials) <i>BJ</i>	

Location 3	Material	Comments
NIWIC. SALSBURY & FRANCES.		STOP SIGN BENT OVER. PLACE TEMP STOP SIGN. REFER TO TRAFFIC TO REPLANT SIGN.
Log # / SR #R / VPD # 1297929.	(1/2 HR)	
Informant:		
Time Received:		
Time of Arrival:		
Time Completed:		TO
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>	
Signage Used:	By: (Initials) <i>BJ</i>	

Location 4	Material	Comments
490 E. BROADWAY		PREMIX 1 PIH.
Log # / SR #R / VPD #	(1/2 HR)	
Informant: FOUND.		REFER TO CREW FOR HOT MIX.
Time Received:		
Time of Arrival:		Day shift
Time Completed:		
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>	
Signage Used:	By: (Initials) <i>BJ</i>	

Location 5	Material	Comments
1133 E. 27th		SINK HOLE. APPROX: 1' x 1' x 1 1/2' D. FILL WITH SAND & PREMIX. REFER TO CREW FOR HOT MIX & REPAIR.
Log # / SR #R / VPD # 1297947	(1/2 HR)	
Informant:		
Time Received:		
Time of Arrival:		
Time Completed:		Marco
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input checked="" type="checkbox"/>	
Signage Used:	By: (Initials) <i>BJ</i>	

Location 6	Material	Comments
Log # / SR #R / VPD #		
Informant:		
Time Received:		
Time of Arrival:		
Time Completed:		
Sign safety when Departing Location:	Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators <input type="checkbox"/>	
Signage Used:	By: (Initials)	

Wagon Location **Manitoba Yard**

A/A **919637868**

**Streets Operations Daily Crew Report**

Rev. \_\_\_\_\_

June 18, 2018

Work order # and Hours

Crew # **63**  
Field Supervisor **Mezzomo 604-619-2057**  
Superintendent **Marco Biagini**

*[Signature]*  
(signed)  
*[Signature]*  
(signed)

1	2	3	4	5
ERD77871	ERD77884	ERD77896		

Hours of Work **7** AM - **3:30** PM

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem Code	1	2	3	4	5
s.22(1)	G. Fiskilis	C1287	P74	6000	GR-320		1	1	6		
s.22(1)	K. Green			6000			1	1	6		
Equipment Name			Equipment ID			Running Hrs					
TRUCK, DUMP, 1 YARD			C1287			1 1 6					
Toilets			Number of			0					
Flashers			Number of								
Dumps (National Yards Only)			Yrds Dumped								

**FILED**

June 18, 2018      Crew # 63      Field Supervisor Mezzomo      Superintendent Marco Biagini

Location 1	EERDT7871	Material	Amount	Comments
		#36	1.15 TONS	- P/H'S FILLED.
	985254 - 3 P/H'S			
			.15 TON	
		Dump:	Location:	

Sign safety when Departing Location:    Cones ☐    Snow Fence ☐    Tape ☐    Barricade ☐    Ramps ☐    Flashers ☐    Delineators ☐

Signage Used:    By: G.F. (Initials)

Activity Code    Units Completed    Measurement

Location 2	EERDT7884	Material	Amount	Comments
	984672 - 6			- S/W TRIPS (MRN).
	985301 - 2			
			.15 TON	
		Dump:	Location:	

Sign safety when Departing Location:    Cones ☐    Snow Fence ☐    Tape ☐    Barricade ☐    Ramps ☐    Flashers ☐    Delineators ☐

Signage Used:    By: G.F. (Initials)

Activity Code    Units Completed    Measurement

Location 3	EERDT7896	Material	Amount	Comments
	985274 - 4	985294 - 1	985265 - 6	- S/W TRIPS.
	985275 - 2	985291 - 1	985259 - 1	
	985215 - 1	985305 - 1	985258 - 1	
	984727 - 1	985247 - 1	985257 - 1	
	984713 - 1	985249 - 3	985256 - 3	
	984706 - 1	985253 - 1	985280 - 4	
	985242 - 2	985251 - 1	985269 - 1	
	985255 - 1	985281 - 2	985260 - 3	
	985243 - 1	985261 - 1	Dump:	Location:

Sign safety when Departing Location:    Cones ☐    Snow Fence ☐    Tape ☐    Barricade ☐    Ramps ☐    Flashers ☐    Delineators ☐

Signage Used:    By: G.F. (Initials)

Activity Code    Units Completed    Measurement

Location 4	11	Material	Amount	Comments
	985264 - 1			11
	984692 - 2			
	984696 - 1			
	984687 - 1			
	984699 - 2			
	984677 - 1			
	984683 - 1		.85 TON	
		Dump:	Location:	

Sign safety when Departing Location:    Cones ☐    Snow Fence ☐    Tape ☐    Barricade ☐    Ramps ☐    Flashers ☐    Delineators ☐

Signage Used:    By: G.F. (Initials)

Activity Code    Units Completed    Measurement

Location 5		Material	Amount	Comments
		Dump:	Location:	

Sign safety when Departing Location:    Cones ☐    Snow Fence ☐    Tape ☐    Barricade ☐    Ramps ☐    Flashers ☐    Delineators ☐

Signage Used:    By:    (Initials)

Activity Code    Units Completed    Measurement

Wagon Location Manitoba Yard

A/A 920323768

Streets Operations Daily Crew Report

Rev. \_\_\_\_\_

January 25, 2019

Work order # and Hours

Crew # 65  
Field Supervisor Mezzomo 604-619-2057  
Superintendent Jim Bruce

*[Signature]*  
(signed)  
*[Signature]*  
(signed)

1	2	3	4	5
EE082094	EE081898	EE082086		

Hours of Work 7 AM - 7:30 PM

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem Code	1	2	3	4	5
s.22(1)	M. Boudreau			6000			1	6	1		
s.22(1)	D. Woods	C1271		6000			1	6	1		
Equipment Name			Equipment ID			Running Hrs					
TRUCK, DUMP, 1 YARD			C1271			6 6 1					
Toilets			Number of								
Flashers			Number of								
Dumps (National Yards Only)			Yrds Dumped								

ENTERED

Sign safety when Departing Location:		<input type="checkbox"/> Cones	<input type="checkbox"/> Snow Fence	<input type="checkbox"/> Tape	<input type="checkbox"/> Barricade	<input type="checkbox"/> Ramps	<input type="checkbox"/> Flashers	<input type="checkbox"/> Delineators	<input type="checkbox"/>
Signage Used:									By: (Initials)
Activity Code		Units Completed		Measurement					

Sign safety when Departing Location:		<input type="checkbox"/> Cones	<input type="checkbox"/> Snow Fence	<input type="checkbox"/> Tape	<input type="checkbox"/> Barricade	<input type="checkbox"/> Ramps	<input type="checkbox"/> Flashers	<input type="checkbox"/> Delineators
Signage Used:		By: (Initials)						
Activity Code		Units Completed		Measurement				

Sign safety when Departing Location:		Cones		<input type="checkbox"/>	Snow Fence		<input type="checkbox"/>	Tape		<input type="checkbox"/>	Barricade		<input type="checkbox"/>	Ramps		<input type="checkbox"/>	Flashers		<input type="checkbox"/>	Delineators		<input type="checkbox"/>			
Signage Used:		By: _____ (Initials)																							
Activity Code						Units Completed										Measurement									

Sign safety when Departing Location:		<input type="checkbox"/> Cones	<input type="checkbox"/> Snow Fence	<input type="checkbox"/> Tape	<input type="checkbox"/> Barricade	<input type="checkbox"/> Ramps	<input type="checkbox"/> Flashers	<input type="checkbox"/> Delineators	<input type="checkbox"/>
Signage Used:									By: (Initials)
Activity Code		Units Completed		Measurement					

Sign safety when Departing Location:		Cones		<input type="checkbox"/>	Snow Fence		<input type="checkbox"/>	Tape		<input type="checkbox"/>	Barricade		<input type="checkbox"/>	Ramps		<input type="checkbox"/>	Flashers		<input type="checkbox"/>	Delineators		<input type="checkbox"/>	
Signage Used:																				By:		(Initials)	
Activity Code						Units Completed								Measurement									

Wagon Location **Manitoba Yard**

A/A 92/778196-CC

## Streets Operations Daily Crew Report

Rev.

April 28, 2020

Work order # and Hours

Crew # 63

Field Supervisor **Mezzomo** 604-619-2057

(signed)

Superintendent **Jim Bruce**

(signed)

Hours of Work 7 AM - 5:00 PM

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem Code					
S.22(1)	B. Harper	C1003	P74	6000	GR-320		.5	7.5			
S.22(1)	R. Murru			6000			.5	7.5			
Equipment Name			Equipment ID			Running Hrs					
TRUCK, DUMP, 1 YARD			C1003			.5 7.5					
Toilets			Number of								
Flashers			Number of								
Dumps (National Yards Only)			Yrds Dumped								

### Comments

Location 2	Material	Amount	Comments
ESD 86749			

Activity Code	Units Completed	Measurement

Location 3	Material	Amount	Comments
Cont.			

Signage Used: \_\_\_\_\_ By: \_\_\_\_\_ (Initials)

Activity Code	Units Completed	Measurement
---------------	-----------------	-------------

Location 4	Material	Amount	Comments
------------	----------	--------	----------

Signage Used: \_\_\_\_\_ By: \_\_\_\_\_ (Initials)

Activity Code	Units Completed	Measurement
---------------	-----------------	-------------

Location 5	Material	Amount	Comments
------------	----------	--------	----------

				Dump:		Location:											
Sign safety when Departing Location:				Cones		Snow Fence		Tape		Barricade		Ramps		Flashers		Delineators	

Signage Used: \_\_\_\_\_ By: \_\_\_\_\_ (Initials)

Activity Code	Units Completed	Measurement
---------------	-----------------	-------------

Wagon Location National yard

A/A 921 848 006-cc

Streets Operations Daily Crew Report

Rev.

May 25, 2020

Work order # and Hours

Crew # 505  
Field Supervisor Gurniak 604-690-3264  
Superintendent Jason Azuelos

  
(signed)  
  
(signed)

Hours of Work 7 AM - 3:30 PM

							1	2	3	4	5
Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Prem Code	50018228	EEER1043003			
s.22(1)	B. Huth			6505				8			
s.22(1)	J. Zimmer			6505				8			
s.22(1)	M. Medved			6505				8			
s.22(1)	D. Gurniak			6000			8				
s.22(1)	K. Green	D1117		6505				8			
s.22(1)	F. Medeiros	A5795	P74	6505	GR320			8			
s.22(1)	C. Smith	a5718	P74	6505	GR320			8			
s.22(1)	m. Deluca			7001							
Equipment Name							Equipment ID				
Running Hrs											
AUTO, PASSENGER, COMPACT							a5718	8			
City Pick-Up							Rent 10	not	with	crew	
TRUCK, PICKUP, HEAVY, GAS							D1117	8			
TRUCK, PICKUP, LIGHT							A5795	8			
TRUCK, PICKUP, LIGHT, FOUR WHEEL DRIVE, GAS							A5825	8			
Toilets							Number of				
Flashers							Number of				
Dumps (National Yards Only)							Yrds Dumped				

Sign safety when Departing Location:		<input type="checkbox"/> Cones	<input type="checkbox"/> Snow Fence	<input type="checkbox"/> Tape	<input type="checkbox"/> Barricade	<input type="checkbox"/> Ramps	<input type="checkbox"/> Flashers	<input type="checkbox"/> Delineators	<input type="checkbox"/>
Signage Used:									By: (Initials)
Activity Code		Units Completed				Measurement			

Sign safety when Departing Location:		<input checked="" type="checkbox"/> Cones	<input type="checkbox"/> Snow Fence	<input type="checkbox"/> Tape	<input type="checkbox"/> Barricade	<input type="checkbox"/> Ramps	<input type="checkbox"/> Flashers	<input type="checkbox"/> Delineators
Signage Used:		By: (Initials)						
Activity Code		Units Completed		Measurement				

Signage Used: ☐ Cones ☐ Snow Fence ☐ Tape ☐ Barricade ☐ Ramps ☐ Flashers ☐ Delineators ☐ Other: \_\_\_\_\_

By: \_\_\_\_\_ (Initials)

Activity Code	Units Completed	Measurement
Location 1	Material	Amount

Signage Used:		<input type="checkbox"/> Sign Safety when Departing Location: <input type="checkbox"/> Cones <input type="checkbox"/> Snow Fence <input type="checkbox"/> Tape <input type="checkbox"/> Barricade <input type="checkbox"/> Ramps <input type="checkbox"/> Flashers <input type="checkbox"/> Delineators		By: _____ (Initials)
Activity Code		Units Completed	Measurement	
Location 5		Material	Amount	Comments

Sign Safety when Departing Location:		<input type="checkbox"/> Cones	<input type="checkbox"/> Snow Fence	<input type="checkbox"/> Tape	<input type="checkbox"/> Barricade	<input type="checkbox"/> Ramps	<input type="checkbox"/> Flashers	<input type="checkbox"/> Detectors
Signage Used:								By: (Initials)
Activity Code		Units Completed		Measurement				

A/A

922063736

## Rev.

August 17, 2020

Work order # and Hours

Crew # 96

Field Supervisor **A. GREEN** 604-690-7364

Superintendent **Vince Santorelli**

Hours of Work

700

AM -

69/32

PM

[illegible]

Sw

City of Vancouver - FOI 2021-317 - Page 86 of 103

Wagon Location **Manitoba Yard**

A/A 922069741

**Streets Operations Daily Crew Report**

Rev. \_\_\_\_\_

August 20, 2020

Work order # and Hours

Crew # **65**  
Field Supervisor **Mezzomo 604-619-2057**  
Superintendent **Jim Bruce**

*[Signature]*  
(signed)  
*[Signature]*  
(signed)

1	2	3	4	5
EER086267	EER086104	EER1042931	EER086109	EER086172

Hours of Work 7 AM - 3:30 PM

Emp #	Employee	Equip #	Activity Type	A/Abs Stat Code	Pay Scale Group	Frem Code	1	2	3	4	5
s.22(1)	M. Boudreau			6000			1	1	3	2	1
s.22(1)	D. Woods	B1295		6000			1	1	3	2	1
Equipment Name			Equipment ID			Running Hrs					
TRUCK, DUMP, 1 YARD			B1295			1 1 3 2 1					
Toilets			Number of			0					
Flashers			Number of								
Dumps (National Yards Only)			Yrds Dumped								

ENTERED

Sign safety when Departing Location:		Cones <input type="checkbox"/>		Snow Fence <input type="checkbox"/>		Tape <input type="checkbox"/>		Barricade <input type="checkbox"/>		Ramps <input type="checkbox"/>		Flashers <input type="checkbox"/>		Delineators <input type="checkbox"/>	
Signage Used:												By: _____		(Initials)	
Activity Code						Units Completed						Measurement			

Activity	Quantity	WO	UNITID	UNITDESC	Group Project	Accomplishment Date	Crew	Assigned to	Comments
Landscape General	1	1053677				8/17/2020	RMG96	ALFREDO MANNARINO	Cassiar & Hastings SWC - Cut back overgrown vegetation. - TGF
Barrier Drop-off/Pickup	2	932751				6/5/2018	REM503	BLAINE HUTH	E Hastings & Cassiar - Pick up 2 abandoned barricades - SE
Median Clean	4	561215				7/28/2015	RMG92	ANDREW MCKILLOP	3400-3500 E Hastings - Clean up traffic island - TJF
Maintain/Clear Catchbasin	1	560922				9/8/2015	RMS75	LUI D'AMATO	3400 E Hastings S/S - Cleaned CBs of leaves - TJF
Debris	1	697677				1/15/2016	REM503	BLAINE HUTH	3495 E. Hastings - Concrete spill cleared to the side of the road. Referred to Sanitation for sweeper. TF
Grind - Surface	10	665344	E HASTINGS ST	3500 to 3599 E HASTINGS ST from SKEENA ST to KOOTENAY ST	55681	9/4/2015	RMS75	LUI D'AMATO	E Hastings at Cassiar EB - TJF
Maintain/Clear Catchbasin	1	1043003				5/25/2020	REM505	BLAINE HUTH	e/s Cassiar n/o E. Hastings - 3 CB's on block. Hydro vac required. - TGF
Inspected	1	560624				7/20/2015	RMT502	STUART MCMILLAN	SR 840989, Cassiar & Hastings - No one on site, no transient garbage. TF
Barrier Drop-off/Pickup	1	560777				7/27/2015	RMS71	TONY FARIA	SR 845925, 3423 E Hastings - Information sign broken. Made safe and waited for owner - TJF
Inspected	1	560624				8/21/2015	RMT502	STUART MCMILLAN	SR 856004, Cassiar & E. Hastings - The people that stay here do not have a structure so I can't move them. - S. McMillan
Em Repair - Pothole	1	815320				5/9/2017	REM503	DEAN MCKEE	SR 1127074, 3491 E. Hastings - Premixed p/h. Referred to M. Biagini. - TF

Blue - Streets  
Green - Streets  
Pink - Originating Office

CITY ENGINEERING SERVICES  
RECORD OF CUTS AND/OR DAMAGED SURFACES

195213

This form is to be completed by the Foreman in charge of a crew making a cut and/or causing damage to a surface, and forwarded to Streets Operations for Permanent Repairs.

Cut(s) made by: W.W. No. of cuts: 1 No. of records: 1 of 1

Location of cut: 3400 BLK. E. HASTINGS

Site address if different from above:

Cut(s) made in: Street; Shoulder; Lane; Sidewalk; Crossing; Curb; Blvd; Other

Surface type: light asphalt; heavy asphalt; concrete; spraycap; gravel; turf; Other Stamp

Purpose of cut(s): CONST. JAS B

Dimensions of cut(s):

Thickness of surface cut(s): Depth of excavation(s):

Backfilled with: Temporary repaired with: Hot Mix ☐ Cold Mix ☐ Gravel ☐ Condition of Temp. repair: Good ☒ Raised ☐ Settled ☐ Needs Attention ☐

Compacted by: hand tool; air tamper; mechanical tamper; or

Foreman's Comments Work Order No. CEWD 2581

B.W.O. No.:

Permit No.

Foreman's Signature Date: JULY 23-10 Superintendent's Signature

For Permanent Repair

E. HASTINGS

CASSIAN SKERNA

Street's Inspector's cut measurements:

FLAT RATE TO REPAIR COLORED STAMPED CONCRETE  
SIDEWALK DAMAGE DUE TO WATER BOX DISC.  
AS PER BILL VISTANJET

Bus Stop to be moved: ☐  
Traffic cones required: ☒  
No parking signs required: ☒  
Meters to hood: ☐  
Traffic restrictions: 7-9 ☐  
4-6 ☐

Street's Inspector's Comments:

Total \$900.00

Street's Foreman's Comments: Foreman's Signature Date Completed

Units Completed

CREW #

Units Charged — Work Order ERF 214 TOTAL \$ 900-

CODE D14 RATE 900 FP

CREDIT ACCOUNT 36/00/4833/874

133059

# Work Order Summary

**Work Order #:** 599817      Roadway Hazard MRN      Pothole Repair  
**Asset ID #:** E HASTINGS ST      Road - Asphalt  
**Group Project #:** 55717      RRw\_PtH\_MRN\_Crew 67\_2015      Streets Operations  
**Location:** 3400 - 3499 E HASTINGS ST  
**Operational Status:**      **Ref #1:** :      **Ref #2:**  
**Service Request:**      **Contact Name:**      **Phone#:**  
**Requested By:**      **Requested Date:**      **Initiated Date:** Apr 23, 2015

**Assigned By:** MARCO BIAGINI      **Assigned To:** KONSTANTINOS FISKILIS  
**Assigned Date:** Apr 23, 2015      **Crew ID:** RMS67      **Work Started:**  
**Result:** Completed      **Work Completed:** Apr 24, 2015

**Comments:** Where: At Intersection NW corner Skeena St  
 Hazard: Crosswalk Distortion  
 Comments: W bound curb lane at edge of conc.bus pad & crossing

This work order created by inspection # s.22(1)  
 Inspector: s.22(1) (ADIL BHATHENA)  
 Inspected Date: 22/04/2015 8:35:25 AM

## Work Orders & Accomplishments:

WO#	Result	Completed Date				
599817	Completed	Apr 24, 2015				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Apr 24, 2015		Pothole Repair	2	RMS67	KONSTANTINOS FISKILIS	MP

**Work Area Prefix:** R      **SAP Network #:** EERD55717      **WBS#:** EER-00008-PR-MR-GN  
**Parent Network:**      **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
<b>TOTAL</b>	<b>\$0.00</b>	<b>\$0.00</b>	<b>\$0.00</b>

# Work Order Summary

**Work Order #:** 599820      Boulevard Hazard MRN      Asphalt Fillet - Sidewalk  
**Asset ID #:** 100976      Sidewalk - General (Reactive)  
**Group Project #:** 55738      RSw\_Flt\_MRN\_Crew 67\_2015      Streets Operations  
**Location:** 3400 - 3499 E HASTINGS ST  
**Operational Status:**      **Ref #1:** :      **Ref #2:**  
**Service Request:**      **Contact Name:**      **Phone#:**  
**Requested By:**      **Requested Date:**      **Initiated Date:** Apr 23, 2015

**Assigned By:** MARCO BIAGINI      **Assigned To:** KONSTANTINOS FISKILIS  
**Assigned Date:** Apr 23, 2015      **Crew ID:** RMS67      **Work Started:**  
**Result:** Completed      **Work Completed:** Apr 24, 2015

**Comments:**

**Where:** At Civic 3475  
**Hazard:** Sidewalk Trip  
**Comments:** Both E & W edge& middle of driveway, & !.0M E of water valve

This work order created by inspection # s.22(1)  
 Inspector: s.22(1) (ADIL BHATHENA)  
 Inspected Date: 22/04/2015 8:41:50 AM

**Work Orders & Accomplishments:**

WO#	Result	Completed Date				
599820	Completed	Apr 24, 2015				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Apr 24, 2015		Asphalt Fillet - Sidewalk	5	RMS67	KONSTANTINOS FISKILIS	MP

**Work Area Prefix:** R      **SAP Network #:** EERD55738      **WBS#:** EER-00009-SF-MR-01  
**Parent Network:**      **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
<b>TOTAL</b>	<u>\$0.00</u>	<u>\$0.00</u>	<u>\$0.00</u>

# Work Order Summary

**Work Order #:** 599829      Boulevard Hazard MRN      Asphalt Fillet - Sidewalk  
**Asset ID #:** 99532      Sidewalk - General (Reactive)  
**Group Project #:** 55738      RSw\_Flt\_MRN\_Crew 67\_2015      Streets Operations  
**Location:** 3400 - 3499 E HASTINGS ST  
**Operational Status:**      **Ref #1:** :      **Ref #2:**  
**Service Request:**      **Contact Name:**      **Phone#:**  
**Requested By:**      **Requested Date:**      **Initiated Date:** Apr 23, 2015

**Assigned By:** MARCO BIAGINI      **Assigned To:** KONSTANTINOS FISKILIS  
**Assigned Date:** Apr 23, 2015      **Crew ID:** RMS67      **Work Started:**  
**Result:** Completed      **Work Completed:** Apr 24, 2015

**Comments:** Where: Opposite Civic 3433 driveway to McDonalds parking lot  
 Hazard: Sidewalk Trip  
 Comments: back of walk & W edge of driveway

This work order created by inspection # **s.22(1)**  
 Inspector **s.22(1)** (ADIL BHATHENA)  
 Inspected Date: 22/04/2015 8:59:01 AM

## Work Orders & Accomplishments:

WO#	Result	Completed Date				
599829	Completed	Apr 24, 2015				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Apr 24, 2015		Asphalt Fillet - Sidewalk	4	RMS67	KONSTANTINOS FISKILIS	MP

**Work Area Prefix:** R      **SAP Network #:** EERD55738      **WBS#:** EER-00009-SF-MR-01  
**Parent Network:**      **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
<b>TOTAL</b>	<b>\$0.00</b>	<b>\$0.00</b>	<b>\$0.00</b>

# Work Order Summary

**Work Order #:** 599831      Roadway Hazard MRN      Fillet Asphalt - Curb  
**Asset ID #:** E HASTINGS ST      Curb - General (Reactive)  
**Group Project #:** 55695      RCb\_Flt\_MRN\_Crew 67\_2015      Streets Operations  
**Location:** 3400 - 3499 E HASTINGS ST  
**Operational Status:**      **Ref #1:** :      **Ref #2:**  
**Service Request:**      **Contact Name:**      **Phone#:**  
**Requested By:**      **Requested Date:**      **Initiated Date:** Apr 23, 2015

**Assigned By:** MARCO BIAGINI      **Assigned To:** KONSTANTINOS FISKILIS  
**Assigned Date:** Apr 23, 2015      **Crew ID:** RMS67      **Work Started:**  
**Result:** Completed      **Work Completed:** Apr 24, 2015

**Comments:** Where: At Civic 3450  
 Hazard: Curb Distortion  
 Comments: in gutter 3M W of pole# 14/84

This work order created by inspection # s.22(1)  
 Inspector: s.22(1) (ADIL BHATHENA)  
 Inspected Date: 22/04/2015 9:02:24 AM

## Work Orders & Accomplishments:

WO#	Result	Completed Date				
599831	Completed	Apr 24, 2015				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Apr 24, 2015		Asphalt Fillet - Curb	2	RMS67	KONSTANTINOS FISKILIS	MP

**Work Area Prefix:** R      **SAP Network #:** EERD55695      **WBS#:** EER-00009-CM-MR-01  
**Parent Network:**      **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
<b>TOTAL</b>	<b>\$0.00</b>	<b>\$0.00</b>	<b>\$0.00</b>

# Work Order Summary

**Work Order #:** 665344      RRw\_Surface\_Grind\_Crew 75/7      Grind - Surface  
**Asset ID #:** E HASTINGS ST      Road - Asphalt  
**Group Project #:** 55681      RRw\_Surface\_Grind\_Crew 75/77\_2015      Streets Operations  
**Location:** 3500 - 3599 E HASTINGS ST  
**Operational Status:**      **Ref #1:** :      **Ref #2:**  
**Service Request:** 853568      **Contact Name:** s.22(1)      **Phone#:** s.22(1)  
**Requested By:**      **Requested Date:**      **Initiated Date:** Sep 04, 2015

**Assigned By:** MARCO BIAGINI      **Assigned To:** LUI D'AMATO  
**Assigned Date:** Sep 04, 2015      **Crew ID:** RMS75      **Work Started:**  
**Result:** Completed      **Work Completed:** Sep 04, 2015

**Comments:** Small Surface Grinding on Roaway - Crew 75/77 - 2015

## Work Orders & Accomplishments:

WO#	Result	Completed Date				
665344	Completed	Sep 04, 2015				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Sep 04, 2015		Grind - Surface	10	RMS75	LUI D'AMATO	E Hastings at Cassiar EB - TJF

**Work Area Prefix:** R      **SAP Network #:** EERD55681      **WBS#:** EER-00009-FG-NM-GN  
**Parent Network:**      **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
<b>TOTAL</b>	<u>\$0.00</u>	<u>\$0.00</u>	<u>\$0.00</u>

# Work Order Summary

**Work Order #:** 855224      RSw\_Flt\_NM 70-2017/1-3      Asphalt Fillet - Sidewalk  
**Asset ID #:** 100976      Sidewalk - Asphalt  
**Group Project #:** 73664      RSw\_Flt\_NM 70-2017      Streets Operations  
**Location:** 3400 - 3499 E HASTINGS ST  
**Operational Status:**      **Ref #1:** :      **Ref #2:**  
**Service Request:** 1103533      **Contact Name:** s.22(1)      **Phone#:** s.22(1)  
**Requested By:**      **Requested Date:**      **Initiated Date:** Mar 20, 2017

**Assigned By:** MARCO BIAGINI      **Assigned To:** BEN HARPER  
**Assigned Date:** Mar 20, 2017      **Crew ID:** RMC70      **Work Started:**  
**Result:** Completed      **Work Completed:** Mar 20, 2017

**Comments:** 2017 Sidewalk Fillet - Non MRN - Crew 70 - January to March  
 Accomplishment: RSwAsFit

## Work Orders & Accomplishments:

WO#	Result	Completed Date				
855224	Completed	Mar 20, 2017				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Mar 20, 2017		Asphalt Fillet - Sidewalk	2	RMC70	BEN HARPER	3423 - CD

**Work Area Prefix:** R      **SAP Network #:** EERD73664      **WBS#:** EER-00009-SF-NM-AP  
**Parent Network:**      **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
<b>TOTAL</b>	<u>\$0.00</u>	<u>\$0.00</u>	<u>\$0.00</u>

# Work Order Summary

**Work Order #:** 867629      RRw\_PtH\_MR 71-2017/1-3  
**Asset ID #:** E HASTINGS ST  
**Group Project #:** 73667      RRw\_PtH\_MR 71-2017/1-3      Streets Operations  
**Location:** 3400 - 3499 E HASTINGS ST  
**Operational Status:**      **Ref #1:** :      **Ref #2:**  
**Service Request:** 1127074      **Contact Name:** s.22(1)      **Phone#:** s.22(1)  
**Requested By:**      **Requested Date:**      **Initiated Date:** May 09, 2017

**Assigned By:** MARCO BIAGINI      **Assigned To:** TONY FARIA  
**Assigned Date:** May 12, 2017      **Crew ID:** RMS71      **Work Started:**  
**Result:** Completed      **Work Completed:** May 18, 2017

**Comments:** 2017 Pothole Repairs - MRN - Crew 71 - January to March  
 Accomplishment: RRwPothole

## Work Orders & Accomplishments:

WO#	Result	Completed Date				
867629	Completed	May 18, 2017				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
May 18, 2017		Pothole Repair	1	RMS71	TONY FARIA	3491 NM

**Work Area Prefix:** R      **SAP Network #:** EERD73667      **WBS#:** EER-00008-PR-MR-GN  
**Parent Network:**      **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
<b>TOTAL</b>	<u>\$0.00</u>	<u>\$0.00</u>	<u>\$0.00</u>

# Work Order Summary

**Work Order #:** 985301      Boulevard Hazard MRN  
**Asset ID #:** 99532  
**Group Project #:** 77884      RSw\_Flt\_MR 63-2018      Streets Operations  
**Location:** 3400 - 3499 E HASTINGS ST  
**Operational Status:**      **Ref #1:** :      **Ref #2:**  
**Service Request:**      **Contact Name:**      **Phone#:**  
**Requested By:**      **Requested Date:**      **Initiated Date:** Jun 11, 2018

**Assigned By:**      **Assigned To:** KONSTANTINOS FISKILIS  
**Assigned Date:** Jun 11, 2018      **Crew ID:** RMS63      **Work Started:**  
**Result:** Completed      **Work Completed:** Jun 18, 2018

**Comments:**

**Where:** At Civic 3458  
**Hazard:** Sidewalk Trip  
**Comments:**

This work order created by inspection # **s.22(1)**  
 Inspector: **s.22(1)** (VERONICA IERACI)  
 Inspected Date: 11/06/2018 1:38:33 PM

**Work Orders & Accomplishments:**

WO#	Result	Completed Date				
985301	Completed	Jun 18, 2018				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Jun 18, 2018		Asphalt Fillet - Sidewalk	2	RMS63	KONSTANTINOS FISKILIS	SE

**Work Area Prefix:** R      **SAP Network #:** EERD77884      **WBS#:** EER-00009-SF-MR-01  
**Parent Network:**      **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
<b>TOTAL</b>	<b>\$0.00</b>	<b>\$0.00</b>	<b>\$0.00</b>

# Work Order Summary

**Work Order #:** 1052346      RSw\_Flt\_MR 65-2019  
**Asset ID #:** 99532  
**Group Project #:** 82086      RSw\_Flt\_MR 65-2019      Streets Operations  
**Location:** 3400 - 3499 E HASTINGS ST  
**Operational Status:**      **Ref #1:** :      **Ref #2:**  
**Service Request:** 1400294      **Contact Name:** s.22(1)      **Phone#:** s.22(1)  
**Requested By:**      **Requested Date:**      **Initiated Date:** Jan 29, 2019

**Assigned By:** RICHARD BRUCE      **Assigned To:** DAVID WOODS  
**Assigned Date:** Jan 29, 2019      **Crew ID:** RMA65      **Work Started:**  
**Result:** Completed      **Work Completed:** Jan 25, 2019  
**Comments:** 2019 - Sidewalk Fillet|65|MRN

## Work Orders & Accomplishments:

WO#	Result	Completed Date				
1052346	Completed	Jan 25, 2019				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Jan 25, 2019		Asphalt Fillet - Sidewalk	1	RMA65	DAVID WOODS	BA - Patched curb with #36

**Work Area Prefix:** R      **SAP Network #:** EERD82086      **WBS#:** EER-00009-SF-MR-01  
**Parent Network:**      **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
<b>TOTAL</b>	<b>\$0.00</b>	<b>\$0.00</b>	<b>\$0.00</b>

# Work Order Summary

**Work Order #:** 1193644      Roadway Hazard MRN  
**Asset ID #:** E HASTINGS ST  
**Group Project #:** 86749      RSw\_Flt\_NM 63-2020      Streets Operations  
**Location:** 3400 - 3499 E HASTINGS ST  
**Operational Status:**      **Ref #1:** :      **Ref #2:**  
**Service Request:**      **Contact Name:**      **Phone#:**  
**Requested By:**      **Requested Date:**      **Initiated Date:** Apr 27, 2020

**Assigned By:**      **Assigned To:** BEN HARPER  
**Assigned Date:** Apr 27, 2020      **Crew ID:** RMS63      **Work Started:**  
**Result:** Completed      **Work Completed:** Apr 28, 2020

**Comments:** Where: Skeena & E Hastings, W crosswalk, N gutter  
 Hazard: Crosswalk Gap  
 Comments:

This work order created by inspection # **s.22(1)**  
 Inspector: **s.22(1)** (BRUCE MCDONALD)  
 Inspected Date: 27/04/2020 10:09:30 AM

## Work Orders & Accomplishments:

WO#	Result	Completed Date				
1193644	Completed	Apr 28, 2020				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Apr 28, 2020		Asphalt Fillet - Sidewalk	1	RMS63	BEN HARPER	SE

**Work Area Prefix:** R      **SAP Network #:** EERD86749      **WBS#:** EER-00009-SF-NM-AP  
**Parent Network:**      **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
<b>TOTAL</b>	<b>\$0.00</b>	<b>\$0.00</b>	<b>\$0.00</b>

# Work Order Summary

**Work Order #:** 1193646      Boulevard Hazard MRN  
**Asset ID #:** 100976  
**Group Project #:** 86749      RSw\_Flt\_NM 63-2020      Streets Operations  
**Location:** 3400 - 3499 E HASTINGS ST  
**Operational Status:**      **Ref #1:** :      **Ref #2:**  
**Service Request:**      **Contact Name:**      **Phone#:**  
**Requested By:**      **Requested Date:**      **Initiated Date:** Apr 27, 2020

**Assigned By:**      **Assigned To:** BEN HARPER  
**Assigned Date:** Apr 27, 2020      **Crew ID:** RMS63      **Work Started:**  
**Result:** Completed      **Work Completed:** Apr 28, 2020

**Comments:**

**Where:** At Civic WPL 3495  
**Hazard:** Sidewalk Trip  
**Comments:**

This work order created by inspection # **s.22(1)**  
 Inspector: **s.22(1)** (BRUCE MCDONALD)  
 Inspected Date: 27/04/2020 10:12:00 AM

**Work Orders & Accomplishments:**

WO#	Result	Completed Date				
1193646	Completed	Apr 28, 2020				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Apr 28, 2020		Asphalt Fillet - Sidewalk	1	RMS63	BEN HARPER	SE

**Work Area Prefix:** R      **SAP Network #:** EERD86749      **WBS#:** EER-00009-SF-NM-AP  
**Parent Network:**      **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
<b>TOTAL</b>	<b>\$0.00</b>	<b>\$0.00</b>	<b>\$0.00</b>

# Work Order Summary

**Work Order #:** 1228687      RRw\_Pothole\_MR 65-2020  
**Asset ID #:** E HASTINGS ST  
**Group Project #:** 86104      RRw\_Pothole\_MR 65-2020      Streets Operations  
**Location:** 3400 - 3499 E HASTINGS ST  
**Operational Status:**      **Ref #1:** :      **Ref #2:**  
**Service Request:**      **Contact Name:**      **Phone#:**  
**Requested By:**      **Requested Date:**      **Initiated Date:** Aug 24, 2020

**Assigned By:** RICHARD BRUCE    **Assigned To:** DAVID WOODS  
**Assigned Date:** Aug 20, 2020    **Crew ID:** RMA65      **Work Started:**  
**Result:** Completed      **Work Completed:** Aug 20, 2020

**Comments:** Crew 65 - Potholes - MRN | Accomplishment Code: RRwPothole

## Work Orders & Accomplishments:

WO#	Result	Completed Date				
1228687	Completed	Aug 20, 2020				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Aug 20, 2020		Pothole Repair	3	RMA65	DAVID WOODS	AC

**Work Area Prefix:** R      **SAP Network #:** EERD86104      **WBS#:** EER-00008-PR-MR-GN  
**Parent Network:**      **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
<b>TOTAL</b>	<u>\$0.00</u>	<u>\$0.00</u>	<u>\$0.00</u>

# Work Order Summary

**Work Order #:** 1228688      RRw\_Pothole\_MR 65-2020  
**Asset ID #:** E HASTINGS ST  
**Group Project #:** 86104      RRw\_Pothole\_MR 65-2020      Streets Operations  
**Location:** 3400 - 3499 E HASTINGS ST  
**Operational Status:**      **Ref #1:** :      **Ref #2:**  
**Service Request:** 1661801      **Contact Name:** s.22(1)      **Phone#:** s.22(1)  
**Requested By:**      **Requested Date:**      **Initiated Date:** Aug 24, 2020

**Assigned By:** RICHARD BRUCE      **Assigned To:** DAVID WOODS  
**Assigned Date:** Aug 20, 2020      **Crew ID:** RMA65      **Work Started:**  
**Result:** Completed      **Work Completed:** Aug 20, 2020

**Comments:** Crew 65 - Potholes - MRN | Accomplishment Code: RRwPothole

## Work Orders & Accomplishments:

WO#	Result	Completed Date				
1228688	Completed	Aug 20, 2020				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Aug 20, 2020		Pothole Repair	1	RMA65	DAVID WOODS	AC

**Work Area Prefix:** R      **SAP Network #:** EERD86104      **WBS#:** EER-00008-PR-MR-GN  
**Parent Network:**      **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
<b>TOTAL</b>	<u>\$0.00</u>	<u>\$0.00</u>	<u>\$0.00</u>