

File No.: 04-1000-20-2021-641

January 24, 2022

s.22(1)

Dear s.22(1)

Re: **Request for Access to Records under the Freedom of Information and Protection of Privacy Act (the "Act")**

I am responding to your request of December 16, 2021 under the ***Freedom of Information and Protection of Privacy Act, (the Act)***, for:

Record of the most recent building inspection report for the London Hotel at 208 East Georgia Street. Date range: approximately December 1 to December 15, 2021

All responsive records are attached. Some information in the records has been severed, (blacked out), under s.22(1) of the Act. You can read or download this section here: http://www.bclaws.ca/EPLibraries/bclaws_new/document/ID/freeside/96165_00

Under section 52 of the Act, and within 30 business days of receipt of this letter, you may ask the Information & Privacy Commissioner to review any matter related to the City's response to your FOI request by writing to: Office of the Information & Privacy Commissioner, info@oipc.bc.ca or by phoning 250-387-5629.

If you request a review, please provide the Commissioner's office with: 1) the request number (#04-1000-20-2021-641); 2) a copy of this letter; 3) a copy of your original request; and 4) detailed reasons why you are seeking the review.

Yours truly,

[Signed by Cobi Falconer]

Cobi Falconer, MAS, MLIS, CIPP/C
Director, Access to Information & Privacy
cobi.falconer@vancouver.ca
453 W. 12th Avenue Vancouver BC V5Y 1V4

If you have any questions, please email us at foi@vancouver.ca and we will respond to you as soon as possible. Or you can call the Acting FOI Case Manager at 604-873-7407.

Encl. (Response package)

:ag

Property Address 208 E. GEORGIA ST	Name of Building LONDON HOTEL	Inspection Date (yy/mm/dd) 2021/11/17
Business Licence (B/L) Number 21-131347 NH	Special Notes on B/L	Security/Video <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Pest Management Company Atlas Monthly	Number of Units 73 S.U.	SRA Tenant Register <input checked="" type="checkbox"/> 24-hr Tenant Check <input checked="" type="checkbox"/>
Owner Information	Building Representative	Inspectors Attending PUI: Mike Elliston
Porte Industries Ltd. Supervisor: Lori Whitney Alma Maintenance	Lori Whitney - Mgr. Chauncey Carr Will Lawrence Steve Mulligan	Alvin Leung ACCS: Zoe Greig Plumbing: Lloyd Cheung Bldg: Adrian Cashato
Ph# 604-732-7651 x108	Ph# 604-871-6968	

Standards of Maintenance By-law No. 5462

Building Exterior: fire escape / drainpipes / windows / finish

Exterior ok.
Remove graffiti as needed.

Common Areas: bathrooms / halls / kitchens / lighting / elevator / stairs / storage rooms

Note: COVID risk mitigation measures in effect.

Bathrooms - provide repairs to restore full functionality of all bathrooms including toilets, sinks, and bathtubs/showers.
- Repair all plumbing as needed to restore full hot/cold water lines, drainage/sewer lines.

Maintain self closing devices on all fire doors.

Heat - restore heating systems on 3rd floor.

* LIFE SAFETY VIOLATIONS TO BE REPAIRED IMMEDIATELY * Subtotal *

Recommendations:

All noted deficiencies must be corrected by **December 20 @ 11AM**

Hand delivered to **Lori Whitney** (Signed) **Lori Whitney**

46

Total # Violations

38

Total Life Safety Violations

Standards of Maintenance By-law No. 5462

Violations

- Room No. 5.22(1)
- | | |
|--|--|
| <input type="checkbox"/> Carpets/floor/baseboards - repair/replace/clean | <input checked="" type="checkbox"/> Window-pane/frame/trim/hardware - repair/replace/clean |
| <input type="checkbox"/> Walls/ceiling/floors - repair/replace/clean/panet | <input type="checkbox"/> Sink/plumbing/taps/leaks - repair/replace/unplug |
| <input type="checkbox"/> Radiator/Electrical baseboard - repair/replace | <input type="checkbox"/> Electrical outlets/fixtures/cover plates - repair or replace |
| <input type="checkbox"/> Door-handset/hinges/frame/room# - repair/replace | <input type="checkbox"/> Pest-rats/mice/roaches/bedbugs/fruit flies - pest control |

Clutter ☐ Y ☐ Doorway 90° ☐ N ☐ Informed Mgr ☐

Notes:

VACANT 12+12

LIFE SAFETY ☐ SMOKE ALARM ☐ SPRINKLER LINE ☐ DOOR CLOSER ☐ HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)

- Room No. Bathroom 5.22(1)
- | | |
|--|---|
| <input type="checkbox"/> Carpets/floor/baseboards - repair/replace/clean | <input type="checkbox"/> Window-pane/frame/trim/hardware - repair/replace/clean |
| <input type="checkbox"/> Walls/ceiling/floors - repair/replace/clean/panet | <input type="checkbox"/> Sink/plumbing/taps/leaks - repair/replace/unplug |
| <input type="checkbox"/> Radiator/Electrical baseboard - repair/replace | <input type="checkbox"/> Electrical outlets/fixtures/cover plates - repair or replace |
| <input type="checkbox"/> Door-handset/hinges/frame/room# - repair/replace | <input type="checkbox"/> Pest-rats/mice/roaches/bedbugs/fruit flies - pest control |

Clutter ☐ Y ☐ Doorway 90° ☐ N ☐ Informed Mgr ☐

Notes:

Out of order. No water.

LIFE SAFETY ☐ SMOKE ALARM ☐ SPRINKLER LINE ☐ DOOR CLOSER ☐ HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)

- Room No. 5.22(1)
- | | |
|---|---|
| <input type="checkbox"/> Carpets/floor/baseboards - repair/replace/clean | <input type="checkbox"/> Window-pane/frame/trim/hardware - repair/replace/clean |
| <input checked="" type="checkbox"/> Walls/ceiling/floors - repair/replace/clean/panet | <input type="checkbox"/> Sink/plumbing/taps/leaks - repair/replace/unplug |
| <input type="checkbox"/> Radiator/Electrical baseboard - repair/replace | <input type="checkbox"/> Electrical outlets/fixtures/cover plates - repair or replace |
| <input type="checkbox"/> Door-handset/hinges/frame/room# - repair/replace | <input type="checkbox"/> Pest-rats/mice/roaches/bedbugs/fruit flies - pest control |

Clutter ☐ Y ☐ Doorway 90° ☐ N ☐ Informed Mgr ☐

Notes:

LIFE SAFETY ☐ SMOKE ALARM ☐ SPRINKLER LINE ☐ DOOR CLOSER ☐ HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)

- Room No. 5.22(1)
- | | |
|--|--|
| <input type="checkbox"/> Carpets/floor/baseboards - repair/replace/clean | <input checked="" type="checkbox"/> Window-pane/frame/trim/hardware - repair/replace/clean |
| <input type="checkbox"/> Walls/ceiling/floors - repair/replace/clean/panet | <input type="checkbox"/> Sink/plumbing/taps/leaks - repair/replace/unplug |
| <input type="checkbox"/> Radiator/Electrical baseboard - repair/replace | <input type="checkbox"/> Electrical outlets/fixtures/cover plates - repair or replace |
| <input type="checkbox"/> Door-handset/hinges/frame/room# - repair/replace | <input type="checkbox"/> Pest-rats/mice/roaches/bedbugs/fruit flies - pest control |

Clutter ☐ Y ☐ Doorway 90° ☐ N ☐ Informed Mgr ☐

Notes:

LIFE SAFETY ☐ SMOKE ALARM ☐ SPRINKLER LINE ☐ DOOR CLOSER ☐ HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)

- Room No. 5.22(1)
- | | |
|--|---|
| <input type="checkbox"/> Carpets/floor/baseboards - repair/replace/clean | <input type="checkbox"/> Window-pane/frame/trim/hardware - repair/replace/clean |
| <input type="checkbox"/> Walls/ceiling/floors - repair/replace/clean/panet | <input type="checkbox"/> Sink/plumbing/taps/leaks - repair/replace/unplug |
| <input type="checkbox"/> Radiator/Electrical baseboard - repair/replace | <input type="checkbox"/> Electrical outlets/fixtures/cover plates - repair or replace |
| <input type="checkbox"/> Door-handset/hinges/frame/room# - repair/replace | <input type="checkbox"/> Pest-rats/mice/roaches/bedbugs/fruit flies - pest control |

Clutter ☐ Y ☐ Doorway 90° ☐ N ☐ Informed Mgr ☐

Notes:

LIFE SAFETY ☐ SMOKE ALARM ☐ SPRINKLER LINE ☒ DOOR CLOSER ☐ HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)

- Room No. 5.22(1)
- | | |
|--|---|
| <input type="checkbox"/> Carpets/floor/baseboards - repair/replace/clean | <input type="checkbox"/> Window-pane/frame/trim/hardware - repair/replace/clean |
| <input type="checkbox"/> Walls/ceiling/floors - repair/replace/clean/panet | <input type="checkbox"/> Sink/plumbing/taps/leaks - repair/replace/unplug |
| <input checked="" type="checkbox"/> Radiator/Electrical baseboard - repair/replace | <input type="checkbox"/> Electrical outlets/fixtures/cover plates - repair or replace |
| <input type="checkbox"/> Door-handset/hinges/frame/room# - repair/replace | <input type="checkbox"/> Pest-rats/mice/roaches/bedbugs/fruit flies - pest control |

Clutter ☐ Y ☐ Doorway 90° ☐ N ☐ Informed Mgr ☐

Notes:

LIFE SAFETY ☐ SMOKE ALARM ☐ SPRINKLER LINE ☐ DOOR CLOSER ☐ HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)

Vacant

No Access

Inspected

Notes:

Total

5

Standards of Maintenance By-law No. 5462		Violations
Room No. <u>5.22(1)</u>	<input type="checkbox"/> Carpets/floor/baseboards - repair/replace/clean <input type="checkbox"/> Walls/ceiling/floors - repair/replace/clean/panet <input type="checkbox"/> Radiator/Electrical baseboard - repair/replace <input type="checkbox"/> Door-handset/hinges/frame/room# - repair/replace <input type="checkbox"/> Window-pane/frame/trim/hardware - repair/replace/clean <input type="checkbox"/> Sink/plumbing/taps/leaks - repair/replace/unplug <input type="checkbox"/> Electrical outlets/fixtures/cover plates - repair or replace <input type="checkbox"/> Pest-rats/mice/roaches/bedbugs/fruit flies - pest control Clutter <input type="checkbox"/> Doorway 90° <input type="checkbox"/> Informed Mgr <input type="checkbox"/> Notes:	—
LIFE SAFETY	<input type="checkbox"/> SMOKE ALARM <input type="checkbox"/> SPRINKLER LINE <input checked="" type="checkbox"/> DOOR CLOSER <input type="checkbox"/> HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)	1
Room No. <u>5.22(1)</u>	<input type="checkbox"/> Carpets/floor/baseboards - repair/replace/clean <input type="checkbox"/> Walls/ceiling/floors - repair/replace/clean/panet <input type="checkbox"/> Radiator/Electrical baseboard - repair/replace <input checked="" type="checkbox"/> Door-handset/hinges/frame/room# - repair/replace <input type="checkbox"/> Window-pane/frame/trim/hardware - repair/replace/clean <input type="checkbox"/> Sink/plumbing/taps/leaks - repair/replace/unplug <input type="checkbox"/> Electrical outlets/fixtures/cover plates - repair or replace <input type="checkbox"/> Pest-rats/mice/roaches/bedbugs/fruit flies - pest control Clutter <input type="checkbox"/> Doorway 90° <input type="checkbox"/> Informed Mgr <input type="checkbox"/> Notes:	1
LIFE SAFETY	<input checked="" type="checkbox"/> SMOKE ALARM <input type="checkbox"/> SPRINKLER LINE <input type="checkbox"/> DOOR CLOSER <input type="checkbox"/> HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)	1
Room No. <u>5.22(1)</u>	<input type="checkbox"/> Carpets/floor/baseboards - repair/replace/clean <input type="checkbox"/> Walls/ceiling/floors - repair/replace/clean/panet <input type="checkbox"/> Radiator/Electrical baseboard - repair/replace <input type="checkbox"/> Door-handset/hinges/frame/room# - repair/replace <input type="checkbox"/> Window-pane/frame/trim/hardware - repair/replace/clean <input type="checkbox"/> Sink/plumbing/taps/leaks - repair/replace/unplug <input type="checkbox"/> Electrical outlets/fixtures/cover plates - repair or replace <input checked="" type="checkbox"/> Pest-rats/mice/roaches/bedbugs/fruit flies - pest control Clutter <input type="checkbox"/> Doorway 90° <input type="checkbox"/> Informed Mgr <input type="checkbox"/> Notes:	1
LIFE SAFETY	<input type="checkbox"/> SMOKE ALARM <input type="checkbox"/> SPRINKLER LINE <input type="checkbox"/> DOOR CLOSER <input type="checkbox"/> HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)	—
Room No. <u>5.22(1)</u>	<input type="checkbox"/> Carpets/floor/baseboards - repair/replace/clean <input type="checkbox"/> Walls/ceiling/floors - repair/replace/clean/panet <input type="checkbox"/> Radiator/Electrical baseboard - repair/replace <input type="checkbox"/> Door-handset/hinges/frame/room# - repair/replace <input type="checkbox"/> Window-pane/frame/trim/hardware - repair/replace/clean <input type="checkbox"/> Sink/plumbing/taps/leaks - repair/replace/unplug <input type="checkbox"/> Electrical outlets/fixtures/cover plates - repair or replace <input type="checkbox"/> Pest-rats/mice/roaches/bedbugs/fruit flies - pest control Clutter <input type="checkbox"/> Doorway 90° <input type="checkbox"/> Informed Mgr <input type="checkbox"/> Notes: <u>Not attached.</u>	—
LIFE SAFETY	<input checked="" type="checkbox"/> SMOKE ALARM <input checked="" type="checkbox"/> SPRINKLER LINE <input type="checkbox"/> DOOR CLOSER <input type="checkbox"/> HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)	✓
Room No. <u>5.22(1)</u>	<input type="checkbox"/> Carpets/floor/baseboards - repair/replace/clean <input type="checkbox"/> Walls/ceiling/floors - repair/replace/clean/panet <input type="checkbox"/> Radiator/Electrical baseboard - repair/replace <input type="checkbox"/> Door-handset/hinges/frame/room# - repair/replace <input type="checkbox"/> Window-pane/frame/trim/hardware - repair/replace/clean <input type="checkbox"/> Sink/plumbing/taps/leaks - repair/replace/unplug <input type="checkbox"/> Electrical outlets/fixtures/cover plates - repair or replace <input type="checkbox"/> Pest-rats/mice/roaches/bedbugs/fruit flies - pest control Clutter <input type="checkbox"/> Doorway 90° <input type="checkbox"/> Informed Mgr <input type="checkbox"/> Notes: <u>covered with bag</u>	—
LIFE SAFETY	<input checked="" type="checkbox"/> SMOKE ALARM <input type="checkbox"/> SPRINKLER LINE <input checked="" type="checkbox"/> DOOR CLOSER <input type="checkbox"/> HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)	2
Room No. <u>Shower Room 2</u>	<input type="checkbox"/> Carpets/floor/baseboards - repair/replace/clean <input type="checkbox"/> Walls/ceiling/floors - repair/replace/clean/panet <input type="checkbox"/> Radiator/Electrical baseboard - repair/replace <input type="checkbox"/> Door-handset/hinges/frame/room# - repair/replace <input type="checkbox"/> Window-pane/frame/trim/hardware - repair/replace/clean <input type="checkbox"/> Sink/plumbing/taps/leaks - repair/replace/unplug <input type="checkbox"/> Electrical outlets/fixtures/cover plates - repair or replace <input type="checkbox"/> Pest-rats/mice/roaches/bedbugs/fruit flies - pest control Clutter <input type="checkbox"/> Doorway 90° <input type="checkbox"/> Informed Mgr <input type="checkbox"/> Notes: <u>out of order.</u>	1
LIFE SAFETY	<input type="checkbox"/> SMOKE ALARM <input type="checkbox"/> SPRINKLER LINE <input type="checkbox"/> DOOR CLOSER <input type="checkbox"/> HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)	—
Vacant		
No Access		
Inspected		
Notes:		Total
<u>3rd: 17°C</u> <u>2nd: 19.9°C</u> <u>1st: 22.3°C</u>		3
		4

City of Vancouver - FOI 2021-641 - Page 4 of 31

$$\frac{5}{11}$$

Standards of Maintenance By-law No. 5462

Violations

Room No. <u>s.22(1)</u>	<input type="checkbox"/> Carpets/floor/baseboards - repair/replace/clean <input type="checkbox"/> Walls/ceiling/floors - repair/replace/clean/panel <input type="checkbox"/> Radiator/Electrical baseboard - repair/replace <input type="checkbox"/> Door-handset/hinges/frame/room# - repair/replace <input type="checkbox"/> Window-pane/frame/trim/hardware - repair/replace/clean <input type="checkbox"/> Sink/plumbing/taps/leaks - repair/replace/unplug <input type="checkbox"/> Electrical outlets/fixtures/cover plates - repair or replace <input type="checkbox"/> Pest-rats/mice/roaches/bedbugs/fruit flies - pest control	—
LIFE SAFETY	Clutter <input type="checkbox"/> Doorway 90° <input type="checkbox"/> Informed Mgr <input type="checkbox"/> Notes: <input checked="" type="checkbox"/> SMOKE ALARM <input type="checkbox"/> SPRINKLER LINE <input type="checkbox"/> DOOR CLOSER <input type="checkbox"/> HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)	1
Room No. <u>s.22(1)</u>	<input type="checkbox"/> Carpets/floor/baseboards - repair/replace/clean <input type="checkbox"/> Walls/ceiling/floors - repair/replace/clean/panel <input type="checkbox"/> Radiator/Electrical baseboard - repair/replace <input type="checkbox"/> Door-handset/hinges/frame/room# - repair/replace <input type="checkbox"/> Window-pane/frame/trim/hardware - repair/replace/clean <input type="checkbox"/> Sink/plumbing/taps/leaks - repair/replace/unplug <input type="checkbox"/> Electrical outlets/fixtures/cover plates - repair or replace <input type="checkbox"/> Pest-rats/mice/roaches/bedbugs/fruit flies - pest control	—
LIFE SAFETY	Clutter <input type="checkbox"/> Doorway 90° <input type="checkbox"/> Informed Mgr <input type="checkbox"/> Notes: <input checked="" type="checkbox"/> SMOKE ALARM <input type="checkbox"/> SPRINKLER LINE <input type="checkbox"/> DOOR CLOSER <input type="checkbox"/> HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)	1
Room No. <u>s.22(1)</u>	<input type="checkbox"/> Carpets/floor/baseboards - repair/replace/clean <input type="checkbox"/> Walls/ceiling/floors - repair/replace/clean/panel <input type="checkbox"/> Radiator/Electrical baseboard - repair/replace <input checked="" type="checkbox"/> Door-handset/hinges/frame/room# - repair/replace <input type="checkbox"/> Window-pane/frame/trim/hardware - repair/replace/clean <input type="checkbox"/> Sink/plumbing/taps/leaks - repair/replace/unplug <input type="checkbox"/> Electrical outlets/fixtures/cover plates - repair or replace <input type="checkbox"/> Pest-rats/mice/roaches/bedbugs/fruit flies - pest control	1
LIFE SAFETY	Clutter <input type="checkbox"/> Doorway 90° <input type="checkbox"/> Informed Mgr <input type="checkbox"/> Notes: <u>bag remove items</u> <input checked="" type="checkbox"/> SMOKE ALARM <input checked="" type="checkbox"/> SPRINKLER LINE <input checked="" type="checkbox"/> DOOR CLOSER <input type="checkbox"/> HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)	2
Room No. <u>s.22(1)</u>	<input type="checkbox"/> Carpets/floor/baseboards - repair/replace/clean <input type="checkbox"/> Walls/ceiling/floors - repair/replace/clean/panel <input type="checkbox"/> Radiator/Electrical baseboard - repair/replace <input type="checkbox"/> Door-handset/hinges/frame/room# - repair/replace <input type="checkbox"/> Window-pane/frame/trim/hardware - repair/replace/clean <input type="checkbox"/> Sink/plumbing/taps/leaks - repair/replace/unplug <input type="checkbox"/> Electrical outlets/fixtures/cover plates - repair or replace <input type="checkbox"/> Pest-rats/mice/roaches/bedbugs/fruit flies - pest control	—
LIFE SAFETY	Clutter <input type="checkbox"/> Doorway 90° <input type="checkbox"/> Informed Mgr <input type="checkbox"/> Notes: <input checked="" type="checkbox"/> SMOKE ALARM <input type="checkbox"/> SPRINKLER LINE <input type="checkbox"/> DOOR CLOSER <input type="checkbox"/> HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)	1
Room No. <u>s.22(1)</u>	<input type="checkbox"/> Carpets/floor/baseboards - repair/replace/clean <input type="checkbox"/> Walls/ceiling/floors - repair/replace/clean/panel <input type="checkbox"/> Radiator/Electrical baseboard - repair/replace <input type="checkbox"/> Door-handset/hinges/frame/room# - repair/replace <input type="checkbox"/> Window-pane/frame/trim/hardware - repair/replace/clean <input type="checkbox"/> Sink/plumbing/taps/leaks - repair/replace/unplug <input type="checkbox"/> Electrical outlets/fixtures/cover plates - repair or replace <input type="checkbox"/> Pest-rats/mice/roaches/bedbugs/fruit flies - pest control	—
LIFE SAFETY	Clutter <input type="checkbox"/> Doorway 90° <input type="checkbox"/> Informed Mgr <input type="checkbox"/> Notes: <u>Remove extension cords</u> <input type="checkbox"/> SMOKE ALARM <input type="checkbox"/> SPRINKLER LINE <input type="checkbox"/> DOOR CLOSER <input type="checkbox"/> HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)	—
Room No. <u>s.22(1)</u>	<input type="checkbox"/> Carpets/floor/baseboards - repair/replace/clean <input type="checkbox"/> Walls/ceiling/floors - repair/replace/clean/panel <input type="checkbox"/> Radiator/Electrical baseboard - repair/replace <input type="checkbox"/> Door-handset/hinges/frame/room# - repair/replace <input type="checkbox"/> Window-pane/frame/trim/hardware - repair/replace/clean <input type="checkbox"/> Sink/plumbing/taps/leaks - repair/replace/unplug <input type="checkbox"/> Electrical outlets/fixtures/cover plates - repair or replace <input type="checkbox"/> Pest-rats/mice/roaches/bedbugs/fruit flies - pest control	—
LIFE SAFETY	Clutter <input type="checkbox"/> Doorway 90° <input type="checkbox"/> Informed Mgr <input type="checkbox"/> Notes: <u>Vacant</u> <input checked="" type="checkbox"/> SMOKE ALARM <input type="checkbox"/> SPRINKLER LINE <input checked="" type="checkbox"/> DOOR CLOSER <input type="checkbox"/> HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)	2
Vacant	<u>s.22(1)</u>	
No Access		
Inspected	<u>s.22(1)</u>	

Notes:

Total

Standards of Maintenance By-law No. 5462

Violations

Room No.	<input type="checkbox"/> Carpets/floor/baseboards - repair/replace/clean <input type="checkbox"/> Walls/ceiling/floors - repair/replace/clean/panel <input type="checkbox"/> Radiator/Electrical baseboard - repair/replace <input type="checkbox"/> Door-handset/hinges/frame/room# - repair/replace Clutter <input type="checkbox"/> Y <input type="checkbox"/> Doorway 90° <input type="checkbox"/> N <input type="checkbox"/> Informed Mgr <input type="checkbox"/> Notes:	<input type="checkbox"/> Window-pane/frame/trim/hardware - repair/replace/clean <input type="checkbox"/> Sink/plumbing/taps/leaks - repair/replace/unplug <input type="checkbox"/> Electrical outlets/fixtures/cover plates - repair or replace <input type="checkbox"/> Pest-rats/mice/roaches/bedbugs/fruit flies - pest control	Violations
s.22(1)	<input type="checkbox"/> Carpets/floor/baseboards - repair/replace/clean <input type="checkbox"/> Walls/ceiling/floors - repair/replace/clean/panel <input type="checkbox"/> Radiator/Electrical baseboard - repair/replace <input type="checkbox"/> Door-handset/hinges/frame/room# - repair/replace Clutter <input type="checkbox"/> Y <input type="checkbox"/> Doorway 90° <input type="checkbox"/> N <input type="checkbox"/> Informed Mgr <input type="checkbox"/> Notes: <u>not attached</u>	<input type="checkbox"/> Window-pane/frame/trim/hardware - repair/replace/clean <input type="checkbox"/> Sink/plumbing/taps/leaks - repair/replace/unplug <input type="checkbox"/> Electrical outlets/fixtures/cover plates - repair or replace <input type="checkbox"/> Pest-rats/mice/roaches/bedbugs/fruit flies - pest control	—
LIFE SAFETY	<input checked="" type="checkbox"/> SMOKE ALARM <input type="checkbox"/> SPRINKLER LINE <input type="checkbox"/> DOOR CLOSER <input type="checkbox"/> HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)		1
s.22(1)	<input type="checkbox"/> Carpets/floor/baseboards - repair/replace/clean <input checked="" type="checkbox"/> Walls/ceiling/floors - repair/replace/clean/panel <input type="checkbox"/> Radiator/Electrical baseboard - repair/replace <input checked="" type="checkbox"/> Door-handset/hinges/frame/room# - repair/replace Clutter <input type="checkbox"/> Y <input type="checkbox"/> Doorway 90° <input type="checkbox"/> N <input type="checkbox"/> Informed Mgr <input type="checkbox"/> Notes:	<input checked="" type="checkbox"/> Window-pane/frame/trim/hardware - repair/replace/clean <input type="checkbox"/> Sink/plumbing/taps/leaks - repair/replace/unplug <input type="checkbox"/> Electrical outlets/fixtures/cover plates - repair or replace <input type="checkbox"/> Pest-rats/mice/roaches/bedbugs/fruit flies - pest control	2
LIFE SAFETY	<input checked="" type="checkbox"/> SMOKE ALARM <input type="checkbox"/> SPRINKLER LINE <input checked="" type="checkbox"/> DOOR CLOSER <input type="checkbox"/> HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)		2
s.22(1)	<input type="checkbox"/> Carpets/floor/baseboards - repair/replace/clean <input type="checkbox"/> Walls/ceiling/floors - repair/replace/clean/panel <input type="checkbox"/> Radiator/Electrical baseboard - repair/replace <input type="checkbox"/> Door-handset/hinges/frame/room# - repair/replace Clutter <input type="checkbox"/> Y <input type="checkbox"/> Doorway 90° <input type="checkbox"/> N <input type="checkbox"/> Informed Mgr <input type="checkbox"/> Notes:	<input type="checkbox"/> Window-pane/frame/trim/hardware - repair/replace/clean <input type="checkbox"/> Sink/plumbing/taps/leaks - repair/replace/unplug <input type="checkbox"/> Electrical outlets/fixtures/cover plates - repair or replace <input type="checkbox"/> Pest-rats/mice/roaches/bedbugs/fruit flies - pest control	—
LIFE SAFETY	<input type="checkbox"/> SMOKE ALARM <input type="checkbox"/> SPRINKLER LINE <input checked="" type="checkbox"/> DOOR CLOSER <input type="checkbox"/> HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)		1
s.22(1)	<input type="checkbox"/> Carpets/floor/baseboards - repair/replace/clean <input checked="" type="checkbox"/> Walls/ceiling/floors - repair/replace/clean/panel <input type="checkbox"/> Radiator/Electrical baseboard - repair/replace <input type="checkbox"/> Door-handset/hinges/frame/room# - repair/replace Clutter <input type="checkbox"/> Y <input type="checkbox"/> Doorway 90° <input type="checkbox"/> N <input type="checkbox"/> Informed Mgr <input type="checkbox"/> Notes: <u>Door frame</u>	<input type="checkbox"/> Window-pane/frame/trim/hardware - repair/replace/clean <input type="checkbox"/> Sink/plumbing/taps/leaks - repair/replace/unplug <input type="checkbox"/> Electrical outlets/fixtures/cover plates - repair or replace <input type="checkbox"/> Pest-rats/mice/roaches/bedbugs/fruit flies - pest control	1
LIFE SAFETY	<input type="checkbox"/> SMOKE ALARM <input type="checkbox"/> SPRINKLER LINE <input checked="" type="checkbox"/> DOOR CLOSER <input type="checkbox"/> HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)		1
s.22(1)	<input type="checkbox"/> Carpets/floor/baseboards - repair/replace/clean <input type="checkbox"/> Walls/ceiling/floors - repair/replace/clean/panel <input type="checkbox"/> Radiator/Electrical baseboard - repair/replace <input type="checkbox"/> Door-handset/hinges/frame/room# - repair/replace Clutter <input type="checkbox"/> Y <input type="checkbox"/> Doorway 90° <input type="checkbox"/> N <input type="checkbox"/> Informed Mgr <input type="checkbox"/> Notes:	<input checked="" type="checkbox"/> Window-pane/frame/trim/hardware - repair/replace/clean <input type="checkbox"/> Sink/plumbing/taps/leaks - repair/replace/unplug <input checked="" type="checkbox"/> Electrical outlets/fixtures/cover plates - repair or replace <input checked="" type="checkbox"/> Pest-rats/mice/roaches/bedbugs/fruit flies - pest control	3
LIFE SAFETY	<input checked="" type="checkbox"/> SMOKE ALARM <input type="checkbox"/> SPRINKLER LINE <input checked="" type="checkbox"/> DOOR CLOSER <input type="checkbox"/> HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)		2
s.22(1)	<input type="checkbox"/> Carpets/floor/baseboards - repair/replace/clean <input checked="" type="checkbox"/> Walls/ceiling/floors - repair/replace/clean/panel <input type="checkbox"/> Radiator/Electrical baseboard - repair/replace <input type="checkbox"/> Door-handset/hinges/frame/room# - repair/replace Clutter <input type="checkbox"/> Y <input type="checkbox"/> Doorway 90° <input type="checkbox"/> N <input type="checkbox"/> Informed Mgr <input type="checkbox"/> Notes:	<input checked="" type="checkbox"/> Window-pane/frame/trim/hardware - repair/replace/clean <input type="checkbox"/> Sink/plumbing/taps/leaks - repair/replace/unplug <input type="checkbox"/> Electrical outlets/fixtures/cover plates - repair or replace <input type="checkbox"/> Pest-rats/mice/roaches/bedbugs/fruit flies - pest control	2
LIFE SAFETY	<input type="checkbox"/> SMOKE ALARM <input type="checkbox"/> SPRINKLER LINE <input type="checkbox"/> DOOR CLOSER <input type="checkbox"/> HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)		—
Vacant	s.22(1)		
No Access			
Inspected			
Notes:			Total
			8
			7

City of Vancouver - FOI 2021-641 Page 8 of 31
LIFE SAFETY

Standards of Maintenance By-law No. 5462

Violations

Room No. S.22(1)

☐ Carpets/floor/baseboards - repair/replace/clean ☐ Window-pane/frame/trim/hardware - repair/replace/clean
☐ Walls/ceiling/floors - repair/replace/clean/panel ☐ Sink/plumbing/taps/leaks - repair/replace/unplug
☐ Radiator/Electrical baseboard - repair/replace ☐ Electrical outlets/fixtures/cover plates - repair or replace
☐ Door-handset/hinges/frame/room# - repair/replace ☐ Pest-rats/mice/roaches/bedbugs/fruit flies - pest control

Clutter Y ☐ Doorway 90° N ☐ Informed Mgr ☐

Notes:

LIFE SAFETY ☐ SMOKE ALARM ☐ SPRINKLER LINE ☒ DOOR CLOSER ☐ HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)

Room No. S.22(1)

☐ Carpets/floor/baseboards - repair/replace/clean ☐ Window-pane/frame/trim/hardware - repair/replace/clean
☐ Walls/ceiling/floors - repair/replace/clean/panel ☐ Sink/plumbing/taps/leaks - repair/replace/unplug
☐ Radiator/Electrical baseboard - repair/replace ☐ Electrical outlets/fixtures/cover plates - repair or replace
☐ Door-handset/hinges/frame/room# - repair/replace ☐ Pest-rats/mice/roaches/bedbugs/fruit flies - pest control

Clutter Y ☐ Doorway 90° N ☐ Informed Mgr ☐

Notes:

LIFE SAFETY ☐ SMOKE ALARM ☐ SPRINKLER LINE ☒ DOOR CLOSER ☐ HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)

Room No. S.22(1)

☐ Carpets/floor/baseboards - repair/replace/clean ☐ Window-pane/frame/trim/hardware - repair/replace/clean
☐ Walls/ceiling/floors - repair/replace/clean/panel ☐ Sink/plumbing/taps/leaks - repair/replace/unplug
☐ Radiator/Electrical baseboard - repair/replace ☐ Electrical outlets/fixtures/cover plates - repair or replace
☐ Door-handset/hinges/frame/room# - repair/replace ☐ Pest-rats/mice/roaches/bedbugs/fruit flies - pest control

Clutter Y ☐ Doorway 90° N ☐ Informed Mgr ☐

Notes:

LIFE SAFETY ☐ SMOKE ALARM ☐ SPRINKLER LINE ☒ DOOR CLOSER ☐ HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)

Room No. S.22(1)

☐ Carpets/floor/baseboards - repair/replace/clean ☐ Window-pane/frame/trim/hardware - repair/replace/clean
☒ Walls/ceiling/floors - repair/replace/clean/panel ☐ Sink/plumbing/taps/leaks - repair/replace/unplug
☐ Radiator/Electrical baseboard - repair/replace ☒ Electrical outlets/fixtures/cover plates - repair or replace
☐ Door-handset/hinges/frame/room# - repair/replace ☐ Pest-rats/mice/roaches/bedbugs/fruit flies - pest control

Clutter Y ☐ Doorway 90° N ☐ Informed Mgr ☐

Notes:

LIFE SAFETY ☐ SMOKE ALARM ☐ SPRINKLER LINE ☐ DOOR CLOSER ☐ HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)

Room No. S.22(1)

☐ Carpets/floor/baseboards - repair/replace/clean ☐ Window-pane/frame/trim/hardware - repair/replace/clean
☐ Walls/ceiling/floors - repair/replace/clean/panel ☐ Sink/plumbing/taps/leaks - repair/replace/unplug
☐ Radiator/Electrical baseboard - repair/replace ☐ Electrical outlets/fixtures/cover plates - repair or replace
☐ Door-handset/hinges/frame/room# - repair/replace ☐ Pest-rats/mice/roaches/bedbugs/fruit flies - pest control

Clutter Y ☐ Doorway 90° N ☐ Informed Mgr ☐

Notes:

LIFE SAFETY ☒ SMOKE ALARM ☐ SPRINKLER LINE ☐ DOOR CLOSER ☐ HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)

Room No. S.22(1)

☐ Carpets/floor/baseboards - repair/replace/clean ☐ Window-pane/frame/trim/hardware - repair/replace/clean
☐ Walls/ceiling/floors - repair/replace/clean/panel ☐ Sink/plumbing/taps/leaks - repair/replace/unplug
☐ Radiator/Electrical baseboard - repair/replace ☐ Electrical outlets/fixtures/cover plates - repair or replace
☒ Door-handset/hinges/frame/room# - repair/replace ☐ Pest-rats/mice/roaches/bedbugs/fruit flies - pest control

Clutter Y ☐ Doorway 90° N ☐ Informed Mgr ☐

Notes:

LIFE SAFETY ☒ SMOKE ALARM ☐ SPRINKLER LINE ☒ DOOR CLOSER ☐ HOLE IN WALL/FLOOR/CEILING (>1SQ.FT)


Vacant
No Access
Inspected

Notes:

Total

3

LIFE SAFETY



CF Number	CF-2021-015561	Date of Inspection (yyyy/mm/dd)	2021/11/17
Main Address	208 E GEORGIA ST	Specifics and/or Suite #	Life safety inspection of all tenant rooms and common areas
Tenant	London Hotel	Number of Storeys	4
Owner	PORTE INDUSTRIES LTD C/O TURNER MEAKIN MANAGEMENT CO LTD 108-2590 GRANVILLE ST VANCOUVER BC V6H 3H1	Permit Number	n/a
Agent	Lori Whitney, manager	Approved Use of Building/Land	SRA
District Zone	HA-1A	Present Use of Building/Land	SRA
Business License	21-131347 NH		

Reason for Inspection SRA Annual Inspection (life safety)

Narrative/Observations

In attendance: Mike Elliston, Lori Whitney (manager), Chauncey Carr (Atira supervisor), Will (Atira maintenance), Lawrance Wilson (Atira maintenance), Steve Mulligan (Atira maintenance).

Inspection conducted at 11am found 38 life safety violations as listed below:

1. Room ^{s 22(1)} - Door closer missing - No Photo
2. Room - Smoke alarm cover with bag - Photo 1
3. Room - Smoke alarm missing - Photo 2
4. Room - Smoke alarm not attached properly - Photo 3
5. Room - Door closer missing - No Photo
6. Room - Smoke alarm not attached properly - Photo 4
7. Room - Smoke alarm covered with bag - Photo 5
8. Room - Door closer missing - No Photo
9. Room - Smoke alarm missing - Photo 6
10. Room - Door closer missing - No Photo
11. Room - Door closer missing - No Photo
12. Room - Door closer missing - No Photo
13. Room - Smoke alarm missing - No Photo
14. Room - Smoke alarm cover missing - Photo 7
15. Room - Door closer missing - No Photo
16. Room - Door closer missing - No Photo
17. Room - Smoke alarm missing - Photo 8
18. Room - Smoke alarm missing - No Photo
19. Room - Smoke alarm missing - No Photo
20. Room - Door closer missing - No Photo
21. Room - Smoke alarm missing - No Photo
22. Room - Door closer missing - No Photo
23. Room - Door closer missing - No Photo
24. Room - Smoke alarm covered with bag - No Photo
25. Room - Door closer missing - No Photo
26. Room - Door closer missing - No Photo
27. Room - Smoke alarm missing - No Photo

28. Room ^{s.22} - Smoke alarm missing - No Photo
 29. Room ⁽¹⁾ - Smoke alarm missing - No Photo
 30. Room - Smoke alarm missing - No Photo
 31. Room - Door closer missing - No Photo
 32. Room - Door closer missing - No Photo
 33. Room - Door closer missing - No Photo
 34. Room - Smoke alarm missing - No Photo
 35. Room - Smoke alarm not attached properly - Photo 9
 36. Room - Smoke alarm missing - No Photo
 37. Room - Door closer missing - No Photo
 38. Room - Door closer missing - No Photo

Requirements

Violations of Standards of Maintenance #5462 - Section 15.1(1)

Recommendations

Immediate Order to R/O with cc to info@atira.ca

Photos Taken? ☒ Yes ☐ No

Date Report Made: November 23, 2021

Mike Elliston
Inspector's Name

Violation Details	
Violation Number: VI-2021-05949 Violation Date: Nov 17, 2021 Violation Type: Standards of Maintenance By-Law No. 5462 Resolve By: Violation Status:	Violation: Room 8.22(1) - Door closer missing Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed. Violation Instructions: Immediate Order
Violation Number: VI-2021-05970 Violation Date: Nov 17, 2021 Violation Type: Standards of Maintenance By-Law No. 5462 Resolve By: Violation Status:	Violation: Room 8.22(1) - Door closer missing Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed. Violation Instructions: Immediate Order
Violation Number: VI-2021-05971 Violation Date: Nov 17, 2021 Violation Type: Standards of Maintenance By-Law No. 5462 Resolve By: Violation Status:	Violation: Room 8.22(1) - Door closer missing Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed. Violation Instructions: Immediate Order

<p>Violation Number: VI-2021-05972</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room 5.22(1) - Smoke alarm missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>
<p>Violation Number: VI-2021-05973</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room 5.22(1) - Smoke alarm cover missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>
<p>Violation Number: VI-2021-05974</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room 5.22(1) - Door closer missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>

<p>Violation Number: VI-2021-05975</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room 5.22(1) - Smoke alarm missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>
<p>Violation Number: VI-2021-05976</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room 5.22(1) - Door closer missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>
<p>Violation Number: VI-2021-05977</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room 5.22(1) - Door closer missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>

<p>Violation Number: VI-2021-05978</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room §.22(1) - Door closer missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>
<p>Violation Number: VI-2021-05979</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room §.22(1) - Smoke alarm cover with bag</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>
<p>Violation Number: VI-2021-05980</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room §.22(1) - Smoke alarm not attached properly</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>

<p>Violation Number: VI-2021-05981</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room §.22(1) - Door closer missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>
<p>Violation Number: VI-2021-05982</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room §.22(1) - Smoke alarm missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>
<p>Violation Number: VI-2021-05983</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room §.22(1) - Smoke alarm not attached properly</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>

<p>Violation Number: VI-2021-05984</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room 5.22(1) - Smoke alarm covered with bag</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>
<p>Violation Number: VI-2021-05969</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room 5.22(1) - Door closer missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>
<p>Violation Number: VI-2021-05968</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room 5.22(1) - Door closer missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>

<p>Violation Number: VI-2021-05967</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room 5.22(1) - Smoke alarm missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>
<p>Violation Number: VI-2021-05966</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room s.22(1) - Smoke alarm not attached properly</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>
<p>Violation Number: VI-2021-05950</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room s.22(1) - Door closer missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>

<p>Violation Number: VI-2021-05951</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room s.22(1) - Smoke alarm missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>
<p>Violation Number: VI-2021-05952</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room s.22(1) - Smoke alarm covered with bag</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>
<p>Violation Number: VI-2021-05953</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room s.22(1) - Door closer missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>

<p>Violation Number: VI-2021-05954</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room s.22(1) - Door closer missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>
<p>Violation Number: VI-2021-05955</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room s.22(1) - Door closer missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>
<p>Violation Number: VI-2021-05956</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room s.22(1) - Door closer missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>

<p>Violation Number: VI-2021-05985</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room s.22(1) - Smoke alarm missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>
<p>Violation Number: VI-2021-05957</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room s.22(1) - Smoke alarm missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>
<p>Violation Number: VI-2021-05959</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room s.22(1) - Smoke alarm missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>

<p>Violation Number: VI-2021-05960</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room 5.22(1) - Smoke alarm missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>
<p>Violation Number: VI-2021-05961</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room 5.22(1) - Smoke alarm missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>
<p>Violation Number: VI-2021-05962</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room 5.22(1) - Door closer missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>

<p>Violation Number: VI-2021-05963</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room 5.22(1) - Smoke alarm missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>
<p>Violation Number: VI-2021-05964</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room 5.22(1) - Smoke alarm missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>
<p>Violation Number: VI-2021-05965</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room 5.22(1) - Door closer missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>

<p>Violation Number: VI-2021-05958</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room 5.22(1) - Smoke alarm missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>
<p>Violation Number: VI-2021-05986</p> <p>Violation Date: Nov 17, 2021</p> <p>Violation Type: Standards of Maintenance By-Law No. 5462</p> <p>Resolve By:</p> <p>Violation Status:</p>	<p>Violation: Room 5.22(1) - Door closer missing</p> <p>Standards of Maintenance #5462 - Section 15.1(1): 15.1 (1) Walls, floors, and roof constructions, including fire protective closures, sprinkler systems, including fire alarm and detection systems and other means of fire protection, shall be maintained in such a manner to afford the fire resistive properties and protection for which they were designed.</p> <p>Violation Instructions: Immediate Order</p>



Photo	Description
	<p>Photo 1 - Violation 2</p> <p>Room s.22(1)</p> <p>- Smoke alarm cover with bag</p>
	<p>Photo 2 - Violation 3</p> <p>Room s.22(1)</p> <p>- Smoke alarm missing</p>


Photo	Description
	<p>Photo 3 - Violation 4</p> <p>Room s.22(1)</p> <p>- Smoke alarm not attached properly</p>
	<p>Photo 4 - Violation 6</p> <p>Room s.22(1)</p> <p>- Smoke alarm not attached properly</p>



Photo	Description
	<p>Photo 5 - Violation 7</p> <p>Room s.22(1)</p> <p>- Smoke alarm covered with bag</p>
	<p>Photo 6 - Violation 9</p> <p>Room s.22(1)</p> <p>- Smoke alarm missing</p>




Photo	Description
	<p>Photo 7 - Violation 14</p> <p>Room s.22(1)</p> <p>- Smoke alarm cover missing</p>
	<p>Photo 8 - Violation 17</p> <p>Room s.22(1)</p> <p>- Smoke alarm missing</p>

Photo	Description
	<p>Photo 9 - Violation 35</p> <p>Room S.22(1)</p> <p>- Smoke alarm not attached properly</p>