

File No.: 04-1000-20-2023-029

February 22, 2023

s.22(1)

Dear s.22(1)

Re: Request for Access to Records under the Freedom of Information and Protection of Privacy Act (the "Act")

I am responding to your request of January 16, 2023 under the *Freedom of Information and Protection of Privacy Act, (the Act)*, for:

Sidewalk Inspection records, including emails, for the south side of 500 block Robson Street between Seymour and Richards, including:

- 1. Any inspections, photos, work orders, emails, and journal entries pertaining to the sidewalk in front of 570 Robson Street; and**
- 2. Any subsequent work orders for repairs on the sidewalk in front of 570 Robson Street.**

Date range: January 1, 2021 to January 10, 2023.

All responsive records are attached.

Under section 52 of the Act, and within 30 business days of receipt of this letter, you may ask the Information & Privacy Commissioner to review any matter related to the City's response to your FOI request by writing to: Office of the Information & Privacy Commissioner, info@oipc.bc.ca or by phoning 250-387-5629.

If you request a review, please provide the Commissioner's office with: 1) the request number (#04-1000-20-2023-029); 2) a copy of this letter; 3) a copy of your original request; and 4) detailed reasons why you are seeking the review.

Yours truly,

[Signed by Cobi Falconer]

Cobi Falconer, MAS, MLIS, CIPP/C
Director, Access to Information & Privacy
cobi.falconer@vancouver.ca
453 W. 12th Avenue Vancouver BC V5Y 1V4

If you have any questions, please email us at foi@vancouver.ca and we will respond to you as soon as possible. Or you can call the FOI Case Manager at 604-871-6584.

Encl. (Response Package)

:dl

CITY ENGINEERING SERVICES

N3

Blue - Streets
Green - Streets
Pink - Originating Office

RECORD OF CUTS AND/OR DAMAGED SURFACES

HANSEN WO# 1303472

20

This form is to be completed by the Foreman in charge of a crew making a cut and/or causing damage to a surface, and forwarded to Streets Operations for Permanent Repairs.

Cut(s) made by: W.W. No. of cuts: 1 No. of records: 2 of 3

Location of cut: S/S 500 blk ROBSON ST

Site address if different from above:

Cut(s) made in: Street; Shoulder; Lane; Sidewalk; Crossing; Curb; Blvd; Driveway; Other

Repair type: light asphalt; heavy asphalt; concrete; spraycap; gravel; turf; paint; loops; Other EXPOSED AGG

Purpose of cut(s): CONSTRUCTION (MIKE M.)

Dimensions of cut(s):

Thickness of surface cut(s): Depth of excavation(s):


Backfilled with: Temporary repaired with: Condition of Temp. repair: Needs Attention

Compacted by: hand tool; air tamper; mechanical tamper; or

Foreman's Comments Work Order No. CEWD 90441 B.W.O. No. Permit No.

Foreman's Signature Kelly Date: MAY 20/21 Superintendent's Signature

For Permanent Repair



Street's Inspector's cut measurements: 3.2' x 1.2'

Street's Inspector's Comments: + EXPOSED/AGG

Street's Foreman's Comments: Foreman's Signature Date Completed Units Completed

Summary table with columns: Units Charged (3.84), Work Order ERF (205), TOTAL \$ (1334.13), CODE (D5), RATE (347.43), CLIENT # (231007)

Blue - Streets
Green - Streets
Pink - Originating Office

CITY ENGINEERING SERVICES
RECORD OF CUTS AND/OR DAMAGED SURFACES

HANSEN WO# 1365390

This form is to be completed by the Foreman in charge of a crew making a cut and/or causing damage to a surface, and forwarded to Streets Operations for Permanent Repairs.

Cut(s) made by: STREETS (CIVIL) No. of cuts: 1 No. of records: 1 of 2

Location of cut: 5550 ROBSON ST

Site address if different from above:

Cut(s) made in: Street; Shoulder; Lane; Sidewalk; Crossing; Curb; Blvd; Driveway; Other EXPOSED AGGREGATE

Repair type: light asphalt; heavy asphalt; concrete; spraycap; gravel; turf; paint; loops; Other EXPOSED AGG.

Purpose of cut(s): INSTALL NEW T.S. BASE

Dimensions of cut(s): 2.6m x 1.2m

Thickness of surface cut(s): .14 Depth of excavation(s): 24"

Backfilled with: #9 Temporary repaired with: Hot Mix Cold Mix Gravel Condition of Temp. repair: Good Raised Settled Needs Attention

Compacted by: hand tool; air tamper; mechanical tamper; or


Foreman's Comments: Work Order No. 2015070 CER 1355810

B.W.O. No.:

Permit No.:

Foreman's Signature: Date: Superintendent's Signature

For Permanent Repair



Street's Inspector's cut measurements: 1.2 x 3.14

Refer to Projects: Taken from Cut Sheet:

#

Street's Inspector's Comments: Archeological Site: Chance Find:

Street's Foreman's Comments: Foreman's Signature: Date Completed

Units Completed

CREW #

Units Charged	<u>4.08</u>	Work Order ERF	<u>205</u>	TOTAL \$	<u>1,450.11</u>	
		CODE	<u>D5</u>	RATE	<u>355.42</u>	
					CLIENT #	<u>219927</u>

Blue - Streets
Green - Streets
Pink - Originating Office

CITY ENGINEERING SERVICES RECORD OF CUTS AND/OR DAMAGED SURFACES

HANSEN WO# 1365389

This form is to be completed by the Foreman in charge of a crew making a cut and/or causing damage to a surface, and forwarded to Streets Operations for Permanent Repairs.

Cut(s) made by: <u>STREETS (CIVIL)</u>	No. of cuts: <u>1</u>	No. of records: <u>2</u> of <u>2</u>
--	-----------------------	--------------------------------------

Location of cut: BLK ROSSON ST.

Site address if different from above:

Cut(s) made in: Street; Shoulder; Lane; Sidewalk; Crossing; Curb; Blvd; Driveway; Other _____

Repair type: light asphalt; heavy asphalt; concrete; spraycap; gravel; turf; paint; loops; Other _____

Purpose of cut(s): INSTALL & REMOVE BOXES

Dimensions of cut(s): 3.3m x 1.5m

Thickness of surface cut(s): .14m Depth of excavation(s): 24"

Backfilled with: H9 Temporary repaired with: Hot Mix Cold Mix Gravel Condition of Temp. repair: Good Raised Settled Needs Attention

Compacted by: hand tool; air tamper; mechanical tamper; or _____

Foreman's Comments: _____


Work Order No. CER 1355890

B.W.O. No.:

Permit No.:

Foreman's Signature: _____ Date: 11/25/2021 Superintendent's Signature: _____

For Permanent Repair



Street's Inspector's cut measurements:

1.6 x 3.4

Refer to Projects:

Taken from Cut Sheet:

Street's Inspector's Comments: TE/A

Archeological Site:

Chance Find:

Street's Foreman's Comments: _____ Foreman's Signature: _____ Date Completed: _____

Units Completed: _____

CREW #

Units Charged	<u>5.44</u>	Work Order ERF	<u>200</u>	TOTAL \$	<u>1,461.02</u>
---------------	-------------	----------------	------------	----------	-----------------

CODE	<u>DO</u>	RATE	<u>268.57</u>	CLIENT #	<u>219928</u>
------	-----------	------	---------------	----------	---------------



Work Order Summary

Work Order #: 1261510 RSw_TreePitExp_Robson St-Be
Asset ID #: 107731
Group Project #: 90307 RSw_TreePitExp_Robson St - Beatty to Granville Street Design
Location: 500 - 599 ROBSON ST
Operational Status: **Ref #1:** : **Ref #2:**
Service Request: **Contact Name:** **Phone#:**
Requested By: **Requested Date:** **Initiated Date:** Jan 13, 2021

Assigned By: **Assigned To:** /
Assigned Date: **Crew ID:** **Work Started:**
Result: **Work Completed:**
Comments:

Work Orders & Accomplishments:

WO#	Result	Completed Date
1261510	Incomplete	

Work Area Prefix: R **SAP Network #:** CERD90307 **WBS#:** CER-00256-HH-04
Parent Network: **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
	\$0.00	\$0.00	\$0.00
TOTAL	<u>\$0.00</u>	<u>\$0.00</u>	<u>\$0.00</u>



Work Order Summary

Work Order #: 1293938 RSw_Inst_Broom_100, 500 & 6
Asset ID #: 107731
Group Project #: 91242 RSw_Inst_Broom_100, 500 & 600 blk Robson Street Design
Location: 500 - 599 ROBSON ST
Operational Status: **Ref #1:** : **Ref #2:**
Service Request: **Contact Name:** **Phone#:**
Requested By: **Requested Date:** **Initiated Date:** Apr 23, 2021

Assigned By: **Assigned To:** /
Assigned Date: **Crew ID:** **Work Started:**
Result: **Work Completed:**
Comments:

Work Orders & Accomplishments:

WO#	Result	Completed Date
1293938	Incomplete	

Work Area Prefix: R **SAP Network #:** CERD91242 **WBS#:** CER-00261-AA-04
Parent Network: **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
	\$0.00	\$0.00	\$0.00
TOTAL	<u>\$0.00</u>	<u>\$0.00</u>	<u>\$0.00</u>



Work Order Summary

Work Order #: 1293940 RSw_Inst_Exposed_100 to 600
Asset ID #: 107731
Group Project #: 91243 RSw_Inst_Exposed_100 to 600 bk Robson Street Design
Location: 500 - 599 ROBSON ST
Operational Status: **Ref #1:** : **Ref #2:**
Service Request: **Contact Name:** **Phone#:**
Requested By: **Requested Date:** **Initiated Date:** Apr 23, 2021

Assigned By: RON BORGER **Assigned To:** AGOSTINHO PATRAO
Assigned Date: Aug 05, 2021 **Crew ID:** RCC20 **Work Started:**
Result: Completed **Work Completed:** Aug 05, 2021

Comments:

Work Orders & Accomplishments:

WO#	Result	Completed Date				
1293940	Completed	Aug 05, 2021				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Aug 05, 2021		Sidewalk - Exposed Aggregate	15	RCC20	AGOSTINHO PATRAO	

Work Area Prefix: R **SAP Network #:** CERD91243 **WBS#:** CER-00261-AA-04
Parent Network: **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
TOTAL	\$0.00	\$0.00	\$0.00



Work Order Summary

Work Order #: 1640989 RSw_Fit_NM 67-2022
Asset ID #: 107731
Group Project #: 94912 RSw_Fit_NM 67-2022 Streets Operations
Location: 500 - 599 ROBSON ST
Operational Status: **Ref #1:** : **Ref #2:**
Service Request: 2053794 **Contact Name:** Bea Hung **Phone#:** 6048716065
Requested By: **Requested Date:** **Initiated Date:** Nov 24, 2022

Assigned By: BLAIR GORDON TODD **Assigned To:** MARK ANSTICE
Assigned Date: Nov 18, 2022 **Crew ID:** RMS67 **Work Started:**
Result: Completed **Work Completed:** Nov 18, 2022
Comments: Crew 67 - Sidewalk Fillets - Non-MRN | Accomplishment Code: RSwAsFit

Work Orders & Accomplishments:

WO#	Result	Completed Date				
1640989	Completed	Nov 18, 2022				
Accomplishment Date		Description	Quantity	Truck#	Assigned To	Comments
Nov 18, 2022		Asphalt Fillet - Sidewalk	1	RMS67	MARK ANSTICE	ds

Work Area Prefix: R **SAP Network #:** EERD94912 **WBS#:** EER-00009-SF-NM-AP
Parent Network: **Billable:** N

Cost Summary	Estimated Costs	Actual Costs	Difference
Equipment	\$0.00	\$0.00	\$0.00
Labour	\$0.00	\$0.00	\$0.00
Material	\$0.00	\$0.00	\$0.00
Other	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
TOTAL	<u>\$0.00</u>	<u>\$0.00</u>	<u>\$0.00</u>