

File No.: 04-1000-20-2023-365

August 8, 2023

s.22(1)

Dear s.22(1)

Re: **Request for Access to Records under the Freedom of Information and Protection of Privacy Act (the "Act")**

I am responding to your request of June 20, 2023 under the ***Freedom of Information and Protection of Privacy Act*** for:

Record of incidents, requests for work, and complaints regarding wind storms, fallen trees and limbs, power outages, and trees to be removed in a one-block radius of West 15th Avenue and Balsam Street (the border of Larch St, West 14th Ave, Vine St, and West 16th Ave) including incidents, complaints, notes, and correspondence. Date range: June 20, 2021 to June 19, 2023.

All responsive records are attached. Some information in the records has been severed (blacked out) under s.22(1) of the Act. You can read or download this section here:

http://www.bclaws.ca/EPLibraries/bclaws_new/document/ID/freeside/96165_00.

Under section 52 of the Act, and within 30 business days of receipt of this letter, you may ask the Information & Privacy Commissioner to review any matter related to the City's response to your FOI request by writing to: Office of the Information & Privacy Commissioner, info@oipc.bc.ca or by phoning 250-387-5629.

If you request a review, please provide the Commissioner's office with: 1) the request number (#04-1000-20-2023-365); 2) a copy of this letter; 3) a copy of your original request; and 4) detailed reasons why you are seeking the review.

Yours truly,

[Signed by Cobi Falconer]

Cobi Falconer, MAS, MLIS, CIPP/C
Director, Access to Information & Privacy
cobi.falconer@vancouver.ca
453 W. 12th Avenue Vancouver BC V5Y 1V4

If you have any questions, please email us at foi@vancouver.ca and we will respond to you as soon as possible. Alternatively, you can call the FOI Case Manager at 604-871-6584.

Encl. (Response package)

:pm

2315 W 15th Av

VANTREE

07/26/2023 12:51 pm

Tree Detail with Work History

Serial 16186

ADDRESS	2,315	W 15TH AV	SPECIES	PRCEAT
ASSIGNED	N		COMMON NAME	PISSARD PLUM
NEIGHBOURHOOD	8		HEIGHT	4
CELL	4		DBH	16.00
SITE COMMENT			CONDITION	6
ON STREET BLOCK	2,300	W 15TH AV	CURB	Y
STREET SIDE	ODD		ROOT BARRIER	N
WIRE			BASE PLANTING	N
LAND USE	R		NEXT MAINTENANCE	SYS LARGE
PLANT AREA	5		LIGHTS	N
TREE COMMENT				
MAINTENANCE COMMENT				

WORK HISTORY

DATE WORKED	WORK TYPE	CREW LEADER	CODE	IPM INFESTATION LEVEL	COMMENT
03/29/1995	SYS SMALL	SP			
05/07/2001	SYS SMALL	RC			
05/04/2005	SYS SMALL	DB			
06/15/2010	CLEARANCE	GO	C-SIDEWALK		
09/06/2016	INSPECT	DY			
11/01/2016	INSPECT	DY			
05/21/2017	PRIORITY-I	BLP	R-BHB		
05/18/2018	SYS LARGE	TK			
02/28/2023	PRIORITY-I	JOC	R-STORM		

2315 W 15th Av

VANTREE Service Request Details Request ID: 233265

Address: 2315 W 15TH AV

Neighbourhood: 8

Request

Name: s.22(1)

Address: , , ,

E-mail: s.22(1)

Phone: s.22(1)

Comments: <File attached in EM Pro> Big Tree branch broken from snow fall and blocking road.

Date Received: 02/26/2023

Received By: DI

Request Type: B/BRANCH

Work Required: PRIORITY 3

Inspection

Comments: BHB on plum over parking lane. Disp Jon C. to attend.

Date: 02/27/2023

Inspected By: KK

Notification: 02/27/2023
NO CONTACT

Inventory Information with Last Work History

Common Name	NB	Cell	DBH	Next Maint.	Cond	Wire	Serial
PISSARD PLUM	8	4	16.0	SYS LARGE	6		16186
Tree Comment:							
Maint. Comment:							
On the: 2300 Block of W 15TH AV				Side: ODD			

2496 W 15th Av

VANTREE

07/26/2023 1:01 pm

Tree Detail with Work History

Serial 16258

ADDRESS 2,496 W 15TH AV

ASSIGNED N

NEIGHBOURHOOD 8

CELL 8

SITE COMMENT

ON STREET BLOCK 3,100 LARCH ST

STREET SIDE EVEN

WIRE

LAND USE R

PLANT AREA N

SPECIES PRCEAT

COMMON NAME PISSARD PLUM

HEIGHT 2

DBH 10.00

CONDITION 6

CURB Y

ROOT BARRIER N

BASE PLANTING N

NEXT MAINTENANCE SYS SMALL

LIGHTS N

TREE COMMENT

MAINTENANCE COMMENT

WORK HISTORY

DATE WORKED	WORK TYPE	CREW LEADER	CODE	IPM INFESTATION LEVEL	COMMENT
03/28/1995	SYS SMALL	SP			
04/20/2001	SYS SMALL	BC			
06/23/2004	CLEARANCE	JN			
12/21/2006	PRIORITY-I	SDD	R-STORM		
01/09/2007	PRIORITY-I	DD	R-STORM		sr88948
07/26/2017	INSPECT	HK			
08/04/2017	SYS SMALL	JAB			
05/01/2020	INSPECT	BC			
01/04/2022	PRIORITY-I	MC	R-BHB		
01/04/2022	INSPECT	SDD			
01/13/2022	PRIORITY-I	JOC	R-FAILURE		branch down on blvd.
02/28/2023	PRIORITY-I	JOC	R-STORM		

2496 W 15th Av

VANTREE Service Request Details Request ID: 205606

Address: 2496 W 15TH AV

Neighbourhood: 8

Request

Name: s.22(1)

Address: s.22(1)

E-mail:

Phone: s.22(1)

Comments: A large branch about 4 m long has broken from the boulevard tree on Larch st, but is still attached.

Date Received: 01/02/2022

Received By: DI

Request Type: B/BRANCH

Work Required: ROUTINE

Inspection

Comments: BHB at this location in cell 8. Info and photo fwd to Josh C. to dispatch crew (9:20AM).

Date: 01/04/2022

Inspected By: SDD

Notification: 01/04/2022
NO CONTACT

Inventory Information with Last Work History

Common Name	NB	Cell	DBH	Next Maint.	Cond	Wire	Serial
PISSARD PLUM	8	8	10.0	SYS SMALL	6		16258
Tree Comment:							
Maint. Comment:							
PISSARD PLUM	8	10	8.0	SYS SMALL	8		16263
Tree Comment:							
Maint. Comment:							
PISSARD PLUM	8	12	14.0	SYS SMALL	6		16266
Tree Comment:							
Maint. Comment:							
On the: 3100 Block of LARCH ST				Side: EVEN			
QUEEN ELIZABETH MAPLE	8	6	3.0	SYS SMALL	8		199927
Tree Comment:							
Maint. Comment:							
On the: 2400 Block of W 15TH AV				Side: EVEN			

2496 W 15th Av

VANTREE Service Request Details Request ID: 233408

Address: 2496 W 15TH AV

Neighbourhood: 8

Request

E-mail: s.22(1)

Name: s.22(1)

Address: s.22(1) Vancouver,

Phone: s.22(1)

Comments: Broken branch impeding the sidewalk in front of this house.

Date Received: 02/26/2023

Received By: DI

Request Type: B/BRANCH

Work Required: PRIORITY 3

Inspection

Comments: Broken branch. Disp crew to attend.

Date: 03/08/2023

Inspected By: KK

Notification: 03/08/2023
NO CONTACT

Inventory Information with Last Work History

Common Name	NB	Cell	DBH	Next Maint.	Cond	Wire	Serial
PISSARD PLUM	8	8	10.0	SYS SMALL	6		16258
Tree Comment:							
Maint. Comment:							
PISSARD PLUM	8	10	8.0	SYS SMALL	8		16263
Tree Comment:							
Maint. Comment:							
PISSARD PLUM	8	12	14.0	SYS SMALL	6		16266
Tree Comment:							
Maint. Comment:							
On the: 3100 Block of LARCH ST				Side: EVEN			
QUEEN ELIZABETH MAPLE	8	6	3.0	SYS SMALL	8		199927
Tree Comment:							
Maint. Comment:							
On the: 2400 Block of W 15TH AV				Side: EVEN			

2385 W 15th Av

VANTREE

07/26/2023 12:51 pm

Tree Detail with Work History

Serial 131509

ADDRESS	2,385	W 15TH AV	SPECIES	CTBG
ASSIGNED	N		COMMON NAME	GLOBE CATALPA
NEIGHBOURHOOD	8		HEIGHT	2
CELL	3		DBH	10.00
SITE COMMENT			CONDITION	4
ON STREET BLOCK	2,300	W 15TH AV	CURB	Y
STREET SIDE	ODD		ROOT BARRIER	N
WIRE			BASE PLANTING	N
LAND USE	R		NEXT MAINTENANCE	SYS SMALL
PLANT AREA	5		LIGHTS	N

TREE COMMENT

MAINTENANCE COMMENT

WORK HISTORY

DATE WORKED	WORK TYPE	CREW LEADER	CODE	IPM INFESTATION LEVEL	COMMENT
01/23/1997	R-PLANT	AP			
05/07/2001	SYS LARGE	RC			
03/14/2002	SYS SMALL	LJ			
05/04/2005	SYS SMALL	DB			
07/11/2008	PRIORITY-I	HK	R-STORM		
07/14/2009	PRIORITY-I	GO	R-MVA		
08/24/2009	SYS SMALL	RC			
07/21/2010	INSPECT	GO			
09/22/2010	PRIORITY-I	DD	R-FAILURE		
08/27/2012	SYS SMALL	BLP			
07/18/2013	INSPECT	DB			
08/28/2014	SYS SMALL	DY			
06/16/2021	INSPECT	BC			Cprune: sidewalk clearance.
08/30/2021	INSPECT	BC			
03/08/2023	PRIORITY-I	BJH	R-STORM		section down blocking sidewalk
03/08/2023	INSPECT	KK	R-STORM		
07/13/2023	CLEARANCE	JAB	C-SIDEWALK		

2385 W 15th Av

VANTREE Service Request Details Request ID: 233996

Address: 2385 W 15TH AV

Neighbourhood: 8

Request

Name: s.22(1)

Address: , , ,

E-mail: s.22(1)

Phone: s.22(1)

Comments: <File attached in EM Pro> Main branch of boulevard tree broken by heavy snow and lying on sidewalk. There is another one same block at east end of the street. While you are here could you remove a dead Rowan tree s.22(1)

Date Received: 02/27/2023

Received By: DI

Request Type: B/BRANCH

Work Required: PRIORITY 3

Inspection

Comments: Section of catalpa down blocking sidewalk and needs to be cleared. Disp Brad H.

Date: 03/08/2023

Inspected By: KK

Notification: 03/08/2023
NO CONTACT

Inventory Information with Last Work History

Common Name	NB	Cell	DBH	Next Maint.	Cond	Wire	Serial
GLOBE CATALPA	8	3	10.0	SYS SMALL	4		131509
Tree Comment:							
Maint. Comment:							
On the: 2300 Block of W 15TH AV				Side: ODD			

2396 W 14th Av

VANTREE

07/26/2023 1:09 pm

Tree Detail with Work History

Serial 193143

ADDRESS 2,396 W 14TH AV

ASSIGNED N

NEIGHBOURHOOD 8

CELL 6

SITE COMMENT

ON STREET BLOCK 2,300 W 14TH AV

STREET SIDE EVEN

WIRE

LAND USE R

PLANT AREA N

SPECIES CHLA

COMMON NAME LAWSON CYPRESS/PORT ORFORD CED

HEIGHT 5

DBH 36.00

CONDITION 0

CURB N

ROOT BARRIER N

BASE PLANTING N

NEXT MAINTENANCE STUMP

LIGHTS N

TREE COMMENT

R-dead

MAINTENANCE COMMENT

WORK HISTORY

DATE WORKED	WORK TYPE	CREW LEADER	CODE	IPM INFESTATION LEVEL	COMMENT
05/29/2002	INVENTORY	GO			
06/25/2008	CLEARANCE	BC			
10/21/2009	INSPECT	GO			
06/09/2010	INSPECT	GO			
07/05/2021	INSPECT	BC	R-DEAD		
10/19/2021	INSPECT	BC	R-DEAD		Tree needs to be removed but is not in ad
01/13/2022	INSPECT	BC	R-DEAD		
03/08/2022	INSPECT	BC	R-DEAD		Tree is listed as a removal s.22(1)
03/15/2022	REMOVAL	MC	R-DEAD		

2396 W 14th Av

VANTREE Service Request Details Request ID: 198198

Address: 2396 W 14TH AV

Neighbourhood: 8

Request

Name: s.22(1)

Address: s.22(1)

E-mail: s.22(1)

Phone: s.22(1)

Comments: Giant cedar appears to be dead and could be dangerous. It needs to be removed.

Date Received: 07/02/2021

Received By: YX

Request Type: INSPECT

Work Required: ROUTINE

Inspection

Comments: Dead cypress in cell 6. R-dead.

Date: 07/05/2021

Inspected By: BC

Notification: 07/05/2021
PHONE

Inventory Information with Last Work History

Common Name	NB	Cell	DBH	Next Maint.	Cond	Wire	Serial
JAPANESE SNOWBELL Tree Comment: Maint. Comment:	8	8	3.0	SYS SMALL	9		232048
ENGLISH HOLLY Tree Comment: Maint. Comment:	8	10	12.8	SYS SMALL	7		14837
On the: 3000 Block of BALSAM ST Side: EVEN							
COMMON HORSECHESTNUT Tree Comment: Maint. Comment:	8	4	26.0	SYS LARGE	6		14834
LAWSON CYPRESS/PORT ORFORD CED Tree Comment: R-dead Maint. Comment:	8	6	36.0	STUMP	0		193143
On the: 2300 Block of W 14TH AV Side: EVEN							

Address: 2396 W 14TH AV

Neighbourhood: 8

Request

E-mail: s.22(1)

Phone: s.22(1)

Name: s.22(1)

Address: s.22(1)

Comments: s.22(1) has concerns about the health of the large cedar tree located on the
s.22(1)
s.22(1) Isn't sure if City tree or private tree. It's on the private
property side of the sidewalk. You can see it using Google Street View. It
was difficult to determine whether this was a private tree by using VanMap
and the Street Tree Open Data catalogue did have a cedar type of tree

Date Received: 07/14/2021

Received By: DI

Request Type: INSPECT

Work Required: ROUTINE

Inspection

Comments: Lawson cypress tree is already listed for removal in cell 6.

Date: 07/15/2021

Inspected By: BC

Notification: 07/15/2021
PHONE

Inventory Information with Last Work History

Common Name	NB	Cell	DBH	Next Maint.	Cond	Wire	Serial
JAPANESE SNOWBELL	8	8	3.0	SYS SMALL	9		232048
Tree Comment:							
Maint. Comment:							
ENGLISH HOLLY	8	10	12.8	SYS SMALL	7		14837
Tree Comment:							
Maint. Comment:							
On the: 3000 Block of BALSAM ST				Side: EVEN			
COMMON HORSECHESTNUT	8	4	26.0	SYS LARGE	6		14834
Tree Comment:							
Maint. Comment:							
LAWSON CYPRESS/PORT ORFORD CED	8	6	36.0	STUMP	0		193143
Tree Comment: R-dead							
Maint. Comment:							
On the: 2300 Block of W 14TH AV				Side: EVEN			

2396 W 14th Av

VANTREE Service Request Details Request ID: 203031

Address: 2396 W 14TH AV

Neighbourhood: 8

Request

Name: s.22(1)

Address: s.22(1)

E-mail:

Phone: s.22(1)

Comments: They received a call from Urban Forestry saying that this dead tree would be removed in September but it is still there and now it is dropping all of its needles everywhere. They are very anxious for it to be removed.

Date Received: 10/18/2021

Received By: DI

Request Type: REMOVAL

Work Required: ROUTINE

Inspection

Comments: Tree needs to be removed but is not in advanced state of decay for cell 6. Superintendent will have to schedule the work.

Date: 10/19/2021

Inspected By: BC

Notification: 10/19/2021
NO CONTACT

Inventory Information with Last Work History

Common Name	NB	Cell	DBH	Next Maint.	Cond	Wire	Serial
JAPANESE SNOWBELL	8	8	3.0	SYS SMALL	9		232048
Tree Comment:							
Maint. Comment:							
ENGLISH HOLLY	8	10	12.8	SYS SMALL	7		14837
Tree Comment:							
Maint. Comment:							
On the: 3000 Block of BALSAM ST Side: EVEN							
COMMON HORSECHESTNUT	8	4	26.0	SYS LARGE	6		14834
Tree Comment:							
Maint. Comment:							
LAWSON CYPRESS/PORT ORFORD CED	8	6	36.0	STUMP	0		193143
Tree Comment: R-dead							
Maint. Comment:							
On the: 2300 Block of W 14TH AV Side: EVEN							

2396 W 14th Av

VANTREE Service Request Details Request ID: 206047

Address: 2396 W 14TH AV

Neighbourhood: 8

Request

Name: s.22(1)

Address: s.22(1)

E-mail:

Phone: s.22(1)

Comments: Large cedar tree is dead. Boulevard tree needs to be removed. Caller says s.22(1) was told the tree would be removed September 2021 but it is still on the boulevard. Previous request 101015171233

Date Received: 01/12/2022

Received By: DI

Request Type: REMOVAL

Work Required: ROUTINE

Inspection

Comments: Cypress tree in cell 6 is already listed as removal as of July 2021, R-dead.

Date: 01/13/2022

Inspected By: BC

Notification: 01/13/2022
NO CONTACT

Inventory Information with Last Work History

Common Name	NB	Cell	DBH	Next Maint.	Cond	Wire	Serial
JAPANESE SNOWBELL	8	8	3.0	SYS SMALL	9		232048
Tree Comment:							
Maint. Comment:							
ENGLISH HOLLY	8	10	12.8	SYS SMALL	7		14837
Tree Comment:							
Maint. Comment:							
On the: 3000 Block of BALSAM ST Side: EVEN							
COMMON HORSECHESTNUT	8	4	26.0	SYS LARGE	6		14834
Tree Comment:							
Maint. Comment:							
LAWSON CYPRESS/PORT ORFORD CED	8	6	36.0	STUMP	0		193143
Tree Comment: R-dead							
Maint. Comment:							
On the: 2300 Block of W 14TH AV Side: EVEN							

2396 W 14th Av

VANTREE Service Request Details Request ID: 208205

Address: 2396 W 14TH AV

Neighbourhood: 8

Request

E-mail:

Phone: s.22(1)

Name: s.22(1)

Address: s.22(1)

Comments: Citizen advises that the tree in s.22(1) has put 2 different requests (15171233, 15675280) through to have it removed. It has not been removed. s.22(1) would like to speak to someone in the department regarding this. Please contact s.22(1) soon.

Date Received: 03/07/2022

Received By: DI

Request Type: REMOVAL

Work Required: ROUTINE

Inspection

Comments: Tree in cell 6 is listed as a removal, R-dead. Homeowner has been waiting patiently. WO generated.

Date: 03/08/2022

Inspected By: BC

Notification: 03/08/2022
NO CONTACT

Inventory Information with Last Work History

Common Name	NB	Cell	DBH	Next Maint.	Cond	Wire	Serial
JAPANESE SNOWBELL	8	8	3.0	SYS SMALL	9		232048
Tree Comment:							
Maint. Comment:							
ENGLISH HOLLY	8	10	12.8	SYS SMALL	7		14837
Tree Comment:							
Maint. Comment:							
On the: 3000 Block of BALSAM ST				Side: EVEN			
COMMON HORSECHESTNUT	8	4	26.0	SYS LARGE	6		14834
Tree Comment:							
Maint. Comment:							
LAWSON CYPRESS/PORT ORFORD CED	8	6	36.0	STUMP	0		193143
Tree Comment: R-dead							
Maint. Comment:							
On the: 2300 Block of W 14TH AV				Side: EVEN			

2406 W 15th Av

VANTREE

07/26/2023 1:03 pm

Tree Detail with Work History

Serial 223706

ADDRESS	2,406	W 15TH AV	SPECIES	PPNIIT
ASSIGNED	N		COMMON NAME	LOMBARDY POPLAR
NEIGHBOURHOOD	8		HEIGHT	6
CELL	19		DBH	94.00
SITE COMMENT			CONDITION	0
ON STREET BLOCK	3,100	BALSAM ST	CURB	N
STREET SIDE	ODD		ROOT BARRIER	N
WIRE	CE		BASE PLANTING	N
LAND USE	R		NEXT MAINTENANCE	STUMP
PLANT AREA	N		LIGHTS	N

TREE COMMENT

R-Failure. split open

MAINTENANCE COMMENT

WORK HISTORY

DATE WORKED	WORK TYPE	CREW LEADER	CODE	IPM INFESTATION LEVEL	COMMENT
12/12/2007	INSPECT	GO			
01/15/2008	SYS LARGE	JJC			
10/20/2009	PRIORITY-I	JJC	R-FAILURE		
02/21/2011	INSPECT	GO			
02/29/2012	INSPECT	LL			
03/15/2012	INSPECT	DG			
06/05/2012	SYS LARGE	KB			
07/23/2015	INSPECT	BC			
08/24/2015	PRIORITY-I	DY	R-BHB		
09/14/2015	INSPECT	BC			
05/27/2016	INSPECT	DG			
11/07/2021	INSPECT	JJC			
11/08/2021	INSPECT	BC			
11/08/2021	PRIORITY-I	MC	R-BHB		
11/09/2021	SYS LARGE	MC			Removed deadwood and reduced a couple
11/25/2021	INSPECT	RAB			No loose looking branches at this time.Has
06/15/2023	REMOVAL	MC	R-FAILURE		
06/15/2023	INSPECT	KK	R-FAILURE		

2406 W 15th Av

VANTREE Service Request Details Request ID: 243681

Address: 2406 W 15TH AV

Neighbourhood: 8

Request

Name: s.22(1)

Address: s.22(1)

E-mail: s.22(1)

Phone: s.22(1)

Comments: Crews are on site working on a gigantic tree whose branches fell and cause an evacuation. s.22(1) are asking and requesting the tree removed because its the s.22(1) Fire Department said a huge portion is rotted.

Date Received: 06/14/2023

Received By: DI

Request Type: B/BRANCH

Work Required: ROUTINE

Inspection

Comments: Lombardi popular at back lane in cell 19 split and crushed vehicles and property damage. Crew started removal. Still head and spar to remove. Incident reports created by Mike C.

Date: 06/15/2023

Inspected By: KK

Notification: 06/15/2023
NO CONTACT

Inventory Information with Last Work History

Common Name	NB	Cell	DBH	Next Maint.	Cond	Wire	Serial
LOMBARDY POPLAR Tree Comment: R-Failure. split open Maint. Comment:	8	19	94.0	STUMP	0	CE	223706
PLANTING SITE Tree Comment: Maint. Comment:	8	21	3.0	TBP-C	9		197322
PLANTING SITE Tree Comment: Maint. Comment:	8	22	3.0	TBP-C	9		197013
PLANTING SITE Tree Comment: Maint. Comment:	8	23	3.0	TBP-C	9		188957
PLANTING SITE Tree Comment: Maint. Comment:	8	24	3.0	TBP-C	9		188956
On the: 3100 Block of BALSAM ST Side: ODD							
HEDGE MAPLE Tree Comment: Maint. Comment:	8	3	11.0	SYS SMALL	9		16215
On the: 2400 Block of W 15TH AV Side: EVEN							

2406 W 15th Av

VANTREE Service Request Details Request ID: 243885

Address: 2406 W 15TH AV

Neighbourhood: 8

Request

E-mail: s.22(1)

Phone:

Name: s.22(1)

Address: , , ,

Comments: *2nd SR.

<File attached in EM Pro> Diameter - approximately 4 feet or more.
Length- approximately 50 ft.
On balsam south of west 15th ave

Date Received: 06/16/2023

Received By: DI

Request Type: REMOVAL

Work Required: ROUTINE

Inspection

Comments: Tree in cell 19 was removed.

Date: 06/19/2023

Inspected By: MC

Notification: 06/19/2023
NO CONTACT

Inventory Information with Last Work History

Common Name	NB	Cell	DBH	Next Maint.	Cond	Wire	Serial
LOMBARDY POPLAR Tree Comment: R-Failure. split open Maint. Comment:	8	19	94.0	STUMP	0	CE	223706
PLANTING SITE Tree Comment: Maint. Comment:	8	21	3.0	TBP-C	9		197322
PLANTING SITE Tree Comment: Maint. Comment:	8	22	3.0	TBP-C	9		197013
PLANTING SITE Tree Comment: Maint. Comment:	8	23	3.0	TBP-C	9		188957
PLANTING SITE Tree Comment: Maint. Comment:	8	24	3.0	TBP-C	9		188956
On the: 3100 Block of BALSAM ST Side: ODD							
HEDGE MAPLE Tree Comment: Maint. Comment:	8	3	11.0	SYS SMALL	9		16215
On the: 2400 Block of W 15TH AV Side: EVEN							

2406 W 15th Av

VANTREE Service Request Details Request ID: 243936

Address: 2406 W 15TH AV

Neighbourhood: 8

Request

Name: s.22(1)

Address: s.22(1), Vancouver,

E-mail: s.22(1)

Phone: s.22(1)

Comments: A large tree had fallen on W 15th Avenue earlier this week and the City crew had come by to remove some debris. There is still a large amount of debris that remains (e.g., a mound of wood) on the City boulevard and s.22(1) would like to know when the City will come by to clean the rest up. Please contact.

Date Received: 06/16/2023

Received By: DI

Request Type: B/BRANCH

Work Required: ROUTINE

Inspection

Comments: Tree was removed in cell 19.

Date: 06/19/2023

Inspected By: MC

Notification: 06/19/2023
NO CONTACT

Inventory Information with Last Work History

Common Name	NB	Cell	DBH	Next Maint.	Cond	Wire	Serial
LOMBARDY POPLAR Tree Comment: R-Failure. split open Maint. Comment:	8	19	94.0	STUMP	0	CE	223706
PLANTING SITE Tree Comment: Maint. Comment:	8	21	3.0	TBP-C	9		197322
PLANTING SITE Tree Comment: Maint. Comment:	8	22	3.0	TBP-C	9		197013
PLANTING SITE Tree Comment: Maint. Comment:	8	23	3.0	TBP-C	9		188957
PLANTING SITE Tree Comment: Maint. Comment:	8	24	3.0	TBP-C	9		188956
On the: 3100 Block of BALSAM ST Side: ODD							
HEDGE MAPLE Tree Comment: Maint. Comment:	8	3	11.0	SYS SMALL	9		16215
On the: 2400 Block of W 15TH AV Side: EVEN							

2406 W 15th Av

VANTREE Service Request Details Request ID: 243882

Address: 2406 W 15TH AV

Neighbourhood: 8

Request

Name: s.22(1)

Address: s.22(1) Vancouver,

E-mail:

Phone: s.22(1)

Comments: Related to case # 201000660524

The large tree that came down this week still hasn't been removed and citizen would like to know when the clean up will be done as the lane between W 15th Ave to W 16th Ave along Balsam St is still closed and there are temporary no parking signs in front of citizen's house, also large portion of the tree is still standing and citizen would like to know will the

Date Received: 06/16/2023

Received By: DI

Request Type: REMOVAL

Work Required: ROUTINE

Inspection

Comments: Tree in cell 19 was removed.

Date: 06/19/2023

Inspected By: MC

Notification: 06/19/2023
NO CONTACT

Inventory Information with Last Work History

Common Name	NB	Cell	DBH	Next Maint.	Cond	Wire	Serial
LOMBARDY POPLAR Tree Comment: R-Failure. split open Maint. Comment:	8	19	94.0	STUMP	0	CE	223706
PLANTING SITE Tree Comment: Maint. Comment:	8	21	3.0	TBP-C	9		197322
PLANTING SITE Tree Comment: Maint. Comment:	8	22	3.0	TBP-C	9		197013
PLANTING SITE Tree Comment: Maint. Comment:	8	23	3.0	TBP-C	9		188957
PLANTING SITE Tree Comment: Maint. Comment:	8	24	3.0	TBP-C	9		188956
On the: 3100 Block of BALSAM ST Side: ODD							
HEDGE MAPLE Tree Comment: Maint. Comment:	8	3	11.0	SYS SMALL	9		16215
On the: 2400 Block of W 15TH AV Side: EVEN							

2406 W 15th Av

VANTREE Service Request Details Request ID: 243884

Address: 2406 W 15TH AV

Neighbourhood: 8

Request

Name: s.22(1)

Address: s.22(1)

E-mail:

Phone: s.22(1)

Comments: *Complaint- Wishes to make a complaint re: the tree issues s.22(1) s.22(1) There is a 7 storey high tree s.22(1) that had large branches fall (and crush 2 vehicles and take out power lines). The fire dept attended and stated the tree is rotted out on the inside and would be removed in a few days. It has been a few days and this has not been done. They have also asked what the status of the tree is (and

Date Received: 06/16/2023

Received By: DI

Request Type: REMOVAL

Work Required: ROUTINE

Inspection

Comments: Tree in cell 19 was removed.

Date: 06/19/2023

Inspected By: MC

Notification: 06/19/2023
NO CONTACT

Inventory Information with Last Work History

Common Name	NB	Cell	DBH	Next Maint.	Cond	Wire	Serial
LOMBARDY POPLAR Tree Comment: R-Failure. split open Maint. Comment:	8	19	94.0	STUMP	0	CE	223706
PLANTING SITE Tree Comment: Maint. Comment:	8	21	3.0	TBP-C	9		197322
PLANTING SITE Tree Comment: Maint. Comment:	8	22	3.0	TBP-C	9		197013
PLANTING SITE Tree Comment: Maint. Comment:	8	23	3.0	TBP-C	9		188957
PLANTING SITE Tree Comment: Maint. Comment:	8	24	3.0	TBP-C	9		188956
On the: 3100 Block of BALSAM ST Side: ODD							
HEDGE MAPLE Tree Comment: Maint. Comment:	8	3	11.0	SYS SMALL	9		16215
On the: 2400 Block of W 15TH AV Side: EVEN							



ARBORICULTURE INCIDENT REPORT

(Report of Damage Due to Tree / Branch Failure)

(Revised Nov 16, 2012)

18
Pics ✓

Incident Location: 2406 W 15th AVE

Incident Date: 11 / 05 / 21 Incident Time: 10:00 (a.m.) / p.m.

MM DD YY

Inspector / Crew Leader: JOSHUA CATES

Inspection Date: 11 / 05 / 21 Inspection Time: 11:00 (a.m.) / p.m.

MM DD YY

(LOMBARDY POPLAR) Tree and Event Information

Tree Species: PPN11T Cell: 19 DBH (in): 94" HGT (ft): 100 ft

Whole Tree Failure: Yes / (No) If No, size of broken limb: Diameter: 10" Length: 20 ft

Condition of part that failed (e.g. "dead"): LIVE

Probable Cause(s) for Failure: CAVITY W/ ANIMAL NESTING
ACTIVITY COUPLED WITH WIND LOAD.

Defects Outwardly Visible, Prior to Failure: Yes / (No) Point of failure visible from the ground: Yes / (No)

Photographs (show number taken): Address: 2x Entire Tree: 2x Fallen Branch: 2x

Point of Attachment: 2x Damage: 2x On which Camera: 604.861-1749

Damage Information

Description of Damage to Property / Vehicle: s.22(1) - ELECTRICAL
BURNS TO GARAGE DOORS, FENCE, ROOF,
GUTTERS, ETC. ...

Damaged Vehicle Information:

1. Make: _____ Model: _____ License: _____

2. Make: _____ Model: _____ License: _____

Property / Vehicle Owner: _____ Phone: _____

Property / Vehicle Owner Address: _____

Completed by: JOSHUA CATES Phone: s.22(1) Date: 11 / 05 / 21

Inspector / Arborist Signature MM DD YY

Superintendent Section

Listed in VanTree: (Yes) / No Serial # 223706 Species Code: PPN11T Condition: 6

Last Drive-by Inspection Prior to Failure: Date: 03 / 24 / 21 conducted by: BC#JSC

MM DD YY

Any work noted at Drive-by Inspection: N/A

Location where photos were uploaded to: H Drive - Risk Management

Reviewed by: [Signature] Phone: 861-1749 Date: 11 / 29 / 21

Supervisor Signature MM DD YY



















