
File No.: 04-1000-20-2025-855

November 14, 2025

s.22(1)



Dear s.22(1)

Re: **Request for Access to Records under the Freedom of Information and Protection of Privacy Act (the “Act”)**

I am responding to your request of November 7, 2025 under the **Freedom of Information and Protection of Privacy Act** for:

**Record of last Fire Inspection report for 5718 Willow Street, dated May 28, 2021.
Date range: May 1, 2021 to November 6, 2025**

All responsive records are attached.

Under Part 5 of the Act, you may ask the Information & Privacy Commissioner to review any matter related to the City's response to your FOI request by writing to: Office of the Information & Privacy Commissioner, info@oipc.bc.ca or by phoning 250-387-5629.

If you request a review, please provide the Commissioner's office with: 1) the request number (2025-855); 2) a copy of this letter; 3) a copy of your original request; and 4) detailed reasons why you are seeking the review.

Yours truly,

Kevin Tuerlings, FOI Case Manager, for

[Signed by Kevin Tuerlings]

**Cobi Falconer, MAS, MLIS, CIPP/C
Director, Access to Information & Privacy**

If you have any questions, please email us at foi@vancouver.ca and we will respond to you as soon as possible. You may also contact 3-1-1 (604-873-7000) if you require accommodation or do not have access to email.

Encl. (Response Package)

:lg



Vancouver Fire and Rescue Services

Property - Inspection History Report

Property Address: **5718 WILLOW ST**

FH District: **22**

Building Name: **King David High School**

FPO District: **39**

Constr. Type: _____

Date of Report: **November 14, 2025**

Business Name: **King David High School**

Last Inspection Date: **May 27, 2021**

Property class: **A2 General Assembly**

Inspection Class General Assembly - A2	Inspected Date May 27, 2021	Status Satisfactory	Assigned To FP General	Inspector Craig, Christian
--	---------------------------------------	-------------------------------	----------------------------------	--------------------------------------

Note: RIOK

- RIOK = Jess Sabado
- AL NSD: 21/Aug/18
- Sprinkler NSD: 21/Aug/18
- FE NSD: 21/Aug/18
- EL NSD: 21/Aug/18
- Housekeeping: Sat
- Egress: Sat

Inspection Class FPO General	Inspected Date June 20, 2017	Status Satisfactory	Assigned To FP Lieut UBC	Inspector Motkaluk, Randy
--	--	-------------------------------	------------------------------------	-------------------------------------

Note: riok

nsd: 8/31/17

Inspection Class FPO General	Inspected Date June 29, 2015	Status Satisfactory	Assigned To FP Lieut UBC	Inspector Pickett, Edward
--	--	-------------------------------	------------------------------------	-------------------------------------

Note: RIOK

All fire safety equipment OK
Verbal on storage in parkade

Inspection Class FPO General	Inspected Date September 11, 2012	Status Satisfactory	Assigned To FP Lieut UBC	Inspector Tierney, David
--	---	-------------------------------	------------------------------------	------------------------------------

Note: routine fire inspection

regular inspection of this premise.
the parkade has a storage issue that can be resolved exponentially.
met with the head master of the school and she mentioned that the issue will be taken care of
priority one .the issue with the storage is teachers old projects boxes of old materials,etc

Inspection Class Schools	Inspected Date February 16, 2011	Status Satisfactory	Assigned To FP Capt Care Facilities/Schools	Inspector Schultz, William
------------------------------------	--	-------------------------------	---	--------------------------------------



Vancouver Fire and Rescue Services

Property - Inspection History Report

Property Address: **5718 WILLOW ST**

FH District: **22**

Building Name: **King David High School**

FPO District: **39**

Note: #1

met with bldg engr routine fire insp
Note to fire alarm panel request additional work required.
they will fax results from Bartec.ok

Inspection Class FPO General	Inspected Date February 16, 2011	Status Satisfactory	Assigned To FP Lieut UBC	Inspector Tierney, David
--	--	-------------------------------	------------------------------------	------------------------------------

Note: met with school mgr

Met with sandy Jorgenson school mgr to conduct routine fire insp
assisted by Jess Sabado bldg engr.Determined that fire alarm panel has additional work required.
they will advise Bartec as per note and fax capt of results.

Inspection Class Care/Hospitals	Inspected Date December 16, 2010	Status Satisfactory	Assigned To FP Lieut UBC	Inspector Tierney, David
---	--	-------------------------------	------------------------------------	------------------------------------

Note: f/s review location

Inspection Class Care/Hospitals	Inspected Date August 4, 2010	Status Satisfactory	Assigned To FP Lieut UBC	Inspector Tierney, David
---	---	-------------------------------	------------------------------------	------------------------------------

Inspection Class FPO General	Inspected Date May 27, 2010	Status Satisfactory	Assigned To FP Lieut UBC	Inspector Tierney, David
--	---------------------------------------	-------------------------------	------------------------------------	------------------------------------

Inspection Class Meeting	Inspected Date May 27, 2010	Status Satisfactory	Assigned To FP General	Inspector Douglas, William
------------------------------------	---------------------------------------	-------------------------------	----------------------------------	--------------------------------------

Note: 1

Obtained contacts . BD

Inspection Class Care/Hospitals	Inspected Date April 8, 2009	Status Satisfactory	Assigned To FP Lieut UBC	Inspector Tierney, David
---	--	-------------------------------	------------------------------------	------------------------------------

Note: locked

Inspection Class Preplan	Inspected Date May 6, 2008	Status Satisfactory	Assigned To FP Lieut UBC	Inspector Ayre, Garry
------------------------------------	--------------------------------------	-------------------------------	------------------------------------	---------------------------------

Note: entered FDM data; 750 w 41st is fire Co.



Vancouver Fire and Rescue Services

Property - Inspection History Report

Property Address: **5718 WILLOW ST**

FH District: **22**

Building Name: **King David High School**

FPO District: **39**

750 W 41st Ave is fire Co.'s response address. remote annunciator panel inside door (5ft. south).
5718 Willow entrance has main annunciator panel

Inspection Class FPO General	Inspected Date May 1, 2008	Status Satisfactory	Assigned To FP Lieut UBC	Inspector Ayre, Garry
--	--------------------------------------	-------------------------------	------------------------------------	---------------------------------

Note: fdm notes

Inspection Class Care/Hospitals	Inspected Date April 8, 2008	Status Satisfactory	Assigned To FP Lieut UBC	Inspector Ayre, Garry
---	--	-------------------------------	------------------------------------	---------------------------------

Inspection Class Fire Safety Plan Review	Inspected Date July 29, 2005	Status Satisfactory	Assigned To FP General	Inspector Nygard, Gary
--	--	-------------------------------	----------------------------------	----------------------------------